

UNIVERSAL

Machinists' Handbook


A Practical Handbook For

Machinists

Engineers

Draftsmen

Aviation Mechanics



Students

Tool Makers

Pattern Makers

Auto Mechanics

*Will Save You Time and Mistakes
Arranged So You Can Understand It.*

Contains Valuable Tables, Formulas and Data on Practical Shop
Problems — Bolts — Screws — Drills — Gears — Angles
Areas and Circumference of Circles — Square and Cube
Roots — Decimals — Multipliers — Metric Measure
Pipe Fitting — Tapers — Tempering Steel
S. A. E. Tables — Diesel Engine Repair
Milling Machine, Lathe and Shaper
Operation—Micrometer Reading
Geometry and Trigonometry
Problems — Welding
6-point Logarithms of
Numbers to 10,000
Miscellaneous
Data

Copyright 1951 By
CHARLES SHIELDS
St. Louis, Mo.


PRICE \$2.00

SHIELDS PUBLISHING COMPANY


3031 NORTH BROADWAY

ST. LOUIS, MO., U. S. A.

FROUSSARD PORTABLE BORING MACHINES




Vertical and Horizontal, All Purpose Machine for Boring Sleeves, Cylinders, Tubes, Engines, Pumps, Compressors, Etc., in Place.
Write For Further Information



THE MULTIPLE FLEXIBLE COUPLING

A rugged heavy duty, flexible Shaft Coupling for Connecting Motors and Engines to Machinery Where Direct Connections Are Required.

TRY ONE ON YOUR TOUGHEST INSTALLATION



We manufacture a complete line of Special and Standard Speed Reducers, consisting of Spur, Bevel, Helical, Herringbone and Worm Gear Drives. Any Ratio for fractional Horsepower on up. Send your Speed Reduction Problems to us.

Multiple Boring Machine Co.
2221 Lucas Ave. St. Louis, Mo.

UNIVERSAL MACHINISTS HANDBOOK

Saves Time

ELIMINATES ERRORS — ARRANGED FOR QUICK AND EASY REFERENCE

•

A PRACTICAL HANDBOOK

for Today's

Machinists • Engineers • Draftsmen
Aviation Mechanics • Students • Tool
Makers • Pattern Makers • Auto
Mechanics • And all others in Mechan-
ical, Technical and Allied Fields.

by

CHARLES SHIELDS
MECHANICAL ENGINEER

•

**SHIELDS PUBLISHING COMPANY
PUBLISHERS**

3031 North Broadway, St. Louis, Mo., U. S. A.

PRICE \$2.00

P R E F A C E

One of the greatest needs of technical and mechanical fields today is well trained mechanics and workers who are skilled not only with their hands — but who are also trained to think about their immediate tasks and those further up the line.

This Handbook is meant for both beginners and experienced mechanics alike who are anxious to do their work so well that progress is assured. It offers in simple, technical form, vital time, labor and error saving information — arranged, indexed and cross-referenced in such a way that it can be found quickly and easily.

Actual experience of mechanics, engineers, draftsmen, etc., has dictated what information should be contained in the Universal Machinists Handbook. Every effort has been made to make this one book more valuable and easier to use than the usual bulky volumes necessary to find adequate information.

Over thirty-six years have elapsed since the first edition of this Handbook was offered as a crude blueprint book. During its fifteen editions, many changes have taken place in machines, tools, parts and materials. These changes have made it necessary to add much new data in order to keep it up-to-date. Material no longer vital has been eliminated.

This Fifteenth Edition is completely revised and thoroughly enlarged to cover wider fields of shop activities than ever before. Every effort has been made to give only the best, most modern and practical data used in today's highly developed machine shop and engineering practice.

Suggestions and criticisms from users of this book are always welcome.

THE PUBLISHERS

CHAPTER INDEX CONTENTS

	Page		Page
Angles	163	Mensuration	168-169-170
Belting	119	Milling Machine.....	42-43-87-102-103-104-105
Bolts, Threads, Screws and Taps.....	24	Pipe Fittings	133
Cams and Cam Cutting.....	109-117	Tapers	141
Decimals	153	Tempering Steel	193
Diesel and Gas Engine.....	234	Thread Cutting	38-61-126
Drills and Speeds.....	46	To Take Accurate Measurements.....	9
Gears	63	Trigonometric Functions	173
Geometry	163	Weights	205
Keys, Key Seats.....	127	Welding	248
Lathe and Lathe Tools.....	58		
Lettering	106		
Logarithms of Numbers from 1 to 10,000 (6 point).....	177-187		

FIFTEENTH EDITION
REVISED and ENLARGED

ALPHABETICAL INDEX

A		Board Measure	210
Acme Standard Thread	35	Boring and Reaming.....	31
Adjustment of Micrometers	18	Boring Work Mounted on	
Air Brake Compressors	242	Lathe Carriage	55
Alignment of Centers	16	Brass and Bronze	268
Allowances for Fits	191	Brickwork	85
Allowance Tables for Bores of Gears.....	90	British Association Standard Thread.....	29
Aluminum	220	British Standard Pipe Flanges.....	134
Aluminum Cast and Sheet	197	Brown & Sharpe Spindles,	
Aluminum Pipe Sizes.....	140	Arbors, Collets, Tapers.....	141
Aluminum Welding	197	Brown & Sharpe Taper Shanks.....	141
Always Use Belt Thickness That is		Building Materials	210
Correct for Pulley	120		
American Coarse-Thread Tap Drills.....	44	C	
American Fine-Thread Tap Drills.....	45	Caliper, Setting Inside.....	11
American or National Bolts and Nuts.....	24	Caliper, to Set an Outside.....	10
An "Atmosphere"	173	Caliper, Reading A Heimaphrodiate.....	12
Angles and Circles, Shfelds	164	Cam Cutting	109-110
Angles Corresponding with Parts of a		Cam Milling Attachment	118
Circle	156	Cam Cutting Attachment	110-117
Angles and Distances	157	Carburetor Adjusting	245
Angles Inscribed	165	Carpenter's Rules Roof Framing.....	232
Angles-Triangles	163	Case Hardening Cast Iron.....	219
Anneal Brass	191	Case Hardening Wrought Iron.....	193
Anneal Tool Steel	191	Cast Iron	254
Application	266	Cast Iron Harden.....	160
Approximate Cutting Speeds		Cast Iron Pipe Weights.....	134
Turning and Boring.....	163	Casting Shrinkage	226
Apothecaries' Measure	229	Center Drilling	46
Apothecaries Weight	227	Center Gauge	83
Approximate Weight and		Centering Irregular Shapes	15
Strength of Cordage	225	Centering Work	87
Approximate Weights of Boiler Tubes.....	205	Change Gears for Milling	
Approximate Weights of		Spirals on the Milling Machine.....	87
Cast Iron Gears.....	70	Change Gears for Thread Milling.....	42-43
Approximate Weights of		Chart of Wrench and Socket Openings	
Various Metals	206	and Sizes of Bolts and Nuts They	
Area of Circles in Square Feet.....	157	Fit	34
Areas, of Numbers from		Circular and Angular Measure.....	227
.000079 to 783828	177-187	Circumference and Areas of Circles.....	160
Area and Volume of		Circumferences of Numbers	
Spherical Segments	108	From .05142 to 3138.5	177-187
Areas and Volumes	151	Cloth Measure	229
A. S. M. E. Standard Machine		Co-Efficients of Linear Expansion.....	253
Screws, Tap Drills	26	Color and Temperature in Heating	
Atomic Weights	222	Steel	195-196
Avordupois or Commercial Weight.....	227	Cold Rolled Low Carbon Sheets	
Arc Welding Data	272	and Strip	199
B		Comparative Strength of Timber	
Bars and Plates	159	and Cast Iron	232
Bearing Adjustment	239	Comparative Weights of Steel	
Bell Center Punch	15	and Brass Bars	219
Belting Section	119	Compound for Welding Cast Steel.....	190
Belt Cement	119	Compression Springs	189
Belting, Horsepower of Single Leather.....	125	Computing Lengths of Curved Sheets.....	200
Bevels	149	Computing the Lead	81
Bevel Gears, See Gears	65	Convenient Multipliers	161
Bevel Gearing Formulas	67	Converting Nautical Miles to	
Bevel Gears Rules	68	Statute Miles	154
Bevel Gears Set-Over for Cutting.....	96	Construction of the Piston.....	236
Bevel Protractor	22	Copper Tubing Open Ends.....	207
Blow Holes in Cast Iron.....	197	Cost	266
Boring Bars and Holders.....	61	Corrosion and Heat Resisting Alloys.....	200
		Corrugated Sheet Data.....	203-204
		Cosecant and Secant	176
		Cosines and Sines	174

Counterbore Sizes for	
Cap Screws and Machine Screws	48
Cotangent and Tangents	175
Crane Chain	218
Crankshaft Testing	194
Crankshaft Turning	193
Cubic Measure	226
Cutting Cast Iron	265
Cutting Depends on Composition of	
Cast Iron	266
Cutting a Gear on a Lathe	91
Cutting a Left Hand Screw Thread	39
Cutting Hints	268
Cutting Spiral Gears	75-36
Cutting Steel	262
Cube Root, Numbers from	
0.2154 to 9.9967	177-187
Cutting Tools for Cincinnati Shapers	126
Cutting Torch	268

D

Decimal Equivalents of an Inch	153
Decimal Equivalents of 128ths, 64ths, 32nds, 16ths, 8ths, of an Inch, Shields	154
Decimal Equivalents of Millimeters and Fractions of Millimeters	155
Decimal Equivalents of 7ths, 14ths, 28ths, 6ths, 12ths, 24ths of an Inch	153
Decimals, Equivalents of Drills, Drill Rods and Letter Size Drills	49
Decimal Equivalents of Inches, Feet, and Yards	156
Decimals of a Foot for Each 1/32 of an Inch	150
Decimal Equivalents of Ounces and Pounds	156
Decimal Parts of a Foot in Square Inches	157
Definition of Angles	159
Design of Worm Gearing	85
Diametral and Circular Pitch of Gears	94
Diametral Pitch Formulas	72
Diameter of Reamer	23
Diesel Engine Parts	234-235
Different Standards for Wire Gauge and Zinc Gauge	216
Distance Across Corners	162
Divider Method	15
Double Compounds of Gearing or the Use of Six Change Gears	100
Double Depth of Threads	35
Drawn Brass Angles	208
Drills, Carbon Steel	47
Drill Chuck Mounted in Tailstock	70
Drilling a Cored Hole	36
Drills, High Speed	46
Drills, Letter Sizes of Drills	49
Drills, Sharpening	50
Duplex Oiling	244
Dysprosium	222
Dry Measure	228

E

Eccentrics, Machining	131
Electrical Carrying Capacity of Pure Copper Wire	210
Electro-Chemical Series of Elements	163
Electric Generators	242
End Mill Sharpening for	
Milling Machine	118
Equipment	266
Estimating Electrode Consumption	282
Estimating Weights of Different Metals in Cubic Inch and Cubic Foot for Foundry	226
Evaporative Power of One Pound of Various Fuels at Atmospheric Pressure (15 Pounds)	154
Expansion of Bodies by Heat	171
Expansion and Contraction	251
Extruded Bronze Angles	207
Extension Springs	188

F

Filing and Polishing	56
Fitting Tapers to Gauges	148
Finishing the End of a Thread	38
Fire Hose Coupling	137
Flame Cutting Procedure	278

Flame Cutting Time and Material	278
Flanges, Pipe, British Standard	136
Flat Centering Drill	46
Formed Threading Tool	103
Formula for the Dieedral Angle Formed by any Two Adjacent Faces	171
For Setting Tools to Cut Square Threads	27
Four-Cylinder Engines	246
Four-Spline Fittings, S.A.E. Standard	190
Foot Bros. Table of Working Stresses Used for the Strength of Worm Gears	92
Free Cutting Steels	200
Front Clearance Table	34

G

Galvanized and Stainless Steel Gauges	206
Galvanized Steel Sheets—Approx. Weight Per Sheet in Pounds	210
Gas Pressure for Cutting with L & M Cutting Torches	260
Gas Pressure for Different Size Tips	251
Gears, Angles to Set Index Head of Milling Machine When Cutting Teeth	96
Gears, Bevel	65
Gears, Bevel Rules	67
Gears, Change Gears for Milling Spirals on the Milling Machine	87
Gears, Circular Pitch Formulas	72
Gears, Circular and Diametral Pitch of Gears	94
Gears, Comparative Sizes of Gear Teeth Involute	82
Gear Cutting Attachment	73
Gears, Cutting a Gear on a Lathe	91
Gears, Diametral Pitch Formulas	72
Gearing Design of Worm Gearing	85
Gears, End Thrust on Bevel Gears	69
Gears, Factors for Calculating Strength of Bevel Gears	69
Gears, Formulas for Calculating Bevel Gears	66
Gears, Formulas for Determining the Dimensions of Gears, by Metric Pitch (Metric System)	92
Gears, Formulas for Helical Gear Calculations	84
Gears, Foot Bros. Table of Working Stresses used for the Strength of Worm Gears	92
Gears, Herring Bone	90
Gears, Instructions on Worm Gears	87-88
Gears, Internal	93
Gears, Internal Spur	63
Gears, Module System Translation Formulas (Metric System)	91
Gears, Racks and Pinions	83
Gears, Rules for Figuring Bevel Gears	68
Gears, Rules and Formulae for Spur Gears	64
Gears, Rules and Formulae for Worm Gearing	85
Gears, Rules for Obtaining Ratio of the Gears Necessary to Cut a Given Spiral	94
Gears, Set-Over for Cutting Bevel	96
Gears, Showing Depth of Space and Thickness of Tooth in Spur Gears Cut with B. & S. Mfs. Cutter	94
Gears, Sizing and Cutting of Gears	71
Gears, Spiral Cutting	73-81
Gears, Spiral Instructions	72
Gears, Spiral Rules	67
Gears, Spur	63
Gears, Strength of Gear Teeth (Lewis)	82
Gears, Strength of Internal Gears	93
Gears, Table for Block or Multiple Indexing for Gear Teeth Cutting	95
Gears, Table of Observed Tooth Dimensions for Spiral Gears	89
Gears, Weights	70
Gears, Worms and Worm Gears	89
General Arc Welding Data	270
Germanium	222
Gib Keys Dimensions	131
Glass, How to Drill	28
Glossary of Terms-V-Belt Drives	122
Governor Mechanism	239

Grease Cup Fitting, Thread Cut.....	32
Grinding in the Lathe.....	54
Grinding Twist Drills.....	50
Grinding Wheel Speeds.....	54
Grinding Wheels for Various Kinds of Work.....	

H

Hafnium.....	222
Heat Conductivity of Metals.....	253
Heat Treatments for Carbon and Alloy Steels, S.A.E.....	198-199
Heat Treatment of Welded Structures.....	280
Horsepower of an Electrical Motor.....	125
Horsepower of an Explosive Motor or Gasoline Engine.....	125
Horsepower of Steam Engines.....	125
How to Calculate Change Gears for Thread Cutting.....	41
How to Determine Curves for Brick and Stone Arches.....	233
How to Find Bevels and Length of Rafters.....	233
How to Read and Hold a Micrometer.....	12
How to Read Micrometers, Graduated for Metric Measure.....	17

I

Identifying Metals by Spark Testing.....	284
Information for Use of Weight Tables.....	224
Index for Angles for Cutting Spirals.....	97-98-99
Indexing, Block or Multiple.....	95
Index Head, Angle Setting.....	96
Index Movements of Spiral Head for Longitudinal Graduating on a Milling Machine.....	102-103-104
Index Plate for Brown & Sharpe Milling Machine.....	102-103-104
Index Plate for Cincinnati Milling Machine.....	105
Imperial Standard Measure.....	229
Iridium.....	222
Inscribed Angles, Shields.....	165
Inside Caliper.....	11-12
Inside Micrometer.....	13
Instructions on Spiral Gears.....	72
Instructions on Worm Gears.....	87
Internal Gears.....	93
International Standard Thread, Metric System.....	24

J

Jacobs Tapers.....	51
Jarno Taper Shanks.....	146

K

Keep Your Belt Speeds Up.....	119
Kennamill Cutter, Single-Bladed.....	109
Keys, Gib.....	131
Keys, Used, Different Types.....	130
Keyways, Half Round.....	128
Key Seat Clamps.....	130
Keyways, For Cutter.....	128
Keyseats and Setscrews for Gears.....	128
Keyseats in Shafting.....	132
Key Seats, Standard IXL.....	127
Keys and Keyways, U. S. Navy Stand.....	129
Knurling Tool.....	62

L

Lanthanum.....	222
Lapping.....	56-57
Lathe Tools.....	59
Lathe Tool Sharpening.....	58
Lead Burning Torch.....	249
Lead Pipe and Calking Lead.....	134
Left-Hand Cutting-Off Tool.....	60
Left-Hand Offset Turning Tools.....	59
Left Hand Screwthread Cutting.....	39
Lengths of Circular Arcs.....	150
Length, Miscel. Units of.....	227
Lettering, Free Hand (Diagram).....	106
Letter Sizes of Drills.....	49
Lighting the Torch.....	260
Linear Measure.....	229
Liquid or Wine Measure.....	228
Lithium.....	222
Locating Center Holes.....	15

Logarithms of Numbers from 2.00000 to 2.99957 (5-point).....	177-187
Long Measure (Measures of Length).....	225
Lubricants for Cutting Tools.....	104

M

Machining Allegheny Stainless Steels.....	52
Machine Bolts and Screws, Whitworth Standard.....	26
Machining Eccentrics.....	131
Machine Screws, Flat Head.....	30
Machine Screws, Flister-Head.....	31
Machine Screws, Oval Head.....	32
Machine Screws, Round Head.....	33
Machine Screw Taps, A.S.M.E. Standard.....	26
Machine Racks and Pinions.....	83
Machine Screws, Tap Drills.....	37
Materials, Inspection.....	107
Magnaflux Tests.....	288
Machine and Wood Screw Gauge.....	27
Measurements, How to Take Accurate.....	9
Measuring Instruments.....	20
Measuring the Length of a Shaft with a Firm Joint Caliper.....	102
Measures of Pressure.....	227
Measuring Screw Threads.....	40
Measuring the Setover.....	148
Measure Used for Diameters and Areas of Electric Wires.....	228
Mechanical Adjustments.....	237
Melting Points of Common Metals.....	215
Melting Points and Color Scale.....	194
Melting Points of Metals.....	196-197-253
Melting Point of Substances.....	214
Mensuration.....	168-169-170
Metric Conversion Tables.....	230
Metric and English Linear Measure.....	155
Metric Pitch Dimensions of Gears (Metric System).....	92
Metric System.....	229
Metric Threads—(Metric System).....	149
Micrometers Graduated to Ten Thousandths.....	17
Micrometers, How to Read and Hold.....	12
Milling Cutters and Arbors.....	84
Milled Steel Stud Dimensions.....	36
Milling a Woodruff Keyway in a Shaft.....	84
Minimum Pulley Diameters.....	123
Miscellaneous Data.....	207
Miscellaneous Metric System.....	231
Miscellaneous S.A.E. Standard, Hexagon Head Screws, Castle and Plain Nuts and Drills.....	28-30
Miscellaneous Units of Length.....	227
Morse Tapers.....	145
Multiple Threads.....	29
Multipliers, Useful.....	158

N

Nails, Estimating Quantity.....	225
National (American) Standard Fire Hose Coupling Screw Thread.....	137
National Coarse Thread Tap Drills.....	44
National Fine-Thread Tap Drills.....	45
Nautical Measure.....	228
Notes on Corrugated Sheets.....	206
Numbers.....	229

O

Oval Head Machine Screws.....	32
Outside Calipers.....	9
Overloads or Peak Loads.....	123

P

Paper Measure.....	229
Pipe, Briggs Pipe Standard.....	133
Pipe, British Standard Pipe Flanges.....	136
Pipe, Cast Iron, Weight Table.....	134
Pipe, Cold Drawn Seamless Steel Tubing Weight Computing Formulas.....	135
Pipe, Fire Hose Coupling Screw Thread.....	137
Pipe, Lead Pipe and Calking Lead.....	134
Pipe, Round Welded Stainless Steel Tubing.....	138-139
Pipe, Standard Dimensions of Couplings.....	133
Pipe, Standard Dimensions for Nipples.....	134

Pipe Threads, External Threads.....	140	Sharpen Reamers	96
Pipe Threads, Internal Threads.....	140	Sheaves for Belts	121
Pipe, U. S. Standard Steam, Gas and Water Pipe	133	Sheet Metal Thickness and Weight	217
Pitch, Circular and Diametral of Gears	94	Shields Brass and Bronze	
Pitch Diameter and Root Diameter of Screw Threads	40	Bushing Table in all Sizes	221
Pitch, Sizes of Wires for Use with Various Pitch Thread	33	Shields Decimal Equivalents of Twist Drills, Drill Rods, and Letter Sizes of Drills	49
Piston Ring—Gap Clearance	236	Shields Definitions of Angles-Triangles.....	163
Piston Ring	236	Shields-Definitions of Polygons.....	165
Plow Steel Wire Rope	218	Shields Definitions of Polyhedrons.....	166-172
Polygons	165	Shields Definitions of Quadrilaterals	166
Polyhedrons	166-172	Shields Definitions of Three Round Bodies	167
Praseodymium	222	Shields Inscribed Angles.....	165
Preparation	266	Shields U. S. Standard Bolt & Threads Table	24
Pressure Table, Type L. Standard Cutting Torch	263	Shipping Measure	228
Prevention of Rusting in of Screws.....	193	Shoulder and Radius Forming.....	47
Proportions of Square Shafts and Fit Allowances	192	Significance of Typical Combinations	286
Properties of Structural Shapes	209	Silicon Manganese Steels	200
Punching the Center	15	Sines and Cosines	174
Q		Sizes of Wires for Use with Various Pitch Threads	33
Quadrilaterals, Shields Definitions	166	Sizes of Wrenches to Use for Counterbores and Spot Facers.....	48
Quadruple Threads	43	Six-Cylinder Engines	247
R		Softened Cast-Iron for Drilling.....	200
Radium	222	Solution by Triangles by Natural Lines	172
Radon	222	Specific Gravity	207
Reading a Heimaphrodiate Caliper.....	12	Specific Gravity of Liquids.....	215
Reading the Vernier English Measure.....	21	Specific Gravity of Metals.....	215
Reading the Vernier on Universal Bevel Protractor.....	21	Specific Gravity and Weight of Solid Substances, Except Metals and Wood.....	214
Reaming in the Lathe	127	Speeds and Feeds for Carbon Steel Drills	47
Reamers, Taper Pin Recommended Practice for Bevel Gearing.....	67	Speeds and Feeds for High Speed Drills	46
Reciprocals of common Units.....	152	Speeds for Engine or Lineshaft Drive Belts.....	120
Reciprocals of Numbers From 10000.000 to 1.00100.....	177-187	Speeds, for Turning and Boring.....	163
Regulation of the Flame	248	Special Equipment	242
Regular Polygons	165-172	Special Lubrication	243
Right Angled Triangles Solving.....	170	Spiral Gear Cutting	73-74
Right-Hand Cutting Off Tool	60	Spring Winding	55
Right-Hand Offset Turning Tools	60	Spur Gears	63
Rivets (Flat Head).....	193	Square Brass Tubing	207
Round Bodies Shields Definitions of Three	167	Square Measure	228
Round-Corners Square Holes.....	161	Squares, Numbers from .0001 to 998001	177-187
Root Diameter, Screw Threads.....	40	Square Root, Numbers from 0.1000 to 31.6070	177-187
Round Seamless Brass Tubing.....	207	Square Screw Threads.....	39
Round Welded Stainless Steel Tubing	138-139	Square Thread, Setting Tools for.....	27
Rules for Calculating Spiral Gears.....	67	Straight Cutting-Off Tools.....	60
Rules and Formulae for Dimensions of Spur Gears.....	64	Standard Gauges of Sheets, Plates, and Wire	217
Rules and Formulae for Helical Gear Calculations.....	84	Standard Gauges and Weights of Tin Plate	208
Rules and Formulae for Internal Spur Gears	63	Standard Round-Cornered Square Holes	161
Rules and Formulae for Worm Gearing	85-86	Standard Structural Beams, Channels, Tees, Angles, Bulb Angles and Zees.....	205
Rules for Obtaining Ratio of the Gears Necessary to Cut a Given Spiral.....	94	Standard Wrought Washers.....	211
Ryerson Color Marks for Stainless Steel	198	Steel and Brass Bars, Comp. Wts.....	219
S		Steels, Carbon	202
S.A.E. Standard Bolts and Nuts.....	28	Steel Chromium	201
S.A.E. Standard Drill Sizes.....	30	Steels, Chromium Vandaium.....	201
S.A.E. Depth and Width of Ring-Groove	236	Steels, Manganese	200
Safe Loads for Ropes and Chains (in Pounds).....	218	Steels, Molybdenum Steels.....	200
Safety Plugs Melting Points.....	167	Steels Nickel	202
Screws Fillister Head Machine.....	31	Steels Nickel-Chromium.....	201
Screws Flat Head	30	Steels Stainless	52
Screws Machine, Tap Drill.....	37	Steels, Tungsten	201
Screws Oval Head Machine.....	32	Stove Bolt Taps	29
Screws Round Head Machine.....	33	Straight Shank Turning Tool.....	59
Screw Stocks	202	Strength of Internal Gears	93
Secant and Cosecant.....	176	Strength of Materials	231
Setscrews and Keyseats for Gears.....	128	Strontium	222
Setover for Tailstock (Tapers).....	148	Structural Timber Columns.....	213
Sharpening Drills	50	Stubs' Gages	207
Sharpening End Mills for Milling Machine	118	Stud Dimensions Milled Steel.....	36
		Surface Speeds in Feet Per Minute.....	124
		Suggested Surface Feet per Minute for Turning and Threading Different Materials	53

Suggestions for Holding	
Micrometer Calipers.....	13
Surveyors Measure.....	228
T	
Table of Approximate Angles	
for Cutting Spirals.....	97-98-99
Table For Converting Minutes	
Into Decimals Of A Degree.....	152
Table of Cutters, Pitches, Gears, and	
Angles for Twist Drills.....	86
Tables of Decimal Equivalents of 7th,	
14th, and 28ths, of 6, 12 and 24.....	153
Table for Estimating Quantity of Nails.....	225
Table for Finding the	
Contents of Square Tanks.....	233
Table of Observed Tooth	
Dimensions for Spiral Gears.....	89
Table of Ratios of Two Gears with	
Their Decimal Equivalents.....	101
Table of Regular Polyhedrons	
Whose Edges are One.....	172
Tailstock in Lathe Setover.....	148
Taking the First Cut.....	40
Tangents and Cotangents.....	175
Tap Drills, American National	
Coarse-Thread Series.....	44
Tap Drills, American National	
Fine Thread Series.....	45
Tap Drills, for A. S. M. E.	
Standard Machine Screws.....	26
Tap Drills, Machine Screws.....	37
Tap Drills, (S. A. E. Standard).....	30
Tapers from 1-16 to 1 1/4 Inch	
per Foot Amount of Taper for	
Lengths up to 24 Inches.....	147
Taper Holes, Brown & Sharpe.....	145
Tapers Brown & Sharpe Taper Shanks.....	141
Tapers, for Spindles, Arbors, Collets,	
Brown & Sharpe Tapers.....	141
Tapers per Foot, and	
Corresponding Angles.....	143
Tapers, Fitting to Gauges.....	148
Tapers Jacobs.....	51
Tapers Jarno.....	146
Taper, for Tailstock in Lathe.....	148
Tapers, Milling Machine Standard.....	147
Tapers, Morse.....	145
Taper, Pin Reamers.....	142
Tapers, Rules for Figuring.....	143
Tapers S. A. E.....	146
Taper, Pins Standard.....	142
Taper Turning with Compound Rest.....	51
Tapping Threads.....	37
Temperature.....	208
Tempering Liquid.....	227
Tempering of Tool Steel.....	193
Threading or Chasing Tools.....	61
Thread-Cutting Data.....	126
Thread-Cutting and Finishing.....	38
Theoretical Weight of Steel Plates.....	209
Thulium.....	222
Time.....	229
Timber American Standard Sizes.....	213
Timber Structural Columns.....	213
Tinning Surfaces.....	219
Titanium.....	222
To Compute the Weight of	
Cast Metal by the Weight	
of the Pattern.....	222
To Compute the Weight of Steel.....	210
To Copper the Surface of Iron	
and Steel Wire.....	216
To Remove Dry Paint.....	192
Triangles.....	172
Trigonometric Functions.....	173
Trigonometric Functions	
Natural Sines, Cosines, Tangents,	
Cotangents, Secant and	
Cosecant.....	174-175-176
Troy Weight, Used for Weighing	
Gold and Silver.....	227
Twist Drills, Grinding and Gauges.....	50
Twist Drill Sizes.....	49
Types of Pulleys.....	41

U	
Unit of Heat.....	125
U. S. Navy Standard Keys.....	129
Using an Internal Micrometer Caliper.....	14
Useful Information on Angles.....	23
Useful Numbers.....	156
Useful Rules for Finding Dimensions	
of Circles, Squares, Etc.....	161
Uranium.....	222
V	
Valve Mechanism.....	237
Valve Timing.....	238
Vanadium.....	222
V-Belting.....	121
Vernier Caliper.....	19
Vernier, Reading, on Universal Bevel	
Protractor.....	21
Vernier, Reading, English Measure.....	21
V-Standard Thread.....	25
W	
Washers Standard.....	211
Weights of Aluminum Brass and Cop-	
per Sheets.....	220
Weight per Bushel of Different	
Grains, Etc.....	227
Weight of Casting Different Metals per	
Pound of Wood Pattern.....	226
Weight Computing Formulas.....	135
Weight of Flat Bar Steel per Lineal	
Foot.....	224
Weight per Inch of Round Bars of	
Carbon and High Speed Steel in	
pounds per Lineal Inch.....	223
Weights of Materials.....	212
Weight Table Miscellaneous.....	223
Weights and Specific of Metals.....	215
Weight, one Square Foot of Metals.....	225
Weights of Steel Angles with Fillet.....	211
Weight of Wire.....	222
Weight of Wood per Foot.....	226
Welding Knowledge.....	250
Welding Steel.....	256
What Belt Thickness to Use.....	120
Whitworth Standard Bolts and Screws.....	26
Wire Gauges.....	49
Work Mounted in Chuck	
and Center Rest.....	68
Worms and Worm Gears.....	89
X	
Xenon.....	222
Y	
Yttrium.....	222
Ytterbium.....	222
Z	
Zees.....	205
Zinc.....	222
Zinc Gauge.....	216
Zirconium.....	222

THANKS TO THE CONTRIBUTORS

We wish to thank the following firms for their courteous co-operation and aid in gathering and preparing certain of the new information and tables contained in this edition of the handbook.

American Iron and Steel Institute
American Leather Belting Ass'n
Bethlehem Steel Co. "Manual of Steel Construction," Copyright 1934
Bonney Forge & Tool Works
Bridgeport Brass Company
Brown & Sharpe Mfg. Co.
Boston Gear Works, Inc.
Carnegie-Illinois Steel Corp.
Cincinnati Milling Machine
Cincinnati Shaper Co.
Cleveland Twist Drill Co.
Crane Company
Dayton Rubber Co.
Division Lead Co.
Eastern Machine Screw Corp.
Foote Bros. Gear & Machine Co.
Gary Screw & Bolt Co.
General Electric Co.
Illinois Tool Works (Catalogue D)


Jacobs Mfg. Co.
Kearney & Trecker Corp.
R. K. LeBond Machine Tool Co.
Lincoln Electric Co.
Link-Belt Co.
Mill & Factory
Modern Engineering Co.
Morse Twist Drill & Machine Co.
National Lumber Mfrs. Ass'n
New Departure, Division of
General Motors Corp.
Republic Steel Co.
Jos. T. Ryerson & Son., Inc.
"General Data Book," Copyright 1940
Sheffield Gage Corp.
South Bend Lathe Works
Standard Tool Co.
The L. S. Starrett Co.
Thermoid Corp.
Waukesha Motor Co.

Turning Wood, Fibre and Plastics

Turning wood in a metal working lathe is a very simple matter. Spur and cup centers are substituted for the 60° centers, a hand rest is attached and the lathe is ready for wood turning.

Special pulleys may be used on the motor and countershaft to provide a series of high spindle speeds for wood turning, in addition to the regular speeds for metal work.

Other materials may be machined as well. Alabaster, Catalin, Bakelite, fibre and other plastics, synthetic resins, etc., may be turned and polished with complete satisfaction.



Hand Rest



Spur Center



Cup Center



Wood Turning in a Metal Working Lathe



Standard Lathe Dog



Safety Lathe Dog

HOW TO TAKE ACCURATE MEASUREMENTS

The ability to take accurate measurements can be acquired only by practice and experience. Careful and accurate measurements are essential to good machine work. All measurements should be made with an accurately graduated steel scale or a micrometer. Never use a cheap steel scale or a wood ruler, as they are likely to be inaccurate and may cause spoiled work.

An experienced mechanic can take measurements with a steel scale and calipers to a surprising degree of accuracy. This is accomplished by developing a sensitive "caliper feel" and by carefully setting the calipers so that they "split the line" graduated on the scale.

Caliper Feel

The accuracy of all contact measurements is dependent upon the sense of touch or feel. The caliper should be delicately and lightly held in the finger tips, not gripped tightly. If the caliper is gripped tightly, the sense of touch is very much impaired

OUTSIDE CALIPERS

Outside calipers are used to measure the diameters of the work being turned. There are three kinds of calipers: Spring Calipers Fig. 1, firm point calipers Fig. 2, and/or "mikes" Fig. 3.

Spring Calipers are provided with a screw and adjusting nut for quick setting to size, whereas the firm joint calipers are set by tapping one leg against a solid object. Both types have their advantages. The spring type is much preferred on small work, while on large diameter work, the solid joint type because of stiffer legs is better.




Fig. 1




Fig. 2




Fig. 3

Continued on next page

TO SET AN OUTSIDE CALIPER

To set calipers to a diameter with the use of a scale in the right hand, using the forefinger to keep the one leg from slipping off end of the scale and adjust the caliper Fig. 4, to the dimension required. Some mechanics become quite expert at setting calipers, acquiring a "feel" that enables them to set calipers to .005 of an inch. In many cases your work will be to reproduce broken parts, and the calipers can be set from the broken part.




Fig. 4

Be certain, however, that the part is not worn where you set the calipers. Try the calipers at different points to see if the piece is round and that you are not caliper-ing on the smallest diameter. When cal-iper-ing a piece of work it is best to hold the caliper in a vertical position Fig. 5, with the legs at right angles to the axis of the piece, and adjust to a point where the weight of the calipers will just allow the points to pass over the diameter of the piece. This slight resistance is known as the




Fig. 5




Fig. 6

"feel". Never force the calipers over the piece as the legs will spring, and inaccuracy will result. If you get the same "feel" on the sample as you get on the piece being turned, the diameter will correspond within the closed limits.

Never try to caliper a piece revolving in the lathe where accuracy is required. For obtaining the approximate diameter this is permissible, but for accurate dimensions, the lathe should be stopped.

The proper method for measuring with an outside caliper. To measure the diameter of a cylinder is shown in Fig. 6. Hold the caliper at right angles to the center line of the work, and is pushed gently back and forth across the diameter of the cylinder to be measured. The caliper when properly adjusted, it should easily slip over the shaft of its own weight.

INSIDE CALIPER




Fig. 7

caliper. This can be done best by holding the micrometer in the left hand and the inside caliper in the right hand Fig. 8, and adjusting it until the proper "feel" is obtained. The adjustment is obtained by rocking the caliper in a vertical plane between the axis of the anvil and spindle of the micrometer. When calipering a hole, Fig. 9, set one leg of the inside micrometer caliper in the hole, pivoting the caliper in a vertical plane and adjusting until the other leg enters the hole. By rocking and




Fig. 8




Fig. 9

holding the outside caliper in the left hand supporting it between the thumb and forefinger, Fig. 10, with the second finger of the left hand supporting the lower legs of the outside and inside calipers to be set. The inside calipers are held in the right hand with the adjusting nut between the thumb and forefinger. By rocking the inside caliper in a vertical plane and adjusting it until the proper "feel" is obtained, accurate transfer from one to the other can be made.

adjusting the caliper, the proper "feel," across the largest diameter can be obtained. If the calipers are forced into the hole, the legs will spring and an inaccurate measurement will be obtained. When boring a hole to fit a shaft or turning a shaft to fit a hole, it is necessary to transfer measurement from outside to inside calipers and vice versa. This can be done by





Fig. 10




READING A HEIMAPHRODITE CALIPER



How to read a Heimaphrodite Caliper shown in Fig. 11, is set from the end of the scale exactly the same as the outside caliper.

HOW TO READ AND HOLD A MICROMETER

The Micrometer Caliper, Fig. 12, is used for measuring to very close dimensions, its graduations reading to one-thousandth of an inch. It consists of five principal parts, the frame "A", the Anvil "B", the Spindle "C", the Sleeve "D", and the Thimble "E". The Spindle "C" has a thread cut on it which fits a tapped hole in the Sleeve "D" that is not exposed. The threads are cut 40 to the inch so that exactly one revolution of 15. The Thimble "E" advances the Spindle "C" one-fortieth of an inch, or twenty-five thousandths (.025) which is the gap between the Anvil "B" and the Spindle "C", the measuring point. The Sleeve "D" is graduated with 40 divisions to the inch and numbered 0—1—2 & to 10, a number at every fourth division, so that the figure one, or four divisions, represents $4 \times .025$ of an inch ($1/40$) or one-tenth of an inch (.100). The number last showing on the Sleeve "D" when the mike is set on a diameter is the first number after the decimal point is your reading. On the bevel edge of the Thimble "E" are twenty-five graduations, each of these representing one-thousandth of an inch. In illustration Fig. 13, you have showing on the sleeve seven graduations representing .025 each, equalling $7 \times .025$ or .175 and three graduations on the thimble beyond the zero (0) mark, each representing .001 so that the caliper is set at .175" plus .003", equalling .178", or for greater convenience



read the highest number showing on the sleeve, one-tenth (.1); beyond this read the number of graduations showing 3 which equals $3 \times .025$ " or .075, then add to this graduations on the Thimble, three making .178. For convenience in using micrometers tables of fraction and decimal equivalents, also English and Metic equivalents, will be found in this book.

When calipering with micrometers the same "feel" is necessary as with the other calipers, and they should not be forced over the work.

Hold the "mikes" between the forefinger and the thumb as shown in Fig. 14, and let the weight carry them over the diameter.


SUGGESTIONS FOR HOLDING MICROMETER CALIPERS

Do not caliper with the piece revolving as this will damage the anvil and the end of the spindle. Check up the "mikes" occasionally with a reference disc (standard gauge) to see that they register correctly.

How to read An Inside Micrometer Caliper Outside Micrometers Fig. 15, are manufactured for diameters of one-half inch and up. They are read the same as outside Micrometers. A few suggestions for holding Micrometer Calipers are given in Figs. 16, 17, 18, 19, 20 and 21.



Fig. 15



Inside Micrometer

Fig. 16

Outside Micrometer Caliper Measuring the Diameter of Work in the Lathe.




Fig. 16




Fig. 17

Fig. 17

In using a one inch Micrometer for small work, hold the tool in one hand, turning the thimble with the same hand, as shown. This permits freedom of the other hand for holding the work. In measuring larger or stationary work, the frame should be held securely in one hand while the other hand turns the thimble.

In using a larger micrometer, the frame should be held securely in one hand at a point where its weight is supported most conveniently without cramping the measuring surfaces. The other hand should turn the thimble.

Fig. 18




Fig. 18

Fig. 19

Using an Internal Micrometer Caliper Measuring the Diameter of a Machined Hole.




Fig. 19




Fig. 20




Fig. 21

Small internal measurements are taken easily and accurately by Inside Micrometer Caliper.

Fig. 20

For quick, accurate measurements, Tubular Inside Micrometers find many uses.

Fig. 21

CENTERING WORK

Lathe work may be divided into two principal classes, namely, work machined between centers and work machined in chucks. Bar or shaft work is done between the centers, the piece to be turned having been previously centered.




Fig. 22

There are many ways of centering a piece of material. In large production shops this work is done in a centering machine. In small shops the lathe operator usually centers his own work. The first thing to do is to find the center on each end of the pieces. This can be done by using hermaphrodite calipers. Set the caliper to about one-half the diameter of the piece, chalk the end of the piece so the scribe marks can be seen, and scribe four arcs, one from each quarter of the circumference (Fig. 22). The center of the piece lies between the four arcs. Mark the center thus located with a center punch. Perform the same operation on the other end of the piece and it is ready to have the centers drilled.

The center of a piece can also be located by the use of a center head on a combination square. Draw two lines at about right angles to each other. Where they bisect will be the center of the piece (Fig. 23).




Fig. 23





Fig. 24

To center irregularly shaped pieces such as a drop forged brake lever, lay the piece in a V-block (Fig. 24) on a plane surface and use a surface gauge for scribing the lines on each end. First set the gauge to the approximate height of the center and scribe a line. Turning the piece, scribe three more lines, each at about 90 degrees. The center of the piece is in the center of the square formed by the scribed lines.

After the center has been found on each end of the piece and it has been center-punched, the actual drilling of the center can be done under a drill press or in the lathe itself.

Locating Center Holes


There are several good methods for accurately locating the center holes which must be drilled in each end of the work before it can be mounted on the lathe centers for machining.



Locating Centers with Dividers

Divider Method

Chalk the ends of the shaft, set the dividers to approximately one-half the diameter of the shaft, and scribe four lines across each end, as shown.



Centering an Irregular Shape

Centering Irregular Shapes



Work that is irregular in shape may be centered with a surface gauge and V-block, as shown.


Bell Center Punch

The bell centering cup is placed over the end of the work and the center punch or plunger is struck a sharp blow with the hammer, automatically locating the center.

Punching the Center

Place the center punch vertically at the center point and tap with a hammer, making a mark sufficiently deep so that the work will revolve on the center points when placed in the lathe.


Punching
the CenterBell
Center Punch



Finding center line of round work is one use for Combination Squares.

A Combination Square makes a very convenient depth gage.

Angles are determined quickly and accurately with a Protractor.




Testing the Accuracy of Center Punch Marks

Alignment of Centers

When turning straight work, try alignment of tailstock center with headstock center to be sure work will not be tapered.

When zero marks are in line on tailstock, top and bottom, centers are approximately in line, but due to the impossibility of seeing an error of .001" misalignment, it is probable that the work will be tapered if a no more sensitive test is applied to the center alignment.





A test bar as shown in illustration is easy to make and use and gives positive results.


Micrometers Graduated to Ten Thousandths

There are eleven parallel lines on the sleeve occupying the same space as ten lines on the thimble; these lines are numbered 0, 1, 2, 3, 4, 5, 6, 7, 8, 9, 0. The difference between the width of one of the ten spaces on the sleeve and one of the nine spaces on the thimble is one-tenth of a space on the thimble or one ten thousandth of an inch in the reading of micrometer.

In Fig. B the third line from 0 on thimble coincides with the first line on the sleeve. The next two lines do not coincide by one-tenth of a space on the thimble, the next two marked 5 and 2 are two-tenths apart, and so on. When the micrometer is opened the thimble is turned to the left and each space on the thimble represents a thousandth of an inch. Therefore, when the thimble is turned so that the lines 5 and 2 coincide the micrometer is opened two-tenths of one thousandth or two ten thousandths. If the thimble be turned down further, so that the line 10 coincides with the line 7 on the sleeve as Fig. C the micrometer has been opened seven ten thousandths.




B



C

How to Read Micrometers Graduated for Metric Measure


The customary pitch of the screw is $\frac{1}{2}$ mm. Thus, the distance traversed by the screw or spindle during one complete revolution is $\frac{1}{2}$ mm, or .50 mm, and two complete revolutions are required to move the spindle a distance of 1.00 mm. The graduations on the barrel conform to the pitch of the screw. The upper set of graduations, representing mm, is numbered every fifth graduation; the lower set of graduations subdivides each mm division into 2 equal parts. The beveled edge of the thimble is graduated into 50 parts and figured every fifth division 0, 5, 10, 15, 20, 25, 30, etc. When fifty of these graduations have passed the horizontal line on the barrel, the spindle, having made one revolution, has moved .50 mm. Thus, when the spindle moves only far enough to cause one graduation to pass the horizontal line on the barrel, it will have moved $\frac{1}{50}$ of .50 mm, or .01 mm. The distance between the graduations on the thimble is great enough to permit half and quarter hundredths of a mm to be readily estimated.




To read—First note the last figure visible on the scale on the barrel representing a whole mm. Note whether or not a half mm division is visible beyond this graduation. Then determine the hundredths mm by the line on thimble coinciding with the horizontal line on the barrel. The mm shown (plus .50 mm if a half mm graduation shows), plus the number of hundredths of a mm, is the reading.

Example:—In cut above, 3 mm graduations are shown; also a $\frac{1}{2}$ mm graduation is visible; on the bevel on the thimble the graduations show 36 divisions from the zero to the line coincident with the line of graduations on the barrel. Then the reading = $3.00 \text{ mm} + .50 \text{ mm} + .36 \text{ mm} = 3.86 \text{ mm}$.


IMPORTANT: Grip micrometer as shown below. Check zero setting after adjustment is made.




1. Carefully clean the measuring surfaces by pulling the spindle and anvil apart, then clean the surfaces while the spindle and anvil are in light contact with the paper. Do not use a hard paper.
2. With the anvil and spindle apart, unlock cap and turn cap until it is tight enough with fingers to bring slight tension between thimble and spindle.
3. Bring anvil and spindle together by turning spindle until the thimble coincides with line on barrel.



4. Move spindle away from anvil by turning spindle, not by turning thimble.
5. Holding thimble only, tighten cap with fingers. Be careful not to touch frame.
6. Lock cap with wrench, still holding thimble only, and adjustment is complete.




Micrometer Caliper No. 215RS accurately measures the thickness of forms.




The rounded anvil of No. 223RS permits accurate measurements of thickness of tubing.

Small parts are measured by thousandths with No. 233RS.




Reliable outside and inside measurements in thousandths of an inch are taken up to 48" with a Vernier Caliper.




Gear teeth are measured accurately with the Gear Tooth Vernier Caliper.

Vernier Height Gages maintain the highest standards for toolroom work.


BROWN & SHARPE MFG. CO.




No. 110 meets the severe conditions under which hot and cold sheet metal must be measured.




Hole Attachment provides a convenient means for internal testing.




A Speed Indicator is essential for determining the speed of spindles.




Dial Test Indicator No. 714 with Magnetic Base can be used in many places that ordinarily require a special fixture.




Dial Gauge of No. 740 used on No. 621 Surface Gauge to test bearings within throws of crankshaft.




A Brown & Sharpe Hook Rule measures work with a very shallow shoulder.



Graduated angular edge of No. 319 makes possible measurements in limited angles.



For measuring recesses, a Steel Rule with Holder is often very convenient.



A Tempered Steel Rule used with Key Seat Clamp assures a correct layout.

Reading the Vernier On Universal Bevel Protractor


THE Vernier indicates every 5 minutes ($5'$), or one twelfth of a degree. Each space upon the Vernier is 5 minutes shorter than two spaces on the scale.

When the zero on the Vernier exactly coincides with a graduation on the scale, the reading is in exact degrees, as in upper cut in which the reading is $17^{\circ} 0'$. When the zero graduation of the Vernier does not exactly coincide with a graduation on the scale, the graduation on the Vernier that does coincide with a graduation on the scale indicates the number of 12ths of a degree or 5 minutes to be added to the whole degree reading.

Read off directly from the scale the number of whole degrees between 0 on the scale and 0 on the Vernier. Then count, in the same direction, the number of divisions from the 0 of the Vernier to the first line on the Vernier that coincides with a line on the scale. As each division on the Vernier represents 5 minutes, the number of these divisions multiplied by 5 will be the number of minutes to be added to the whole number of degrees.

Example: Lower cut shows the zero on the Vernier between 12 and 13 on the scale. Counting to the right from zero on the scale, the zero on the Vernier has therefore moved twelve whole degrees. In the same direction the 10th line of the Vernier, representing 50 minutes ($50'$), is the line which exactly coincides with a line on the scale. We, therefore, have 50 minutes as indicated by the Vernier, to be added to the reading of twelve degrees on the scale. The reading, then, is $12^{\circ} 50'$.

Since the divisions, both on the scale and on the Vernier, are numbered both to the right and left from a basis of zero, any size angle can be measured, and the readings on the scale and on the Vernier, are taken either to the right or left, according to the direction in which the zero on the Vernier is moved.



Reading the Vernier—English Measure

Cuts show the Vernier used with a scale which is graduated into 40ths or .025ths of an inch. The Vernier has 25 divisions, which are numbered every 5th division and which equal, in extreme length, 24 divisions on the scale, or $24 \times 1/40" = 24 \times .025" = .600"$. Thus, one division on the Vernier equals $1/25$ of $.600" = .024"$. Therefore, the difference between a division on the Vernier and a division on the scale = $.025" - .024" = .001"$.


When the reading is exact, with respect to the number of fortieths of an inch, the zero on the Vernier coincides with a graduation on the scale—either inch, tenth or fortieth, as the case may be. This leaves a space between lines on the scale and the 1, 2, 3, 4, 5, 6, etc., lines on the Vernier of $.001$, $.002$, $.003$, $.004$, $.005$, $.006$, etc., respectively, the difference increasing $.001"$ at each Vernier division in numerical order until, at the 25th graduation, the lines again coincide (see upper cut).

Thus, when the 1st, 2nd or 3rd, etc., line on the Vernier coincides with a line on the scale, the zero on the Vernier has moved 1, 2 or 3, etc., thousandths of an inch past the previous fortieth graduation to bring these lines together.

To read:—Note the inches, tenths and fortieths of an inch that the zero on the Vernier has moved from the zero on the scale and to this reading add the number of thousandths indicated by the line on the Vernier that coincides with a line on the scale.


Example:—The upper cut shows the zero graduation on the Vernier coinciding with a fortieth graduation on the scale (the second fortieth beyond an even tenth graduation). This indicates that the reading is exact with respect to the fortieths of an inch. The reading therefore equals $2.000" + .300" + .050" = 2.350"$. The lower cut, however, shows the 18th Vernier graduation coinciding with a line on the scale. This indicates that $.018"$ should be added to the scale reading. The reading, then, equals $2.000" + .300" + .050" + .018" = 2.368"$.

Verniers with 25 divisions are used, for English Measure, on all Brown & Sharpe Verniers with the exception of Gear Tooth Verniers No. 580, 20 to 2 diam. pitch, on which Verniers with 20 divisions are used.







Bevel Protractor measuring angular clearance on ring gear.



Bevel Protractor measures angle and determines its relationship to other surfaces.




Bevel Protractor used with a test block to measure fixture angle.



Small angles are measured easily with an acute angle attachment.



Inside Micrometer No. 263 measures holes as small as 1".




With No. 263, the measuring point adjusts itself to the measurement.

BROWN & SHARPE MFG. CO.

Circular Land Widths and Clearances

If it becomes necessary to regrind the diameter of a reamer, the lands must be cleared or relieved to prevent the reamer from binding in the hole. The best clearance angle and the best circular land width vary with the job, but the following table gives average figures.

Diameter of Reamer	Circular Land Width	Primary Clearance Angle
$\frac{1}{4}$ "	.007"	14°
$\frac{1}{2}$ "	.009"	11°
1"	.013"	9°
$1\frac{1}{2}$ "	.016"	7°
2"	.023"	7°



A secondary clearance is usually ground on reamers as shown above. This clearance is only to insure the back of the land being well away from the wall of the reamed hole in order to prevent rubbing.

Care of Reamers

Reamers are precision tools and careful treatment of their cutting edges will pay big dividends in smooth accurate holes and long life. The use of racks, containers, or boxes will be of great help in preventing nicks along the cutting edges.

Useful Information

Included Point Angle 37°—for bottom and keel plates.

Included Point Angle 45°—for shell, side and deck plates.

Included Point Angle 53°—for oil tank and oil tight holes.

Included Point Angle 45°, 60°, and 78°—for boiler plates.

Rivet Size	Hole Size	Countersunk Face, Diameter, Inches	Size Countersink Required, Inches
$\frac{5}{8}$	$1\frac{1}{16}$	1	$1\frac{1}{2}$ or $1\frac{3}{4}$
$\frac{3}{4}$	$1\frac{3}{16}$	$1\frac{3}{16}$	$1\frac{1}{2}$ or $1\frac{3}{4}$
$\frac{7}{8}$	$1\frac{5}{16}$	$1\frac{3}{8}$	$1\frac{3}{4}$
1	$1\frac{1}{2}$	$1\frac{9}{16}$	$1\frac{3}{4}$
$1\frac{1}{8}$	$1\frac{3}{4}$	$1\frac{3}{4}$	2 or $2\frac{1}{4}$
$1\frac{1}{4}$	$1\frac{5}{8}$	$1\frac{15}{16}$	2 or $2\frac{1}{4}$

SHIELDS TAP DRILL TABLE

Tap Drill List for V-Standard Thread

Size of Tap	Threads per Inch	Tap Drill for Full Thread	Tap Drill for Shop Practice	Size of Tap	Threads per Inch	Tap Drill for Full Thread	Tap Drill for Shop Practice	Size of Tap	Threads per Inch	Tap Drill for Full Thread	Tap Drill for Shop Practice
A	B	C	D	A	B	C	D	A	B	C	D
$\frac{3}{32}$	48	50	47	$\frac{5}{16}$	16	1	$\frac{1}{4}$	$\frac{5}{8}$	12	$\frac{33}{64}$	$\frac{35}{64}$
$\frac{3}{32}$	56	49	46	$\frac{5}{16}$	18	$\frac{15}{64}$	$\frac{1}{4}$	$\frac{21}{32}$	10	$\frac{33}{64}$	$\frac{17}{32}$
$\frac{3}{32}$	60	48	45	$\frac{5}{16}$	20	E $\frac{1}{4}$	$\frac{17}{64}$	$\frac{21}{32}$	11	$\frac{17}{32}$	$\frac{9}{16}$
$\frac{7}{64}$	32	50	45	$\frac{5}{16}$	24	F $\frac{17}{64}$	$\frac{17}{64}$	$\frac{21}{32}$	12	$\frac{35}{64}$	$\frac{37}{64}$
$\frac{7}{64}$	36	49	44	$\frac{11}{32}$	16	F $\frac{17}{64}$	$\frac{9}{32}$	$\frac{3}{4}$	10	$\frac{39}{64}$	$\frac{5}{8}$
$\frac{7}{64}$	40	47	43	$\frac{11}{32}$	18	$\frac{17}{64}$	$\frac{9}{32}$	$\frac{3}{4}$	11	$\frac{5}{8}$	$\frac{41}{64}$
$\frac{1}{8}$	32	44	40	$\frac{3}{8}$	14	$\frac{9}{32}$	$\frac{19}{64}$	$\frac{3}{4}$	12	$\frac{41}{64}$	$\frac{21}{32}$
$\frac{1}{8}$	36	43	38	$\frac{3}{8}$	16	L $\frac{19}{64}$	$\frac{5}{16}$	$\frac{25}{32}$	10	$\frac{41}{64}$	$\frac{21}{32}$
$\frac{1}{8}$	40	42	37	$\frac{3}{8}$	18	$\frac{19}{64}$	$\frac{5}{16}$	$\frac{25}{32}$	11	$\frac{21}{32}$	$\frac{11}{16}$
$\frac{1}{8}$	44	37	36	$\frac{3}{8}$	24	P $\frac{21}{64}$	$\frac{11}{32}$	$\frac{25}{32}$	12	$\frac{43}{64}$	$\frac{45}{64}$
$\frac{9}{64}$	30	41	35	$\frac{13}{32}$	14	N $\frac{19}{64}$	$\frac{21}{32}$	$\frac{13}{16}$	10	$\frac{43}{64}$	$\frac{45}{64}$
$\frac{9}{64}$	32	40	32	$\frac{13}{32}$	16	P $\frac{21}{64}$	$\frac{11}{32}$	$\frac{27}{32}$	10	$\frac{45}{64}$	$\frac{47}{64}$
$\frac{9}{64}$	36	37	35	$\frac{13}{32}$	18	$\frac{21}{64}$	$\frac{11}{32}$	$\frac{7}{8}$	9	$\frac{23}{32}$	$\frac{3}{4}$
$\frac{5}{32}$	30	33	31	$\frac{7}{16}$	14	R $\frac{11}{32}$	$\frac{25}{64}$	$\frac{7}{8}$	10	$\frac{47}{64}$	$\frac{49}{64}$
$\frac{5}{32}$	32	32	30	$\frac{7}{16}$	16	S $\frac{11}{32}$	$\frac{25}{64}$	$\frac{29}{32}$	9	$\frac{3}{4}$	$\frac{49}{64}$
$\frac{5}{32}$	36	31	29	$\frac{7}{16}$	27	$\frac{3}{8}$	$\frac{25}{64}$	$\frac{29}{32}$	10	$\frac{49}{64}$	$\frac{25}{32}$
$\frac{5}{32}$	40	30	29	$\frac{15}{32}$	14	$\frac{3}{8}$	$\frac{25}{64}$	$\frac{15}{16}$	9	$\frac{49}{64}$	$\frac{53}{64}$
$\frac{3}{16}$	24	29	27	$\frac{15}{32}$	16	W $\frac{25}{64}$	$\frac{13}{32}$	$\frac{31}{32}$	9	$\frac{13}{16}$	$\frac{53}{64}$
$\frac{3}{16}$	30	27	23	$\frac{1}{2}$	12	$\frac{25}{64}$	$\frac{13}{32}$	1	8	$\frac{27}{32}$	$\frac{7}{8}$
$\frac{3}{16}$	32	27	20	$\frac{1}{2}$	13	$\frac{25}{64}$	$\frac{13}{32}$	$\frac{11}{32}$	8	$\frac{55}{64}$	$\frac{57}{64}$
$\frac{7}{32}$	24	20	17	$\frac{1}{2}$	14	$\frac{13}{32}$	$\frac{13}{32}$	$\frac{11}{16}$	8	$\frac{57}{64}$	$\frac{15}{16}$
$\frac{7}{32}$	28	16	15	$\frac{17}{32}$	12	$\frac{27}{64}$	$\frac{7}{16}$	$\frac{13}{32}$	8	$\frac{59}{64}$	$\frac{61}{64}$
$\frac{7}{32}$	30	16	15	$\frac{17}{32}$	13	$\frac{27}{64}$	$\frac{7}{16}$	$\frac{11}{8}$	7	$\frac{59}{64}$	$\frac{63}{64}$
$\frac{7}{32}$	32	15	15	$\frac{17}{32}$	14	$\frac{7}{16}$	$\frac{29}{64}$	$\frac{11}{8}$	8	$\frac{61}{64}$	1
$\frac{1}{4}$	18	17	$\frac{3}{16}$	$\frac{9}{16}$	12	$\frac{29}{64}$	$\frac{15}{32}$	$\frac{15}{32}$	7	$\frac{61}{64}$	1
$\frac{1}{4}$	20	14	$\frac{3}{16}$	$\frac{9}{16}$	14	$\frac{15}{32}$	$\frac{1}{2}$	$\frac{15}{32}$	8	$\frac{63}{64}$	$\frac{11}{16}$
$\frac{1}{4}$	24	9	6	$\frac{19}{32}$	12	$\frac{31}{64}$	$\frac{1}{2}$	$\frac{13}{16}$	7	$\frac{63}{64}$	$\frac{13}{16}$
$\frac{1}{4}$	27	7	6	$\frac{19}{32}$	14	$\frac{1}{2}$	$\frac{33}{64}$	$\frac{11}{4}$	7	$\frac{19}{64}$	$\frac{17}{64}$
$\frac{9}{32}$	18	$\frac{13}{64}$	$\frac{7}{32}$	$\frac{5}{8}$	10	$\frac{31}{64}$	$\frac{3}{8}$	$\frac{13}{8}$	6	$\frac{17}{64}$	$\frac{17}{32}$
$\frac{9}{32}$	20	3	2	$\frac{5}{8}$	11	$\frac{1}{2}$	$\frac{17}{32}$	$\frac{11}{2}$	6	$\frac{17}{64}$	$\frac{11}{32}$


The dimensions for taps and tap drills, given in the Shields Tap Drill Table, are represented by the following letters:

A, — Size of Tap. B, — Threads per Inch. C, — Size of Tap Drill for Full Thread. D, — Size of Tap Drill for $\frac{3}{4}$ Thread, or Shop Practice. Few Suggestions for Drilling Tap Holes. From $\frac{3}{32}$ Tap to $\frac{3}{8}$ Tap allow $\frac{1}{128}$ or .0078. From $\frac{3}{8}$ Tap up, allow $\frac{1}{64}$. For C. I. and for Steel allow $\frac{1}{32}$. This is to be added on letter C, the Full Thread.

Copyrighted 1916 by Chas. J. Shields, St. Louis, Mo.

SHARP "V" THREAD (THEORETICAL)

"MODIFIED" V THREAD



Formula



$$\left\{ \begin{array}{l} p = \text{pitch} = \frac{1}{\text{No. threads per inch}} \\ d = \text{depth} = p \times .86603 \end{array} \right.$$

SIZES OF TAP DRILLS

For Machine Screw Taps A. S. M. E. Standard

Size of Tap. No.	Size of Drill. No.	Size of Tap. No.	Size of Drill. No.	Size of Tap. No.	Size of Drill. No.	Size of Tap. No.	Size of Drill. No.
0-80	56	5-44	37	10-24	25	20-16	G
1-56	54	6-32	36	10-28	23	20-18	$1\frac{1}{64}$ I
1-64	53	6-36	34	10-30	22	20-20	I
1-72	53	6-40	33	10-32	21	22-16	$\frac{3}{32}$ L
2-56	50	7-30	31	12-24	16	22-18	L
2-64	50	7-32	31	12-28	14	24-16	$\frac{5}{16}$ O
3-48	47	7-36	$\frac{1}{8}$	12-32	13	24-18	O
3-56	45	8-30	30	14-20	10	26-14	$2\frac{1}{64}$ R
4-32	45	8-32	29	14-24	7	26-16	R
4-36	44	8-36	29	16-18	3	28-14	T
4-40	43	8-40	28	16-20	$\frac{1}{2}$	28-16	$2\frac{3}{64}$ V
4-48	42	9-24	29	16-22	2	30-14	$\frac{25}{64}$
5-36	40	9-30	27	18-18	B	30-16	
5-40	38	9-32	26	18-20	D		

WHITWORTH STANDARD BOLTS AND SCREWS



WHITWORTH THREAD FORMULA

$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$
$$D = \text{Depth} = P \times .6403$$
$$R = \text{Radius} = .1373 P$$

Whitworth Screw Thread Form

								*DRILL SIZES Nearest Commer- cial Drill Size to Produce 75% Depth of Thread	
Full Diam.	Decimal Equiv. Outside Diam.	No. of Th'ds. Per Inch	Pitch Inches	Stand. Depth of Thread	Effective Diam. (pitch diam.)	Core Diam.	Cross Sectional Area at Bottom of Th'ds.	(Actual) Inch Decim.	(Nearest) Com. Desig.
$\frac{1}{4}$.25	20	.0500	.03201	.2179	.1856	.0272	.202	$1\frac{3}{64}$ in.
$\frac{5}{16}$.3125	18	.0556	.03557	.2769	.2413	.0458	.2592	F
$\frac{3}{8}$.375	16	.0625	.04002	.3349	.2949	.0833	.3150	O
$\frac{7}{16}$.4375	14	.0714	.04573	.3917	.3460	.0940	.3689	U
$\frac{1}{2}$.5	12	.0833	.05336	.4466	.3932	.1215	.4200	$2\frac{7}{64}$ in.
$\frac{9}{16}$.5625	12	.0833	.05336	.5091	.4557	.1632	.4825	$3\frac{1}{64}$ in.
$\frac{5}{8}$.625	11	.0909	.05821	.5667	.5085	.2032	.5377	$3\frac{5}{64}$ in.
$\frac{11}{16}$.6875	11	.0909	.05821	.6292	.5710	.2562	.6002	$2\frac{9}{64}$ in.
$\frac{3}{4}$.75	10	.1000	.06403	.6859	.6219	.3038	.6539	$2\frac{1}{32}$ in.
$\frac{13}{16}$.8125	10	.1000	.06403	.7484	.6844	.3679	.7164	$2\frac{3}{32}$ in.
$\frac{7}{8}$.875	9	.1111	.07114	.8338	.7327	.4216	.7683	$4\frac{9}{64}$ in.
1	1.000	8	.1250	.08004	.9199	.8399	.5540	.8799	$1\frac{1}{8}$ in.
$1\frac{1}{8}$	1.125	7	.1429	.09147	1.0335	.9421	.6969	.9877	1 in.
$1\frac{1}{4}$	1.25	7	.1429	.09147	1.1585	1.0671	.8942	1.1127	$1\frac{1}{64}$ in.
$1\frac{3}{8}$	1.375	6	.1667	.10372	1.2682	1.1615	1.0597	1.2149	$1\frac{1}{32}$ in.
$1\frac{1}{2}$	1.5	6	.1667	.10372	1.3932	1.2865	1.3001	1.3399	$1\frac{1}{32}$ in.
$1\frac{5}{8}$	1.625	5	.2000	.12806	1.4969	1.3688	1.4718	1.4329	$1\frac{1}{32}$ in.
$1\frac{3}{4}$	1.75	5	.2000	.12806	1.6219	1.4938	1.7528	1.5579	$1\frac{9}{16}$ in.
2	2.000	$4\frac{1}{2}$.2222	.14228	1.8577	1.7154	2.3111	1.7865	$1\frac{25}{32}$ in.

MACHINE AND WOOD SCREW GAUGE

Number of Screw Gauge	Size of Number in Decimals	Number of Screw Gauge	Size of Number in Decimals
000	.03152	25	.38684
00	.04468	26	.40000
0	.05784	27	.41316
1	.07100	28	.42632
2	.08416	29	.43948
3	.09732	30	.45264
4	.11048	31	.46580
5	.12364	32	.47896
6	.13680	33	.49212
7	.14996	34	.50528
8	.16312	35	.51844
9	.17628	36	.53160
10	.18944	37	.54476
11	.20260	38	.55792
12	.21576	39	.57108
13	.22892	40	.58424
14	.24208	41	.59740
15	.25524	42	.61056
16	.26840	43	.62372
17	.28156	44	.63688
18	.29472	45	.65004
19	.30788	46	.66320
20	.32104	47	.67636
21	.33420	48	.68952
22	.34736	49	.70268
23	.36052	50	.71584
24	.37368		

The difference between consecutive sizes is .01316 inch.

FOR SETTING TOOLS TO CUT SQUARE THREADS

By Edw. Greasse 3945 Blaine Ave., St. Louis, Mo.


Threads Per Inch	Width of Tool for Single Thread	Width of Tool for Double Thread	Width of Tool for Triple Thread
1	.500	.250	.166
2	.250	.125	.083
3	.166	.083	.055
4	.125	.062	.042
5	.100	.050	.033
6	.083	.042	.028
7	.071	.035	.023
8	.062	.031	.021
9	.055	27½	18½
10	.050	25	16⅔
11	.045	22½	15
12	.041½	21	14

HEXAGON HEAD SCREWS, CASTLE AND PLAIN NUTS

S. A. E. Standard

It is assumed that where screws are to be used in soft material, such as castiron, brass, bronze or aluminum, the United States standard pitches will be used.

DIMENSIONS



D	1/4	5/16	3/8	7/16	1/2	9/16	5/8	11/16	3/4	7/8	1	1 1/8	1 1/4	1 3/8	1 1/2
P	2S	24	24	20	20	18	18	16	16	14	14	12	12	12	12
A	5/32	21/64	13/32	29/64	9/16	89/64	23/32	49/64	19/16	25/32	1	15/32	1 1/4	1 13/32	1 1/2
A ¹	7/32	17/64	21/64	3/8	7/16	31/64	35/64	19/32	21/32	40/64	7/8	93/64	1 3/32	1 13/64	1 9/16
B	7/16	1/2	9/16	5/8	3/4	7/8	15/16	1	1 1/16	1 1/4	1 1/2	1 5/8	1 13/16	2	2 1/8
C	5/32	3/32	1/8	1/8	5/16	3/8	1/4	1/4	1/4	1/4	1/4	5/16	5/16	3/8	3/8
E	5/64	5/64	1/8	1/8	1/8	5/32	5/32	5/32	5/32	5/32	5/32	7/32	7/32	1/4	1/4
H	3/16	15/64	9/32	21/64	3/8	27/64	15/32	37/64	9/16	21/32	3/4	27/32	15/16	1 1/32	1 1/8
I	5/32	7/64	1/8	1/8	1/8	1/8	1/8	1/8	1/8	1/8	1/8	7/32	7/32	1/4	1/4
K	1/16	1/16	5/32	5/32	5/32	5/32	5/32	5/32	5/32	5/32	5/32	5/32	5/32	3/16	3/16
d	1/16	1/16	5/32	5/32	5/32	1/8	1/8	1/8	1/8	1/8	1/8	1 1/64	1 1/64	1 1/64	1 1/64

Dimensions. All dimensions in inches.

Finish. All heads and nuts to be semi-finish.

Material. For all screws and nuts — steel.

Screws are to be left soft. Screw heads are to be left soft. The plain nuts are to be soft. The Castle nuts are to be case-hardened.

HOW TO DRILL GLASS


Take an old three-cornered file — one that is worn out will do — break it off and sharpen to a point like a drill and place in a carpenter's brace or vise. Have the glass fastened on a good solid table so there will be no danger of its breaking. Wet the glass at the point where the hole is to be made with the following solution:

Ammonia.....	6 1/2 drachms
Ether.....	3 1/2 drachms
Turpentine.....	1 ounce

Keep the drill wet with the above solution and bore the hole part way from each side of the glass. Another solution is to dissolve a piece of gum camphor the size of a walnut in one ounce of turpentine.

Another method is to use a steel drill hardened, but not drawn. Saturate spirits of turpentine with camphor and wet the drill. The drill should be ground with a long point and plenty of clearance. Run the drill fast and with a light feed. In this manner glass can be drilled with holes, up to 3/16-inch diameter, nearly as rapidly as cast steel.

BRITISH ASSOCIATION STANDARD THREAD



Formula

$$\begin{cases} p = \text{pitch} \\ d = \text{depth} = p \times .6 \\ r = \text{radius} = \frac{2 \times p}{11} \end{cases}$$

Number	Diameter m/m	Pitch m/m	Number	Diameter m/m	Pitch m/m
0	6.0	1.00	7	2.5	0.48
1	5.3	0.90	8	2.2	0.43
2	4.7	0.81	9	1.9	0.39
3	4.1	0.73	10	1.7	0.35
4	3.64	0.66	12	1.3	0.28
5	3.2	0.59	14	1.0	0.23
6	2.8	0.53	16	.79	0.19

STOVE BOLT TAPS Cut Thread — Manufacturers Standard Thread Limits


Size	Threads per Inch S. B.	Major Diameter			Pitch Diameter		
		Basic	Mini- mum	Maxi- mum	Basic	Mini- mum	Maxi- mum
1/8	32	.1250	.1280	.1310	.1080	.1110	.1130
5/16	28	.1630	.1660	.1690	.1440	.1470	.1490
3/8	24	.1950	.1980	.2010	.1730	.1760	.1780
7/16	22	.2220	.2255	.2285	.1980	.2015	.2035
1/2	18	.2500	.2525	.2555	.2240	.2275	.2295
5/8	18	.3125	.3150	.3180	.2764	.2779	.2804
3/4	16	.3750	.3780	.3810	.3344	.3359	.3384
7/8	14	.4375	.4400	.4440	.3911	.3926	.3956
1 1/8	13	.5000	.5030	.5070	.4500	.4515	.4545

Lead Tolerance

A maximum lead error of plus or minus .003" in one inch of thread is permitted.


Multiple Threads

The following drawing illustrates the relation of "pitch" and "lead" of multiple threads. Both these dimensions should always be given when ordering.



Relation of Lead and Pitch of Multiple Threads

FLAT HEAD MACHINE SCREWS



Nominal Size	D Basic Major Diameter	*A Head Diameter		H Height of Head		J Width of Slot		T Depth of Slot	
		Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.
2	.086	.172	.156	.051	.040	.036	.024	.023	.015
3	.099	.199	.181	.059	.048	.038	.026	.027	.017
4	.112	.225	.207	.067	.055	.040	.028	.030	.020
5	.125	.252	.232	.075	.062	.043	.031	.034	.022
6	.138	.279	.257	.083	.069	.045	.033	.038	.024
8	.164	.332	.308	.100	.084	.050	.037	.045	.029
10	.190	.385	.359	.116	.098	.055	.041	.053	.034
12	.216	.438	.410	.132	.112	.059	.045	.060	.039
1/4	.250	.507	.477	.153	.131	.066	.051	.070	.046
5/16	.3125	.636	.600	.192	.166	.077	.061	.088	.058
3/8	.375	.762	.722	.230	.200	.088	.072	.106	.070

FORMULAS

HEAD DIAMETER:

Maximum A = 2.040 D - 0.003

Minimum A = 1.960 D - 0.013

WIDTH OF SLOT:

Maximum J = 0.182 D + 0.020

Minimum J = 0.164 D + 0.010

HEIGHT OF HEAD:

Maximum H = 0.619 D - 0.002

Minimum H = 0.552 D - 0.007

DEPTH OF SLOT:

Maximum T = 0.288 D - 0.002

Minimum T = 0.192 D - 0.002

COUNTERSINK ANGLE:

Maximum 82 Deg.

Minimum 80 Deg.


Machine screws up to and including 2" length are threaded to the head. Screws longer than 2" are threaded 2".

*Flat heads cannot be measured on head diameter. Use form gauges.

(S.A.E. Standard)

Size of Tap, No.	Size of Drill, No.	Size of Tap, No.	Size of Drill, No.	Size of Tap, No.	Size of Drill, No.	Size of Tap, No.	Size of Drill, No.
1/4-28	3	1/2-20	29/64	3/4-16	11/16	1 1/4-12	1 11/64
5/16-24	1	3/8-18	33/64	7/8-14	13/16	1 3/8-12	1 19/64
3/8-24	Q	5/8-18	37/64	1 -14	15/16	1 1/2-12	1 27/64
7/16-20	25/64	1 1/16-16	5/8	1 1/8-12	1 3/64		

FILLISTER HEAD MACHINE SCREWS



Nom- inal Size	D	A		H		J		T		F		F + H	
	Basic Major Dia.	Head Diameter		Height of Head		Width of Slot		Depth of Slot		Height of Oval		Total Height of Head	
		Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.
2	.086	.140	.124	.055	.045	.036	.024	.037	.021	.028	.018	.073	.063
3	.099	.161	.145	.063	.052	.038	.026	.043	.026	.032	.021	.084	.073
4	.112	.183	.166	.072	.060	.040	.028	.048	.031	.035	.024	.096	.084
5	.125	.205	.187	.081	.068	.043	.031	.054	.036	.039	.027	.107	.095
6	.138	.226	.208	.089	.076	.045	.033	.060	.041	.043	.029	.118	.105
8	.164	.270	.250	.106	.091	.050	.037	.071	.050	.050	.035	.141	.126
10	.190	.313	.292	.123	.107	.055	.041	.083	.060	.057	.041	.164	.148
12	.216	.357	.334	.141	.123	.059	.045	.094	.070	.064	.047	.187	.169
1/4	.250	.414	.389	.163	.143	.066	.051	.109	.083	.074	.054	.217	.197
5/16	.3125	.519	.490	.205	.181	.077	.061	.137	.106	.092	.068	.272	.249
3/8	.375	.622	.590	.246	.218	.088	.072	.164	.129	.109	.082	.327	.300

HEAD DIAMETER:

Maximum A = 1.670 D - 0.004

Minimum A = 1.610 D - 0.014

HEIGHT OF HEAD (SIDE):

Maximum H = 0.660 D - 0.002

Minimum H = 0.600 D - 0.007

WIDTH OF SLOT:

Maximum J = 0.182 D + 0.020

Minimum J = 0.164 D + 0.010

DEPTH OF SLOT:

Maximum T = 0.440 D - 0.001

Minimum T = 0.374 D - 0.011

HEIGHT OF HEAD:

Maximum F = 0.280 D + 0.004

Minimum F = 0.220 D - 0.001

TOTAL HEIGHT OF HEAD:


Maximum F + H = Maximum F +

Minimum H = 0.88 D - 0.003

Minimum F + H = Minimum F +

Minimum H = 0.82 D - 0.008

Machine screws up to and including 2" length are threaded to the head. Screws longer than 2" are threaded 2".




To produce absolutely straight and true holes, drill used to rough out stock should leave hole about $\frac{3}{4}$ " to $\frac{1}{16}$ " small.

Use boring bar mounted in tool post (as illustrated), and bore hole until about eight to ten thousandths stock are left.

To act as true guide for reamer, bore hole at outer end—or end reamer enters for $\frac{1}{8}$ "—to about three thousandths small.

OVAL HEAD MACHINE SCREWS



Nom- inal Size	D	*A		H		J		T		F		F + H	
	Basic Major Dia.	Head Diameter		Height of Head		Width of Slot		Depth of Slot		Height of Oval		Total Height of Head	
		Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.
2	.086	.172	.156	.051	.040	.036	.024	.045	.037	.029	.022	.080	.063
3	.099	.199	.181	.059	.048	.038	.026	.052	.043	.033	.026	.092	.073
4	.112	.225	.207	.067	.055	.040	.028	.059	.049	.037	.029	.104	.084
5	.125	.252	.232	.075	.062	.043	.031	.067	.055	.041	.033	.116	.095
6	.138	.279	.257	.083	.069	.045	.033	.074	.060	.045	.036	.128	.105
8	.164	.332	.308	.100	.084	.050	.037	.088	.072	.053	.043	.152	.126
10	.190	.385	.359	.116	.098	.055	.041	.103	.084	.061	.050	.176	.148
12	.216	.438	.410	.132	.112	.059	.045	.117	.096	.069	.057	.200	.169
1/4	.250	.507	.477	.153	.131	.066	.051	.136	.112	.079	.066	.232	.197
5/16	.3125	.636	.600	.192	.166	.077	.061	.171	.141	.098	.083	.290	.249
3/8	.375	.762	.722	.230	.200	.088	.072	.206	.170	.117	.100	.347	.300

FORMULAS

- HEAD DIAMETER:

Maximum $A = 2.04 D - 0.003$

Minimum $A = 1.96 D - 0.013$
- HEIGHT OF HEAD:

Maximum $H = 0.619 D - 0.002$

Minimum $H = 0.552 D - 0.007$
- WIDTH OF SLOT:

Maximum $J = 0.182 D + 0.020$

Minimum $J = 0.164 D + 0.010$
- TOTAL HEIGHT OF HEAD:

Maximum $(F + H) = \text{Maximum } F + \text{Maximum } H = 0.923 D + 0.001$

Minimum $(F + H) = \text{Minimum } F + \text{Minimum } H = 0.820 D - 0.008$
- Machine screws up to and including 2" length are threaded to the head.

Screws longer than 2" are threaded 2".
- *Oval heads cannot be measured on head diameter. Use form gauges.
- DEPTH OF SLOT:

Maximum $T = 0.556 D - 0.003$

Minimum $T = 0.460 D - 0.003$
- HEIGHT OF OVAL:

Maximum $F = 0.304 D + 0.003$

Minimum $F = 0.268 D - 0.001$
- COUNTERSINK ANGLE:


Maximum 82 Deg.

Minimum 80 Deg.

Cut Thread—For Grease Cup Fittings

Nominal Size Inches	Number of Threads to Inch Amer. Std.	Major Diameter			Pitch Diameter		
		Basic	Minimum	Maximum	Basic	Minimum	Maximum
1/8	27	.4044	.3975	.3995	.3748	.3680	.3700
1/4	18	.5343	.5255	.5275	.4899	.4810	.4830
3/8	18	.6714	.6625	.6645	.6270	.6180	.6200
1/2	14	.8355	.8245	.8270	.7784	.7670	.7695
3/4	14	1.0460	1.0345	1.0370	.9889	.9775	.9800
1	11 1/2	1.3082	1.2945	1.2970	1.2386	1.2245	1.2275

ROUND HEAD MACHINE SCREWS



Nominal Size	D Basic Major Diameter	A Head Diameter		H Height of Head		J Width of Slot		T Depth of Slot	
		Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.
2	.086	.162	.146	.070	.059	.036	.024	.048	.036
3	.099	.187	.169	.078	.067	.038	.026	.053	.040
4	.112	.211	.193	.086	.075	.040	.028	.058	.043
5	.125	.236	.217	.095	.083	.043	.031	.062	.047
6	.138	.260	.240	.103	.091	.045	.033	.067	.050
8	.164	.309	.287	.119	.107	.050	.037	.076	.057
10	.190	.359	.334	.136	.124	.055	.041	.086	.064
12	.216	.408	.382	.152	.140	.059	.045	.095	.071
$\frac{1}{4}$.250	.472	.443	.174	.161	.066	.051	.108	.080
$\frac{5}{16}$.3125	.591	.557	.214	.200	.077	.061	.130	.097
$\frac{3}{8}$.375	.708	.670	.254	.239	.088	.072	.153	.114

FORMULAS

HEAD DIAMETER:

Maximum A = 1.887 D.

Minimum A = 1.813 D - 0.010

HEIGHT OF HEAD:

Maximum H = 0.636 D + 0.015

Minimum H = 0.624 D + 0.005

Machine screws up to and including 2" length are threaded to the head.

Screws longer than 2" are threaded 2"

WIDTH OF SLOT:

Maximum J = 0.182 D + 0.020

Minimum J = 0.164 D + 0.010

DEPTH OF SLOT:

Maximum T = 0.362 D + 0.017

Minimum T = 0.268 D + 0.013

SIZES OF WIRES FOR USE WITH
VARIOUS PITCH THREADS.

PITCH	WIRE
4 to 6	.150"
7 to 9	.090"
10 to 12	.070"
13 to 16	.050"
18 to 24	.035"
26 to 30	.030"
32 to 40	.025"
42 to 50	.018"
52 to 60	.015"





Chart of Wrench and Socket Openings and Sizes of Bolts and Nuts they fit

Wrench Opening	American Standard Reg. Bolts	American Standard Reg. Nuts, Size Bolts	Amer. Std. Heavy Nuts (U.S.S.), Size Bolts	Amer. Std. Light Nuts (S.A.E.), Jam Nuts, Castle Nuts and Slotted Nuts, Size Bolts	Cap Screws	Set Screws	Machine Screw Nuts and Stove Bolt Nuts	Wrench Opening
5/32							No. 0 & No. 1	5/32
3/16							No. 2 & No. 3	3/16
1/4						1/4	No. 4	1/4
5/16						5/16	No. 5 & No. 6	5/16
11/32							No. 8	11/32
3/8	1/4					3/8	No. 10	3/8
7/16		3/4		1/4	1/4	7/16	No. 12 & No. 14	7/16
1/2	5/16		1/4	5/16	5/16	1/2		1/2
9/16	3/8	5/16		3/8	3/8	9/16		9/16
1 1/32			5/16					1 1/32
1 1/8	7/16	3/8		7/16	7/16	3/4		3/4
1 1/16			3/8					1 1/16
3/4	1/2	7/16		1/2	1/2	3/4		3/4
25/32			3/16					25/32
13/16		1/2		13/16	13/16	3/4		13/16
7/8	9/16	9/16	1/2	7/8	7/8	7/8		7/8
1 5/16	3/8		9/16	3/4				1 5/16
1		3/4			3/4	1		1
1 1/16			3/4	3/4				1 1/16
1 1/8	3/4	3/4			7/8	1 1/8		1 1/8
1 1/4			3/4	7/8		1 1/4		1 1/4
1 5/8	7/8	7/8			1			1 5/8
1 3/4						1 3/4		1 3/4
1 7/8			7/8	1				1 7/8
1 1/2	1	1			1 1/2	1 1/2		1 1/2
1 3/8			1	1 1/8				1 3/8
1 11/16	1 1/8	1 1/8			1 1/4			1 11/16
1 13/16			1 1/8	1 1/4				1 13/16
1 7/8	1 1/4	1 1/4						1 7/8
2			1 1/4	1 3/8				2
2 1/16	1 3/8	1 3/8						2 1/16
2 1/8			1 3/8	1 1/2				2 1/8
2 1/4	1 1/2	1 1/2						2 1/4
2 3/8			1 1/2					2 3/8
2 1/2	1 3/4	1 3/4						2 1/2
2 5/8			1 3/4					2 5/8
2 3/4	1 3/4	1 3/4						2 3/4
2 7/8			1 3/4					2 7/8
2 15/16	1 7/8	1 7/8						2 15/16
2 11/16			1 7/8					2 11/16
3	2	2						3
3 1/8			2					3 1/8
3 1/4	2 1/4	2 1/4						
3 1/2			2 1/4					
3 3/4	2 1/2	2 1/2						
3 7/8			2 1/2					
4 1/8	2 3/4	2 3/4						
4 1/4			2 3/4					
4 1/2	3	3						
4 3/4			3					
5			3 1/4					
5 1/8			3 1/2					
5 1/4			3 3/4					
6 1/8			4					

Front Clearance

There must be sufficient front clearance on the cutter bit to permit it to cut freely. Usually the front clearance is sufficient to prevent the tool from dragging in the helix angle of the thread so that except for very coarse pitches the helix angle may be ignored.



Side View of Lathe Tool
Cutter Bit Ground for Cutting Screw
Threads

Double Depth of Threads

Threads per Inch	Double Depth U. S. Standard Thread	Double Depth Sharp V Thread	Double Depth Whitworth Standard Thread	Threads per Inch	Double Depth U. S. Standard Thread	Double Depth Sharp V Thread	Double Depth Whitworth Standard Thread
2 1/4	0.5774	0.7698	0.5692	30	0.0433	0.0577	0.0427
2 3/8	0.5470	0.7293	0.5392	32	0.0406	0.0541	0.0400
2 1/2	0.5196	0.6928	0.5123	34	0.0382	0.0509	0.0377
2 5/8	0.4949	0.6598	0.4879	36	0.0361	0.0481	0.0356
2 3/4	0.4724	0.6298	0.4657	38	0.0342	0.0456	0.0337
2 7/8	0.4518	0.6025	0.4454	40	0.0325	0.0433	0.0320
3	0.4330	0.5774	0.4269	42	0.0309	0.0412	0.0305
3 1/4	0.3997	0.5329	0.3940	44	0.0295	0.0394	0.0291
3 1/2	0.3712	0.4949	0.3659	46	0.0282	0.0377	0.0278
4	0.3248	0.4330	0.3202	48	0.0271	0.0361	0.0267
4 1/2	0.2887	0.3849	0.2846	50	0.0260	0.0346	0.0256
5	0.2598	0.3464	0.2561	52	0.0250	0.0333	0.0246
5 1/2	0.2362	0.3149	0.2328	54	0.0241	0.0321	0.0237
6	0.2165	0.2887	0.2134	56	0.0232	0.0309	0.0229
7	0.1856	0.2474	0.1830	58	0.0224	0.0299	0.0221
8	0.1624	0.2165	0.1601	60	0.0217	0.0289	0.0213
9	0.1443	0.1925	0.1423	62	0.0209	0.0279	0.0206
10	0.1299	0.1732	0.1281	64	0.0203	0.0271	0.0200
11	0.1181	0.1575	0.1164	66	0.0197	0.0263	0.0194
12	0.1083	0.1443	0.1067	68	0.0191	0.0255	0.0188
13	0.0999	0.1332	0.0985	70	0.0185	0.0248	0.0183
14	0.0928	0.1237	0.0915	72	0.0180	0.0241	0.0178
15	0.0866	0.1155	0.0854	74	0.0175	0.0234	0.0173
16	0.0812	0.1083	0.0800	76	0.0171	0.0228	0.0167
18	0.0722	0.0962	0.0711	78	0.0167	0.0222	0.0164
20	0.0650	0.0866	0.0640	80	0.0162	0.0217	0.0160
22	0.0590	0.0787	0.0582	82	0.0158	0.0211	0.0156
24	0.0541	0.0722	0.0534	84	0.0155	0.0206	0.0152
26	0.0500	0.0666	0.0493	86	0.0151	0.0201	0.0148
27	0.0481	0.0642	0.0474	88	0.0148	0.0196	0.0145
28	0.0464	0.0619	0.0457	90	0.0144	0.0192	0.0142


Double Depth for U. S. Standard Thread..... = $\frac{1.299}{N}$

Double Depth for Sharp V Thread..... = $\frac{1.732}{N}$

Double Depth for Whitworth Standard Thread..... = $\frac{1.281}{N}$

	D	T	S	W	R
No. of Threads Per Inch.	Depth of Thread.	Thickness at Top of Thread.	Width Space at Bottom of Thread.	Space at Top of Thread.	Thickness at Root of Thread.
1	.5100	.3707	.3655	.6293	.6345
1 1/2	.3850	.2780	.2728	.4720	.4772
2	.2600	.1853	.1801	.3147	.3199
3	.1767	.1235	.1183	.2098	.2150
4	.1350	.0927	.0875	.1573	.1625
5	.1100	.0741	.0689	.1259	.1311
6	.0933	.0618	.0566	.1049	.1101
7	.0814	.0529	.0478	.0899	.0951
8	.0725	.0463	.0411	.0787	.0839
9	.0655	.0412	.0361	.0699	.0751
10	.0600	.0371	.0319	.0629	.0681

ACME STANDARD.—29° THREAD





FORMULA

$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$

$D = \text{Depth} = \frac{1}{2} P. + .010 \text{ In.}$

$F = \text{Flat} = .3707 P.$


$C = \text{Flat} = .3707 P. - .0052 \text{ In.}$



Milled Steel Stud Dimensions

American Standard Coarse Thread

(FORMERLY U.S.S.)



Diameter	$\frac{3}{8}$		$\frac{7}{16}$		$\frac{1}{2}$		$\frac{5}{8}$		$\frac{3}{4}$		$\frac{7}{8}$		1	
Threads per Inch	16		14		13		11		10		9		8	
	N	T	N	T	N	T	N	T	N	T	N	T	N	T
Length														
1	$\frac{1}{2}$	$\frac{1}{2}$	$\frac{1}{2}$	$\frac{1}{2}$										
$1\frac{1}{4}$	$\frac{5}{8}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{5}{8}$						
$1\frac{1}{2}$	$\frac{5}{8}$	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{9}{16}$	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{5}{8}$						
$1\frac{3}{4}$	$\frac{5}{8}$	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{9}{16}$	$\frac{3}{4}$	$\frac{5}{8}$	$\frac{7}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	$\frac{3}{4}$				
2	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{9}{16}$	$\frac{3}{4}$	$\frac{5}{8}$	$\frac{7}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	$\frac{7}{8}$				
$2\frac{1}{4}$	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{9}{16}$	$\frac{3}{4}$	$\frac{5}{8}$	$\frac{7}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	$\frac{7}{8}$	1	1		
$2\frac{1}{2}$	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{9}{16}$	$\frac{3}{4}$	$\frac{5}{8}$	$\frac{7}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	$\frac{7}{8}$	$1\frac{1}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{8}$
$2\frac{3}{4}$	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{9}{16}$	$\frac{7}{8}$	$\frac{3}{4}$	1	$\frac{7}{8}$	1	$\frac{7}{8}$	$1\frac{1}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{8}$
3	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{7}{8}$	$\frac{9}{16}$	$\frac{7}{8}$	$\frac{3}{4}$	1	$\frac{7}{8}$	1	$\frac{7}{8}$	$1\frac{1}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{8}$
$3\frac{1}{4}$			$\frac{7}{8}$	$\frac{9}{16}$	1	$\frac{3}{4}$	1	$\frac{7}{8}$	1	$\frac{7}{8}$	$1\frac{1}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{8}$
$3\frac{1}{2}$			$\frac{7}{8}$	$\frac{9}{16}$	1	$\frac{3}{4}$	1	$\frac{7}{8}$	$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{4}$	1	$1\frac{1}{4}$	$1\frac{1}{8}$
$3\frac{3}{4}$		1	$1\frac{1}{16}$	1	$\frac{3}{4}$	$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{4}$	1	1	$1\frac{1}{4}$	$1\frac{1}{8}$
4			1	$1\frac{1}{16}$	$1\frac{1}{4}$	$\frac{3}{4}$	$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{4}$	1	$1\frac{1}{4}$	1	$1\frac{1}{2}$	$1\frac{1}{4}$
$4\frac{1}{4}$					$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{2}$	1	$1\frac{1}{2}$	$1\frac{1}{8}$	$1\frac{1}{2}$	$1\frac{1}{4}$
$4\frac{1}{2}$					$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{2}$	1	$1\frac{1}{2}$	$1\frac{1}{8}$	$1\frac{3}{4}$	$1\frac{1}{4}$
$4\frac{3}{4}$					$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{2}$	1	$1\frac{1}{2}$	$1\frac{1}{8}$	$1\frac{3}{4}$	$1\frac{1}{4}$
5					$1\frac{1}{4}$	$\frac{7}{8}$	$1\frac{1}{2}$	$\frac{7}{8}$	$1\frac{1}{2}$	1	$1\frac{3}{4}$	$1\frac{1}{8}$	2	$1\frac{1}{4}$
$5\frac{1}{4}$							$1\frac{1}{2}$	$\frac{7}{8}$	$1\frac{1}{2}$	1	$1\frac{3}{4}$	$1\frac{1}{8}$	2	$1\frac{1}{2}$
$5\frac{1}{2}$							$1\frac{1}{2}$	$\frac{7}{8}$	$1\frac{3}{4}$	1	$1\frac{3}{4}$	$1\frac{1}{8}$	2	$1\frac{1}{2}$
$5\frac{3}{4}$							$1\frac{1}{2}$	$\frac{7}{8}$	$1\frac{3}{4}$	1	$1\frac{3}{4}$	$1\frac{1}{4}$	2	$1\frac{1}{2}$
6							$1\frac{1}{2}$	$\frac{7}{8}$	$1\frac{3}{4}$	1	$1\frac{3}{4}$	$1\frac{1}{4}$	2	$1\frac{1}{2}$

Drilling a Cored Hole

Castings having cored holes are usually drilled with a four lip drill. The hole in the casting should be beveled, as shown in Fig. 1 to start the drill true; otherwise, the drill will follow the cored hole and may be thrown off center. For accurate drilling it is advisable to counterbore the hole a short depth to give the drill point a perfectly concentric starting point.




Fig. 1 Machining a Bevel in Cored Hole to Start Drill True

MACHINE SCREWS — TAP DRILL

Size of Tap	Size of Drill for Outside Diam. of Screw	Size of Drill for Tapping Hole	Size of Tap	Size of Drill for Outside Diam. of Screw	Size of Drill for Tapping Hole	Size of Tap	Size of Drill for Outside Diam. of Screw	Size of Drill for Tapping Hole						
2x48 } 2x56 } 2x64 }	44	50	9x24 } 9x28 } 9x30 } 9x32 }	16	30 28 28 26	16x16 } 16x18 } 16x20 }	I	12 8 7						
3x40 } 3x48 } 3x56 }		39	49 47 45		10x24 } 10x30 } 10x32 }	11		26 24 24	17x16 } 17x18 } 17x20 }	L	8 4 3			
6x32 } 6x36 } 6x40 }			33		46 44 43			11x24 } 11x28 } 11x30 }	6		21 20 19	18x16 } 18x18 } 18x20 }	1 ⁹ / ₆₄	2 2 1
5x30 } 5x32 } 5x36 } 5x40 }					1 ¹ / ₈			43 42 41 38			12x20 } 12x22 } 12x24 } 12x28 }	7 ¹ / ₃₂		24 20 19 18
6x30 } 6x32 } 6x36 } 6x40 }	28			38 37 36 35			13x20 } 13x22 } 13x24 }	15 ¹⁵ / ₆₄			17 17 15			22x16 } 22x18 }
7x28 } 7x30 } 7x32 }		24		34 33 32		14x20 } 14x22 } 14x24 }	1 ¹ / ₄			15 11 10	24x14 } 24x16 } 24x18 }			3 ³ / ₈
8x24 } 8x30 } 8x32 }			19	31 31 30		15x18 } 15x20 } 15x22 } 15x24 }			F	12 10 8 7	26x14 } 26x16 }		13 ¹³ / ₃₂	
												28x14 } 28x16 }		
										30x14 } 30x16 }	29 ²⁹ / ₆₄	U V		

Tapping Threads

Threads may be tapped in the lathe, using a tap as shown in Fig. 1. The lathe spindle should be operated at slow speed and the tap fed to the work by turning the tailstock handwheel, or by sliding the entire tailstock on the lathe bed. Taps may also be held in a drill chuck.




Fig. 1. Tapping in the Lathe

THREAD CUTTING AND FINISHING

Resetting Tool After Cut Has Been Started

If for any reason it is necessary to remove the thread cutting tool before the thread has been completed, the tool must be carefully readjusted so that it will follow the original groove when it is replaced in the lathe.

Before adjusting the tool, take up all the lost motion by pulling the belt forward by hand.

The compound rest top should be set at an angle, and by adjusting the cross feed screw and compound rest feed screw simultaneously the point of the tool can be made to enter exactly into the original groove.

Finishing the End of a Thread

The end of the thread may be finished by any one of several methods. The 45° chamfer on the end of the thread, as shown in Fig. 39 is commonly used for bolts, cap screws, etc. For machine parts and special screws the end is often finished by rounding with a forming tool, as shown in Fig. 40.

It is difficult to stop the threading tool abruptly so some provision is usually made for clearance at the end of the cut. In Fig. 39 a hole has been drilled in the end of the shaft, and in Fig. 40 a neck or groove has been cut around the shaft. The groove is preferable as the lathe must be run very slowly in order to obtain satisfactory results with the drilled hole.

A multiple thread having two grooves is known as a double thread, three threads a triple thread, etc. (See Fig. 41.) The pitch and lead of a multiple thread should not be confused. The pitch is the distance from a point on one thread to the corresponding point on the next thread, while the lead is the distance a screw thread advances in one turn.

When cutting multiple threads in the lathe the first thread is cut to the desired depth. The work is then revolved part of a turn, and the second thread cut, etc.

In order to obtain an exact spacing it is advisable to mill as many equally spaced slots in the face plate for the lathe dog as there are multiple threads to be cut. For a double thread, two slots; a triple thread, three slots, etc. If it is not convenient to cut slots in the face plate, equally spaced studs may be attached to the face plate and a straight tail lathe dog used.




Fig. 38. Adjusting Point of Threading Tool to Conform with Thread




Fig. 39. Finish End of Thread with 45° Chamfer




Fig. 40. Finishing End of Thread with Forming Tool

Cutting Multiple Screw Threads




Fig. 41. A Multiple Screw Thread Having Two Grooves (Double Thread)

Cutting a Left Hand Screw Thread

A left hand screw is one that turns counter-clockwise when advancing (looking at head of screw) as shown in Fig. 42. This is just the opposite of a right hand screw. Left hand threads are used for the cross feed screws of lathes, the left hand end of axles for automobiles and wagons, one end of a turnbuckle, some pipe threads, etc.




Fig. 42. A Left Hand Screw Thread



Fig. 43. A Left Hand Screw, Advances When Turned Counter-clockwise

In cutting left hand screw threads the lathe is set up exactly the same as for cutting right hand screw threads, except that the lathe must be arranged to feed the tool from left to right, instead of from right to left, when the spindle is revolving forward.

Square Screw Threads

Square threads are used for vice screws, jack screws, etc. The sides of the tool for cutting square threads should be ground at an angle to conform with the helix angle of the thread, as shown in Fig. 44

To determine the helix angle of a screw thread, draw line A-C2 equal to the circumference of the thread to be cut. Draw line C2-C equal to the lead of the thread and at right angles to line A-C2. Complete the triangle by drawing line A-C. Angle B in the triangle is the helix angle of the thread. The sides of the tool E and F should be given a little clearance.




Fig. 44. A 29° Worm Thread Form

The width of the cutting edge of the tool for cutting square screw threads is exactly one-half the pitch, but the width of the tool for threading the nut should be from one thousandth to three thousandths of an inch larger, to permit a free fit on the screw.




Fig. 44. Tool for Cutting Square Threads




Fig. 45. Design and Proportions of Square Screw Threads

A 29° Worm Thread should not be confused with the Acme Standard Thread because it differs in the depth of the thread, the width of the top of the tooth and the width of the bottom of the tooth, as shown above. Fig. 44 "A"

29° Worm Thread (Brown & Sharpe)

FORMULA

$$P = \text{Pitch} = \frac{1}{\text{No. Th'ds. Per In.}}$$

$$D = \text{Depth} = .6866 P.$$

$$F = \text{Flat} = .31 P.$$

$$C = \text{Flat} = .335 P.$$

Measuring Screw Threads

To check the number of threads per inch, place a scale against the work, as shown in Fig. 1 so that the end of the scale rests on the point of the thread or on one of the scribed lines. Count the spaces between the end of the scale and the first inch mark, and this will give you the number of threads per inch. Fig. 1 shows eight threads per inch.




Fig. 1 Measuring Screw Threads

Taking the First Cut

After setting up the lathe, as explained on the preceding pages, take a very light trial cut just deep enough to scribe a line on the surface of the work, as shown in Fig. 2. The purpose of this trial cut is to make sure the lathe is arranged for cutting the desired pitch of thread.




Fig. 2 Trial Cut to Check the Set-up for Thread Cutting

Pitch Diameter and Root Diameter of Screw Threads

To find the pitch diameter or root diameter of any screw thread, subtract the constant for the number of threads per inch from the outside diameter.

Threads per Inch	Constants for Finding Pitch Diameter			Constants for Finding Root Diameter		
	National Thread	Whitworth Thread	Theoretical V	National Thread	Whitworth Thread	Theoretical V
72	.00902	.00889	.01203	.01804	.01786	.02406
64	.01015	.01000	.01353	.02030	.02001	.02706
60	.01083	.01067	.01443	.02165	.02134	.02887
56	.01160	.01144	.01546	.02320	.02286	.03093
50	.01299	.01281	.01732	.02598	.02562	.03464
48	.01353	.01334	.01804	.02706	.02668	.03608
44	.01476	.01455	.01968	.02952	.02910	.03936
40	.01624	.01601	.02165	.03248	.03202	.04330
36	.01804	.01779	.02406	.03608	.03558	.04811
32	.02030	.02001	.02706	.04059	.04002	.05413
30	.02165	.02134	.02887	.04330	.04268	.05773
28	.02320	.02287	.03093	.04639	.04574	.06186
27	.02406	.02372	.03207	.04812	.04742	.06416
26	.02498	.02463	.03331	.04996	.04926	.06662
24	.02706	.02668	.03608	.05413	.05336	.07217
22	.02952	.02911	.03936	.05905	.05821	.07873
20	.03248	.03202	.04330	.06495	.06403	.08660
18	.03608	.03557	.04811	.07217	.07114	.09623
16	.04059	.04002	.05413	.08119	.08004	.10825
14	.04639	.04574	.06186	.09279	.09147	.12372
13	.04996	.04926	.06662	.09993	.09851	.13323
12	.05413	.05336	.07217	.10825	.10672	.14434
11 1/2	.05648	.05568	.07531	.11296	.11132	.15062
11	.05905	.05821	.07873	.11809	.11642	.15746
10	.06495	.06403	.08660	.12990	.12806	.17321
9	.07217	.07115	.09623	.14434	.14230	.19245
8	.08119	.08004	.10825	.16238	.16008	.21651
7	.09279	.09148	.12372	.18558	.18295	.24744
6	.10825	.10672	.14434	.21651	.21344	.28868
5 1/4	.11809	.11642	.16746	.23619	.23284	.31492
5	.12990	.12807	.17321	.25981	.25613	.34641
4 1/2	.14434	.14230	.19245	.28868	.28458	.38490
4	.16238	.16008	.21651	.32476	.32017	.43301
3 1/2	.18558	.18295	.24744	.37115	.36590	.49487
3 1/4	.19985	.19702	.26647	.39970	.39404	.53294
3	.21651	.21344	.28868	.43301	.42689	.57733




Fig. 1 Simple gearing




Fig. 2 Compound gearing

How to Calculate Change Gears for Thread Cutting

If it is necessary to cut a special thread that does not appear on the index chart of a lathe or if no index chart is available, the gears required can easily be calculated. If simple gearing is to be used, as shown; that is, the stud gear revolves the same number of revolutions as the headstock spindle, and when gears of the same size are used on both the lead screw and stud, the lead screw and spindle revolve the same number of revolutions, so it is not necessary to consider the gearing between the headstock spindle and the stud gear when calculating change gears.

If simple gearing is to be used, as shown in Fig. 1 the ratio of the number of teeth in the change gears used will be the same as the ratio between the thread to be cut and the thread on the lead screw. For example, if 10 threads per inch are to be cut on a lathe having a lead screw with 6 threads per inch, the ratio of the change gears would be 6 to 10. These numbers may be multiplied by any common multiplier to obtain the number of teeth in the change gears that should be used.

Rule—To calculate change gears, multiply the number of threads per inch to be cut and the number of threads per inch in the lead screw by the same number.

Example: Problem—To cut 10 threads per inch on lathe having lead screw with 6 threads per inch.

Solution— $6 \times 8 = 48$ — No. of teeth in gear on stud.

$10 \times 8 = 80$ — No. of teeth in gear on lead screw.

If these gears are not to be found in the change gear set, any other number may be used as a common multiplier, such as 3, 5, 7, etc.

When compound gearing, as shown in Fig. 2 is used, the ratio of the compound idler gears must also be taken into consideration, but otherwise the calculations are the same as for simple gearing. Usually, the compound idler gear ratio is 2 to 1, so that the threads cut are just twice the number per inch as when simple gearing is used.

Types of Pulleys—Two types of pulleys are used for flat belts, the crowned face pulley and the flat face pulley. Crowned pulleys should always be used if possible, as it is the crown that keeps the belt on the pulley. Flat face pulleys should be used only when it is necessary to shift the belt from one position on the pulley to another, as in a drum pulley or a wide faced pulley on a machine used to match a tight and loose pulley on a countershaft.

CHANGE GEARS FOR THREAD MILLING

Single Thread													
Threads Per Inch	A	B	C	D	F	G	Threads Per Inch	A	B	C	D	F	G
40							10	36	20	20	30	1	96
39							9	40	20	20	30	1	96
38	20	38	24	40	1	96	8	36	20	20	24	1	96
36	20	36	24	40	1	96	7	30	21	24	20	1	96
35							6	40	24	36	30	1	96
34	20	34	24	40	1	96	5½	40	20	24	22	1	96
32	20	32	24	40	1	96	5	40	20	24	20	1	96
30	20	30	24	40	1	96	4½	24	20	20	36	1	24
29	20	29	24	40	1	96	4	24	20	20	32	1	24
28	20	28	24	40	1	96	3½	24	20	20	28	1	24
27	20	27	24	40	1	96	3¼	24	20	20	26	1	24
26	20	26	24	40	1	96	3	36	24	20	30	1	24
25	20	25	24	40	1	96	2¾	24	20	20	23	1	24
24	30	36	24	40	1	96	2¾	36	22	20	30	1	24
23	24	23	20	40	1	96	2½	32	20	20	28	1	24
22	24	22	20	40	1	96	2½	30	20	20	25	1	24
21	24	21	20	40	1	96	2¾	24	38	40	20	1	24
20	24	20	20	40	1	96	2¼	40	20	20	30	1	24
19	24	20	20	38	1	96	2¼	40	20	24	34	1	24
18	24	20	20	36	1	96	2	40	20	24	32	1	24
17	24	20	20	34	1	96	1¾	40	20	24	30	1	24
16	24	20	20	32	1	96	1¾	30	21	24	20	1	24
15	24	20	20	30	1	96	1½	40	20	24	26	1	24
14	24	20	20	28	1	96	1½	40	24	36	30	1	24
13	24	20	20	26	1	96	1¾	40	20	24	22	1	24
12	36	24	20	30	1	96	1¼	40	20	24	20	1	24
11½	24	20	20	23	1	96	1½	40	20	28	21	1	24
11	30	20	20	40	1	96	1	21	28	20	40	8	24

Double Thread

Threads per Inch	A	B	C	D	F	G	Threads per Inch	A	B	C	D	F	G
40	24	20	20	40	1	96	10	24	20	20	40	1	24
39	32	26	20	40	1	96	9	24	20	20	36	1	24
38	24	20	20	38	1	96	8	30	20	20	40	1	24
36	24	20	20	36	1	96	7	24	20	20	28	1	24
35	20	25	24	28	1	96	6	36	24	20	30	1	24
34	24	20	20	34	1	96	5½	36	22	20	30	1	24
32	24	20	20	32	1	96	5	30	20	20	25	1	24
30	24	20	20	30	1	96	4½	40	20	20	30	1	24
29	24	20	20	29	1	96	4	40	20	24	32	1	24
28	24	20	20	28	1	96	3½	30	21	24	20	1	24
27	24	20	20	27	1	96	3¼	40	20	24	26	1	24
26	24	20	20	26	1	96	3	40	24	36	30	1	24
25	24	20	20	25	1	96	2¾	40	20	24	23	1	24
24	36	24	20	30	1	96	2¾	40	20	24	22	1	24
23	24	20	20	23	1	96	2½	40	20	24	21	1	24
22	36	22	30	30	1	96	2½	40	20	30	25	1	21
21	32	20	20	8	1	96	2¾	20	40	24	38	8	24
20	36	20	20	30	1	96	2¼	20	30	20	40	8	24
19	20	38	24	40	1	24	2¼	20	34	24	40	8	24
18	20	36	24	40	1	24	2	20	23	21	40	8	24
17	20	34	24	40	1	24	1¾	20	30	24	40	8	24
16	20	32	24	40	1	24	1¾	20	28	24	40	8	24
15	20	30	24	40	1	24	1½	20	26	24	40	8	24
14	20	28	24	40	1	24	1½	21	28	24	36	8	24
13	20	26	24	40	1	24	1¾	20	22	24	40	8	24
12	20	28	21	30	1	24	1¼	20	25	21	28	8	24
11½	24	23	20	40	1	24	1½	20	36	24	20	8	21
11	24	22	20	40	1	24	1	30	20	20	40	8	24

CAUTION — See That Table Trip Lever is Locked.

Kearney & Trecker Corporation, Milwaukee, Wis.
Change Gears for Thread Milling—

CHANGE GEARS FOR THREAD MILLING

Triple Thread													
Threads per Inch	A	B	C	D	F	G	Threads per Inch	A	B	C	D	F	G
40	36	20	20	40	1	96	10	27	20	20	30	1	24
39	24	20	20	26	1	96	9	25	20	24	20	1	24
38	36	20	20	38	1	96	8	27	20	20	24	1	24
36	36	24	20	30	1	96	7	36	20	20	28	1	24
35	36	25	20	28	1	96	6	36	20	20	24	1	24
34	36	20	20	34	1	96	5½	36	20	20	22	1	24
33	36	22	20	30	1	96	5	40	20	27	30	1	24
32	30	20	24	32	1	96	4½	32	20	25	20	1	24
30	36	20	20	30	1	96	4	36	32	40	20	1	24
29	36	20	20	29	1	96	3½	40	20	27	21	1	24
28	36	20	20	28	1	96	3¼	40	20	36	26	1	24
27	36	20	20	27	1	96	3	40	20	36	24	1	24
26	36	20	20	26	1	96	2⅞	40	20	36	23	1	24
25	36	20	20	25	1	96	2¾	40	20	36	22	1	24
24	36	20	20	24	1	96	2⅝	24	28	20	20	8	24
23	36	20	20	23	1	96	2½	24	28	21	40	8	24
22	36	20	20	22	1	96	2⅜	24	38	20	40	8	24
21	36	20	20	21	1	96	2¼	24	30	25	40	8	24
20	30	20	24	20	1	96	2⅜	21	28	24	34	8	24
19	36	38	40	20	1	96	2	21	40	20	28	8	24
18	30	20	28	21	1	96	1⅞	24	20	20	40	8	24
17	40	20	36	34	1	96	1¾	30	28	24	40	8	24
16	36	20	30	24	1	96	1⅝	21	26	24	28	8	24
15	24	20	20	40	1	24	1½	30	20	20	40	8	24
14	20	40	36	28	1	24	1⅜	21	22	24	28	8	24
13	20	30	27	26	1	24	1¼	30	20	24	40	8	24
12	30	20	20	40	1	24	1⅝	30	24	20	25	8	24
11½	20	40	36	23	1	24	1	36	24	30	40	8	24
11	27	22	20	30	1	24							

Kearney & Trecker Corp.,

Quadruple Thread

Threads per Inch	A	B	C	D	F	G	Threads per Inch	A	B	C	D	F	G
40	36	20	20	30	1	96	10	36	20	20	30	1	24
39	40	30	24	26	1	96	9	36	20	20	27	1	24
38	40	20	24	38	1	96	8	36	20	20	24	1	24
36	40	20	20	30	1	96	7	36	20	20	21	1	24
35	36	21	20	25	1	96	6	36	30	40	24	1	24
34	40	20	24	34	1	96	5½	40	22	24	20	1	24
33	40	22	24	30	1	96	5	36	30	40	20	1	24
32	40	20	24	32	1	96	4½	24	36	20	40	8	24
30	24	30	20	40	1	24	4	24	32	20	40	8	24
29	24	29	20	40	1	24	3½	24	28	20	40	8	24
28	24	28	20	40	1	24	3¼	24	26	20	40	8	24
27	24	27	20	40	1	24	3	30	36	24	40	8	24
26	24	26	20	40	1	24	2⅞	24	23	20	40	8	24
25	24	25	20	40	1	24	2¾	24	22	20	40	8	24
24	24	40	20	36	1	24	2⅝	24	21	20	40	8	24
23	24	23	20	40	1	24	2½	24	20	20	40	8	24
22	24	22	20	40	1	24	2⅜	24	20	20	38	8	24
21	20	25	20	28	1	24	2¼	24	20	20	36	8	24
20	24	20	20	40	1	24	2⅜	24	20	20	34	8	24
19	24	20	20	38	1	24	2	24	20	20	32	8	24
18	24	20	20	36	1	24	1⅞	24	20	20	30	8	24
17	24	20	20	34	1	24	1¾	24	20	20	28	8	24
16	24	20	20	32	1	24	1⅝	24	20	20	26	8	24
15	24	20	20	30	1	24	1½	30	24	20	25	8	24
14	24	20	20	28	1	24	1⅜	36	22	20	30	8	24
13	24	20	20	26	1	24	1¼	36	20	20	30	8	24
12	20	25	30	24	1	24	1⅝	36	20	20	27	8	24
11½	24	20	20	23	1	24	1	36	20	20	24	8	24
11	24	20	20	22	1	24							

CAUTION — See That Table Trip Lever is Locked.

—Sizes of Tap Drills, American National Coarse-Thread Series

Size of thread	Threads per inch	Minor diameter of nut			Stock drills corresponding to 100 percent to 50 percent of basic thread depth		
		Basic	Maximum	Minimum	Nominal size	Diameter	Percentage of depth of basic thread
5	40	.0925	.1062	.0979	#39	.0995	79
					#38	.1015	72
					2.60 mm	.1024	70
					#37	.1040	65
6	32	.0974	.1145	.1042	#36	.1065	78
					$\frac{7}{64}$ in.	.1094	70
					#33	.1130	62
8	32	.1234	.1384	.1302	3.40 mm	.1339	74
					#29	.1360	69
					3.50 mm	.1378	65
10	24	.1359	.1559	.1449	#26	.1470	79
					#24	.1520	70
12	24	.1619	.1801	.1709	$1\frac{1}{4}$ in.	.1719	82
					#17	.1730	79
					#16	.1770	72
					#15	.1800	67
$\frac{1}{4}$	20	.1850	.2060	.1959	#9	.1960	83
					#8	.1990	79
					$1\frac{1}{4}$ in.	.2031	72
$\frac{5}{16}$	18	.2403	.2630	.2524	F	.2570	77
					G	.2610	71
$\frac{3}{8}$	16	.2938	.3184	.3073	$\frac{3}{8}$ in.	.3125	77
					O	.3160	73
$\frac{7}{16}$	14	.3447	.3721	.3602	U	.3680	75
$\frac{1}{2}$	13	.4001	.4290	.4167	$2\frac{3}{4}$ in.	.4219	78
$\frac{9}{16}$	12	.4542	.4850	.4723	$3\frac{1}{4}$ in.	.4844	72
$\frac{5}{8}$	11	.5069	.5397	.5266	$1\frac{1}{2}$ in.	.5312	79
					13.5 mm	.5315	79
$\frac{3}{4}$	10	.6201	.6553	.6417	16.5 mm	.6496	77
$\frac{7}{8}$	9	.7307	.7689	.7547	$4\frac{3}{4}$ in.	.7656	76
					19.5 mm	.7677	74
1	8	.8376	.8795	.8647	22 mm	.8661	82
					$\frac{7}{8}$ in.	.8750	77
1 $\frac{1}{8}$	7	.9394	.9858	.9704	25 mm	.9842	76
					$3\frac{3}{4}$ in.	.9844	76
1 $\frac{1}{4}$	7	1.0644	1.1108	1.0954	28 mm	1.1024	80
					$1\frac{1}{4}$ in.	1.1094	76
1 $\frac{3}{8}$	6	1.1585	1.2126	1.1946	30.5 mm	1.2008	80
					$1\frac{3}{4}$ in.	1.2031	79
1 $\frac{1}{2}$	6	1.2835	1.3376	1.3196	$1\frac{3}{4}$ in.	1.3281	79
1 $\frac{3}{4}$	5	1.4902	1.5551	1.5335	39 mm	1.5354	83
					$1\frac{3}{4}$ in.	1.5469	78
					39.5 mm	1.5551	75
2	4 $\frac{1}{2}$	1.7113	1.7835	1.7594	$1\frac{9}{16}$ in.	1.7656	81
					45 mm	1.7716	79
					$1\frac{1}{2}$ in.	1.7812	76

—Sizes of Tap Drills, American National Fine-Thread Series

Size of thread	Threads per inch	Minor diameter of nut			Stock drills corresponding to 100 percent to 50 percent of basic thread depth		
		Basic	Maximum	Minimum	Nominal size	Diameter	Percentage of depth of basic thread
5--	44	.0955	.1068	.1004	{ 2.60 mm ----- #37 ----- #36 -----	.1024 .1040 .1065	77 71 63
6--	40	.1055	.1179	.1109	{ #33 ----- #32 -----	.1130 .1160	77 68
8--	36	.1279	.1402	.1339	{ 3.40 mm ----- #29 ----- 3.50 mm ----- 3/16 in -----	.1339 .1360 .1378 .1406	83 78 73 65
10--	32	.1494	.1624	.1562	{ 1/2 in ----- #21 ----- #20 ----- #19 -----	.1562 .1590 .1610 .1660	83 76 71 59
12--	28	.1696	.1835	.1773	{ #15 ----- 4.70 mm #13 ----- 5/16 in -----	.1800 .1850 .1875	78 67 61
1/4--	28	.2036	.2173	.2113	#3 -----	.2130	80
5/16--	24	.2584	.2739	.2674	{ 17/64 in ----- 1 -----	.2656 .2720	87 75
3/8--	24	.3209	.3364	.3299	Q -----	.3320	79
7/16--	20	<i>Inch</i> 0.3725	<i>Inch</i> 0.3906	<i>Inch</i> 0.3834	{ W ----- 25/64 in -----	<i>Inch</i> 0.3860 .3906	79 72
1/2--	20	.4350	.4531	.4459	29/64 in -----	.4531	72
9/16--	18	.4903	.5100	.5024	0.5062 -----	.5062	78
5/8--	18	.5528	.5725	.5649	14.5 mm -----	.5709	75
3/4--	16	.6688	.6903	.6823	{ 11/16 in ----- 17.5 mm -----	.6875 .6890	77 75
7/8--	14	.7822	.8062	.7977	{ 51/64 in ----- 20.5 mm -----	.7969 .8071	84 73
1--	14	.9072	.9312	.9227	23.5 mm -----	.9252	81
1 1/8--	12	1.0167	1.0438	1.0348	26.5 mm -----	1.0433	75
1 1/4--	12	1.1417	1.1688	1.1598	29.5 mm -----	1.1614	82
1 3/8--	12	1.2667	1.2938	1.2848	{ 9/16 in ----- 19/64 in -----	1.2812 1.2969	8 72
1 1/2--	12	1.3917	1.4188	1.4098	36 mm -----	1.4173	76

Tap drill size for 75% full thread for ANY American National Thread equals major diameter minus pitch in inches.

Table of Speeds and Feeds — For High Speed Drills

Diameter of Drill	Feed per Revolution	Mild Steel	Tool Steel	Cast Iron	Brass and Bronze	Drop Forgings
		Cutting Speed, Feet per Minute				
		120 Feet	60 Feet	140 Feet	300 Feet	60 Feet
		REVOLUTIONS PER MINUTE				
$\frac{1}{16}$.003	7334	3666	8566	18336	3666
$\frac{3}{32}$.0035	5500	2750	6417	13750	2750
$\frac{1}{8}$.004	3666	1834	4278	9168	1834
$\frac{5}{32}$.0045	3055	1528	3565	7640	1528
$\frac{3}{16}$.005	2444	1222	2852	6112	1222
$\frac{7}{32}$.0055	2139	1069	2496	5348	1069
$\frac{1}{4}$.006	1834	916	2140	4584	916
$\frac{9}{32}$.0065	1650	825	1926	4125	825
$\frac{5}{16}$.007	1466	734	1712	3666	734
$\frac{11}{32}$.0075	1344	673	1569	3361	673
$\frac{3}{8}$.008	1222	612	1426	3056	612
$\frac{13}{32}$.0085	1135	568	1324	2838	568
$\frac{7}{16}$.009	1048	524	1222	2620	524
$\frac{15}{32}$.0095	982	491	1146	2456	491
$\frac{1}{2}$.010	916	458	1070	2292	458
$\frac{9}{16}$.0105	825	412	963	2063	412
$\frac{5}{8}$.011	734	366	856	1834	366
$\frac{11}{16}$.0115	673	336	785	1681	336
$\frac{3}{4}$.012	612	306	714	1528	306
$\frac{13}{16}$.0125	568	284	663	1419	284
$\frac{7}{8}$.013	524	262	612	1310	262
$\frac{15}{16}$.0135	491	246	573	1228	246
1	.014	458	230	534	1146	230
$1\frac{1}{8}$.015	408	204	476	1018	204
$1\frac{1}{4}$.016	366	184	428	916	184
$1\frac{3}{8}$.016	334	166	388	834	166
$1\frac{1}{2}$.016	306	152	356	764	152
$1\frac{5}{8}$.016	282	140	330	706	140
$1\frac{3}{4}$.016	262	130	306	654	130
$1\frac{7}{8}$.016	244	122	286	612	122
2	.016	230	114	268	574	114




Fig. 1

Center Drilling

When greater accuracy is required it is best to provide a true starting point for the drill. To do this the work should first be center drilled using a combination center drill and countersink, as shown in Fig. 1. The point of the center drill may be ground off as shown in Fig. 2 to prevent breaking.

Grind off
Tip of
Drill,
Shown by
dotted line



Fig. 2




Fig. 3

Flat Centering Drill

A flat centering tool or drill of forged steel held rigidly in the tool post of the lathe, as shown in Figs. 3 and 4 is often used for production drilling. This type of centering drill provides an accurate starting point for the drill, and since the centering drill is mounted in the tool post, it may be moved back out of the way for the drill which is to follow. This saves time as it eliminates the necessity of changing drills in the tailstock spindle.




Fig. 4


**Table of Speeds and Feeds
For Carbon Steel Drills**

Diameter of Drill	Feed per Revolution	Mild Steel	Tool Steel	Cast Iron	Brass and Bronze	Drop Forging
		Cutting Speed, Feet per Minute				
		60 Feet	30 Feet	70 Feet	150 Feet	30 Feet
		REVOLUTIONS PER MINUTE				
$\frac{1}{16}$.003	3667	1833	4278	9168	1833
$\frac{3}{32}$.0035	2750	1375	3208	6875	1375
$\frac{1}{8}$.004	1833	917	2139	4584	917
$\frac{5}{32}$.0045	1527	764	1782	3820	764
$\frac{3}{16}$.005	1222	611	1426	3056	611
$\frac{7}{32}$.0055	1069	534	1248	2674	534
$\frac{1}{4}$.006	917	458	1070	2292	458
$\frac{9}{32}$.0065	825	412	963	2062	412
$\frac{5}{16}$.007	733	367	856	1833	367
$\frac{11}{32}$.0075	672	336	784	1680	336
$\frac{3}{8}$.008	611	306	713	1528	306
$\frac{13}{32}$.0085	567	284	662	1419	284
$\frac{7}{16}$.009	524	262	611	1310	262
$\frac{15}{32}$.0095	491	245	573	1228	245
$\frac{1}{2}$.010	458	229	535	1146	229
$\frac{9}{16}$.0105	412	206	481	1031	206
$\frac{5}{8}$.011	367	183	428	917	183
$\frac{11}{16}$.0115	336	168	392	840	168
$\frac{3}{4}$.012	306	153	357	764	153
$\frac{13}{16}$.0125	284	142	331	709	142
$\frac{7}{8}$.013	262	131	306	655	131
$\frac{15}{16}$.0135	245	123	286	614	123
1	.014	229	115	267	573	115
$1\frac{1}{8}$.015	204	102	238	509	102
$1\frac{1}{4}$.016	183	92	214	458	92
$1\frac{3}{8}$.016	167	83	194	417	83
$1\frac{1}{2}$.016	153	76	178	382	76
$1\frac{5}{8}$.016	141	70	165	353	70
$1\frac{3}{4}$.016	131	65	153	327	65
$1\frac{7}{8}$.016	122	61	143	306	61
2	.016	115	57	134	287	57


Shoulder and Radius Forming

The corners in turned work are at various times finished square, necked, either square or round, or with a small radius. Also with square or radius tool at an angle of 45° to allow clearance for grinding both diameter and face.


The square corner is the simplest type and is used where the piece is not subject to excess stress at the corner section. The necked corner is used as above, also where grinding allowance is left



in turning. The undercut neck prevents undue wear on the corner of the grinding wheel.



Counterbore Sizes for Cap Screws and Machine Screws

													
Fillister Head Cap Screw		Fillister Head Cap Screw		Body and Tap Hole for any Screw		Round or Hexagon Head Cap Screw		Fillister Head Machine Screw		Round or Hex. Head Machine Screw			
Head and Body		Head and Tap Hole				Head and Body		Head and Body		Head and Body			
Size Thread N.F. and N.C.	Cutter for Head	Pilot for Body	Cutter for Head	Pilot for Tap Hole	Cutter for Body	Pilot for Tap Hole	Cutter for Head	Pilot for Body	Cutter for Head	Pilot for Body	Cutter for Head	Pilot for Body	Tap Drills
$\frac{1}{4}$ -28	.375	.250	.375	.213	.250	.213	.500	.250	.437	.250	.500	.250	3
$\frac{1}{4}$ -20	.375	.250	.375	.201	.250	.201	.500	.250	.437	.250	.500	.250	7
$\frac{3}{8}$ -24	.437	.312	.437	.272	.312	.272	.625	.312	.531	.312	.625	.312	1
$\frac{3}{8}$ -18	.437	.312	.437	.257	.312	.257	.625	.312	.531	.312	.625	.312	F
$\frac{3}{8}$ -24	.562	.375	.562	.332	.375	.332	.687	.375	.625	.375	.750	.375	Q
$\frac{3}{8}$ -16	.562	.375	.562	.312	.375	.312	.687	.375	.625	.375	.750	.375	$\frac{5}{16}$
$\frac{1}{2}$ -20	.625	.437	.625	.390	.437	.390	.813	.437	.718	.437	.875	.437	$\frac{25}{64}$
$\frac{1}{2}$ -14	.625	.437	.625	.368	.437	.368	.813	.437	.718	.437	.875	.437	U
$\frac{1}{2}$ -20	.750	.500	.750	.453	.500	.453	.875	.500	.843	.500	1.000	.500	$\frac{29}{64}$
$\frac{1}{2}$ -13	.750	.500	.750	.421	.500	.421	.875	.500	.843	.500	1.000	.500	$\frac{27}{64}$
$\frac{1}{2}$ -18	.812	.562	.812	.515	.562	.515	1.000	.562					$\frac{33}{64}$
$\frac{1}{2}$ -12	.812	.562	.812	.484	.562	.484	1.000	.562					$\frac{31}{64}$
$\frac{3}{4}$ -18	.875	.625	.875	.578	.625	.578	1.062	.625					$\frac{37}{64}$
$\frac{3}{4}$ -11	.875	.625	.875	.531	.625	.531	1.062	.625					$\frac{17}{32}$
$\frac{3}{4}$ -16	1.000	.750	1.000	.687	.750	.687	1.312	.750					$\frac{11}{16}$
$\frac{3}{4}$ -10	1.000	.750	1.000	.656	.750	.656	1.312	.750					$\frac{13}{32}$
$\frac{3}{4}$ -14	1.125	.875	1.125	.812	.875	.812	1.375	.875					$\frac{15}{16}$
$\frac{3}{8}$ -9	1.125	.875	1.125	.765	.875	.765	1.375	.875					$\frac{49}{64}$
1-14	1.312	1.000	1.312	.937	1.000	.937	1.500	1.000					$\frac{15}{16}$
1-8	1.312	1.000	1.312	.875	1.000	.875	1.500	1.000					$\frac{1}{8}$

Sizes of Wrenches to Use for Counterbores and Spot Facers

Range of Sizes of
Counterbores
Inches

Size of Wrench for Hollow
Hexagon Set Screw
Inches

$\frac{1}{4}$ to $\frac{11}{32}$	$\frac{1}{16}$ Hex.
$\frac{3}{8}$ to $\frac{7}{16}$	$\frac{5}{64}$ Hex.
$\frac{15}{32}$ to $\frac{11}{16}$	$\frac{3}{32}$ Hex.
$\frac{23}{32}$ to $\frac{13}{16}$	$\frac{1}{8}$ Hex.
$\frac{17}{32}$ to $\frac{15}{16}$	$\frac{5}{32}$ Hex.
2 to 3.....	$\frac{3}{16}$ Hex.

The measurements used for the wrench are across the flat.

SHIELDS DECIMAL EQUIVALENTS

of Twist Drills, Drill Rods, Stub Steel Wire Gauges, and Letter Sizes of Drills

FOUR TABLES IN ONE

This Table is to Show the Difference Between the Sizes of Twist Drills, and Drill Rods;
to Save Time and Mistakes

Number of Twist Drill Wire Gauge Drill Rod Letter Size of Drills.	Size of Number in Decimals of Twist Drills.	Size of Number in Decimals of Drill Rods Wire Gauge and Letter Size of Drills.	Number of Twist Drill Wire Gauge Drill Rod Letter Size of Drills.	Size of Number in Decimals of Twist Drills.	Size of Number in Decimals of Drill Rods Wire Gauge and Letter Size of Drills.	Number of Twist Drill Wire Gauge Drill Rod Letter Size of Drills.	Size of Number in Decimals of Twist Drills.	Size of Number in Decimals of Drill Rods Wire Gauge and Letter Size of Drills.
1	.2280	.227	37	.1040	.103	73	.0240	.023
2	.2210	.219	38	.1015	.101	74	.0225	.022
3	.2130	.212	39	.0995	.099	75	.0210	.020
4	.2090	.207	40	.0980	.097	76	.0200	.018
5	.2055	.204	41	.0960	.095	77	.0180	.016
6	.2040	.201	42	.0935	.092	78	.0160	.015
7	.2010	.199	43	.0890	.088	79	.0145	.014
8	.1990	.197	44	.0860	.085	80	.0135	.013
9	.1960	.194	45	.0820	.081			
10	.1935	.191	46	.0810	.079			
11	.1910	.188	47	.0785	.077	A $\frac{15}{64}$.234	.234
12	.1890	.185	48	.0760	.075	B	.238	.238
13	.1850	.182	49	.0730	.072	C	.242	.242
14	.1820	.180	50	.0700	.069	D	.246	.246
15	.1800	.178	51	.0670	.066	E $\frac{1}{4}$.250	.250
16	.1770	.175	52	.0635	.063	F	.257	.257
17	.1730	.172	53	.0595	.058	G	.261	.261
18	.1695	.168	54	.0550	.055	H $\frac{17}{64}$.266	.266
19	.1660	.164	55	.0520	.050	I	.272	.272
20	.1610	.161	56	.0465	.045	J	.277	.277
21	.1590	.157	57	.0430	.042	K $\frac{9}{32}$.281	.281
22	.1570	.155	58	.0420	.041	L	.290	.290
23	.1540	.153	59	.0410	.040	M $\frac{19}{64}$.295	.295
24	.1520	.151	60	.0400	.039	N	.302	.302
25	.1495	.148	61	.0390	.038	O $\frac{5}{16}$.316	.316
26	.1470	.146	62	.0380	.037	P $\frac{21}{64}$.323	.323
27	.1440	.143	63	.0370	.036	Q	.332	.332
28	.1405	.139	64	.0360	.035	R $\frac{11}{32}$.339	.339
29	.1360	.134	65	.0350	.033	S	.348	.348
30	.1285	.127	66	.0330	.032	T $\frac{23}{64}$.358	.358
31	.1200	.120	67	.0320	.031	U	.368	.368
32	.1160	.115	68	.0310	.030	V $\frac{3}{8}$.377	.377
33	.1130	.112	69	.02925	.029	W $\frac{25}{64}$.386	.386
34	.1110	.110	70	.0280	.027	X	.397	.397
35	.1100	.108	71	.0260	.026	Y $\frac{13}{32}$.404	.404
36	.1065	.106	72	.0250	.024	Z	.413	.413

Copyright 1925 by Chas. J. Shields, St. Louis, Mo.

Use Turpentine instead of oil, when drilling hard steel, saw plate, etc. It will drill readily, when you could not touch it with oil. Try it.



TWIST DRILLS, GRINDING AND GAUGES

Grinding of Twist Drills

GAUGES FOR GRINDING DRILLS

STYLE No. 1

STYLE No. 2



DIPPING HIGH SPEED
 DRILLS IN WATER
 IS BAD PRACTICE

ANGLE OF POINTS

Steel Rails 7%-13% Manganese and hard materials
Heat Treated Steels—Drop Forgings (Automobile Connecting Rods) Brinell Hardness No. 250
Cast Iron—Soft
Brass
Wood
Hard Rubber } Bakelite } Fiber }
Copper
Crankshafts

Point
Fig. 4 { 150° included angle 10° lip clearance Slightly flat face of cutting lips.
Fig. 5 { 125° included angle 12° lip clearance
Fig. 6 { 90° included angle 12° lip clearance
Fig. 7 { 118° included angle 12° lip clearance Slightly flat face of cutting lips.
Fig. 8 { 60° included angle 12° lip clearance
Figs. 6 & 8 { 60° and 90° included angle
Fig. 9 { 100° included angle 12° lip clearance
Fig. 10 { 118° included angle Chisel Point.

Material Used On


Fig. 1 {
Fig. 2 { Average Class of Work.
Fig. 3 {
Fig. 4 { Steel Rails 7% to 13% Manganese and Hard Material.
Fig. 5 { Heat Treated Steels, Drop Forgings (Automobile Connecting Rods) Brinell Hardness 250.
Fig. 6 { Cast Iron—Soft.
Fig. 7 { Brass.
Fig. 8 { Wood, Hard Rubber, Bakelite and Fiber (No. 6 may also be used).
Fig. 9 { Copper.
Fig. 10 { Crankshafts.

In up-to-date drilling practice drilling different grades of materials requires at times a modification of the commercial 118° drill point for maximum results.

Hard materials require a blunter point with the more acute angle for softer materials.

We have conducted exhaustive experiments with different angles of points in various grades of materials and are giving this information herewith in hopes that it will be of value to the consumers of drills. Also a list of speeds and feeds for drills used in various materials which were established on a production basis and which will be of value as a standard reference from which to deviate according to conditions. There are many variable factors involved in drilling operations, such as different materials, degrees of hardness, depth of holes, lack of uniformity of materials, lubrication, etc., which make it difficult to establish a list on speeds and feeds that will conform satisfactorily to all conditions.

FINISH DIMENSIONS OF JACOBS TAPERS FOR REFERENCE USE ONLY
SEE INDIVIDUAL DRAWINGS FOR COMPLETE DETAILS OF PLUG & RING GAGES




JACOBS TAPER	E	G	D	TAPER PER FOOT	RING GAGE Dia No.	PLUG GAGE Dia No.	MODEL NUMBER OF CHUCK USING THE TAPER
0	.2496	.228	.4375	.5914	B 375	B 366	0
1	.3846	.334	.6563	.9251	B 376	B 367	1A, 7-1A, 30-1A, 255, 42001, 250-1A, 40001, 42101
2	.5594	.488	.875	.9786	B 377	B 368	2A, 4A-2A, 8, 11, 11N, 5E, 575, 381, 44002, 44102
2.5 SHORT	.5492	.488	.750	.9786	B 378	B 369	7, 8 1/2 N, 30, 250, 312, 313, 42002, 42102
3	.8109	.746	1.2188	.6390	B 379	B 370	3, 3A, 14N, 16N, 36, 75A, 100 CR
4	1.1238	1.037	1.6563	.6289	B 380	B 371	18 N
5	1.4129	1.316	1.875	.6201	B 381	B 372	20 N
6	.6759	.624	1.000	.6229	B 382	B 373	6, 34, 500, 3A-6A, 44006, 44106
33	.6245	.561	1.000	.7619	B 383	B 374	6A-33, 33
VALVE REPACKERS							
32VR	.6759	.624	1.000	.6229	B 382	B 373	32 VR
34VR(S)	.7925	.746	.875	.6390	C 2273	C 2503	34 VR(S)
34VR(L)	.8860	.761	1.500	1.0000	C 3145		34 VR(L)
3AVR	.8919	.842	.9380	.6390	C 2503	C 2506	3AVR
4AVR	1.1073	1.037	1.3430	.6289			4AVR
58VR	1.1249	1.000	1.500	1.0000	C 2504	C 2507	58VR - 75 VR
100VR	1.6851	1.482	2.4375	1.0000			100 VR

THE JACOBS MFG. CO.
Hartford, Conn., U.S.A.

Taper Turning with Compound Rest

The compound rest of the lathe is usually used for turning and boring short tapers and bevels, especially for bevel gear blanks and for die and pattern work, etc. The compound rest swivel is set at the required angle and the taper is machined by turning the compound rest feed screw by hand.



Machining a Conical Punch and Die with Compound Rest

MACHINING ALLEGHENY STAINLESS STEELS

The machining characteristics of Stainless Steels depend on composition, structural condition and hardness. High alloy content in stainless steel produces high tensile strength and great toughness. Stainless cannot be machined as rapidly as carbon steel or the lower alloy steels, it requires a suitable technique for each type of operation and for each different grade. The following outline is a guide for the development of such technique:

Chromium Nickel Alloys contain 16% to 26% chromium and 17% to 21% nickel, depending on the analysis type. These tend to work-harden very rapidly. For machining: maintain a continuous cut, at a relatively low speed, with a heavy cut and feed. (Type 303 is the only free-machining analysis in this group, it rates about 60% of screw stock machinability.

Straight Chromium Alloys contain 10% to 30% chromium. Type 416 and 430-F are the free-machining types in this grade, rate about 80% of screw stock machinability.

Cutting Tools: Use high speed steel or cemented carbide, depending on application. Straight carbon steel tools are not satisfactory. Keep cutting edges keen at all times. Honing of top surface is recommended. In grinding high speed tools for cutting and turning, make the side and end clearance approximately 8° , top rake of about 20° , and side rake about 4° .

Speeds and Feeds for Lathe, Shaper, Planer, Milling and Screw Machine: Because of work-hardening, especially the chromium nickel types, it is important to maintain a constant feed and not allow the tool to ride on the work. Take the heaviest practical cut, with the heaviest possible feed, with a corresponding reduction in surface speeds. The work and tools must be held rigid.

Lubricants: Where possible, lubricate all machining operations. Use any good grade of sulfur base oil or a good grade of lard oil with sulfur added (one pound per gallon makes a good lubricant). Water soluble cutting oils with sulfur added are sometimes satisfactory but use a heavier cutting compound than for ordinary alloys.

Threading and Tapping: Use high speed steel chasers and taps and have as many flutes as possible to provide the maximum number of cutting edges. The tools should be ground so that only 3 or 4 full threads are being cut at one time. Flood the tools with lubricant at all times.

Drilling: Don't work-harden the point of entry with heavy center punch blows. Lubricate plentifully—particularly on heavy work. Use high speed drills with keen cutting edges and good back clearance. Use drills with a heavy web and a quick spiral ground slightly flatter than for ordinary work. Always keep drill cutting, because riding will work-harden the hole. **Drilling Through-Holes:** Back up the metal firmly with plates.

Sawing: Use high speed hack-saw blades with fine wavy teeth. Follow manufacturers' data. Don't let saw ride on work. Use same type coolant recommended above.

Important: Final machined finish directly effects corrosion resistance. A smooth polished surface resists corrosion much better than when rough or pitted. For chromium nickel alloys subject to severe corrosion, relieve the machining stresses by subsequent heat treatment. Clean the piece prior to heat treatment.

Castings: Straight chromium and chromium nickel alloys are machinable under the same conditions as apply to these alloys in wrought form. In machining castings, use heavy tools to offset the effects of vibration and dragging.

NOTE: When steels are heat-treated, use lower figures in table

A.I.S.I. NUMBER	TURNING	THREADING	A.I.S.I. NUMBER	TURNING	THREADING
Sulphurized Carbon Steels			Chromium Steels		
B 1112	140-190	30-60	A 5045	95-125	20-40
C 1113	180-250	40-80	A 5120	100-130	20-40
C 1120	110-150	25-50	A 5140	95-125	20-40
Non Sulphurized Carbon Steels			A 5150	80-115	20-35
C 1010	70-100	15-30	Chromium High Carbon Steel		
C 1015	70-100	15-30	E 52100	40-60	10-20
C 1020	100-130	20-40	Chromium Vanadium Steels		
C 1030	100-130	20-40	A 6120	75-105	15-35
C 1040	85-115	15-35	A 6145	75-105	15-35
C 1050	75-105	15-35	A 6152	70-100	15-30
Manganese Steels			NE		
A 1320	75-105	15-35	NUMBER	TURNING	THREADING
A 1330	75-105	15-35	Manganese Molybdenum Steels		
A 1335	75-105	15-35	NE 8024	85-115	20-35
A 1340	70-100	15-30	NE 8124	75-105	15-35
Nickel Steels			NE 8233	85-115	20-35
A 2317	85-115	20-35	NE 8339	85-115	20-35
A 2330	70-100	15-30	NE 8442	65- 85	15-25
A 2340	70-100	15-30	Nickel Chromium Molybdenum Steel		
A 2515	55- 75	10-20	NE 8620	85-115	20-35
Nickel Chromium Steels			NE 8720	100-130	20-40
A 3045	85-115	20-35	NE 8949	70-100	15-30
A 3120	85-115	20-35	Manganese Silicon		
A 3130	75-105	15-35	NE 9260	70-100	15-30
A 3140	70-100	15-30	Manganese Silicon Nickel Chromium Molybdenum Steel		
A 3240	70-100	15-30	NE 9420	85-115	20-35
E 3310	65- 85	15-25	NE 9440	70-100	15-30
Molybdenum Steels			NE 9537	70-100	15-30
A 4023	105-145	25-45	NE 9550	65- 85	15-25
A 4032	100-130	20-40	Manganese Silicon Chromium Steel		
A 4042	95-125	20-40	NE 9630	70-100	15-30
A 4047	85-115	20-35	NE 9650	65- 85	15-25
Chromium Molybdenum Steels			A = Basic Open Hearth Alloy Steels		
A 4119	100-130	20-40	B = Acid Bessemer Carbon Steels		
A 4130	100-130	20-40	C = Basic Open Hearth Carbon Steels		
A 4137	95-125	20-40	E = Electric Furnace of both carbon & alloy		
A 4145	85-115	20-35	NE = National Emergency Steels		
A 4150	75-105	15-35			
Nickel Chromium Molybdenum Steel					
A 4320	75-105	15-35			
A 4340	70-100	15-30			
Nickel Molybdenum Steel					
A 4615	95-125	20-40			
A 4640	75-105	15-35			
A 4815	70-100	15-30			
Stainless Steels					
Type 416 (14 Chrome) F.M.	95-125	15-35			
Type 430 (14 Chrome) F.M.	95-125	15-35			
Type 303 (18-8) F.M.	55-75	10-20			
Other Materials					
Monel	65-85	15-25			
Nickel Silver	65-85	15-25			
Nickel Silver Lead	110-150	25-50			
Tool Steels	25-50	5-10			
Steel Tubing	95-125	20-40			
Cast Iron	100-130	20-40			

Grinding in the Lathe

When equipped with a good electric grinding attachment the lathe can be used for sharpening reamers and milling cutters, grinding hardened bushings and shafts and many other grinding operations.

The V-ways of the lathe bed should be covered with a heavy cloth or canvas to protect them from dust and grit from the grinding wheel, and the lathe spindle bearings should also be protected. A small pan of water or oil placed just below the grinding wheel will collect most of the grit.

A large, powerful grinder is most satisfactory for external grinding. The wheel should be at least four inches in diameter and the grinder should be mounted direct on the compound rest of the lathe, as shown in Fig. 1.

A small high speed grinder is best for internal grinding, as speed is more important than power for this class of work.

Grinding Wheel Speeds

The tabulation below shows grinding wheel speeds in revolutions per minute for surface speeds of 4000 and 5000 feet per minute.

Diam. Wheel	1 in.	2 in.	3 in.	4 in.	5 in.	6 in.	7 in.	8 in.	10 in.	12 in.
R.P.M. for surface Speed of 4,000 ft.....	15,279	7,639	5,093	3,820	3,056	2,546	2,183	1,910	1,529	1,273
R.P.M. for surface Speed of 5,000 ft.....	19,099	9,549	6,366	4,775	3,820	3,183	2,728	2,387	1,910	1,592

GRINDING WHEELS FOR VARIOUS KINDS OF WORK

Tabulation shows grade of Norton Grinding wheels.

Kind of Work	Rough Grind	Finish Grind
Cast Iron.....	3736-K Crystolon	3760-J Crystolon
Soft Steel.....	46-M5BE	60-M5BE
Hardened Steel.....	3846-L5BE	3860-L5BE
High Speed Steel.....	3846-K5BE	3860-K5BE
Brass or Bronze.....	3736-K Crystolon	3760-J Crystolon
General Work.....	46-N5BE	46-N5BE
Aluminum.....	30-M3L Shellac	36-M3L Shellac
Bakelite.....	3736-K Crystolon	3746-K Crystolon
Soft Rubber.....	3720-K5T-2 Crystolon Bakelite	3746-K5T-2 Crystolon Bakelite
Hard Rubber.....	3730-K5T-2 Crystolon Bakelite	3760-K5T-2 Crystolon Bakelite
Automobile Valves.....	1960-M	80-L6BE
Tungsten Carbide.....	3760/1-17 Crystolon	37100/2-H7 Crystolon




Fig. 1 External Grinding Attachment for the Lathe




Fig. 2. Internal Grinding Attachment for Lathe

Winding Coils in the Lathe

The unusually wide range of positive power longitudinal feeds available on the lathe make it an ideal machine for winding electrical coils of all kinds. A revolution counter may be attached to register the number of turns, as shown in Fig. 1. Special gearing may be obtained for odd leads not in the usual thread cutting range of the lathe. Any type of coil form or wire guide required may be used.




Fig. 1 Winding a Coil

Spring Winding

Coil springs of all kinds may be wound on the lathe, as shown in Fig. 2. Special mandrels are used for irregular shaped springs. The lead screw and half nuts of the lathe are usually used to obtain a uniform lead so that the coils are all equally spaced.




Fig. 2 Winding a Spring

Boring Work Mounted on Lathe Carriage

Large work may be mounted on the lathe carriage for boring, as shown in Fig. 5.

The boring bar is held between centers and driven by a lathe dog. The work is clamped to the top of the lathe saddle and is fed to the tool by the automatic longitudinal feed of the carriage.

Several good types of boring bars for this class of work are shown in Figs. 3, 4 and 6.



Fig. 3 Boring Bar with Fly Cutter




Fig. 4 Boring Bar with Boring Head




Fig. 5 Boring on the Lathe Carriage




Fig. 6 Boring Bar for Sizing the Hole

Filing and Polishing

All tool marks can be removed and a smooth, bright finish obtained on the surface of a piece of work by filing and polishing, as shown in Figs. 1 and 2

Use a fine mill file and file with the lathe running at a speed so that the work will make two or three revolutions for each stroke of the file. File just enough to obtain a smooth surface. If too much filing is done the work will be uneven and inaccurate.

Keep the left elbow high and the sleeves rolled up so there will be no danger from the lathe dog.

Keep the file clean and free from chips, using a file card frequently.

A very smooth, bright finish may be obtained by polishing with several grades of emery cloth after filing. Use oil on the emery cloth and run the lathe at high speed. Be careful not to let the emery cloth wrap around the revolving work.

Lapping

Hardened gauges, bushings and bearings are often finished in the lathe by lapping, as shown in Fig. 3

Emery cloth, emery dust and oil, diamond dust and other abrasives are used. Usually the lathe spindle is operated at high speed.

The lap may be very simple, consisting of a strip of emery cloth attached to a shaft, or it may be elaborately constructed of lead, copper, cast iron, etc. Some very fine and precise work may be accomplished by careful lapping.




Fig. 1. Filing to Remove Tool Marks




Fig. 2 Polishing with Emery Cloth and Oil




Fig. 3 Lapping the Inside of a Hardened Steel Bushing with Emery Dust and Oil





Fig. 4 A Cast Iron Lap for Emery Dust

Continued on next page

A good serviceable lap for general use is illustrated on this page. The construction of such a lap is simple. Turn the cast-iron piece all over to rough size—turn handle end to size—turn lap surface to standard size minus one thousandth of an inch or two thousandths if the holes you lap are apt to come that small. With work turning at a slow spindle speed, turn slight line in lap surface at very coarse lead about one inch per revolution. This feed can be done by hand as there is nothing particular about it. Make two such cuts, one right-hand lead, the other left hand. The purpose of these grooves is simply to act as grit and oil distributor troughs. They should be about $\frac{1}{64}$ " to $\frac{1}{32}$ " wide and $\frac{1}{64}$ " to $\frac{1}{32}$ " deep, depending on diameter of the lap. Cut with a sharp vee tool.



The lap surface is next split with a milling cutter within about $\frac{1}{4}$ " to $\frac{3}{8}$ " from the end of the lapped surface as shown above. It is then drilled and tapped at right angles to the split for the expansion screws. This slit through lap permits expansion by means of set screws in one-half acting on other half through the slot as shown.

The best grits to employ are Arkansas grit, of the correct grain for the work to be tapped, and Bon Ami cleaning powder. These grits are not as fast cutting as some but produce good accurate work with a high finish. The grit used is mixed with machine oil to a light paste consistency and applied to the lap evenly.

The lap is then pushed into the hole with a combination push and twist drill going in and pull and twist in opposite direction coming out. The lap is rotated slightly in the hole after every complete stroke to avoid lapping too much in a position which might keep the hole from being lapped cylindrically round.


Sufficient take-up should always be given to the adjusting screw to insure the lap fitting the hole snugly. If this is not done the hole may be lapped bell mouthed.

The above-mentioned grits and procedure may be used when lapping holes in steel, either hard or soft, cast iron and bronze, and are advantageous in that the work is not charged with the cutting grit as may occur when emery or carborundum is employed.

LATHE TOOL SHARPENING

The angle of the cutter bit with the bottom of the tool holder must be taken into consideration when grinding cutter bits.

The side clearance Fig. 1. is to permit the cutting edge to advance freely without the heel of the tool rubbing against the work.



Correct Side Clearance and Side Rake of Cutter Bit

The front clearance Fig. 2 is to permit the cutting edge to cut freely as the tool is fed to the work.

Too much clearance will weaken the cutting edge so that it will break; but insufficient clearance will prevent the tool from cutting.

Side rake and back rake (Figs. 1 and 2) also facilitate free cutting. For cast iron, hard bronze and hard steel, very little side rake or back rake are required.






Fig. 2. Correct Front Clearance and Back Rake of Cutter Bit



Set of Ground Cutter Bits

The angle of keenness Fig. 1 may vary from 60° for soft steel to nearly 90° for cast iron, hard steel, bronze, etc.

Figs. 3 to 4 inclusive, show the various steps in grinding a cutter bit for general machine work. Honing the cutting edge (Fig. 8) will improve the quality of the finish and lengthen the life of the tool.




Fig. 3. Grinding Left Side of Cutter Bit

Fig. 4. Grinding Right Side of Cutter Bit




Fig. 5. Grinding Front of Cutter Bit

Fig. 6. Rounding End of Cutter Bit




Fig. 7. Grinding Side Rake and Back Rake

Fig. 8. Honing the Cutting Edge of Cutter Bit with an Oil Stone



Unground Cutter Bit

LATHE TOOLS




Fig. 1




Fig. 2






Fig. 3



Each lathe should be equipped with a complete set of lathe tools for turning, facing, threading and boring. They can be either of the forged type (1), or of the tool holder type using high-speed steel bits, such as are made by Williams, Armstrong (2) or O. K. (3). The tool holder type is the most commonly used because it is more convenient. No forging or dressing is necessary with this type.

A complete set of tools consists of the following:

Straight shank turning tool (4), which can be used with various types of tool bits for right and left-hand turning, right and left-hand facing, and threading. Bits can also be ground to special shapes for fillets in corners, etc.




Fig. 4

Left-hand offset turning tools (5) are desirable when the operator wishes to work close to the chuck or the driving dog. By using this type of tool it is possible to turn the




Fig. 5




Fig. 6



Fig. 7

For turning brass, there should be no top rake (6) and the cutting edge of the tool should be about horizontal. For turning soft copper, babbitt, and some die casting alloys, a negative rake (7) is often used.

Continued on next page

piece up to the chuck and at the same time have the chuck clear the side of the carriage and compound rest.




Fig. 8

Right-hand offset turning tools (8) answer the same purpose when working at the tailstock end. Various shaped bits can be used in either right or left-hand turning tool holders to suit the work being done.




Fig. 9

Straight cutting-off tools (9) are used for cutting off in the lathe. The blade used in this tool is ground with the proper side clearance. Then, when properly set in the holder, the tool does not drag.




Fig. 10

The right-hand cutting-off tool (10) is used for cutting off work close to the chuck. To prevent chatter, when using a tool of this type, excessive overhang of the work should be avoided.

The left-hand cutting-off tool (11) is for use near the tailstock end of the lathe. This type of tool is rarely used and in most cases the right-hand cutting-off tool serves all purposes.




Fig. 11

Steel finishing side tools are ground with a 10° to 12° side clearance, about 10° to 15° side rake, no top rake, and about 8° front clearance.

Cast iron, brass, etc., the same clearance except no side rake is used on tool.




Fig. 12

Threading or chasing tools

(12). There are many patented types of threading tools. The tool shown is provided with a formed cutter, and is ground on the top to maintain the correct thread

form. On some classes of material where it is not possible to cut a smooth thread with a rigid chasing tool, a spring threading tool (13) will produce better results.




Fig. 13

The spring threading tool is built with a nut for the lockable spring head which provides rigid backing for coarse threads and heavy cuts, and when loosened, the holder becomes a spring tool for finishing work. Neither of these tools is

absolutely essential as most threads can be cut by grinding a tool bit to the proper shape, with the use of a thread gauge. The bit is held in a turning tool holder.




Fig. 14

Boring bars and holders.

Tools of the type shown are used for boring holes and chasing internal threads. Two basic types of boring bars are used, namely, the forged type and the bar and holder type. Three of the bar and holder types are




Fig. 15

shown in the accompanying illustrations.

No. 14 is used for small holes, which in addition to holding bars with bits as shown, can be used to hold boring tools made of drill rod for

very small holes, and also for holding drills for drilling. The boring bar shown in illustration (15) is used for medium size holes and is adjustable for different depths of holes. It is held in the regular tool post by a shank, the same as the turning tool.

A tool properly ground should have the point set on the center line of the work. Some operators make a practice of setting the tool above the center line, about $\frac{1}{4}$ of an inch for each 1" clearance in diameter. This, however, necessitates changing the clearance and rake angles of the tool and for this reason we do not recommend it for the student or beginner.

Figure (16) shows a boring bar for heavy work that is held in the compound rest T-slot. This makes the bar more rigid than when held in the tool post. Various shaped tool bits for boring, facing, counterboring and threading holes can be used in the different bars.




Fig. 16.





Fig. 17

Knurling tool (17). On some classes of work such as thumb screws, it is necessary to roughen the diameter to give a better grip and prevent oily fingers from slipping. This is called knurling and is used extensively on optical, radio and other electrical work.

A tool holder carrying two knurled wheels is fed into the work while it is revolving and impresses a pattern on the work. Wheels of different patterns can be obtained for the knurling tool holder.

Nomenclature of Lathe Tools



On work to be finish ground, make the finish turned diameter 15 thousandths over actual finish ground diameter.

On work to be file finished and polished, leave 2 to 3 thousandths of an inch over finish size to provide stock to file and remove slight tool marks and give polish finish.

ENGINEERING INFORMATION COVERING THE DESIGN AND APPLICATION OF SPUR GEARS

To Say 3 P. or 3 Pitch Means 3 Diametral Pitch
 To Say 3" P. or 3 inch Pitch Means 3 inch Circular Pitch

The word "*diameter*" when applied to gears is always understood to mean the pitch diameter.


Diametral pitch of the gear is the number of teeth to each inch of its pitch diameter.

Circular pitch is the distance from the center of one tooth to the center of the next tooth, measured along the pitch circle.

Addendum is the distance measured from pitch circle to the outside or circumference of the gear.

Dedendum is the distance measured from the pitch circle to the bottom of the tooth.

Clearance is equivalent to 1.57 divided by the diametral pitch, or about $\frac{1}{16}$ of the depth of tooth.



RULES AND FORMULAE FOR INTERNAL SPUR GEARS

(Where rules and formulas are not given, they are the same as for external gears)

To Find	Rule	Formula
Center Distance	Subtract the number of teeth in the pinion from the number of teeth in the gear and divide the remainder by 2 times the diametral pitch.	$C = \frac{N_g - N_p}{2P}$
Center Distance	Multiply the difference of the numbers of teeth in the gear and pinion by the circular pitch and divide the product by 6.2832.	$C = \frac{(N_g - N_p) P'}{6.2832}$

(Continued on top of next page.)

Inside Diameter	Subtract 2 from the number of teeth and divide the remainder by the diametral pitch.	$I = \frac{N-2}{P}$
Inside Diameter	Subtract 2 from the number of teeth, multiply the remainder by the circular pitch, and divide the product by 3.1416.	$I = \frac{(N-2) P'}{3.1416}$
Pitch Diameter	Add twice the addendum to the inside diameter.	$D = I + 2S$
Inside Diameter	Subtract twice the addendum from the pitch diameter.	$I = D - 2S$

RULES AND FORMULAE FOR DIMENSIONS OF SPUR GEARS

No. of Rule	To Find	Rule	Formula
1	Diametral Pitch	Divide 3.1416 by circular pitch.	$P = \frac{3.1416}{P'}$
2	Circular Pitch	Divide 3.1416 by diametral pitch.	$P' = \frac{3.1416}{P}$
3	Pitch Diameter	Divide number of teeth by diametral pitch.	$D = \frac{N}{P}$
4	Pitch Diameter	Multiply number of teeth by circular pitch and divide the product by 3.1416.	$D = \frac{NP'}{3.1416}$
5	Center Distance	Add the number of teeth in both gears and divide the sum by two times the diametral pitch.	$C = \frac{N_g + N_p}{2P}$
6	Center Distance	Multiply the sum of the number of teeth in both gears by circular pitch and divide the product by 6.2832.	$C = \frac{(N_g + N_p)P'}{6.2832}$
7	Addendum	Divide I by diametral pitch.	$S = \frac{I}{P}$
8	Addendum	Divide circular pitch by 3.1416.	$S = \frac{P'}{3.1416}$
9	Clearance	Divide 0.157 by diametral pitch.	$F = \frac{0.157}{P}$
10	Clearance	Divide circular pitch by 20.	$F = \frac{P'}{20}$
11	Whole Depth of Tooth	Divide 2.157 by diametral pitch.	$W = \frac{2.157}{P}$
12	Whole Depth of Tooth	Multiply 0.6866 by circular pitch.	$W = 0.6866 P'$
13	Thickness of Tooth	Divide 1.5708 by diametral pitch.	$T = \frac{1.5708}{P}$
14	Thickness of Tooth	Divide circular pitch by 2.	$T = \frac{P'}{2}$
15	Outside Diameter	Add 2 to the number of teeth and divide the sum by diametral pitch.	$O = \frac{N+2}{P}$
16	Outside Diameter	Multiply the sum of the number of teeth plus 2 by circular pitch and divide the product by 3.1416.	$O = \frac{(N+2) P'}{3.1416}$
17	Diametral Pitch	Divide number of teeth by pitch diameter.	$P = \frac{N}{D}$
18	Circular Pitch	Multiply pitch diameter by 3.1416 and divide by number of teeth.	$P' = \frac{3.1416 D}{N}$
19	Pitch Diameter	Subtract two times the addendum from outside diameter.	$D = O - 2S$
20	Number of Teeth	Multiply pitch diameter by diametral pitch.	$N = P \times D$
21	Number of Teeth	Multiply pitch diameter by 3.1416 and divide the product by circular pitch.	$N = \frac{3.1416 D}{P'}$
22	Outside Diameter	Add two times the addendum to the pitch diameter.	$O = D + 2S$
23	Length of Rack	Multiply number of teeth in rack by 3.1416 and divide by diametral pitch.	$L = \frac{3.1416 N}{P}$
24	Length of Rack	Multiply the number of teeth in the rack by circular pitch.	$L = NP'$

BEVEL GEARS

The curve of teeth in bevel gears, when correctly formed, changes constantly from one end of the tooth to the other. Therefore bevel gears, whose teeth are produced with a cutter of fixed curve, are not theoretically correct, the cutter usually being of a curve that will make the correct form at the outer part of the face of the gear, and of necessity will leave the curves too large at the inside ends of the teeth.




Small bevel gearing is almost universally produced in this manner, which practically answers the purpose, except when the teeth are very coarse or the gears very small, in which cases their operation is not satisfactory.

In place of cutting by changing position of cutter, etc., the teeth are often filed slightly, in order to round them off to the curve required for their free running.


On all bevel gears cut with a cutter of fixed curve, it is necessary to cut through twice owing to the necessity of making the thickness of the cutter on the pitch line equal to about .005" thinner than the space between the teeth at the smallest pitch diameter. As the width of space between the teeth on the largest pitch diameter should be greater than the thickness of the cutter, it must be made so by passing the cutter through a second time.

The cuts on this page will explain the forms of spur, bevel and mitre gears, also the terms "pitch diameter," "outside diameter," "largest pitch diameter," "length of face," etc


When a pair of bevel gears are of same size and number of teeth, with their lines of centres at right angles, they are called "mitre gears," and one cutter will answer for both; but where one gear has a greater number of teeth, or differs in bevel from the one running into it, then each of the pair of gears may require a different cutter.



RULES AND FORMULAS FOR CALCULATING BEVEL GEARS WITH SHAFTS AT RIGHT ANGLES



α_p = Pitch cone angle of pinion;
 α = Pitch cone angle of gear;
 N_p = Number of teeth in pinion, etc.



No.	To Find	Rule	Formula
1	Pitch Cone Angle (or Edge Angle) of Pinion.	Divide the number of teeth in the pinion by the number of teeth in the gear to get the tangent.	$\tan \alpha_p = \frac{N_g}{N_p}$
2	Pitch Cone Angle (or Edge Angle) of Gear.	Divide the number of teeth in the gear by the number of teeth in the pinion to get the tangent.	$\tan \alpha_g = \frac{N_p}{N_g}$
3	Proof of Calculations for Pitch Cone Angles	The sum of the pitch cone angles of the pinion and gear equals 90 degrees.	$\alpha_p + \alpha_g = 90^\circ$
4	Pitch Diameter.	Divide the number of teeth by the diametral pitch; or multiply the number of teeth by the circular pitch and divide by 3.1416.	$D = \frac{N}{P} = \frac{NP'}{\pi}$
5	Addendum.	Divide 1.0 by the diametral pitch; or multiply the circular pitch by 0.318.	$S = \frac{1.0}{P} = 0.318 P'$
6	Dedendum.	Divide 1.157 by the diametral pitch; or multiply the circular pitch by 0.368.	$S + A = \frac{1.157}{P} = 0.368 P'$
7	Whole Depth of Tooth Space.	Divide 2.157 by the diametral pitch; or multiply the circular pitch by 0.687.	$W = \frac{2.157}{P} = 0.687 P'$
8	Thickness of Tooth at Pitch Line.	Divide 1.571 by the diametral pitch; or divide the circular pitch by 2.	$T = \frac{1.571}{P} = \frac{P'}{2}$
9	Pitch Cone Radius.	Divide the pitch diameter by twice the sine of the pitch cone angle.	$C = \frac{D}{2 \times \sin \alpha}$
10	Addendum of Small End of Tooth.	Subtract the width of face from the pitch cone radius, divide the remainder by the pitch cone radius and multiply by the addendum.	$s = S \times \frac{C - F}{C}$
11	Thickness of Tooth at Pitch Line at Small End.	Subtract the width of face from the pitch cone radius, divide the remainder by the pitch cone radius and multiply by the thickness of the tooth at the pitch line.	$t = T \times \frac{C - F}{C}$
12	Addendum Angle.	Divide the addendum by the pitch cone radius to get the tangent.	$\tan \theta = \frac{S}{C}$
13	Dedendum Angle.	Divide the dedendum by the pitch cone radius to get the tangent.	$\tan \Phi = \frac{S + A}{C}$
14	Face Angle.	Subtract the sum of the pitch cone and addendum angles from 90 degrees.	$\phi = 90^\circ - (\alpha + \theta)$
15	Cutting Angle.	Subtract the dedendum angle from the pitch cone angle.	$\zeta = \alpha - \Phi$
16	Angular Addendum.	Multiply the addendum by the cosine of the pitch cone angle.	$K = S \times \cos \alpha$
17	Outside Diameter.	Add twice the angular addendum to the pitch diameter.	$O = D + K$
18	Apex Distance.	Multiply one-half the outside diameter by the tangent of the face angle.	$J = \frac{O}{2} \times \tan \phi$

(Continued on top of next page)

- | | | | |
|----|---|---|---|
| 19 | Apex Distance at Small End of Tooth. | Subtract the width of face from the pitch cone radius; divide the remainder by the pitch cone radius and multiply by the apex distance. | $j = J \times \frac{C - F}{C}$ |
| 20 | Number of Teeth for which to Select Cutter. | Divide the number of teeth by the cosine of the pitch cone angle. | $N' = \frac{N}{\cos a}$ |
| 21 | Proof of Calculations by Rules Nos. 9, 12, 14, 16 and 17. | The outside diameter equals twice the pitch cone radius multiplied by the cosine of the face angle and divided by the cosine of the addendum angle. | $O = \frac{2C \times \cos \phi}{\cos \theta}$ |

RECOMMENDED PRACTICE FOR BEVEL GEARING

The American Gear Manufacturers Assn. has adopted as recommended practice the following rules:

The maximum length of face of bevel gears should not be over $\frac{1}{3}$ of the cone distance for gears up to 3 in. pitch diameter and not over $\frac{1}{4}$ of the cone distance for gears from 3 to 20 inch pitch diameter, assuming that the pitch in every case will be in proper proportion to the size of the gears. A safe rule is to make the face from $1\frac{1}{2}$ to $2\frac{1}{2}$ times the circular pitch.

The minimum length of bearing along the face is to be at least $\frac{1}{2}$ the length of the face when the gears are held in correct alignment.

Bevel gears with generated involute teeth of standard addendum having a pressure angle of $14\frac{1}{2}^\circ$ may be used according to the following rule:

RATIO	No. OF TEETH
1 to 1	14 and over
$1\frac{1}{2}$ to 1	18 and over
2 to 1	19 and over
3 to 1 and over	21 and over

This rule is given applying mainly to gears up to 20 inches pitch diameter and to average industrial machine design as distinguished from automobiles.

RECOMMENDED PRACTICE FOR BACKING DIMENSIONS OF BEVEL AND MITRE GEARS

The following formulae are recommended for the calculation of backing dimensions of Bevel and Mitre Gears.

BEVEL GEARS AND PINIONS

Backing in inches of Pinion = Pitch diameter of gear $\times .250$
(Ratio of Gear to Pinion) + 1

Backing in inches of Gear = (Pitch diameter of gear $\times .250$) — Backing of Pinion

MITRE GEARS

Backing in inches of Gear = Pitch diameter $\times .125$

This does not allow for set screws in pinions below 4 inches Pitch Diameter.

RULES FOR CALCULATING SPIRAL GEARS

The following rules are used for calculating the dimensions of spiral or helical gears:

Rule 1. The sum of the tooth angles of a pair of mating helical gears is equal to the shaft angle.

Rule 2. To find the pitch diameter of a helical gear, divide the number of teeth by the product of the normal pitch and the cosine of the tooth angle.

Rule 3. To find the center distance, add together the pitch diameters of the two gears and divide by 2. This rule is evidently the same as for spur gears.

Rule 4. To prove the calculations for pitch diameters and center distance, multiply the number of teeth in the first gear by the tangent of the tooth angle of that gear, and add the number of teeth in the second gear to the product; the sum should equal twice the product of the center distance multiplied by the normal diametral pitch, multiplied by the sine of the tooth angle of the first gear.

Rule 5. To find the number of teeth for which to select the cutter, divide the number of teeth in the gear by the cube of the cosine of the tooth angle.

Rule 6. To find the lead of the tooth helix, multiply the pitch diameter by 3.1416 times the cotangent of the tooth angle. The rules relating to the addendum and the whole depth of tooth are the same as for spur gears.


Rule 7. To find the addendum, divide 1 by the normal diametral pitch.

Rule 8. To find the whole depth of tooth space, divide 2.157 by the normal diametral pitch.

Rule 9. To find the normal tooth thickness at the pitch line, divide 1.571 by the normal diametral pitch.


Rule 10. To find the outside diameter, add twice the addendum to the pitch diameter.

Rule 11. To find the equivalent diameter of a helical gear, divide the number of teeth of the gear by the diametral pitch of the cutter by which it is cut.




Rules for Figuring Bevel Gears

To Find	Rule
Pitch Diameter	$\frac{\text{Number of teeth}}{\text{Diametral Pitch}} \text{ or } \text{No. of teeth} \times \text{circular pitch}$ $\frac{3.1416}{\text{or, No. of teeth} \times \text{circ. pitch} \times .3183''}$
Pitch Depth	$\frac{1}{\text{Diametral Pitch}} \text{ or } \text{Circular Pitch} \times .3183''$
Full Depth	$\text{Pitch Depth} \times 2 + \text{Circular pitch} \times .05$ <p>(Standard) (Special)</p>
Ratio	$\frac{\text{Number of teeth in Gear}}{\text{Number of teeth in Pinion}}$
Diameter Increment	$(\text{Pitch Depth} \times 2) \times \text{cosine of Pitch Angle.}$
Outside Diameter	$\text{Pitch Diameter} + \text{Diameter Increment}$
Tangent Pitch Angle Gear	$\frac{\text{Number of teeth in Gear}}{\text{Number of teeth in Pinion}}$
Tangent Pitch Angle Pinion	$\frac{\text{Number of teeth in Pinion}}{\text{Number of teeth in Gear}}$
Cone distance at Pitch Line	$\frac{\text{Pitch Radius of Gear}}{\text{Sine of Pitch Angle of Gear}}$
Back Cone distance	$\text{Cone distance} \times \text{tangent Pitch Angle}$
Tangent of Addendum Angle	$\frac{\text{Pitch Depth}}{\text{Cone Distance}}$
Tangent of Block or Dedendum Angle.	$\frac{\text{Flank Depth}}{\text{Cone Distance}}$
Face Angle	$\text{Pitch Angle} + \text{Addendum Angle}$
Root Angle	$\text{Pitch Angle} - \text{Dedendum Angle}$
Distance from Crown to Pitch Line	$\text{Pitch Depth} \times \text{Sine Pitch Angle}$
Pitch at Inside	$\text{Pitch at outside is to Pitch at inside as Cone distance is to (Cone distance) - face}$
Tooth Angle Tangent	$(\frac{1}{2} \text{ thickness of tooth at Pitch Line} + \text{flank depth} \times \text{tangent pressure angle})$ cone distance



Work Mounted in Chuck and Center Rest




Work Mounted on Center and in Center Rest

FACTORS FOR CALCULATING STRENGTH OF BEVEL GEARS

These Y Factors are for Diametral Pitch. To obtain Circular Pitch Y Factors divide by 3.1416.

Table of Outline Factors (Y) for 14½° and 20° Involute					
N'	Outline Factor = Y		N'	Outline Factor = Y	
	14½° Involute (Std.)	20° Involute		14½° Involute (Std.)	20° Involute
12	0.210	0.245	27	0.314	0.349
13	0.220	0.261	30	0.320	0.358
14	0.226	0.276	34	0.327	0.371
15	0.236	0.289	38	0.336	0.383
16	0.242	0.295	43	0.346	0.396
17	0.251	0.302	50	0.352	0.408
18	0.261	0.308	60	0.358	0.421
19	0.273	0.314	75	0.364	0.434
20	0.283	0.320	100	0.371	0.446
21	0.289	0.327	150	0.377	0.459
23	0.295	0.333	300	0.383	0.471
25	0.305	0.339	Rack	0.390	0.484



$$N' = \frac{\text{Number of teeth}}{\cos \alpha}$$

END THRUST ON BEVEL GEARS

In designing bearings to be used with bevel and mitre gears it is important to know the end thrust exerted by the bevel gears and pinions so that proper end thrust bearings may be provided.

The method of calculation of end thrusts is as follows:

A = Pressure angle of the gear teeth

P = Tooth Pressure at middle of tooth face

F = Separating Force = $P \times \tan A$

B = Pitch angle of Pinion

T = Thrust on pinion = $P \times \tan A \times \sin B$

T₁ = Thrust on gear = $P \times \tan A \times \cos B$

The following table gives the factors by which the tooth pressure is multiplied to find the thrust which give practically the same values found by solving the formulae for T & T₁ given above.

Gear Ratio	PRESSURE ANGLE A							
	14½°		15°		20°		22°	
	Gear	Pinion	Gear	Pinion	Gear	Pinion	Gear	Pinion
1 -1	.183	.183	.189	.189	.257	.257	.286	.286
1½ -1	.215	.143	.223	.148	.303	.202	.336	.224
2 -1	.232	.116	.239	.120	.325	.163	.361	.181
2½ -1	.240	.096	.249	.100	.338	.135	.375	.150
3 -1	.246	.082	.254	.085	.345	.115	.383	.128
3½ -1	.249	.071	.258	.074	.350	.100	.389	.111
3¾ -1	.250	.067	.259	.069	.352	.094	.390	.104
4 -1	.251	.062	.260	.065	.353	.088	.392	.097
4½ -1	.253	.056	.262	.058	.355	.079	.394	.087
5 -1	.254	.051	.263	.053	.357	.072	.396	.080
5½ -1	.255	.046	.264	.048	.358	.065	.398	.072


Fitting a Chuck Plate to a Chuck

Before a chuck can be used on a lathe it must be fitted with a chuck plate that has been threaded to fit the spindle nose of the lathe. Semi-machined chuck plates that have been accurately threaded to fit the lathe spindle can be obtained from the lathe manufacturer.

APPROXIMATE WEIGHTS OF CAST IRON GEARS

Diam. Inches	Pitch In.		3%		1 1/2%		1%		1 1/4%		1 1/2%		1 3/4%		2%		2 1/4%		2 1/2%		2 3/4%		3%	
	Face	In.	1 1/8%	1 1/4%	1 1/2%	1 3/4%	2%	2 1/4%	2 1/2%	2 3/4%	3%	3 1/4%	3 1/2%	3 3/4%	4%	4 1/4%	4 1/2%	4 3/4%	5%	5 1/4%	5 1/2%	5 3/4%	6%	6 1/4%
6	5	6	11	13	15	18	21	24	27	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378
8	6	8	13	15	18	21	24	27	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432
10	8	11	16	18	21	24	27	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498
12	10	12	18	21	24	27	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498	576
15	12	15	21	24	27	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498	576	672
18	15	18	24	27	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498	576	672	784
21	18	21	27	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498	576	672	784	912
24	21	24	30	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498	576	672	784	912	1056
27	24	27	33	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498	576	672	784	912	1056	1224
30	27	30	36	40	48	64	86	109	134	164	200	238	282	324	378	432	498	576	672	784	912	1056	1224	1408
33	30	33	39	42	45	48	51	54	57	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102
36	33	36	42	45	48	51	54	57	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105
39	36	39	45	48	51	54	57	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108
42	39	42	48	51	54	57	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108	111
45	42	45	51	54	57	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108	111	114
48	45	48	54	57	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108	111	114	117
51	48	51	57	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108	111	114	117	120
54	51	54	60	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108	111	114	117	120	123
57	54	57	63	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108	111	114	117	120	123	126
60	57	60	66	69	72	75	78	81	84	87	90	93	96	99	102	105	108	111	114	117	120	123	126	129
66	63	66	72	75	78	81	84	87	90	93	96	99	102	105	108	111	114	117	120	123	126	129	132	135
72	69	72	78	81	84	87	90	93	96	99	102	105	108	111	114	117	120	123	126	129	132	135	138	141
78	75	78	84	87	90	93	96	99	102	105	108	111	114	117	120	123	126	129	132	135	138	141	144	147
84	81	84	90	93	96	99	102	105	108	111	114	117	120	123	126	129	132	135	138	141	144	147	150	153
90	87	90	96	99	102	105	108	111	114	117	120	123	126	129	132	135	138	141	144	147	150	153	156	159
96	93	96	102	105	108	111	114	117	120	123	126	129	132	135	138	141	144	147	150	153	156	159	162	165
102	99	102	108	111	114	117	120	123	126	129	132	135	138	141	144	147	150	153	156	159	162	165	168	171
108	105	108	112	115	118	121	124	127	130	133	136	139	142	145	148	151	154	157	160	163	166	169	172	175
114	111	114	118	121	124	127	130	133	136	139	142	145	148	151	154	157	160	163	166	169	172	175	178	181

NOTE—The above are safe weights for estimating Spur Gears. These weights will vary according to bores, hubs, etc. Bevel Gears will average from ten to twenty per cent less in weight than Spur Gears. This table is published simply as a help in estimating freight costs and for engineers in figuring supports, etc.



If hole is to be just a rough job both as to size and straightness, use large drill $\frac{1}{64}$ " or $\frac{1}{32}$ " smaller than finish size, and run through piece. Drill is held in taper hole in tailstock spindle if taper shank drill is used, or in drill chuck mounted in tailstock spindle if straight shank drill is used.

THE SIZING AND CUTTING OF GEARS

Diameter, when applied to gears, is always understood to mean the pitch diameter.
Diametral Pitch is the number of teeth to each inch of the pitch diameter.

Example. If a gear has 40 teeth and the pitch diameter is 4 inches, there are 10 teeth to each inch of the pitch diameter and the diametral pitch is 10, or, in other words, the gear is 10 diametral pitch.

Diametral Pitch required, circular pitch given. Divide 3.1416 by the circular pitch.

Example. If the circular pitch is 2 inches, divide 3.1416 by 2 and the quotient, 1.5708, is the diametral pitch.

Diametral Pitch required, number of teeth and outside diameter given. Add 2 to the number of teeth and divide by the outside diameter.

Example. If the number of teeth is 40, the diameter of the blank is $10\frac{1}{2}$ inches; add 2 to the number of teeth, making 42, and divide by $10\frac{1}{2}$; the quotient, 4, is the diametral pitch.

Circular Pitch is the distance from the center of one tooth to the center of the next measured along the pitch circle.

Example. If the distance from the center of one tooth to the center of next tooth, measured along the pitch circle, is $\frac{1}{2}$ inch, the gear is $\frac{1}{2}$ inch circular pitch.

Circular Pitch required, diametral pitch given. Divide 3.1416 by the diametral pitch.

Example. If the diametral pitch is 4, divide 3.1416 by 4, and the quotient, .7854 inch, is the circular pitch.

Number of Teeth required, pitch diameter and diametral pitch given. Multiply the pitch diameter by the diametral pitch.

Example. If the diameter of the pitch circle is 10 inches and the diametral pitch is 4, multiply 10 by 4, and the product, 40, will be the number of teeth in the gear.

Number of Teeth required, outside diameter and diametral pitch given. Multiply the outside diameter by the diametral pitch and subtract 2.

Example. If the whole diameter is $10\frac{1}{2}$ inches and the diametral pitch is 4, multiply $10\frac{1}{2}$ by 4, and the product, 42, less 2, or 40, is the number of teeth.

Pitch Diameter required, number of teeth and diametral pitch given. Divide the number of teeth by the diametral pitch.

Example. If the number of teeth is 40 and the diametral pitch is 4, divide 40 by 4, and the quotient, 10, expressed in inches, is the pitch diameter.

Outside Diameter or size of gear blank required, number of teeth and diametral pitch given. Add 2 to the number of teeth and divide by the diametral pitch.

Example. If the number of teeth is 40 and the diametral pitch is 4, add 2 to the 40, making 42, and divide by 4; the quotient, $10\frac{1}{2}$, is the whole diameter of the gear or blank.

Thickness of Tooth at Pitch Line required. Divide the circular pitch by 2, or 1.57 by the diametral pitch.

Example. If the circular pitch is 1.047 inches, or the diametral pitch is 3, divide 1.047 by 2, or 1.57 by 3, and the quotient, .523 inch, is the thickness of tooth.

Whole Depth of Tooth required. Divide 2.157 by the diametral pitch.

Example. If the diametral pitch of a gear is 6, the whole depth is 2.157 divided by 6, which equals .3595.

Whole Depth of Tooth is about $\frac{1}{2}$ or exactly .6866 of the circular pitch.

Example. If the circular pitch is 2 inches, the whole depth of tooth is .6866 X 2 inches, or $1\frac{3}{8}$ inches nearly.


Distance between Centers of two gears required. Add the number of teeth together and divide one half the sum by the diametral pitch.

Example. If two gears have 50 and 30 teeth, respectively, and are 5 pitch, add 50 and 30, making 80, divide by 2, and then divide the quotient, 40, by the diametral pitch, 5, and the result, 8 inches, is the center distance.

INSTRUCTIONS ON SPIRAL GEARS

The art of designing helical or "spiral" gears opens with an apology. The subject is one which, from its very nature, can be approached by any one of a number of different ways. It has been approached by so many of these possible different ways that perhaps the subject has become quite confused in the minds of many technical readers.

We show on page 52 the drawing with illustrating terms used in calculations of spiral gear. The normal diametral pitch, or diametral pitch of the cutter used, is reckoned from measurements taken along the pitch cylinder at right angles to the length of the tooth. P' represents the regular circular pitch, while P'n represents the normal circular pitch. The diametral pitch may be found from this by dividing 3.1416 by



P'n. This is the pitch of the cutter to be used. The cutter cannot be selected for the actual number of teeth in the gear, but must take into account the helix angle of the teeth as well, since the curvature as measured on a line at right angles to the helix is at a greater radius than when measured on the circle. The length of the helix, or the lead, as shown in the above drawing, is the length of pitch cylinder required to permit one complete revolution of the tooth if the latter were carried around for the full length of this cylinder. The addendum S and whole depth W of the tooth for helical gears is the same as for plain spur gears.

The normal thickness of tooth at the pitch line, Tn, as shown in the above drawing, is measured in a direction perpendicular to the face of the tooth. The regular tooth thickness is shown at T, but with this we are not concerned. The outside diameter, as for spur gears, is found by adding twice the addendum to the pitch diameter.

CIRCULAR PITCH FORMULAS

Circular Pitch is the Distance from Centre of One Tooth to Centre of the Next Tooth, Measured along the Pitch Circle.

To Obtain	Having	Rule
Circular Pitch	Diametral Pitch.	Divide 3.1416 by the Diametral Pitch.
Circular Pitch	Pitch Diameter and the Number of Teeth.	Divide Pitch Diameter by the product of .3183 and Number of Teeth.
Circular Pitch	Outside Diameter and the Number of Teeth.	Divide Outside Diameter by the product of .3183 and Number of Teeth plus 2.
Pitch Diameter	Number of Teeth and the Circular Pitch.	The continued product of the Number of Teeth, the Circular Pitch and .3183.
Pitch Diameter	Number of Teeth and the Outside Diameter.	Divide the product of Number of Teeth and Outside Diameter by Number of Teeth plus 2.
Pitch Diameter	Outside Diameter and the Circular Pitch.	Subtract from the Outside Diameter the product of the Circular Pitch and .6366.
Outside Diameter	Number of Teeth and the Circular Pitch.	The continued product of the Number of Teeth plus 2, the Circular Pitch and .3183.
Outside Diameter	Pitch Diameter and the Circular Pitch.	Add to the Pitch Diameter the product of the Circular Pitch and .6366.
Outside Diameter	Number of Teeth and the Addendum.	Multiply Addendum by Number of Teeth plus 2.
Number of Teeth	Pitch Diameter and the Circular Pitch.	Divide the product of Pitch Diameter and 3.1416 by the Circular Pitch.
Thickness of Tooth	Circular Pitch.	One half the Circular Pitch.
Addendum	Circular Pitch.	Multiply the Circular Pitch by .3183, or $s = \frac{D'}{N}$.
Whole Depth	Circular Pitch.	Multiply the Circular Pitch by .6866.
Clearance	Circular Pitch.	Multiply the Circular Pitch by .05.

DIAMETRAL PITCH FORMULAS


Diametral Pitch is the Number of Teeth to Each Inch of the Pitch Diameter

To Obtain	Having	Rule
Diametral Pitch	Circular Pitch.	Divide 3.1416 by the Circular Pitch.
Diametral Pitch	Pitch Diameter and the Number of Teeth.	Divide Number of Teeth by Pitch Diameter.
Diametral Pitch	Outside Diameter and the Number of Teeth.	Divide Number of Teeth plus 2 by Outside Diameter.
Pitch Diameter	Number of Teeth and the D.P.	Divide Number of Teeth by the Diametral Pitch.
Pitch Diameter	Number of Teeth and Outside Diameter.	Divide the product of Outside Diameter and Number of Teeth plus 2.
Pitch Diameter	Outside Diameter and the Diametral Pitch.	Subtract from the Outside Diameter the quotient of 2 divided by the Diametral Pitch.
Outside Diameter	Number of Teeth and the D.P.	Divide Number of Teeth plus 2 by the D.P.
Outside Diameter	Pitch Diameter and the Diametral Pitch.	Add to the Pitch Diameter the quotient of 2 divided by the Diametral Pitch.
Outside Diameter	Pitch Diameter and the Number of Teeth.	Divide the Number of Teeth plus 2 by the quotient of Number of Teeth divided by the Pitch Diameter.
Number of Teeth	Pitch Diameter and the D.P.	Multiply Pitch Diameter by the Diametral Pitch.
Number of Teeth	Outside Diameter and the Diametral Pitch.	Multiply Outside Diameter by the Diametral Pitch and subtract 2.
Thickness of Tooth	Diametral Pitch.	Divide 1.5708 by the D.P.
Addendum	Diametral Pitch.	Divide 1 by the D.P.
Whole Depth (B&S)	Diametral Pitch.	Divide 2.157 by the Diametral Pitch.
Whole Depth (Fellows)	Diametral Pitch.	Up to 16 D.P. inc. = $\frac{2.25}{D.P.}$ 17 to 32 D.P. inc. = $\frac{2}{D.P.} + .015$ 33 to 40 D.P. inc. = $\frac{2}{D.P.} + .010$
Clearance (B&S)	Diametral Pitch.	Divide .157 by the D.P.
Clearance (Fellows)	Diametral Pitch.	Up to 16 D.P. inc. = $\frac{.250}{D.P.}$ 17 to 32 D.P. inc. = .015 33 to 40 D.P. inc. = .010

Cutting Gears on the Lathe

Gear Cutting Attachment

The gear cutting attachment for the lathe, shown in Fig. 1, will cut spur and bevel gears of all kinds. It will do graduating and milling, external key seating, cutting at angles, splining, slotting and all regular dividing head milling work.

**SPIRAL GEAR CUTTING**

Spiral gears may have their axes parallel, the same as spur gears, or the axes may be at an angle with each other. A spiral gear differs from a spur gear in that the teeth are not placed parallel with the axis, but are wound spirally around the pitch circle. The name "spiral gears" is really wrong. The teeth are not wound in a SPIRAL, but in a HELIX around the pitch circle. The distinction between a spiral and a helix will be clear when we remember that the main spring of a watch is a good example of a spiral, while the threads on a lead screw form a helix. However, in our discussion, we will use the name "spiral gears," as this is the name by which the average mechanic knows them. This chapter will not treat of all the properties of spiral gears, but only of such as need be known in order to design or make them.

If we have two shafts with a center distance of $7\frac{1}{4}"$, and we must drive one shaft from the other with a given speed ratio, we will find considerable trouble if we try to use spur gears. If, for instance, the speed ratio is 4 to 5, we will not be able to use spur gears except by making them 18 pitch. The sum of the diameters is $14\frac{1}{2}"$, being twice the center distance, and we must select the pitch so that the sum of the numbers of teeth of the two gears can be split up into two numbers which have a ratio of 4 and 5. If we should select 4 pitch for the gears, we would find that the sum of the numbers of teeth of these two gears is 4 times the sum of their diameters, or 4 times $14\frac{1}{2}$ equals 58. However, 58 can not be split up into two numbers which have a ratio of 4 and 5. In order to do so, 58 should be divisible by 4 plus 5 which equals 9. If we should select 5-pitch gears, then the sum of the numbers of teeth of the two gears would be $5 \times 14\frac{1}{2} = 72\frac{1}{2}$, and this, of course, is impossible, as the sum of the number of teeth of two gears must be an integral number. If we make the pitch 18, then the sum of the numbers of teeth of the two gears would be $18 \times 14\frac{1}{2} = 261$, and

Continued on next page

one gear would have $\frac{4}{9}$ of 261 teeth, and the other gear $\frac{5}{9}$ of this num-

ber. However, 18 pitch is probably entirely too fine for the work we have to do, so that we must choose one of two things. We must either make special cutters with an odd pitch, or we must be satisfied with a compromise as to the gear ratio. The first of these two things is costly and consumes a great deal of time and the other may be absolutely prohibitive if an exact gear ratio is required.

Substituting spiral gears for spur gears would solve the question at once.

Definitions - Pitch, Lead, Normal Pitch, etc. A tooth of a spiral gear is much like the thread of a screw. It does not have the same cross section, nor is it meant to do the same kind of work, but in many respects the two are very similar. The distance from a point on a screw thread to the corresponding point on the next thread is called the **PITCH**. The distance the screw travels in an **axial direction**, if we give it one complete turn, is called the **LEAD**. These same terms apply in the same way to a spiral gear. There is, however, this distinction: We measure the pitch of a screw along the axis of the screw, whereas, we measure the pitch of a spiral gear around the circumference, that is, at right angles to the axis. However, there are two things which are called pitch in the spiral gear. The pitch, as we described it, that is, the distance between two corresponding points of two adjoining teeth measured at right angles to the axis, is called the **REAL** pitch, whereas the distance between two corresponding points of two adjoining teeth, measured in a direction **AT RIGHT ANGLES TO THE DIRECTION OF THE TEETH**, is called the **NORMAL** pitch. The normal section, which would give us the normal pitch, would show us the true section of the teeth. A section, taken at right angles to the axis, would give us the distorted view of the shape of the teeth as seen when looking at the end of a spiral gear. A section through the axis would also give a distorted view. If the spiral angle is 45° , then the distorted views of the teeth would be the same whether we take the sections through the axis, or at right angles with the axis. If the angle of the spiral with the axis is less than 45° , that is, if the spiral gear approaches more nearly a spur gear, then the right angle section would give a less and the axial section a more distorted view. This is reversed if the angle of the spiral with the axis is more than 45° , that is, if the spiral gear approaches more nearly the shape of a worm.

Cutting Spiral Gears. Spiral gears are ordinarily cut with common spur gear cutters. The normal pitch is, therefore, given in the same way as the pitch of spur gears, that is, we talk of a 5, a 7, or a 10-pitch gear. The real pitch is measured along the circular section of the gear, and if this pitch is P and the number of teeth of the gear is n , then the length of the circumference of the normal section is nP .




Fig. 1

Fig. 1 shows that the normal pitch and real pitch bear such a relation to each other that the normal pitch is a right angle side of a right angle triangle, of which the real pitch is the hypotenuse and the tooth line is the base. If the angle between the tooth line and the axis is called L , and if the normal pitch is P , then the real pitch is $P \sec L$. If we know the pitch of the cutter, the number of teeth and the spiral angle, we can easily figure the pitch diameter of the spiral gear. We figure as if it were a spur gear and then multiply the diameter by the secant of the spiral angle. For instance, a

Continued on next page

spiral gear with 16 teeth, 5 pitch, and a spiral angle of 37 degrees, will have a diameter of 16 divided by 5 and multiplied by the secant of 37 degrees. If we were dealing with a spur gear the pitch diameter

would be $\frac{16}{5} = 3.2''$.

From a table of secants we find $\sec 37^\circ = 1.2521$. Then we have $3.2 \times 1.2521 = 4.0067''$, the pitch diameter of the spiral gear.

The pitch circumference is $4.0067 \times \pi = 4.0067 \times 3.14159 = 12.587''$.

If we should make a wooden cylinder with a diameter equal to the pitch diameter of our spiral gear, and then cut out a paper right angle triangle, Fig. 2, of which one right angle side is equal to the circumference of the pitch circle, and the opposing angle equal




Fig. 2

to the spiral angle, and wrap this triangle around the cylinder, we will find that the hypotenuse describes a spiral line around the cylinder, and that the end of the hypotenuse will come in line with the beginning. In other words, the two ends of the hypotenuse will be a distance apart on the cylinder equal to the lead of the spiral. If now we unwrap the paper triangle we have in this triangle all the important elements of a tooth of the spiral gear. One right angle side is the circumference of the pitch circle, the second right angle side is the lead, the hypotenuse is the length of a tooth wrapped once around the pitch cylinder, the angle opposite the circumference is the angle of the spiral with the axis of the gear. This is commonly called the spiral angle or helix angle. It is the angle to which the milling machine table must be set. The angle opposite the lead is the angle which the tooth makes with the body of the gear.

Addendum, dedendum and clearance are the same as in a spur gear of the same pitch as the normal pitch of the spiral gear.

Selecting the Cutter. It is now possible to figure all the dimensions of the spiral gear and turn up the blank in the lathe. However, when it comes to cutting the teeth, a new element comes in. Although the gear may have 16 teeth, 5 pitch, this does not mean that we can use a 16-tooth, 5-pitch gear cutter for this spiral gear. It is true, we will have to use a 5-pitch cutter, but not for 16 teeth. We must select a spur gear cutter for a different number of teeth. The rule usually given is to divide the number of teeth of the spiral gear by the cube of the cosine of the spiral angle.

This gives good results for gears having a spiral angle in the neighborhood of 45° , but anyone who has followed this rule for gears with a spiral angle differing greatly from 45° will have found that such gears do not run properly and the running of the gears becomes worse as the spiral differs more from 45° . For such gears we recommend the following rule:

Divide the number of teeth of the spiral gear by the product of the square of the cosine multiplied by the sine of the spiral angle.

$$N = \frac{n}{\cos^2 L \times \sin L}$$
 in which N is the number of teeth of the selected gear cutter, and n is the number of teeth of the spiral gear.

Taking the above case

$$N = \frac{n}{\cos^2 37^\circ \times \sin 37^\circ} = \frac{16}{.79864^2 \times .60182} = \frac{16}{.6378 \times .60182} = 41.$$

We should select a cutter suitable for cutting a gear with 41 teeth.

The speed ratio of two spiral gears is, as with spur gears, the ratio of their numbers of teeth. For instance, a 16-tooth gear driving a 32-tooth gear will cause this latter gear to run half as many revolutions per minute as the former. The center distance between two spiral gears, as with spur gears, is equal to half the sum of their pitch diameters.

Shafts Parallel. Computation of a pair of spiral gears which are to be used in place of spur gears.

If we have two shafts, say 8" apart, and wish to drive one from the other by means of spiral gears with a given gear ratio, and, if we desire to use standard gear cutters we should proceed as is shown in the following example:

Continued on next page

The two gears shown in Fig. 3 must have a ratio of 2 to 1; a center distance of 8", and in order to make them of the proper strength the teeth must have about 5 pitch. As we want to use standard gear cutters, we will make the pitch exactly 5.




Fig. 3

A pair of spiral gears on parallel shafts to give a speed ratio of 2 to 1.

Number of Teeth and Spiral Angle. Taking the number of teeth in the small gear = n , and the number in the large gear = $2n$, and the spiral angle of the teeth in the small gear L , we have:

Pitch diameter small gear = $\frac{n \sec L}{5}$, and

Pitch diameter large gear = $\frac{2n \sec L}{5}$, because, in a pair of spiral

gears with shafts parallel, the spiral angle is the same in both.

The sum of the pitch diameters of the gears is, therefore

$$\frac{n \sec L}{5} + \frac{2n \sec L}{5}$$

and this sum equals double the center distance.

Continued on next page

Therefore,

$$\frac{n}{5} \sec L + \frac{2n}{5} \sec L = 16.$$

Multiplying both sides of this equation by 5, in order to simplify it, we get

$$n \sec L + 2n \sec L = 80.$$

This is a very simple equation, but unfortunately there are two unknown quantities: The number of teeth n , and the spiral angle L . However, there is one thing we know about n ; it must be an INTEGRAL number. There is still another thing we know, and that is that we would like the angle to be about 20 degrees, for this gives the maximum efficiency of the gear system. We will, therefore, try the equation by giving L the value of 20° : $\sec 20 = 1.0642$, and therefore the equation

$$n \sec L + 2n \sec L = 80$$

$$\text{becomes } (n \times 1.0642) + (2n \times 1.0642) = 80.$$

$$3n \times 1.0642 = 80.$$

$$n \times 3.1926 = 80.$$

$$n = 25.058.$$

$$2n = 50.116.$$

As n must be an integral number, we will assume a value of $n = 25$, and therefore $2n = 50$.

Substituting in the above equation, we get

$$25 \times 1.0642 + 50 \times 1.0642 = 79.815.$$

Since the second member of the equation should be 80 and not 79.815, it is evident that the assumed value of 20° for L , the spiral angle will not do, if we decide to use 25 and 50 teeth. In proceeding to find the correct angle, we will first determine whether the angle should be more or less than 20° . For trial, we will select 19° and 21° . With 20° the value of the second member was too small. Therefore, it must be increased. Since our value is too small we will try a larger angle, 21° :

$\sec 21 = 1.0711$. Substituting this in our equation, we get
 $25 \times 1.0711 + 50 \times 1.0711 = 80.3325.$

The value, using 20° , was .185 too small. Our new value is .3325 too large. The correct angle is, therefore, between $20'$ and $21'$. By trial, we find that $20^\circ 22'$ (sec $20^\circ 22' = 1.0667$) gives us

$25 \times 1.0667 + 50 \times 1.0667 = 80.0025$, or .0025 too large, and $20^\circ 21'$ (sec $20^\circ 21' = 1.0666$) gives us

$25 \times 1.0666 + 50 \times 1.0666 = 79.9950$, or .005 too small.

We will, therefore, choose as our value of L , $20^\circ 21'$. Let us try this out and find what the new center distance between the gears will be.

Since the gears are 5 pitch and we have taken $2 \times$ center distance for our second member of the equation, then the center distance is

$$\frac{79.9950}{2 \times 5} = 7.99950$$

which is .0005" short, which is close enough for all practical purposes.* Our gears, therefore, will have a spiral angle of $20^\circ 21'$, the small one with 25 teeth and the large one with 50 teeth.

Selecting the Cutter. Referring back to the rule given on page 77, we have for the small gear

$$N = \frac{n}{\cos^2 20^\circ 21' \times \sin 20^\circ 21'} = \frac{25}{.93759^2 \times .34775} =$$

$$\frac{25}{.8780 \times .34775} = 81,$$

and for the large gear

$$\frac{50}{.93759^2 \times .34775} = \frac{50}{.8780 \times .34775} = 163.$$

Therefore, the cutters should be selected for 81 and 163 teeth respectively.

* We have already decided that the center distance between the shafts on which these gears will work in our machine is 8". Were we to use an angle of $20^\circ 22'$, our gears would have a center distance .00025" too large, and they would not go into place, or at least they would work too tight if all other dimensions were correct. We therefore choose $20^\circ 21'$ which makes gears that are .0005" small and will have just this much working clearance. This is satisfactory for ordinary work. If closer accuracy is required we must either change our center distance in the machine or continue trying by selecting angles reading in seconds until a satisfactory one is found.

Computing the Lead. Referring to Fig. 2 We know angle L = $20^{\circ}21'$. However, we do not know the pitch circumference. We must therefore first find the

PITCH DIAMETERS

$$\text{Pitch diameter} = \frac{n}{p} \times \sec L.$$

Then for the small gear we have

$$\frac{25}{5} \times \sec 20^{\circ}21' = \frac{25}{5} \times 1.0666 = 5.3330,$$

and for the large gear

$$\frac{50}{5} \times \sec 20^{\circ}21' = \frac{50}{5} \times 1.0666 = 10.666$$

Since the outside diameter equals the pitch diameter plus twice the addendum, $OD = PD + \frac{2}{p}$ therefore,

$$\text{outside diameter of small gear} = 5.3330 + \frac{2}{5} = 5.7330'';$$

$$\text{outside diameter of large gear} = 10.6660 + \frac{2}{5} = 11.0660''.$$

The PITCH CIRCUMFERENCES are:

$$\text{small gear } 5.333 \times 3.1416 = 16.754$$

$$\text{large gear } 10.666 \times 3.1416 = 33.508.$$

$$\text{Lead} = \frac{\text{pitch circumference}}{\text{Tangent } L} = \frac{16.754}{\text{Tangent } 20^{\circ}21'} = \frac{16.754}{.37090} = 45.17''$$


for the small gear, and $2 \times 45.17'' = 90.34''$ for the large gear.

We now proceed to select the change gears by following the instructions given in the chapter on Change Gears for Cutting Spirals.

Our gears are as follows, shafts parallel:

Pitch.....	= 5.
Number of teeth in small gear.....	= 25.
Number of teeth in large gear.....	= 50.

Comparative Sizes of Gear Teeth INVOLUTE



STRENGTH OF GEAR TEETH (Lewis)

W = load transmitted in pounds (force at pitch line of gear)
 p' = circular pitch
 f = face
 y = factor for different numbers and forms of teeth (Table II)

s = safe working stress of material (Table I)
 V = velocity in feet per minute
 $W = s p' f y$

$$\text{Horsepower} = \frac{W V}{33000}$$

Table I—SAFE WORKING STRESS s IN POUNDS PER SQUARE INCH FOR DIFFERENT SPEEDS

Speed of Teeth in Ft. Per Min.	Cast Iron	Steel
100 or less	8000	20000
200	6000	15000
300	4800	12000
600	4000	10000
900	3000	7500
1200	2400	6000
1800	2000	5000
2400	1700	4300

Table III—AVERAGE VALUES FOR s IN POUNDS PER SQUARE INCH

Material	s
Non-metallic.....	6000
Cast iron.....	8000
Bronze.....	8000
Steel { .20C Natural.....	12000
.20C Case-hardened.....	25000
.30C Natural.....	15000
.40C ".....	20000
.40C Heat-treated.....	30000

Table II—VALUES OF FACTOR y FOR LEWIS' FORMULA

No. of Teeth	Value of Factor y		No. of Teeth	Value of Factor y	
	Involute 20°	Involute 15°		Involute 20°	Involute 15°
12	0.078	0.067	27	0.111	0.100
13	0.083	0.070	30	0.114	0.102
14	0.088	0.072	34	0.118	0.104
15	0.092	0.075	38	0.122	0.107
16	0.094	0.077	43	0.126	0.110
17	0.096	0.080	50	0.130	0.112
18	0.098	0.083	60	0.134	0.114
19	0.100	0.087	75	0.138	0.116
20	0.102	0.090	100	0.142	0.118
21	0.104	0.092	150	0.146	0.120
23	0.106	0.094	300	0.150	0.122
25	0.108	0.097	Rack	0.154	0.124


Lewis' Formula for the strength of gears originally read as above. The following revision by Barth provides a practical means for calculating the Horsepower of material of any known static stress and velocity.

S = static stress of material (Table III).

$$W = S p' f y \frac{600}{600 + V}$$

$$\text{Horsepower} = \frac{W V}{33000}$$

MACHINE RACKS AND PINIONS



Rack

Pitch....	{ Circular.....	= C
	{ Diametral.....	= $3.1416 \div C$
Thickness.....		= T
Face.....		= W
Length of Rack.....		= S
Material.....		=
Center of Pinion to Bottom of Rack.....		= A

Pinion

Number of Teeth.....		=
Pitch....	{ Circular.....	= C
	{ Diametral.....	= *
Pitch Diameter.....		= D'
Outside Diameter.....		= E
Bore.....		= B
Face.....		= F
Keyway.....		= K.S.
Material.....		=

*Number of teeth to each inch of Pitch Diameter.

Use of Center Gauge

The point of the cutter bit must be ground to an angle of 60° for cutting American National screw threads in the lathe, as shown in Fig. 1 at right. A center gauge having a 60° included angle is used for grinding the tool to the exact angle required. The top of the tool is usually ground flat, with no side rake or back rake. However, for cutting threads in steel, side rake is sometimes used.






Fig. 1. Cutter Bit for Cutting Screw Threads is Ground to 60° Center Gauge

RULES AND FORMULAS FOR HELICAL GEAR CALCULATIONS




In the formulas, N , a , etc., are the numbers of teeth, spiral angle, etc., for *either* gear or pinion; the notation N_a , N_b , a_a , a_b , etc., refer to the teeth or angles in the pinion or gear, respectively, in a pair of gears a and b .

To Find	Rule	Formula
Relation between Shaft and Tooth Angles.	The sum of the tooth angles of a pair of mating helical gears is equal to the shaft angle.	$\gamma = \alpha_a + \alpha_b$
Pitch Diameter.	Divide the number of teeth by the product of the normal pitch and the cosine of the tooth angle.	$D = \frac{N}{P_n \cos \alpha}$
Center Distance.	Add together the pitch diameters of the two gears and divide by 2.	$C = \frac{D_a + D_b}{2}$
Checking Calculations in (2) and (3).	To prove the calculations for pitch diameters and center distance, multiply the number of teeth in the first gear by the tangent of the tooth angle of that gear, and add the number of teeth in the second gear to the product; the sum should equal twice the product of the center distance multiplied by the normal diametral pitch, multiplied by the sine of the tooth angle of the first gear.	$N_b + (N_a \times \tan \alpha_a) = 2CP_n \times \sin \alpha_a$
Number of Teeth for which to Select Cutter.	Divide the number of teeth in the gear by the cube of the cosine of the tooth angle.	$N' = \frac{N}{(\cos \alpha)^3}$
Lead of Tooth Helix.	Multiply the pitch diameter by 3.1416 times the cotangent of the tooth angle.	$L = \pi D \cot \alpha$
Addendum.	Divide 1 by the normal diametral pitch.	$S = \frac{1}{P_n}$
Whole Depth of Tooth.	Divide 2.157 by the normal diametral pitch.	$W = \frac{2.157}{P_n}$
Normal Tooth Thickness at Pitch	Divide 1.571 by the normal diametral pitch.	$T_n = \frac{1.571}{P_n}$
Outside Diameter.	Add twice the addendum to the pitch diameter.	$O = D + 2S$





An Assortment of Milling Cutters and Arbors



Milling a Woodruff Keyway in a Shaft

DESIGN OF WORM GEARING

The uses and advantages of worm gearing have been thoroughly covered



CALCULATION OF DIMENSIONS

P = circular pitch of wheel and linear pitch of worm;
 l = lead of worm;
 n = number of teeth or threads in worm;
 S = addendum, or height of worm tooth above pitch line;
 d = pitch diameter of worm;
 D = pitch diameter of worm-wheel;
 o = outside diameter of worm;
 O = throat diameter of worm-wheel;
 O' = outside diameter of worm-wheel (to sharp corners);

b = bottom or root diameter of worm;
 N = number of teeth in worm-wheel;
 W = whole depth of worm tooth;
 T = width of thread tool at end;
 α = face angle of worm-wheel;
 β = helix angle of worm and gashing angle of wheel;
 U = radius of curvature of worm-wheel throat;
 C = distance between centers;
 x = threaded length of worm.

RULES AND FORMULAE FOR WORM GEARING

To Find	Rule	Formula
Linear Pitch.	Divide the lead by the number of threads.—It is understood that by the number of threads is meant, not number of threads per inch, but the number of threads in the whole worm—one, if it is single-threaded, four, if it is quadruple-threaded, etc.	$P = \frac{l}{n}$
Addendum of Worm Tooth.	Multiply the linear pitch by 0.3183.	$S = 0.3183P$
Pitch Diameter of Worm.	Subtract twice the addendum from the outside diameter.	$d = o - 2S$
Pitch Diameter of Worm-wheel.	Multiply the number of teeth in the wheel by the linear pitch of the worm, and divide the product by 3.1416.	$D = \frac{NP}{3.1416}$
Center Distance between Worm and Gear.	Add together the pitch diameter of the worm and the pitch diameter of the worm-wheel, and divide the sum by 2.	$C = \frac{D + d}{2}$
Whole Depth of Worm Tooth.	Multiply the linear pitch by 0.6866.	$W = 0.6866P$
Bottom Diameter of Worm.	Subtract twice the whole depth of tooth from the outside diameter.	$b = o - 2W$
Helix Angle of Worm.	Multiply the pitch diameter of the worm by 3.1416, and divide the product by the lead; the quotient is the cotangent of the helix angle of the worm.	$\cot \beta = \frac{3.1416d}{l}$
Width of Thread Tool at End.	Multiply the linear pitch by 0.31.	$T = 0.31P$
Throat Diameter of Worm-wheel.	Add twice the addendum of the worm tooth to the pitch diameter of the worm-wheel.	$O = D + 2S$

(Continued on top of next page.)

RULES AND FORMULAE FOR WORM GEARING—Cont'd.

Radius of Worm-wheel Throat.	Subtract twice the addendum of the worm tooth from half the outside diameter of the worm.	$U = \frac{O}{2} - 2S$
Diameter of Worm-wheel to Sharp Corners.	Multiply the radius of curvature of the worm-wheel throat by the cosine of half the face angle, subtract this quantity from the radius of curvature, multiply the remainder by 2, and add the product to the throat diameter of the worm-wheel.	$O' = 2 \left(U - U \times \cos \frac{\alpha}{2} \right) + O$
Minimum Length of Worm for Complete Action.	Subtract four times the addendum of the worm thread from the throat diameter of the wheel, square the remainder, and subtract the result from the square of the throat diameter of the wheel. The square root of the result is the minimum length of worm advisable.	$x = \sqrt{O'^2 - (O - 4S)^2}$
Outside Diameter of Worm.	Add together the pitch diameter and twice the addendum.	$o = d + 2S$
Pitch Diameter of Worm.	Subtract the pitch diameter of the worm-wheel from twice the center distance.	$d = 2C - D$

Careful distinction must be made between the terms "pitch" and "lead." The term lead is defined as the distance which any one thread advances in one revolution of the worm, while the pitch, or, more correctly, the linear pitch, is the distance between the centers of two adjacent threads. The lead and pitch are equal for a single-threaded worm. For a double-threaded worm the lead is twice the linear pitch, and for a triple-threaded worm, three times the linear pitch.

TABLE OF CUTTERS, PITCHES, GEARS AND ANGLES
FOR TWIST DRILLS

DIAMETER OF DRILL	THICKNESS OF CUTTER	PITCH IN INCHES	GEAR ON WORM	FIRST GEAR ON STUD	SECOND GEAR ON STUD	GEAR ON SCREW	ANGLE OF SPIRAL
$\frac{1}{16}$.06	.67	24	86	24	100	16° 20'
$\frac{1}{8}$.08	1.12	24	86	40	100	19° 20'
$\frac{3}{16}$.11	1.67	24	64	32	72	19° 25'
$\frac{1}{4}$.15	1.94	32	64	28	72	21°
$\frac{5}{16}$.19	2.92	24	64	56	72	20°
$\frac{3}{8}$.23	3.24	40	48	28	72	21°
$\frac{7}{16}$.27	3.89	56	48	24	72	20° 10'
$\frac{1}{2}$.31	4.17	40	72	48	64	20° 30'
$\frac{9}{16}$.35	4.86	40	64	56	72	20°
$\frac{5}{8}$.39	5.33	48	40	32	72	20° 12'
$\frac{11}{16}$.44	6.12	56	40	28	64	19° 30'
$\frac{3}{4}$.50	6.48	56	48	40	72	20°
$\frac{13}{16}$.56	7.29	56	48	40	64	19° 20'
$\frac{7}{8}$.62	7.52	64	48	32	56	19° 50'
$\frac{15}{16}$.70	8.33	48	32	40	72	19° 30'
$\frac{1}{4}$.77	8.95	86	48	28	56	19° 20'
$\frac{11}{8}$	85	9.33	56	40	48	72	20° 40'

CHANGE GEARS FOR MILLING SPIRALS ON THE MILLING MACHINE

The worm wheel in the universal indexing head of the milling machine has 40 teeth and the table feed screw usually has four threads per inch. It therefore requires 40 turns of the worm to rotate the spindle of the dividing head once, and it requires four turns of the feed screw to advance the milling machine table one inch. If gears of equal size were put on the feed screw and worm shafts and were geared directly (that is, simple, not compound, geared), 40 turns of the feed screw would cause one turn of the spindle and at the same time advance the table $\frac{1}{4} \times 40 = 10$ inches, giving a spiral with a pitch of 10 inches.

In calculations for spirals, we must have the ratio

4 times pitch of spiral

40

equal to

teeth in driven gear

teeth in driving gear

Expressed in the form of a proportion, this is, $4 \times \text{pitch of spiral} : 40 :: \text{teeth in driven gear} : \text{teeth in driving gear}$. For example: If a spiral pitch of 6 inches were required, $6 \times 4 = 24$, which is the number of revolutions the screw must make while the work rotates through one revolution. Then the ratio

$$\frac{24}{40} = \frac{\text{teeth in driven gear}}{\text{teeth in driving gear}}$$

Put a 40-tooth gear on the feed screw and a 24-tooth gear on the worm shaft.

COMPOUND GEARING

It is best when possible to use the simple gearing. If, however, the ratio is such that one of the gears would be extremely large or small, then the gearing should be compounded. For example: Required pitch of spiral $32\frac{1}{2}$ inches, $32\frac{1}{2} \times 4 = 130$, or the revolutions of the screw per revolution of the work.

$$\frac{130}{40} = \frac{\text{No. teeth in driven gear}}{\text{No. teeth in driving gear}}$$

As 130 would be a rather large gear, and probably not furnished with the machine, we can reduce the ratio to $\frac{65}{20}$, but this would also give numbers of teeth not usually furnished. It would then be necessary to

compound. Resolve the ratio $\frac{130}{40}$ into factors $\frac{10}{5} \times \frac{13}{8}$; as these numbers are too low, we can multiply both numerator and denominator by the same number, and we would have, for example,

$$\frac{10}{5} \times \frac{4}{4} = \frac{40}{20} \text{ and } \frac{13}{8} \times \frac{4}{4} = \frac{52}{32} \text{ and as } \frac{40}{20} \times \frac{52}{32} = \frac{130}{40} \text{ we may use gears 40 and 52 as the}$$

driven gears. Either 20 or 32 can be placed on the screw and the other will be the inside gear on the stud. Either the 40 or 52 can be put on the worm shaft and the other will be the outside gear on the stud. If any of the gears called for were not found in the regular set, the numbers could be changed by treating both numerator and denominator without changing the ratio. Thus, in the last problem, if the last set did not contain a gear tooth of 20 teeth, we could divide both numerator and denominator by a common factor and

multiply the results by some other number. Thus in the ratio $\frac{40}{20}$ divide both by 5, giving $\frac{8}{4}$ and multiply

both by 6. This would give $\frac{48}{24}$ which alters the numbers, but does not change the ratio. In this manner


it is usually possible to so manipulate the ratios that the exact or a very close approximation to the required pitch can be obtained with the regular gears.

INSTRUCTIONS ON WORM GEARS

We show on the next page three worms. The first one is a single-threaded; the second one is a double-threaded; the third one is a triple-threaded. The word "lead" is assumed to mean the distance, which a given thread advances in one revolution of the worm, while by "pitch," or, more strictly, "linear pitch," we mean the distance between the centers of two adjacent threads. As may be clearly seen, the lead and linear pitch are equal for a single-threaded worm. For a double-threaded worm the lead is twice the linear pitch, and for a triple-threaded worm it is three times the linear pitch. It is understood, of course, that by the number of threads is meant, not the number of threads per inch, but the number of threads in the whole worm — one, if it is single-threaded; four, if it is quadruple-threaded, etc.

The standard form of worm thread, measured, has the same dimensions as the standard form of involute rack tooth of the same linear or circular pitch. It is not of exactly the same shape, however, not being rounded at the top, nor provided with fillets. The thread is cut with a straight-sided tool having a square flat end. The sides have an inclination with each other of 29 degrees, or $14\frac{1}{2}$ degrees with the center line. The following rules in the next table will give the dimensions of the teeth in various linear pitches.

Continued on next page




The above drawing shows the distinction between the terms lead and linear pitch as applied to worm gears.

RULES FOR CALCULATING WORM GEARS

- No. 1 Rule. To find the lead of a worm, multiply the linear pitch by the number of threads.
- No. 2 Rule. To find the linear pitch of a worm, divide the lead by the number of threads.
- No. 3 Rule. To find the whole depth of the worm tooth, multiply the linear pitch by 0.6866.
- No. 4 Rule. To find the width of the thread tool at the end, multiply the linear pitch by 0.31.
- No. 5 Rule. To find the addendum or height of worm tooth above the pitch line, multiply the linear pitch by 0.3183.
- No. 6 Rule. To find the outside diameter of the worm, add together the pitch diameter and twice the addendum.
- No. 7 Rule. To find the pitch diameter of the worm, subtract twice the addendum from the outside diameter.
- No. 8 Rule. To find the bottom diameter of the worm, subtract twice the whole depth of tooth from the outside diameter.
- No. 9 Rule. To find the helix angle of the worm and the gashing angle and the worm wheel tooth, multiply the pitch diameter of the worm by 3.1416, and divide the product by the lead; the quotient is the cotangent of the throat angle of the worm.
- No. 10 Rule. To find the pitch diameter of the worm wheel, multiply the number of teeth in the wheel by the linear pitch of the worm, and divide the product by 3.1416.
- No. 11 Rule. To find the throat diameter of the worm wheel, add twice the addendum of the worm tooth to the pitch diameter of the worm wheel.
- No. 12 Rule. To find the radius of curvature of the worm wheel throat, subtract twice the addendum of the worm tooth from the outside diameter of the worm.
- No. 13 Rule. To find the diameter of the worm wheel to sharp corners, multiply the throat radius by the cosine of the half the face angle, subtract this quantity from the throat radius, multiply the remainder by 2, and add the product to the throat diameter of the worm wheel.
- No. 14 Rule. To find the velocity ratio of a worm and worm wheel, divide the number of teeth in the wheel by the number of threads in the worm.
- No. 15 Rule. To find the distance between the center of the worm wheel and the center of the worm, add together the pitch diameter of the worm and the pitch diameter of the worm wheel, and divide the sum by 2.
- No. 16 Rule. To find the pitch diameter of the worms, subtract the pitch diameter of the worm wheel from twice the center distance.
- No. 17 Rule. To find the minimum length of worms for complete action with the worm wheel, subtract four times the addendum of the worm thread from the throat diameter of the wheel, square the remainder, and subtract the result from the square of the throat diameter of the wheel. The square root of the result is the minimum length of worm advisable.
- No. 18 Rule. The length of the worms should ordinarily be longer than the dimension thus found. Hobs, particularly, should be long enough for the largest wheels they are ever likely to be called upon to cut.
- No. 19 Rule. The throat diameter of the wheel and the center distance may have to be altered in some cases from the figures given by the preceding rules. If worm wheels with small numbers of teeth are made to the dimensions given, it will be found that the flanks of the teeth will be partly cut away by the tops of the hob teeth, so that the full bearing area is not available. The matter becomes serious when there are less than 25 teeth in the worm wheel. There are two ways of avoiding the difficulty. One of them is to increase the included angle of the sides of the thread tool. This departure from standard form, however, may be avoided by an increase in the throat diameter of the wheel, and consequently in the center distance. On the other hand, some designers claim to get better results in efficiency and durability by making the throat diameter of the worm wheel smaller than standard, where it is possible to do so without too much under cutting.

WORMS AND WORM GEARS



WORM GEAR

Number of Teeth.....	
Pitch (Circular).....	= C
Face.....	= F
Bore.....	= B
Pitch Diameter.....	= D
Length through Hub.....	= L
Projection from Center.....	= M
Keyway.....	= KS
Material.....	
Right or Left Hand.....	

WORM


Pitch.....	= c
(Distance from center to center of teeth.)	
Lead (Advance in one revolution.)	
Pitch Diameter.....	= d
Outside Diameter.....	= d'
Bore.....	= b
Length.....	= f
Projection of Hub.....	= n
Keyway.....	= ks
Material.....	
Right or Left Hand.....	

Distance between Centers..... = A

Table of Observed Tooth Dimensions for Spiral Gears

Angle of Table Setting, Degrees	Width of Tooth at a Depth of Inches						
	0	0.050	0.100	0.125	0.150	0.200	0.250
45	0.104	0.145	0.185	0.200	0.203	0.221	0.239
44	0.102	0.144	0.181	0.195	0.202	0.220	0.238
43	0.099	0.142	0.176	0.188	0.200	0.218	0.236
42	0.094	0.135	0.168	0.180	0.196	0.215	0.234
41	0.087	0.128	0.158	0.171	0.185	0.211	0.232
40	0.078	0.115	0.146	0.158	0.171	0.205	0.230

HERRINGBONE GEARS



GEAR

Circular Pitch	= P_c
(Circumferential)	
Normal Circular Pitch	= P_n
Pitch Diameter	= D
Outside Diameter	= O
Center Distance	= C
No. of Teeth	= N
Face	= F
Length of Hub	= L
Bore	= B
Key seat	= KS

PINION

Circular Pitch	= P_c
(Circumferential)	
Normal Circular Pitch	= P_n
Pitch Diameter	= d
Outside Diameter	= o
Center Distance	= C
No. of Teeth	= n
Face	= F
Length of Hub	= l
Bore	= b
Key seat	= ks

Helix Angle = 30° on all gears and pinions.

All Herringbone gears are figured on the basis of Diametrical pitch.

Diametrical pitch = 3.1416 divided by the circular pitch.

Allowance Tables for Bores of Gears

RUNNING FIT ALLOWANCE				DRIVE FIT ALLOWANCE			
Inches	Inches	Inches	Inches	Inches	Inches	Inches	Inches
$\frac{1}{4}$.00058	7	.0027	$\frac{1}{4}$.00035	7	.0040
$\frac{1}{2}$.00065	8	.0030	$\frac{1}{2}$.0005	8	.0045
$\frac{3}{4}$.00073	9	.0033	$\frac{3}{4}$.0005	9	.0050
1	.0008	10	.0036	1	.0010	10	.0055
$1\frac{1}{2}$.0010	11	.0039	$1\frac{1}{2}$.0013	11	.0060
2	.0011	12	.0043	2	.0015	12	.0065
3	.0014	14	.0049	3	.0020	14	.0075
4	.0018	16	.0055	4	.0025	16	.0085
5	.0021	18	.0061	5	.0030	18	.0095
6	.0024	20	.0068	6	.0035		

Module System Translation

FORMULAS

Module is the Pitch diameter in m/m divided by number of teeth in the gear.

Or, the outside diameter in m/m divided by the number of teeth in gear plus 2.

To find circular pitch in millimeters from Module multiply 3.142 m/m by the number of module. $\therefore 2 \text{ module} \times 3.142 \text{ m/m} = 6.284 \text{ m/m}$.


To find circular pitch in inches from the circular pitch in m/m, multiply the number of m/m by .03937". $\therefore 6.284 \text{ m/m} \times .03937 = .2474"$.

To find diametral pitch from circular pitch in inches, divide 3.1416 by the circular pitch in inches. $\therefore 3.1416 \div .2474" = 12.6999 \text{ diametral pitch}$.

MODULE—TABLE OF TOOTH PARTS

Module m/m	Circular Pitch m/m	Thickness of Tooth at Pitch Line m/m	Addendum m/m	Dedendum m/m	Clearance m/m	Working Depth of Tooth m/m	Total Height of Tooth m/m	Width of Thread Tool at End m/m	Width of Thread at End m/m	Nearest English Diametral Pitch
M	Pc	t	a	d	c	a ₂	H	T'	T	Pd
.50	1.57	.78	.50	.58	.08	1	1.08	.48	.52	50.800
.75	2.36	1.18	.75	.87	.12	1.50	1.62	.73	.78	33.866
1	3.14	1.57	1	1.16	.16	2	2.16	.97	1.05	25.400
1.25	3.93	1.96	1.25	1.45	.20	2.50	2.70	1.21	1.31	20.320
1.50	4.71	2.36	1.50	1.73	.23	3	3.23	1.46	1.57	16.933
1.75	5.50	2.75	1.75	2.02	.27	3.50	3.77	1.70	1.84	14.514
2	6.28	3.14	2	2.31	.31	4	4.31	1.94	2.10	12.700
2.25	7.07	3.53	2.25	2.60	.35	4.50	4.85	2.19	2.37	11.288
2.50	7.85	3.93	2.50	2.89	.39	5	5.39	2.43	2.63	10.160
2.75	8.64	4.32	2.75	3.18	.43	5.50	5.93	2.68	2.89	9.236
3	9.42	4.71	3	3.47	.47	6	6.47	2.92	3.15	8.466
3.50	10.99	5.50	3.50	4.05	.55	7	7.55	3.40	3.68	7.257
4	12.57	6.28	4	4.63	.63	8	8.63	3.89	4.20	6.350
4.50	14.14	7.07	4.50	5.21	.71	9	9.71	4.38	4.73	5.644
5	15.71	7.85	5	5.78	.78	10	10.78	4.87	5.26	5.080
5.50	17.28	8.64	5.50	6.36	.86	11	11.86	5.35	5.79	4.618
6	18.85	9.42	6	6.94	.94	12	12.94	5.84	6.31	4.233
7	21.99	10.99	7	8.10	1.10	14	15.10	6.81	7.36	3.628
8	25.13	12.57	8	9.26	1.26	16	17.26	7.79	8.42	3.175
9	28.27	14.14	9	10.41	1.41	18	19.41	8.76	9.47	2.822
10	31.42	15.71	10	11.57	1.57	20	21.57	9.73	10.52	2.540
11	34.56	17.28	11	12.73	1.73	22	23.73	10.71	11.57	2.309
12	37.70	18.85	12	13.88	1.88	24	25.88	11.68	12.63	2.116
14	43.98	21.99	14	16.20	2.20	28	30.20	13.63	14.73	1.814
16	50.26	25.13	16	18.51	2.51	32	34.51	15.58	16.83	1.587

The dividing head construction is based on the principle of interchangeable gears, the same as regularly used on gear cutting machines. The index plate shows the proper gears to use for divisions from 2 to 360.



Cutting a Gear on a Lathe

Formulas for Determining the Dimensions of Gears by Metric Pitch

Module is the pitch diameter in millimeters divided by the number of teeth in the gear.

Pitch diameter in millimeters is the Module multiplied by the number of teeth in the gear.

$$M = \frac{D'}{N} \text{ or } \frac{D}{N+2} = \text{Module}$$

$D' = N M$ = The pitch diameter of gear in millimeters

$D = (N + 2) M$ = The whole diameter of gear in millimeters


$N = \frac{D'}{M} \text{ or } \frac{D}{M} - 2$ = The number of teeth in gear

$D' = 2 M$ = The working depth of teeth

$t = M 1.5708$ = Thickness of teeth on pitch line

$f = \frac{M 1.5708}{10} = .157 M$ = Amount added to depth for clearance

The Module is equal to the part marked "S" in cut opposite, measured in millimeters and parts of millimeters.




Pitches Commonly Used

Module in Millimeters

Module, m/m	Corresponding English Diametral Pitch	Module, m/m	Corresponding English Diametral Pitch	Module, m/m	Corresponding English Diametral Pitch
0.5	50.800	2.75	9.236	8.	3.175
0.75	33.867	3.	8.466	9.	2.822
1.	25.400	3.5	7.257	10.	2.540
1.25	20.320	4.	6.350	11.	2.309
1.5	16.933	4.5	5.644	12.	2.117
1.75	14.514	5.	5.080	13.	1.954
2.	12.700	5.5	4.618	14.	1.814
2.25	11.288	6.	4.233	15.	1.693
2.5	10.160	7.	3.628	16.	1.587

FOOTE BROS. TABLE OF WORKING STRESSES USED FOR THE STRENGTH OF WORM GEARS

Velocity in feet Min. = V	600 600+V	Allowable Unit Stress at Given Velocity = S in pounds per sq. in.	
		Cast Iron	Phosphor Bronze
0	1.000	5300	8000
100	.857	4550	6800
200	.750	4000	6000
300	.666	3550	5350
450	.571	3000	4500
600	.500	2650	4000



GEAR

PINION

Number of Teeth.....	=		Number of Teeth.....	=	
Pitch..... { Circular.....	=	C	Pitch..... { Circular.....	=	c
{ Diameter.....	=	*	{ Diameter.....	=	*
Pitch Diameter.....	=	P	Pitch Diameter.....	=	p
Rim Diameter.....	=	D	Outside Diameter.....	=	e
Inside Diameter.....	=	E	Face.....	=	f
Face.....	=	F	Bore.....	=	b
Material.....	=		Keyway.....	=	ks
.....	=		Material.....	=	
Distance between Centers.....			= A		

When ordering, Internal Gears are the same as spur gears in regards to the number of teeth and pitch on pitch line. But you subtract two addendums or two teeth in place of adding as on spur gears for inside diameter.

Distance from end of teeth to plate or web varies according to pitch and size of gear, from $\frac{1}{4}$ to 1 inch.

*Number of teeth to each inch of pitch diameter.

STRENGTH OF INTERNAL GEARS

In designing internal gears with which pinions or idlers are used, it is not necessary to calculate the strength of the internal gear or H. P. capacity because the pinion is always the weakest member if the two gears are made of the same material. This is due to the fact that the torque arm or lever of the internal gear is longer than the torque arm of the pinion and consequently the load on the teeth of the internal gear is less than on the pinion.

For theoretical purposes the strength of internal gear teeth can be calculated in approximately the same manner as ordinary external spur gears or racks.

It will be found that the strength of the internal gear tooth is greater than a rack tooth of the same pitch, pressure angle and depth of tooth. also that the strength increases as the number of teeth decreases. With an external gear the reverse is just the case, the tooth becomes weaker as teeth decrease in number.

The larger the number of teeth the more closely the internal gear tooth approaches that of a rack tooth consequently decreasing the strength.

DIAMETRAL AND CIRCULAR PITCH OF GEARS

Diamet- ral Pitch	Circular Pitch, Inches	Diamet- ral Pitch	Circular Pitch, Inches	Circular Pitch, Inches	Diamet- ral Pitch	Circular Pitch, Inches	Diamet- ral Pitch
1 $\frac{1}{4}$	2.5133	11	.286	2	1.571	$\frac{3}{4}$	4.189
1 $\frac{1}{2}$	2.0944	12	.262	1 $\frac{7}{8}$	1.676	$\frac{11}{16}$	4.570
1 $\frac{3}{4}$	1.7952	14	.224	1 $\frac{3}{4}$	1.795	$\frac{5}{8}$	5.027
2	1.571	16	.196	1 $\frac{5}{8}$	1.933	$\frac{9}{16}$	5.585
2 $\frac{1}{4}$	1.396	18	.175	1 $\frac{1}{2}$	2.094	$\frac{1}{2}$	6.283
2 $\frac{1}{2}$	1.257	20	.157	1 $\frac{1}{16}$	2.185	$\frac{7}{16}$	7.181
2 $\frac{3}{4}$	1.142	22	.143	1 $\frac{3}{8}$	2.285	$\frac{3}{8}$	8.378
3	1.047	24	.131	1 $\frac{5}{16}$	2.394	$\frac{5}{16}$	10.053
3 $\frac{1}{2}$.898	26	.121	1 $\frac{1}{4}$	2.513	$\frac{1}{4}$	12.566
4	.785	28	.112	1 $\frac{3}{16}$	2.646	$\frac{3}{16}$	16.755
5	.628	30	.105	1 $\frac{1}{8}$	2.793	$\frac{1}{8}$	25.133
6	.524	32	.098	1 $\frac{1}{16}$	2.957	$\frac{1}{16}$	50.266
7	.449	36	.087	1	3.142
8	.393	40	.079	$\frac{15}{16}$	3.351
9	.349	48	.065	$\frac{7}{8}$	3.590
10	.314			$\frac{13}{16}$	3.867

**SHOWING DEPTH OF SPACE AND THICKNESS OF
TOOTH IN SPUR GEARS CUT WITH B. & S.
MFGS. CUTTER**

Pitch of Cutter	Depth to be Cut in Gear, Inches	Thickness of Tooth at Pitch Line, Inches	Pitch of Cutter	Depth to be Cut in Gear, Inches	Thickness of Tooth at Pitch Line, Inches
1 $\frac{1}{4}$	1.726	1.257	11	.196	.143
1 $\frac{1}{2}$	1.438	1.047	12	.180	.131
1 $\frac{3}{4}$	1.233	.898	14	.154	.112
2	1.079	.785	16	.135	.098
2 $\frac{1}{4}$.959	.698	18	.120	.087
2 $\frac{1}{2}$.863	.628	20	.108	.079
2 $\frac{3}{4}$.784	.571	22	.098	.071
3	.719	.524	24	.090	.065
3 $\frac{1}{2}$.616	.449	26	.083	.060
4	.539	.393	28	.077	.056
5	.431	.314	30	.072	.052
6	.360	.262	32	.067	.049
7	.308	.224	36	.060	.044
8	.270	.196	40	.054	.039
9	.240	.175	48	.045	.033
10	.216	.157

Rules for Obtaining Ratio of the Gears Necessary to Cut a Given Spiral. Note the ratio of the required lead to 10. This ratio is the compound ratio of the driven to the driving gears. Example: If the lead of required spiral is 12 inches, 12 to 10 will be the ratio of the gears.

Or, divide the required lead by 10 and note the ratio between the quotient and 1. This ratio is usually the most simple form of the compound ratio of the driven to the driving gears. Example: If the required lead is 40 inches, the quotient is $40 \div 10$ and the ratio 4 to 1.

TABLE FOR BLOCK OR MULTIPLE INDEXING

Teeth to be Cut	No. Indexed at Once	First Driver	First Follower	Second Driver	Second Follower	Turns of Locking Disc	Teeth to be Cut	No. Indexed at Once	First Driver	First Follower	Second Driver	Second Follower	Turns of Locking Disc
25	4	100	50	72	30	4	62	5	100	30	90	62	2
26	3	100	50	90	52	4	63	5	100	30	80	56	2
27	2	100	50	60	54	4	64	5	100	30	90	64	2
28	3	100	50	90	56	4	65	4	100	50	96	52	2
29	3	100	50	90	58	4	66	5	100	44	80	40	2
30	1	100	50	60	60	2	67	5	100	30	90	67	2
31	3	100	50	90	62	4	68	5	100	30	90	68	2
32	3	100	50	90	64	4	69	5	100	46	80	40	2
33	4	100	50	80	44	4	70	3	100	50	90	70	2
34	3	100	50	90	68	4	72	5	100	30	90	72	2
35	4	100	50	90	50	4	74	5	100	30	90	74	2
36	5	100	48	80	40	4	75	7	100	30	84	50	2
37	5	100	30	90	74	4	76	5	100	30	90	76	2
38	5	100	30	90	76	4	77	4	100	70	96	44	2
39	5	100	30	90	78	4	78	5	100	30	90	78	2
40	3	100	50	90	80	4	80	3	100	50	90	80	2
41	5	100	30	90	82	4	81	7	100	30	84	52	2
42	5	100	30	90	84	4	82	5	100	30	90	82	2
43	5	100	30	90	86	4	84	5	100	30	90	84	2
44	5	100	30	90	88	4	85	4	100	50	96	68	2
45	7	100	50	70	30	4	86	5	100	30	90	86	2
46	5	100	30	90	92	4	87	7	100	30	84	58	2
47	5	100	30	90	94	4	88	5	100	30	90	88	2
48	5	100	30	90	96	4	90	7	100	30	70	50	2
49	5	100	30	90	98	4	91	3	100	70	72	52	2
50	7	100	50	84	40	4	92	5	100	30	90	92	2
51	4	100	30	96	68	2	93	7	100	30	84	62	2
52	5	100	30	90	52	2	94	5	100	30	90	94	2
54	5	100	30	90	54	2	95	4	100	50	96	76	2
55	4	100	50	96	44	2	96	5	100	30	90	96	2
56	5	100	30	90	56	2	98	5	100	30	90	98	2
57	4	100	30	96	70	2	99	10	100	30	80	44	2
58	5	100	30	90	58	2	100	7	100	50	84	40	2
60	7	100	30	84	40	2	102	5	100	30	60	68	2

BRICKWORK

Brickwork is estimated by the thousand, and of various thicknesses of wall, runs as follows:

8¼ inch Wall, or 1 Brick in thickness, 14 Bricks per superficial foot

12¾ inch Wall, or 1½ Brick in thickness, 21 Bricks per superficial foot

17 inch Wall, or 2 Brick in thickness, 28 Bricks per superficial foot

21½ inch Wall, or 2½ Brick in thickness, 35 Bricks per superficial foot

An ordinary Brick measures about 8¼ x 4 x 2 inches, which is equal to 66 cubic inches or 26.2 Bricks to a cubic foot. The average weight is 4½ lbs.

ANGLES TO SET INDEX HEAD OF MILLING MACHINE WHEN CUTTING CLUTCHES WITH ANGULAR CUTTERS

No. of Teeth	Angle of Cutter			No. of Teeth	Angle of Cutter		
	60°	70°	80°		60°	70°	80°
5			82° 12'	18	84° 9'	86° 19'	88° 13'
6		77° 52'	84° 9'	19	84° 30'	86° 31'	88° 19'
7	73° 50'	79° 54'	85° 10'	20	84° 46'	86° 42'	88° 24'
8	76° 10'	81° 20'	85° 48'	21	85° 1'	86° 51'	88° 29'
9	77° 52'	82° 23'	86° 19'	22	85° 13'	87° 00'	88° 33'
10	79° 12'	83° 13'	86° 43'	23	85° 27'	87° 8'	88° 37'
11	80° 14'	83° 54'	87° 4'	24	85° 38'	87° 15'	88° 40'
12	81° 6'	84° 24'	87° 18'	25	85° 49'	87° 22'	88° 43'
13	81° 49'	84° 51'	87° 30'	26	85° 59'	87° 28'	88° 46'
14	82° 26'	85° 12'	87° 42'	27	86° 8'	87° 34'	88° 50'
15	82° 57'	85° 34'	87° 51'	28	86° 16'	87° 39'	88° 52'
16	83° 24'	85° 51'	87° 59'	29	86° 24'	87° 44'	88° 54'
17	83° 48'	86° 6'	88° 7'	30	86° 31'	87° 48'	88° 56'

TABLE FOR OBTAINING SET-OVER FOR CUTTING BEVEL GEARS

Ratio of Apex Distance to Width of Face— $\frac{\text{Face}}{\text{Apex}}$

No. of CUTTER	3 1	3¼ 1	3½ 1	3¾ 1	4 1	4¼ 1	4½ 1	4¾ 1	5 1	5½ 1	6 1	7 1	8 1
1	.254	.254	.255	.256	.257	.257	.257	.258	.258	.259	.260	.262	.264
2	.266	.268	.271	.272	.273	.274	.274	.275	.277	.279	.280	.283	.284
3	.266	.268	.271	.273	.275	.278	.280	.282	.283	.286	.287	.290	.292
4	.275	.280	.285	.287	.291	.293	.296	.298	.298	.302	.305	.308	.311
5	.280	.285	.290	.293	.295	.296	.298	.300	.302	.307	.309	.313	.315
6	.311	.318	.323	.328	.330	.334	.337	.340	.343	.348	.352	.356	.362
7	.289	.298	.308	.316	.324	.329	.334	.338	.343	.350	.360	.370	.376
8	.275	.286	.296	.309	.319	.331	.338	.344	.352	.361	.368	.380	.386

TO SHARPEN REAMERS.

HAND REAMERS, when dull through wear, should be stoned first on the face of the flutes then on top of the flutes. The stone should always be held perfectly flat with the face and clearance that the original shape of the flutes may be preserved.

THE NORTON Co. make a Stone which is adapted for the purpose, and gives quicker results than any oil stone. The stone should be kept clean by the use of turpentine.

END CUTTING REAMERS should be first ground on centres with a wheel, and then recleared to insure reaming a hole the same size of Reamer.

Double Compounding of Gearing, or the Use of Six Change Gears. In milling machine work, it is often necessary to obtain longer or more accurate leads than are possible by the use of four change gears. Therefore, the table of gear ratios on the opposite page is given to supplement the ordinary table of leads and permit the quick selection of the other two change gears.

The table of gear ratios is based upon the change gears furnished with Brown & Sharpe Universal Milling Machines. These change gears are as follows: 24 (2), 28, 32, 40, 44, 48, 56, 64, 72, 86, 100. Occasionally in determining the most accurate lead, the proper change gears will necessitate the use of two gears with the same number of teeth. Inasmuch as there are no two gears with the same number of teeth (with the exception of two gears with 24 teeth) it will be necessary to employ the next nearest gear ratio, resulting in a lead very close to the one desired.

Determining the Proper Change Gears to Use when Six Change Gears are Necessary.

Example: To find the proper change gears for gashing a hob with a lead of 167.5".

Referring to the Table of Leads we find that 149.31" is the longest obtainable with four regular change gears. Assuming that a greater degree of accuracy is desired, divide the lead desired (167.5) by the decimal equivalent 4.1667 given in the table on the opposite page and we have 40.1997". The decimal equivalent 4.1667 is taken, as it corresponds to the first gear ratio (100 : 24) given for lead 149.31" in the table of leads. The nearest lead to 40.1997 (which was found above) listed in the table of leads is 40.18". Inasmuch as two 100 tooth gears are required to obtain this lead, it is necessary to try the next gear ratio.

Dividing 167.5 by 3.5833 (the decimal equivalent of the next ratio), we have 46.7446. Referring to the Table of Leads it will be found that the nearest lead is 46.67, for which the change gears are $\frac{64}{24}$ and $\frac{56}{32}$.

Adding the two gears from the Table of Ratios and to the driven gears the constant 10 (which is the constant of the lead of the machine), we have

$$\frac{64 \times 56 \times 86 \times 10}{24 \times 32 \times 24} = 167.2222$$

Continued


Thus the six change gears 64, 24, 56, 32, 86 and 24 will give a lead of 167.2222. The error of lead .2778" or the difference between the lead desired and the lead obtained is for this length of lead practically negligible and is considered near enough for all practical purposes.

TABLE OF RATIOS OF TWO GEARS WITH THEIR DECIMAL EQUIVALENTS

RATIO	DEC. EQUIV.	RATIO	DEC. EQUIV.	RATIO	DEC. EQUIV.
100:24	4.1667	100:72	1.3889	28:40	.7000
86:24	3.5833	44:32	1.3750	44:64	.6875
100:28	3.5714	86:64	1.3438	48:72	.6667
100:32	3.1250	64:48	1.3333	32:48	.6667
86:28	3.0714	32:24	1.3333	56:86	.6512
72:24	3.0000	72:56	1.2857	64:100	.6400
86:32	2.6875	56:44	1.2727	28:44	.6364
64:24	2.6667	40:32	1.2500	40:64	.6250
72:28	2.5714	48:40	1.2000	44:72	.6111
100:40	2.5000	86:72	1.1944	24:40	.6000
56:24	2.3333	56:48	1.1667	28:48	.5833
64:28	2.2857	28:24	1.1667	32:56	.5714
100:44	2.2727	100:86	1.1628	56:100	.5600
72:32	2.2500	64:56	1.1429	48:86	.5581
86:40	2.1500	32:28	1.1429	40:72	.5556
100:48	2.0833	72:64	1.1250	24:44	.5455
48:24	2.0000	44:40	1.1000	44:86	.5116
56:28	2.0000	48:44	1.0909	24:48	.5000
64:32	2.0000	44:48	.9167	28:56	.5000
86:44	1.9545	40:44	.9091	32:64	.5000
44:24	1.8333	64:72	.8889	48:100	.4800
72:40	1.8000	56:64	.8750	40:86	.4651
86:48	1.7917	28:32	.8750	32:72	.4444
100:56	1.7857	86:100	.8600	44:100	.4400
56:32	1.7500	48:56	.8571	28:64	.4375
48:28	1.7143	24:28	.8571	24:56	.4286
40:24	1.6667	72:86	.8372	40:100	.4000
72:44	1.6364	40:48	.8333	28:72	.3889
64:40	1.6000	32:40	.8000	24:64	.3750
44:28	1.5714	44:56	.7857	32:86	.3721
100:64	1.5625	56:72	.7778	24:72	.3333
86:56	1.5357	24:32	.7500	28:86	.3256
48:32	1.5000	48:64	.7500	32:100	.3200
72:48	1.5000	64:86	.7442	28:100	.2800
64:44	1.4545	32:44	.7273	24:86	.2791
40:28	1.4286	72:100	.7200	24:100	.2400
56:40	1.4000	40:56	.7143		

INDEX MOVEMENTS OF SPIRAL HEAD FOR LONGITUDINAL GRADUATING ON A MILLING MACHINE

MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE
.0001275	1	49	.0006377	5	49	.0011479	9	49	.0016447	5	19
.0001330	1	47	.0006410	4	39	.0011574	5	27	.0016581	13	49
.0001454	1	43	.0006465	3	29	.0011628	8	43	.0016666	4	15
.0001524	1	41	.0006579	2	19	.0011718	3	16	.0016768	11	41
.0001603	1	39	.0006649	5	47	.0011824	7	37	.0016892	10	37
.0001689	1	37	.0006757	4	37	.0011905	4	21	.0017045	9	33
.0001894	1	33	.0006944	3	27	.0011968	9	47	.0017241	8	29
.0002016	1	31	.0006944	2	18	.0012096	6	31	.0017288	13	47
.0002155	1	29	.0007268	5	43	.0012195	8	41	.0017361	5	18
.0002315	1	27	.0007353	2	17	.0012500	4	20	.0017442	12	43
.0002551	2	49	.0007576	4	33	.0012500	3	15	.0017628	11	39
.0002660	2	47	.0007622	5	41	.0012755	10	49	.0017857	6	21
.0002717	1	23	.0007653	6	49	.0012820	8	39	.0017857	14	49
.0002907	2	43	.0007813	2	16	.0012930	6	29	.0018144	9	31
.0002976	1	21	.0007979	6	47	.0013081	9	43	.0018292	12	41
.0003049	2	41	.0008012	5	39	.0013158	4	19	.0018382	5	17
.0003125	1	20	.0008064	4	31	.0013257	7	33	.0018518	8	27
.0003205	2	39	.0008152	3	23	.0013298	10	47	.0018581	11	37
.0003289	1	19	.0008333	2	15	.0013513	8	37	.0018617	14	47
.0003378	2	37	.0008446	5	37	.0013587	5	23	.001875	6	20
.0003472	1	18	.0008621	4	29	.0013722	9	41	.0018896	13	43
.0003676	1	17	.0008721	6	43	.0013888	6	27	.0018939	10	33
.0003788	2	33	.0008929	7	49	.0013888	4	18	.0019021	7	23
.0003826	3	49	.0008929	3	21	.0014031	11	49	.0019132	15	49
.0003906	1	16	.0009146	6	41	.0014113	7	31	.0019231	12	39
.0003989	3	47	.0009259	4	27	.0014422	9	39	.0019396	9	29
.0004032	2	31	.0009308	7	47	.0014535	10	43	.0019532	5	16
.0004167	1	15	.0009375	3	20	.0014628	11	47	.0019737	6	19
.0004310	2	29	.0009469	5	33	.0014706	4	17	.0019818	13	41
.0004361	3	43	.0009616	6	39	.0014881	5	21	.0019947	15	47
.0004573	3	41	.0009869	3	19	.0015086	7	29	.0020161	10	31
.0004630	2	27	.0010081	5	31	.0015152	8	33	.0020271	12	37
.0004808	3	39	.0010136	6	37	.0015202	9	37	.002035	14	43
.0005068	3	37	.0010174	7	43	.0015244	10	41	.0020485	16	49
.0005102	4	49	.0010204	8	49	.0015306	12	49	.0020833	13	39
.0005319	4	47	.0010417	3	18	.0015625	5	20	.0020833	5	15
.0005435	2	23	.0010638	8	47	.0015625	4	16	.0020833	11	33
.0005682	3	33	.0010671	7	41	.0015957	12	47	.0020833	9	27
.0005814	4	43	.0010776	5	29	.0015989	11	43	.0020833	7	21
.0005952	2	21	.0010869	4	23	.0016026	10	39	.0020833	6	18
.0006048	3	31	.0011029	3	17	.0016128	8	31	.0021277	16	47
.0006098	4	41	.0011218	7	39	.0016204	7	27	.0021342	14	41
.0006250	2	20	.0011363	6	33	.0016303	6	23	.0021552	10	29



Measuring the Length of a Shaft with a Firm Joint Caliper

INDEX MOVEMENTS OF SPIRAL HEAD FOR LONGITUDINAL GRADUATING ON A MILLING MACHINE

MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE
.0021682	17	49	.0026785	9	21	.0032014	21	41	.003699	29	49
.0021738	8	23	.0026785	21	49	.003205	20	39	.0037038	16	27
.0021802	15	43	.0027028	16	37	.0032095	19	37	.0037163	22	37
.0021875	7	20	.0027174	10	23	.0032197	17	33	.0037234	28	47
.002196	13	37	.0027243	17	39	.0032257	16	31	.003750	12	20
.0022059	6	17	.0027344	7	16	.0032327	15	29	.003750	9	15
.0022176	11	31	.002744	18	41	.0032408	14	27	.0037793	26	43
.0022436	14	39	.0027618	19	43	.0032607	12	23	.0037878	20	33
.0022607	17	47	.0027777	8	18	.0032738	11	21	.0038043	14	23
.0022728	12	33	.0027777	12	27	.0032895	10	19	.0038112	25	41
.0022866	15	41	.0027925	21	47	.0033088	9	17	.0038195	11	18
.0022959	18	49	.0028017	13	29	.0033164	26	49	.0038265	30	49
.0023027	7	19	.002806	22	49	.0033245	25	47	.0038305	19	31
.0023148	10	27	.0028125	9	20	.0033333	8	15	.003846	24	39
.0023257	16	43	.0028225	14	31	.0033431	23	43	.0038564	29	47
.0023438	6	16	.0028409	15	33	.0033538	22	41	.0038692	13	21
.0023649	14	37	.0028717	17	37	.0033654	21	39	.0038794	18	29
.0023706	11	29	.0028846	18	39	.0033784	20	37	.0038853	23	37
.0023809	8	21	.0028963	19	41	.0034091	18	33	.0039063	10	16
.0023937	18	47	.002907	20	43	.0034273	17	31	.0039246	27	43
.0024038	15	39	.0029167	7	15	.0034375	11	20	.0039352	17	27
.0024192	12	31	.0029256	22	47	.0034439	27	49	.0039475	12	19
.0024235	19	49	.0029337	23	49	.0034482	16	29	.003954	31	49
.0024306	7	18	.0029412	8	17	.0034574	26	47	.0039636	26	41
.002439	16	41	.0029605	9	19	.0034722	10	18	.0039773	21	33
.0024455	9	23	.0029762	10	21	.0034722	15	27	.0039894	30	47
.0024622	13	33	.002989	11	23	.0034885	24	43	.0040064	25	39
.002471	17	43	.0030094	13	27	.0035063	23	41	.0040322	20	31
.00250	8	20	.0030172	14	29	.0035156	9	16	.0040443	11	17
.00250	6	15	.0030241	15	31	.0035255	22	39	.0040541	24	37
.0025266	19	47	.0030303	16	33	.0035325	13	23	.0040625	13	20
.0025339	15	37	.0030406	18	37	.0035474	21	37	.00407	28	43
.0025463	11	27	.0030448	19	39	.0035714	12	21	.0040759	15	23
.002551	20	49	.0030488	20	41	.0035714	28	49	.0040817	32	49
.002564	16	39	.0030524	21	43	.0035904	27	47	.0040948	19	29
.0025736	7	17	.0030586	23	47	.0035984	19	33	.004116	27	41
.0025862	12	29	.0030611	24	49	.0036186	11	19	.0041223	31	47
.0025915	17	41	.003125	9	18	.0036289	18	31	.0041666	22	33
.0026164	18	43	.003125	10	20	.0036339	25	43	.0041666	14	21
.0026209	13	31	.003125	8	16	.0036585	24	41	.0041666	18	27
.0026316	8	19	.0031889	25	49	.0036637	17	29	.0041666	12	18
.0026515	14	33	.0031915	24	47	.0036765	10	17	.0041666	10	15
.0026596	20	47	.0031978	22	43	.0036858	23	39	.0041666	26	39

Formed Threading Tool

A formed threading tool is sometimes used if considerable threading is to be done. Fig. 1 illustrates a good type of formed threading tool. The formed threading tool requires grinding on top only to sharpen, and therefore always remains true to form and correct angle.




Fig. 1. Formed Thread Cutting Tool, Solid Type

INDEX MOVEMENTS OF SPIRAL HEAD **FOR** **LONGITUDINAL GRADUATING ON A MILLING MACHINE**

MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE	MOVEMENT OF TABLE	HOLES	CIRCLE
.0042091	33	49	.0047256	31	41	.0052327	36	43	.0057433	34	37
.0042152	29	43	.0047299	28	37	.0052365	31	37	.0057692	36	39
.0042232	25	37	.0047349	25	33	.0052419	26	31	.0057874	25	27
.0042338	21	31	.0047414	22	29	.0052635	16	19	.0057927	38	41
.0042553	32	47	.004762	16	21	.0052884	33	39	.0058142	40	43
.0042685	28	41	.0047796	13	17	.005303	28	33	.0058187	27	29
.0042765	13	19	.0047873	36	47	.0053125	17	20	.0058336	14	15
.0042971	11	16	.0047968	33	43	.0053194	40	47	.0058466	29	31
.0043104	20	29	.0048074	30	39	.0053242	23	27	.0058512	44	47
.0043268	27	39	.0048384	24	31	.0053364	35	41	.0058599	15	16
.0043368	34	49	.004847	38	49	.0053572	42	49	.0058674	46	49
.0043477	16	23	.0048613	14	18	.0053572	18	21	.0058871	31	33
.0043562	23	33	.0048613	21	27	.0053781	37	43	.0058825	16	17
.0043605	30	43	.0048782	32	41	.005388	25	29	.0059027	17	18
.004375	14	20	.0048912	18	23	.0054057	32	37	.0059122	35	37
.0043883	33	47	.0048989	29	37	.005417	13	15	.0059215	18	19
.0043922	26	37	.0049202	37	47	.0054348	20	23	.0059294	37	39
.004398	19	27	.0049244	26	33	.0054434	27	31	.0059375	19	20
.0044119	12	17	.0049345	15	19	.0054486	34	39	.0059455	39	41
.004421	29	41	.004942	34	43	.0054522	41	47	.0059524	20	21
.0044354	22	31	.0049569	23	29	.005469	14	16	.0059598	41	43
.0044643	15	21	.0049677	31	39	.0054848	43	49	.0059782	22	23
.0044643	35	49	.0049745	39	49	.0054878	36	41	.0059841	45	47
.0044871	28	39	.005	16	20	.0054924	29	33	.0059951	47	49
.004506	31	43	.005	12	15	.0055148	15	17	.0060188	26	27
.004514	13	18	.0050308	33	41	.0055238	38	43	.0060346	28	29
.0045213	34	47	.0050402	25	31	.0055555	24	27	.006048	30	31
.0045259	21	29	.0050532	38	47	.0055555	15	18	.0060607	32	33
.0045452	24	33	.0050596	17	21	.0055746	33	37	.0060812	36	37
.004561	27	37	.0050676	30	37	.0055852	42	47	.0060898	38	39
.0045732	30	41	.0050785	13	16	.0055925	17	19	.006098	40	41
.0045835	11	15	.0050876	35	43	.0056035	26	29	.0061052	42	43
.004592	36	49	.0050928	22	27	.0056088	35	39	.0061171	46	47
.0046055	14	19	.0051022	40	49	.0056123	44	49	.0061224	48	49
.0046194	17	23	.0051136	27	33	.005625	18	20	.00625		1
.0046296	20	27	.0051281	32	39	.0056403	37	41			
.0046371	23	31	.0051474	14	17	.005645	28	31			
.0046473	29	39	.0051627	19	23	.0056546	19	21			
.0046512	32	43	.0051721	24	29	.005669	39	43			
.0046543	35	47	.005183	34	41	.0056816	30	33			
.0046875	15	20	.0051861	39	47	.0057065	21	23			
.0046875	12	16	.0052083	15	18	.005718	43	47			
.0047195	37	49	.0052296	41	49	.00574	45	49			

Lubricants for Cutting Tools

Material	Turning	Chucking	Drilling Milling	Reaming	Tapping
Tool Steel	Dry or Oil	Oil or Soda Water	Oil	Lard Oil	Oil
Soft Steel	Dry or Soda Water	Soda Water	Oil or Soda Water	Lard Oil	Oil
Wrought Iron	Dry or Soda Water	Soda Water	Oil or Soda Water	Lard Oil	Oil
Cast Iron	Dry	Dry	Dry	Dry	Oil
Brass	Dry	Dry	Dry	Dry	Oil
Copper	Dry	Oil	Oil	Mixture	Oil
Babbitt	Dry	Dry	Dry	Dry	Oil
Glass			Turpentine or	Kerosene	

Mixture is $\frac{1}{2}$ Crude Petroleum, $\frac{1}{2}$ Lard Oil. When two lubricants are mentioned the first is preferable.

A Plate of Free Hand Lettering

A B C D E F G H I J K L M N O P

Q R S T U V

W X

1 2 3 4 5 6 7 8 9 0 Y Z


a b c d e f g h i j k l m n o p

q r s t u v w x y z


THE ART OF LETTERING MAY
BE ACQUIRED BY PRACTICE.

*Utility is the first requisite of a
working drawing. Care and judgement
must be exercised at all times.*


— MATERIALS IN SECTION —




Cast Iron



Wrought Iron




Steel



Brass or Bronze




Copper



Babbitt or Lead



Insulation



Glass

— ALPHABET OF LINES —



Visible outline



Invisible outline




Center line



Extension line



Cross-hatching line



Dimension line



Cutting plane



Alternate position



Line of motion



Broken metal




Broken wood

Area and Volume of Spherical Segments

Where r=radius
c=length of cord
h=height

Area of Curved Surface = $2 \pi r h = \frac{\pi}{4} (4h^2 + c^2)$

Volume of Segment = $\frac{\pi}{3} h^2 (3r - h) = \frac{\pi}{24} h (3c^2 + 4h^2)$



Capacity of Cylindrical Tanks and Cisterns

1 gallon = 231 cubic inches = 0.13368 cubic foot


1 cubic foot = 7.4805 gallons

Capacities given in U.S. gallons for 1 foot in depth

Diam-eter, ft. in.	Area, square feet	Gallons, 1 foot depth	Diam-eter, ft. in.	Area, square feet	Gallons, 1 foot depth	Diam-eter, ft. in.	Area, square feet	Gallons, 1 foot depth
1 0	.785	5.87	5 8	25.22	188.66	19 0	283.53	2120.9
1 1	.922	6.89	5 9	25.97	194.25	19 3	291.04	2177.1
1 2	1.069	8.00	5 10	26.73	199.92	19 6	298.65	2234.0
1 3	1.227	9.18	5 11	27.49	205.67	19 9	306.35	2291.7
1 4	1.396	10.44	6 0	28.27	211.51	20 0	314.16	2350.1
1 5	1.576	11.79	6 3	30.68	229.50	20 3	322.06	2409.2
1 6	1.767	13.22	6 6	33.18	248.23	20 6	330.06	2469.1
1 7	1.969	14.73	6 9	35.78	267.69	20 9	338.16	2529.6
1 8	2.182	16.32	7 0	38.48	287.88	21 0	346.36	2591.0
1 9	2.405	17.99	7 3	41.28	308.81	21 3	354.66	2653.0
1 10	2.640	19.75	7 6	44.18	330.48	21 6	363.05	2715.8
1 11	2.885	21.58	7 9	47.17	352.88	21 9	371.54	2779.3
2 0	3.142	23.50	8 0	50.27	376.01	22 0	380.13	2843.6
2 1	3.409	25.50	8 3	53.46	399.88	22 3	388.82	2908.6
2 2	3.687	27.58	8 6	56.75	424.48	22 6	397.61	2974.3
2 3	3.976	29.74	8 9	60.13	449.82	22 9	406.49	3040.8
2 4	4.276	31.99	9 0	63.62	475.89	23 0	415.48	3108.0
2 5	4.587	34.31	9 3	67.20	502.70	23 3	424.56	3175.9
2 6	4.909	36.72	9 6	70.88	530.24	23 6	433.74	3244.0
2 7	5.241	39.21	9 9	74.66	558.51	23 9	443.01	3314.6
2 8	5.585	41.78	10 0	78.54	587.52	24 0	452.39	3384.1
2 9	5.940	44.43	10 3	82.52	617.26	24 3	461.86	3455.0
2 10	6.305	47.16	10 6	86.59	647.74	24 6	471.44	3526.6
2 11	6.681	49.98	10 9	90.76	678.95	24 9	481.11	3598.9
3 0	7.069	52.88	11 0	95.03	710.90	25 0	490.87	3672.0
3 1	7.467	55.86	11 3	99.40	743.58	25 3	500.74	3745.8
3 2	7.876	58.92	11 6	103.87	776.99	25 6	510.71	3820.3
3 3	8.296	62.06	11 9	108.43	811.14	25 9	520.77	3895.6
3 4	8.727	65.28	12 0	113.10	846.03	26 0	530.93	3971.6
3 5	9.168	68.58	12 3	117.86	881.65	26 3	541.19	4048.4
3 6	9.621	71.97	12 6	122.72	918.00	26 6	551.55	4125.9
3 7	10.085	75.44	12 9	127.68	955.09	26 9	562.00	4204.1
3 8	10.559	78.99	13 0	132.73	992.91	27 0	572.56	4283.0
3 9	11.045	82.62	13 3	137.89	1031.5	27 3	583.21	4362.7
3 10	11.541	86.33	13 6	143.14	1070.8	27 6	593.96	4443.1
3 11	12.048	90.13	13 9	148.49	1110.8	27 9	604.81	4524.3
4 0	12.566	94.00	14 0	153.94	1151.5	28 0	615.75	4606.2
4 1	13.095	97.96	14 3	159.48	1193.0	28 3	626.80	4688.8
4 2	13.635	102.00	14 6	165.13	1235.3	28 6	637.94	4772.1
4 3	14.186	106.12	14 9	170.87	1278.2	28 9	649.18	4856.2
4 4	14.748	110.32	15 0	176.71	1321.9	29 0	660.52	4941.0
4 5	15.321	114.61	15 3	182.65	1366.4	29 3	671.96	5026.6
4 6	15.90	118.97	15 6	188.69	1411.5	29 6	683.49	5112.9
4 7	16.50	123.42	15 9	194.83	1457.4	29 9	695.13	5199.9
4 8	17.10	127.95	16 0	201.06	1504.1	30 0	706.86	5287.7
4 9	17.72	132.56	16 3	207.39	1551.4	30 3	718.69	5376.2
4 10	18.35	137.25	16 6	213.82	1599.5	30 6	730.62	5465.4
4 11	18.99	142.02	16 9	220.35	1648.4	30 9	742.64	5555.4
5 0	19.63	146.88	17 0	226.98	1697.9	31 0	754.77	5646.1
5 1	20.29	151.82	17 3	233.71	1748.2	31 3	766.99	5737.5
5 2	20.97	156.83	17 6	240.53	1799.3	31 6	779.31	5829.7
5 3	21.65	161.93	17 9	247.45	1851.1	31 9	791.73	5922.6
5 4	22.34	167.12	18 0	254.47	1903.6	32 0	804.25	6016.2
5 5	23.04	172.38	18 3	261.59	1956.8	32 3	816.86	6110.6
5 6	23.76	177.72	18 6	268.80	2010.8	32 6	829.58	6205.7
5 7	24.48	183.15	18 9	276.12	2065.5	32 9	842.39	6301.5

Rectangular Tanks

To find the capacity of rectangular tanks multiply the length by the width by the depth (all in inches) and divide the result by 231. The answer is the capacity in gallons.



Single-Bladed "Kennamill" Cutter

At a time when manufacturers of standard milling cutters are unable to keep up with the demand, McKenna Metals Co., 381 Lloyd Ave., Latrobe, Pa., announces a method by which simple facing cutter heads may be made in almost any shop. Due to its high speed of cutting, this single-bladed "Kennamill," employing Kennametal tools, will often work more efficiently than a standard cutter requiring many high speed steel blades.

Designed with a large negative spiral angle of 35° to 55° and positive hook of 15° to 25° , this cutter mills steel efficiently only because Kennametal does not "gall" or permit the adherence of steel chips to the hard, strong, non-galling tool tip which "skids" the steel chip off

smoothly at these angles.

For roughing, with cuts up to $\frac{3}{8}$ " deep, a 35° negative helical angle and 15° positive hook on a 12" diameter cutter head has been found to work efficiently. For light finishing cuts a negative helical of 55° with 20° positive hook angle is most efficient. The hook angle should be less on a smaller diameter head.

Kennametal cutters should be run to give 300 to 600 ft. per min. peripheral speed, with a table feed of .008" per revolution, depending on the material being machined. A 6" dia. head gives about 3" per min. table feed at 380 r.p.m. (600 ft./min. cutting speed.) Clearances should be kept to a minimum and only a slight radius used. No coolant should be used as it is impossible to keep the cutting point flooded at the speeds employed.

The Kennametal-tipped blades can be removed from the cutter heads and reground quickly, an important advantage over standard cutters, which require removal of the entire head from the machine, with consequent loss of time.

The manufacturer will be pleased to furnish additional information upon request.

Cam Cutting

Although, in most factories, the operations discussed in this chapter are looked upon as toolroom jobs, there are numerous concerns in which cam and gear cutting are strictly manufacturing propositions. Many screw machine shops lay out and make their own cams — using a milling machine for the purpose — in such quantities that a machine may be employed almost exclusively for cam cutting. Other shops have to cut all sorts of gears — spur, spiral, bevel, etc., — but in such small lots that the installation of sufficient gear cutting machinery to fill their requirements in variety would call for a prohibitive outlay of capital, and would burden them with a number of machines that could be kept busy only a fraction of the time. In this type of

(Continued on top of next page.)

plant it is not unusual to see one or more milling machines engaged primarily upon gear cutting.

Gratuating is more likely to be confined to an occasional toolroom or experimental job, but, since it involves the use of the Universal Index Centers in conjunction with table movements, as do so many gear and cam cutting operations, we have included it in this chapter.

Face, peripheral and cylindrical cams of all ordinary sizes can be cut upon a milling machine, and a far more satisfactory job can be obtained than is possible by drilling around the outline on a cam blank, breaking it off and then milling or filing to a line.

When it is required to cut several cams of the same outline at frequent intervals, it is an advantage to add the Cam Cutting Attachment, illustrated and described in Chapter II, to the equipment of the machine. The formers that are required to produce the different cams can be preserved, and it is then only a matter of a few minutes' time to set up the machine to cut any number of cams for which a former is at hand.

Another method that is often followed, in cutting peripheral cams, especially those for use on automatic screw machines, is that of using the universal spiral index head and a vertical milling attachment.




Fig. 1




Fig. 2

Cam Cutting Attachment.

The headstock is geared to the table feed screw, the same as in cutting ordinary spirals, and the cam blank is fastened to the end of the index spindle. An end mill is used in the vertical milling attachment, which is set in each case to mill the periphery of the cam at right-angles to its sides, or, in

Continued on next page

other words, the axes of the headstock spindle and attachment spindle must always be parallel to mill cams according to this method. The cutting is done by the teeth on the periphery of the end mill. The principle of this method is as follows: Suppose the headstock is elevated to 90° , or at exact right angles to the surface of the table (see Fig. 1), and is geared for any given lead. It is then apparent that, as the table advances and the blank is turned, the distance between the axes of the index spindle and attachment spindle becomes less. In other words, the cut becomes deeper and the radius of the cam is shortened, producing a spiral lobe, the lead of which is the same as that for which the machine is geared.

Now, suppose the same gearing is retained and the headstock is set at zero, or parallel to the surface of the table (see Fig. 2). It is apparent, also, that the axes of the index spindle and attachment spindle are parallel to one another. Therefore, as the table advances, and the blank is turned, the distance between the axes of the index spindle and attachment spindle remains the same. As a result, the periphery of the blank, if milled, is concentric or the lead is 0.

If, then, the headstock is elevated to any angle between zero and 90° (see Fig. 3), the amount of lead given to the cam will be between that for which the machine is geared and 0. Hence it is clear that cams with a very large range of different leads can be obtained with one set of change gears, and the problem of milling the lobes of a cam is reduced to a question of finding the angle at which to set the head to obtain any given lead.

In order to illustrate the method of obtaining the correct angle, drawings of two cams to be milled, and data connected with same, are given in Figs. 4 and 5.

It is first necessary to know the lead of the lobes of a cam, that is, the amount of rise of each lobe if continued the full circumference of the cam. This can be obtained from the drawings as follows: For cams where the face is divided into hundredths, as those shown: multiply 100 by the rise of the lobe in inches and divide by the number of hundredths of circumference occupied by the lobe. For cams that are figured in degrees of circumference: multiply 360 by the rise of the lobe in inches and





Fig. 3

Continued on next page



divide by the number of degrees of circumference occupied by the lobe. Taking Fig. 4 for example, we have a cam of one lobe which extends through 91 hundredths of the circumference, and has a rise .178". Then $\frac{100 \times .178''}{91} = .1956$ lead of lobe, or .196", which is near enough for all practical purposes.

Fig. 4 As a .196" lead is much less than .67", which is the shortest lead regularly obtainable on the milling machine.

Divide the given lead of the cam lobe by a lead obtainable on the machine, and the result is the sine of the angle at which to set the head.

Continuing the calculation for the lobe of the cam in Fig. 4, we therefore have: $\frac{.196''}{.67''} = .29253$.

Hence, .29253 is the sine of the correct angle. Turning to a table of natural sines and cosines, we find that .29253 is very near .29265, which is the sine of an angle of 17° and 1'. As the headstock is not graduated closer than quarter degrees, it will be satisfactory to elevate the head just a hair over 17°; then, with the gearing for a lead of .67", a cam with a lead of .196" will be obtained.

The minute errors between the actual lead .1956" and .196", and in the sines and angles of this calculation can be safely ignored, as it is not possible in practice to work very much closer than we have outlined.




Fig. 5

The portion of the periphery of the cam from 91 hundredths to zero represents a clearance of the cutting tool prior to the beginning of the throw. It is usually milled to a line, or drilled, broken out, and filed.

In Fig. 5, we have a cam with two lobes, one, A, having a rise of 2.493" in 47 hundredths, and the other, B, having a rise of 2.443" in 29 hundredths. On

cams such as this, where it is necessary to remove considerable stock, it is usually the practice to first outline the approximate shape of the lobes on the blank and drill and break off the surplus stock.

Following the same method of figuring to find the lead of the lobes on this cam, we have: $\frac{100 \times 2.493''}{47} = 5.304''$ lead for lobe A, and $\frac{100 \times 2.443''}{29} = 8.424''$ lead for lobe B.

Where there are two or more lobes on a cam, the machine is geared for a lead slightly longer than the longest one required, which in this case is 8.424'', then the other lobes are milled without changing the gears. Referring to the Table of Leads, we find a lead of 8.437'', which is slightly larger than 8.424''. This gearing is, therefore, accepted, and it is required to find the sine of the angle at which to set the head for lobe B.

$\frac{8.424}{8.437} = .99846$ sine of angle at which to set head. Looking at a table of sines and cosines, .99846 is found to be the sine of an angle of 86° and 49'. The head is, therefore, set at a trifle over 86 3/4°.


When lobe B has been milled, the head is set for lobe A.

$\frac{5.304}{8.437} = .62865$ sine of an angle at which to set head. Referring again to a table of sines and cosines, we find that .62865 is very near to .62864, which is the sine of an angle of 38° and 57'. The head is, therefore, set slightly under 39° for this lobe.

The other portions of the periphery of this cam are formed up either by filing to a line before the blank is put on the milling machine or by milling to the line after the lobes have been formed.

Whenever possible, the job should be set up so that the end mill will cut on the lower side of the blank, as this brings the mill and table nearer together and makes the job more rigid. It also prevents chips from accumulating, and enables the operator to better see any lines that may be laid out on the face of the cam.


When the lead of the machine is over 2'' the automatic feed can be used, but when the lead is less than 2'' the job should be fed by hand, with the index crank, unless a short lead attachment is used.



Milling a Cam, Using Universal Spiral Index Head and Vertical Milling Attachment

The cam blank is mounted on an expansion arbor inserted in the taper hole of the headstock spindle.


Suitable change gears are selected to give the approximate lead and the headstock is elevated to obtain the exact lead; the vertical attachment is then set to bring the end mill parallel with the axis of the cam. Where such short leads as this are being milled, there is great stress brought upon the headstock gearing in attempting to use the automatic feed, unless a short lead attachment, such as is used here, is available.



Cutting a Cylindrical Cam, Using Cam Milling Attachment

For cutting a cylindrical cam, the attachment head and footstock are bolted to the bed parallel to the table and the cam blank is supported on an arbor mounted on the attachment centers. The attachment centers are placed at the same height as the axis of the spindle. A spiral end mill is used for this operation and the necessary movement to feed the work is obtained from the attachment, the table remaining clamped in one position.


The former, itself a cam, is usually made with the aid of the universal spiral index head, in the manner previously described.



Cutting a Peripheral Cam, Using the Cam Milling Attachment

In this operation the head of the attachment is bolted to the bed at right angles to the table and the cam blank is fastened to the attachment spindle by means of a bolt. A face cam would be milled in the same manner. The necessary rotative movement is obtained by hand feed, and the longitudinal movement to give the proper lead and shape to the cam is produced by the cam former and the mechanism of the attachment, as described.

A spiral end mill is used. The machine table remains clamped in one position.



Milling Heart Shaped Cam

The cam shown in place on the cam milling attachment in this photograph required a method of machining that is a little out of the ordinary, because of the abrupt rise and drop of the lobes.

To overcome the stresses caused by these steep lobes, a former was made in the same shape as the required cam, but with its center of rotation much closer to its actual center than in the case of the work itself. The work was then mounted upon a special holder with a stud to fit the hole in the work, offset the proper distance. By this means, such heart shaped cams can be milled more easily and accurately.

Cam Milling Attachment

The Cam Milling Attachment, shown in Fig. 1, is used for cutting either Face, Peripheral or Cylindrical Cams from a flat former. The former is made from a disk about $\frac{1}{2}$ inch thick, on which the required outline is laid out. The disk is machined or filed to the required shape.

The table of the machine remains clamped in one position during cutting, and the necessary rotative and longitudinal movements are contained in the mechanism itself. The rotative movement is obtained by a worm driving a wormwheel fixed to the spindle of the attachment. The former is secured to the face of the wormwheel, and




Fig. 1. Cam Milling Attachment

as the wheel revolves, the former depresses a sliding rack that in turn drives a pinion geared to another rack in the sliding bed of the attachment, thus giving the necessary longitudinal movement. In the illustration, the former is shown in position on the face of the wormwheel.

The attachment is sometimes driven automatically by means of a round belt leading from a small jackshaft to a three-step cone pulley fastened on the end of the worm shaft. The pulley is clutched to the worm so that either hand or automatic feed may be used by the simple movement of a lever.

In sharpening Brown & Sharpe Spiral End Mills and Two Lipped Spiral End Mills the double angle lands with which these mills are furnished should be preserved. These double angle lands permit the correct cutting clearance to be maintained with a strong tooth shape.

Fig. 1





Fig. 2



In sharpening End Mills having end teeth as shown in the illustrations, either a straight wheel can be used as shown in Fig. 1 or a cup wheel as shown in Fig. 2. Wheels should be set to give approximately 4° cutting clearance and sufficient concavity to make the points of the teeth higher than any other part. Should repeated sharpenings eliminate the center hole, the efficiency of the end mill is not impaired.

BELTING SECTION

The driving power of a single belt is usually taken as one horse-power for every inch of width at a speed of 600 to 700 feet per minute, from 400 to 500 feet per minute for a double belt.

To find the length of belt wanted. Add the diameter of both pulleys together, divide by 2, and multiply quotient by $3\frac{1}{4}$; add this product to twice the distance in inches between the center of shafts, and the final sum will be the length required. Example. Diameter of large pulley 24 in. + 12 diameter of small pulley = $36 \div 2 = 18 \times 3\frac{1}{4} = 58\frac{1}{2} + 216$ twice distance between shafts = $274\frac{1}{2}$ inches, length required.

To find width of belt required for a given horse-power. Multiply the horse-power by the constant 2,750, then multiply the diameter by driven pulley by the number of revolutions and divide the first product by the latter, the quotient will be the width of belt required. Example. Horse-power 28 \times constant 2,750 = 77,000; diameter of pulley 36 in. \times revolution 200 = 7,200; $77,000 \div 7,200 = 10$ inches, width required.

To find the horse-power which a belt will transmit. Multiply the width of belt by diameter of driven pulley in inches, multiply this product by revolutions per minute, then divide final product by constant 2,750, the quotient will be the horse-power. Example. Belt 10 in. \times 36 diameter of pulley = 360 \times 200 revolutions = 72,000 \div 2,750 constant = 26.5 horse-power required.

The horse-power and width of belt given, find the diameter of driven pulley required. Multiply the horse-power by constant 2,750, now multiply revolutions of pulley by width of belt, then divide the first product by the latter, the quotient will be the diameter wanted. Example. Horse-power 28 \times 2,750 = 77,000; revolutions 200 \times 10 = 2,000; $77,000 \div 2,000 = 38.5$, diameter wanted.

To find the size of driving pulley, multiply the diameter driven by revolutions it should make, and divide the product by revolutions of driver. Example. Diameter of driven, 12 inches; revolutions, 240; revolutions of driver, 160 then $12 \times 240 = 2,880 \div 160 = 18$, diameter of driver wanted.

To find the size of driven pulley, multiply diameter of driver by its revolutions, and divide the product by revolutions of driven. Example. Diameter of driver, 18; revolutions, 160; revolutions of driven, 240: then $18 \times 160 = 2,880 \div 240 = 12$, revolutions of driven wanted.

To find the number of revolutions of driven, multiply diameter of driver by its revolutions, and divide product by diameter of driven. Example. Diameter of driver, 18; revolutions, 160; diameter of driven, 12 inches; then $18 \times 160 = 2,880 \div 12 = 240$, revolutions of driven wanted.

To find the horse-power of a driving pulley, multiply the circumference of pulley by the revolutions, and this product by width of belt, and divide final product by 600. Example. Circumference of pulley, 56.55; revolutions, 160; width of belt, 6 inches; then $56.55 \times 160 = 9,048 \times 6 = 54,288 \div 600 = 9.04$, horse-power of pulley wanted.

To find the length of belt when closely rolled, add the diameter of the roll in inches to the diameter of the eye, multiply this by the number of turns. The result multiplied by the decimal, .1309, will give the length of roll in feet.

BELT CEMENT

For leather belts, take of common glue and American isinglass equal parts; place them in a glue pot and add water sufficient to cover the whole. Let it soak 10 hours, then bring the whole to a boiling heat, and add pure tannin until the whole appears like the white of an egg. Apply warm. Buff the grain of the leather where it is to be cemented, rub the joint surfaces solidly together, let it dry for a few hours, and the belt will be ready for use. For rubber belts take 16 parts of gutta percha, 4 parts india rubber, 2 parts common calker's pitch, 1 part linseed oil; melt together and use hot. This cement can also be used for leather.

Keep your belt speeds up.

Within reasonable limits and ignoring the effect of centrifugal force, doubling belt speed doubles the horsepower a given belt will transmit, or cuts in half the stress in the belt for the same horsepower. So keep belt speeds up — to keep belt costs down.

Speeds for engine or lineshaft drive belts.

To figure a belt drive from an engine or lineshaft or for any purpose other than an electric motor drive, again make the diameter of your driving pulley to give as high belt speed as is possible — from 3,500 to 4,500 F.P.M. This is the safe way to get a drive that will perform well — and *be cheaper*, because of the narrower belt and pulleys that can be used.


What belt thickness to use.

Having determined suitable motor or driving pulley for your job and knowing the belt speed, your next step is to determine *thickness of belt* to use. The diameter of the small pulley in the drive determines the belt thickness. This is important. The smaller the diameter of the pulley around which the belt bends, the quicker the belt will wear out. So belt thickness depends on the diameter of the small pulley.

Referring to table below, if the small pulley is 4" diameter then a *medium single* belt is recommended. If the small pulley is 8" diameter a *medium double* belt is recommended. But if, for the 8" diameter pulley, the belt finally figures more than 8 inches in width, then, to better conform to the wider and higher pulley crown, a *light double* is recommended.

ALWAYS USE BELT THICKNESS THAT IS CORRECT FOR PULLEY DIAMETER

	SINGLE PLY		DOUBLE PLY			TRIPLE PLY	
	Med.	Heavy	Light	Med.	Heavy	Med.	Heavy
	These are the minimum recommended pulley diameters for the above thickness belts						
Belts Under 8" Wide	3"	5"	6"	8"	12"		
Belts 8" and Wider			8"	10"	14"	24"	30"

BELTING—V-Shaped V-BELT DRIVES

ARC OF CONTACT: Amount of wrap or measure of belt contact with pulley measured in degrees. See sketch.

CENTER DISTANCE: Distance between axis of pulley or sheave shafts, see sketch. The best center distance is one that approximately equals the diameter of the large sheave. Do not use a center distance greater than the sum of the diameters of both sheaves unless necessary.

COMBINATION STOCK DRIVE: A drive incorporating a Light Duty sheave and Standard sheave in combination with a standard length belt.

FIXED CENTER DRIVE: A drive where no take-up for belt stretch is provided. Avoid such a design if possible.

R. P. M.: Number of Revolutions Per Minute made by sheave. Driving sheave R. P. M. can usually be obtained from name plate on prime movers, motors or engines. The most accurate information can best be obtained by use of a tachometer.

SHEAVE: Pulley with outside surface or periphery grooved to accommodate V-shaped belts.

(a) *Pitch Diameter (P. D.)*—Approximate location of neutral belt axis with reference to sheave groove where V-belt is in contact with sheave. *Belt speeds are figured on pitch diameters.*

(b) *Outside Diameter O.D.* —To get O.D. of sheave when P.D. is given see following table.

Belt Cross Section—	SHEAVES		BELTS		V-Flat Drive
	Recommended Range of Small Sheave Diameters	To Obtain O.D. of Sheaves Add to Pitch Diameter	To Obtain Pitch Length	To Obtain Outside Length	Add to O.D. of Flat Pulley to Obtain P.D.
			Add to Inside Circum.		
FHP. { 0000—13/32" x 7/32" 1000—33/64" x 19/64" 2000—21/32" x 23/64"	1.5"— 2.5"	.14"	.69"	1.38"	7/32"
	2.0"— 3.0"	.19"	.93"	1.86"	19/64"
	3.0"— 4.0"	.29"	1.13"	2.26"	23/64"
A—½" x 11/32"	3.0"— 5.0"	⅜"	.98"	2.16"	11/32"
B—21/32" x 7/16"	5.4"— 7.5"	½"	1.18"	2.75"	7/16"
C—⅞" x 17/32"	9.0"—12.0"	¾"	1.57"	3.38"	17/32"
D—1¼" x ¾"	13.0"—20.0"	⅞"	1.96"	4.71"	¾"
E—1½" x 1"	21.6"—28.0"	1⅞"	2.75"	6.28"	1.0"

Continued on next page

(c) *Bushing*—Metallic lining used in hub of sheave. Inasmuch as the bushing can be bored to various diameters to fit shafting, most sheaves are manufactured to accommodate interchangeable bushings.

(d) *Hub*—Central part of sheave.

(e) *Bore*—The interior diameter of the hole in a hub or bushing.

(f) *Keyway or Keyscat*—Corresponding grooves in hub, bushing and shaft to accommodate key for locking bushing and hub in position to prevent rotation.


SPEED RATIO: Relation between speed of Driver (Dr.) Sheave and Driven (Dn.) Sheave. Can be obtained by dividing R.P.M. of smaller sheave by R.P.M. of larger sheave or by dividing pitch daimeter of larger sheave by pitch diameter of smaller sheave.

GLOSSARY OF TERMS—V-BELT DRIVES

STANDARD DRIVE: A drive incorporating standard size sheaves and standard length belts. Where stock sheaves are called for, the drive is termed a STANDARD STOCK DRIVE.

V-FLAT DRIVE: Name given drive where one pulley (usually the Driver) is V-grooved and the other pulley is a regular flat face pulley.

V-V DRIVE: This is a regular V-Belt drive and merely indicates that both pulleys are V-grooved.



*PITCH LINE OF BELT—Neutral axis of belt. Exact location depends upon several factors but for ordinary calculations can be considered as being half-way between top and base of belt.

PITCH LENGTH OF BELT—Length of belt measured along *Pitch Line*.

Horsepower	MOTOR SPEED—RPM					
	1750	1160	870	600	575	435
$\frac{1}{2}$	A*	A*	A
$\frac{3}{4}$	A*	A	A
1	A	A	A
$1\frac{1}{2}$	A	A	A
2	A	A	A
3	A	A	B (or A)
5	B (or A)	B (or A)	B
$7\frac{1}{2}$	B	B	B
10	B	B	B or C
15	B	B or C	C (or B)
20	B or C	C (or B)	C	D	D
25	C (or B)	C	C	D	D
30	C	C	C	D	D
40	C	C or D	C or D	D	D
50	C	C or D	C or D	D	D	E
60	C	C or D	D (or C)	D	D	E
75	C	D (or C)	D	D	D or E	E
100	C	D	D	D or E	E (or D)	E
125	D	D	D or E	E (or D)	E
150	D	D	E (or D)	E	E
200	D	D	E	E	E
250	D	D	E	E	E
300 and above	D	D	E	E	E

(Continued from preceding page)

CENTER DISTANCES: V-Belt Drives permit very short centers. Where no limitation of Minimum Center Distance is involved, a Center Distance equalling or slightly greater than the Large Pulley Diameter will usually give a very satisfactory and economical drive. It is simply necessary to have an Arc of Contact on the Small Pulley of approximately 120 degrees.

RECOMMENDED BELT CROSS-SECTIONS: The various Belt Cross-Sections should normally be used for the Horsepowers outlined in Table B on this page. Naturally, the smaller Cross-Section is used where the pulley diameters are limited.

MINIMUM PULLEY DIAMETERS: The Minimum Pulley Diameters shown in Table "A" will be found satisfactory for normal motor speeds. For slower speeds, these diameters should be increased if possible. Otherwise, due to the low belt velocity, more belts will be required. The Absolute Minimum Diameters may be used where the particular limitations of the drive make their use imperative. They should not be used, however, on V-Flat Drives or on applications subject to severe operating conditions, such as high starting torques, heavy peak loads, etc.

PITCH DIAMETERS: Pitch Diameters are determined by subtracting the amounts shown in Table "B" from the Outside Diameters. The amount to be subtracted depends on the Belt Cross-Section being used.

Cross-Section	TABLE "A" Minimum Pulley Diameters—Inches		TABLE "B" Outside and Pitch Diameters of Pulleys—Inches	
	Minimum Outside Diameters Recommended for Motor Pulleys	Absolute Minimum Outside Diameters or Motor Pulleys	Deduct from Outside Diameter of V-Pulley to Obtain Pitch Diameter	On V-Flat Drives, Add to Outside Diameter of Flat Pulley to Obtain Pitch Diameter
A	3	2½	*¾	.25
B	5	4	*1½	.35
C	8	7	¾	.45
D	11	10	7⁄8	.65
E	17	15	1½	.95

OVERLOADS OR PEAK LOADS: *Average Load Conditions* are those where the starting torque is equal to or less than full load torque and frequent peak loads are not encountered. For conditions more severe than average, *the number of belts should be increased.*

Where the Starting Torques or Peak Loads are greater than 100 per cent, but not over 150 per cent, of Full Load Values, use approximately 25 per cent more Belts.

Continued on next page

Where the Starting Torques or Peak Loads are greater than 150 per cent, but not over 200 per cent, of Full Load Values, use approximately 40 per cent more Belts.

Reversing Applications, such as cranes, hoists, etc., require approximately 25 per cent more Belts.

Textile Machines, such as Spinning Frames, usually require 40-50 per cent more Belts.

For Linestart Motor Applications, where the motor is started on full voltage, use approximately 20 per cent more Belts.

It is impossible to list all of the applications in the various industries that will require an increase in the number of belts, but, as a general rule, the foregoing corrections will apply.

The use of an increased number of belts under severe conditions, such as outlined above, will prevent slippage when starting or under peak loads, and will materially increase the life of the belts.

SURFACE SPEEDS IN FEET PER MINUTE in Relation to RPM

$$\text{Surface speed} = \text{diameter} \times \pi \times \text{RPM} \div 12$$

Diam.	Revolutions per minute									
	10	11	12	13	14	15	16	17	18	19
$\frac{1}{2}$ "	1.3000	1.4300	1.5708	1.7017	1.8326	1.9635	2.0944	2.2251	2.3562	2.4871
$\frac{3}{4}$ "	1.9635	2.1508	2.3382	2.5255	2.7128	2.9001	3.0874	3.2747	3.4620	3.6493
1"	2.6180	2.8708	3.1236	3.3764	3.6292	3.8820	4.1348	4.3876	4.6404	4.8932
$1\frac{1}{2}$ "	3.9270	4.3107	4.7124	5.1051	5.4978	5.8905	6.2832	6.6759	7.0686	7.4613
2"	5.2360	5.7500	6.2640	6.7780	7.2920	7.8060	8.3200	8.8340	9.3480	9.8620
$2\frac{1}{2}$ "	6.5450	7.1905	7.8360	8.4815	9.1270	9.7725	10.4180	11.0635	11.7090	12.3545
3"	7.8540	8.6304	9.4128	10.2002	10.9876	11.7750	12.5624	13.3498	14.1372	14.9246
$3\frac{1}{2}$ "	9.1630	10.0704	10.9957	11.9121	12.8284	13.7447	14.6610	15.5773	16.4936	17.4099
4"	10.4720	11.5192	12.5664	13.6136	14.6608	15.7080	16.7552	17.8024	18.8496	19.8968
$4\frac{1}{2}$ "	11.7810	12.9591	14.1372	15.3153	16.4934	17.6715	18.8496	20.0277	21.2058	22.3839
5"	13.0900	14.3900	15.7080	17.0170	18.3260	19.6350	20.9440	22.2520	23.5610	24.8700
6"	15.7080	17.2788	18.8496	20.4204	21.9911	23.5619	25.1327	26.7035	28.2743	29.8451
$7\frac{1}{2}$ "	20.6150	22.5084	24.5019	26.5254	27.4880	29.4524	31.4150	33.3794	35.3420	37.3061
10"	26.1799	28.7903	31.4150	34.0339	36.6510	39.2680	41.8870	44.5059	47.1230	49.7410
12"	31.4159	34.5575	37.6991	40.8407	43.9823	47.1239	50.2655	53.4071	56.5487	59.6901

Diam.	Revolutions per minute									
	20	30	40	50	60	70	80	90	100	
$\frac{1}{2}$ "	2.6180	3.9270	5.2360	6.5450	7.8540	9.1630	10.4720	11.7810	13.0900	
$\frac{3}{4}$ "	3.9270	5.8905	7.8540	9.8175	11.7810	13.7445	15.7080	17.6715	19.6350	
	5.2360	7.8540	10.4720	13.0900	15.7080	18.3260	20.9440	23.5610	26.1799	
$1\frac{1}{2}$ "	7.8540	11.7810	15.7080	20.6350	25.5619	30.4889	35.4159	40.3429	45.2699	
2"	10.4720	15.7080	20.9440	26.1799	31.4159	36.6510	41.8870	47.1230	52.3599	
$2\frac{1}{2}$ "	13.0900	19.6349	26.1799	32.7249	39.2699	45.8149	52.3599	58.9049	65.4499	
3"	15.7080	23.5619	31.4159	39.2699	47.1230	54.9770	62.8310	70.6850	78.5399	
$3\frac{1}{2}$ "	18.3260	27.4894	36.6525	45.8150	54.9787	64.1418	73.3050	82.4681	91.6312	
4"	20.9440	31.4159	41.8879	52.3599	62.8319	73.3038	83.7758	94.2478	104.7198	
$4\frac{1}{2}$ "	23.5610	35.3420	47.1230	58.9040	70.6850	82.4668	94.2478	106.0287	117.8097	
5"	26.1799	39.2699	52.3599	65.4498	78.5398	91.6298	104.7198	117.8097	130.8997	
6"	31.4159	47.1230	62.8319	78.5398	94.2478	109.9557	125.6637	141.3717	157.0797	
$7\frac{1}{2}$ "	39.2699	58.9040	78.5398	98.1748	117.8097	137.4447	157.0796	176.7146	196.3495	
10"	52.3599	78.5398	104.7198	130.8997	157.0796	183.2596	209.4395	235.6195	261.7994	
12"	65.4499	94.2478	125.6637	157.0796	188.4936	219.9115	251.3274	282.7433	314.1593	

HORSEPOWER OF SINGLE LEATHER BELTING

Multiply diameter of pulley in inches by its number of revolutions per minute, and this product by width of the belt in inches; divide this product by 3,300 for single belting, or by 2,200 for double belting, and the quotient will be the amount of horsepower that can be safely transmitted.

Speed in Feet Per Min.	WIDTH OF BELTS IN INCHES											
	1	2	3	4	5	6	8	10	12	14	16	
	H. P.	H. P.	H. P.	H. P.	H. P.	H. P.	H. P.	H. P.	H. P.	H. P.	H. P.	
400	$\frac{1}{2}$	1	$1\frac{1}{2}$	2	$2\frac{1}{2}$	3	4	5	6	7	8	
600	$\frac{3}{4}$	$1\frac{1}{2}$	$2\frac{1}{4}$	3	$3\frac{3}{4}$	$4\frac{1}{2}$	6	$7\frac{1}{2}$	9	$10\frac{1}{2}$	12	
800	1	2	3	4	5	6	8	10	12	14	16	
1000	$1\frac{1}{4}$	$2\frac{1}{2}$	$3\frac{3}{4}$	5	$6\frac{1}{4}$	$7\frac{1}{2}$	10	$12\frac{1}{2}$	15	$17\frac{1}{2}$	20	
1200	$1\frac{1}{2}$	3	$4\frac{1}{2}$	6	$7\frac{1}{2}$	9	12	15	18	21	24	
1500	$1\frac{3}{4}$	$3\frac{3}{4}$	$5\frac{1}{4}$	$7\frac{1}{2}$	$9\frac{1}{2}$	11	15	$18\frac{3}{4}$	22	$26\frac{1}{2}$	30	
1800	$2\frac{1}{4}$	$4\frac{1}{2}$	$6\frac{3}{4}$	9	$11\frac{1}{4}$	13	18	$22\frac{1}{2}$	27	$31\frac{1}{2}$	36	
2000	$2\frac{1}{2}$	5	$7\frac{1}{2}$	10	$12\frac{1}{2}$	15	20	25	30	35	40	
2400	3	6	9	12	15	18	24	30	36	42	48	
2800	$3\frac{1}{2}$	7	10	14	17	21	28	35	42	49	56	
3000	$3\frac{3}{4}$	$7\frac{1}{2}$	11	15	18	22	30	37	45	52	60	
3500	$4\frac{1}{4}$	$8\frac{3}{4}$	13	$17\frac{1}{2}$	22	26	35	44	52	61	70	
4000	5	10	15	20	25	30	40	50	60	70	80	
4500	$5\frac{1}{2}$	11	17	22	28	34	45	57	69	78	90	
5000	6	12	19	25	31	37	50	62	75	87	100	

Double leather, six-ply rubber or six-ply cotton belting will transmit about 60 per cent more power than is shown on this table. (One-inch wide, double, 550 feet per minute = one horse-power.)

UNIT OF HEAT

What is meant by the expression unit of heat?

A heat unit (B. t. u.) is the quantity of heat required to raise the temperature of one pound of water one degree, or from 39 degrees to 40 degrees F. The heat unit is used for calculating the quantity of heat contained in any form and know weight of matter.

The mechanical equivalent of heat, or rather of one heat unit, is 778 foot pounds. (A foot pound is one pound weight raised one foot high.)

How to calculate horsepower from the above data: One horsepower equals 33,000 lbs. raised one foot high in one minute of time. One heat unit equals 778 foot lbs. or 778 divided by 33,000 equals about 1-43 of a horsepower.

HORSEPOWER OF STEAM ENGINES

The rate at which steam does work upon the engine piston equals indicated horsepower, I. H. P. equals to average total pressure on piston, pounds, times distance moved by piston in feet per minute divided by 33,000. Also I. H. P. equals average effective pressure on piston, pounds, per square inch times (piston displacement, cubic inches, per minute) divided by 336,000.

I. H. P. = M. E. P., lb. per sq. in. x piston area, sq. in. x piston speed, ft. per min.

33,000

PLAN

Also, I. H. P. = $\frac{\text{PLAN}}{33,000}$, where P equals mean indicated pressure, lbs. per square inch; L equals

length of stroke, feet; A equals effective area of piston, square inches, after deducting area of piston rod or tail rod; N equals number of working strokes per minute. A horsepower equals 33,000 foot pounds per minute, or 1,980,000 foot pounds per hour, or $1,980,000 \times 12 = 23,760,000$ inch pounds per hour, meaning that the same amount of energy required to lift 33,000 pounds one foot high in one minute of time would lift 23,760,000 pounds one inch high in one minute of time.

ELECTRICAL HORSEPOWER

What constitutes one electrical horsepower? The current (C) in amperes multiplied by the electro-motive force (E) in volts, divided by 746; expressed as follows:

$$\text{E. H. P.} = \frac{E \times C}{746}$$

It takes 1,000 watts, expressed as one kilowatt, to deliver one mechanical, or brake, horsepower in practice.

If the brake horsepower of an electric motor be known, how may the efficiency be calculated? By the following formula:

$$e = \frac{B. H. P. \times 746}{E \times C}$$

in which e equals efficiency; B. H. P. equals brake horsepower; E equals volts; C equals amperes.



HORSEPOWER OF AN EXPLOSIVE MOTOR OR GASOLINE ENGINE

First ascertain the number of strokes per minute; then

$$\text{H. P.} = \frac{\text{PLAN}}{33,000}$$

in which H. P. equals horsepower; P equals mean effective pressure; L equals length of stroke in feet; A equals area of piston in square inches; N equals number of power strokes per minute.

CUTTING TOOLS RECOMMENDED FOR USE ON CINCINNATI SHAPERS



No. of Threads
per Inch

8
10
11
12
13
16
20

No. of Chasing
Cuts

18
14
13
11
10
9
8

Thread-Cutting Data


This table is based on .005" per cut allowing an extra cut for finish which is the actual practice in our shop.

STANDARD IXL KEY SEATS

Strength of Sunk Keys — The strength of a sunk key is the measure of its holding power. A key of width w , thickness t , length l , all in inches, a unit shearing strength of f_s , and unit crushing resistance of f_c in lb. per square in. will have a shearing strength, lb. per sq. in., of $f_s w l$ and a crushing resistance $f_c (\frac{1}{2} t l)$.

If r = radius of the shaft, in., the moment which the key can resist will be $r w l f_s$ or $\frac{1}{2} r t l f_c$, whichever is smaller.

Experiments made by Professor Lanza indicate that the ultimate value of f_s for cast-iron = 30,000 lb., for wrought-iron = 40,000 lb., and for machinery steel = 60,000 lb. A factor of safety of 2 would be advisable with these values.



Diameter of Hole, Inches	O Width of Key Seat	P Depth of Key Seat	Diameter of Hole, Inches	O Width of Key Seat	P Depth of Key Seat
$\frac{3}{8}$	$\frac{3}{32}$	$\frac{3}{64}$	$3\frac{1}{4}$ to $3\frac{1}{16}$	$\frac{7}{8}$	$\frac{7}{16}$
$\frac{7}{16}$ to $\frac{1}{2}$	$\frac{1}{8}$	$\frac{1}{16}$	$3\frac{3}{4}$ to $4\frac{3}{16}$	1	$\frac{1}{2}$
$\frac{9}{16}$ to $\frac{5}{8}$	$\frac{5}{32}$	$\frac{5}{64}$	$4\frac{1}{4}$ to $4\frac{1}{16}$	$1\frac{1}{8}$	$\frac{9}{16}$
$\frac{11}{16}$ to $\frac{3}{4}$	$\frac{3}{16}$	$\frac{3}{32}$	$4\frac{3}{4}$ to $5\frac{3}{16}$	$1\frac{1}{4}$	$\frac{5}{8}$
$\frac{13}{16}$ to $\frac{7}{8}$	$\frac{7}{32}$	$\frac{7}{64}$	$5\frac{1}{4}$ to $5\frac{1}{16}$	$1\frac{3}{8}$	$1\frac{1}{16}$
$\frac{15}{16}$ to $1\frac{1}{8}$	$\frac{1}{4}$	$\frac{1}{8}$	$5\frac{3}{4}$ to $6\frac{3}{16}$	$1\frac{1}{2}$	$\frac{3}{4}$
$1\frac{3}{16}$ to $1\frac{3}{8}$	$\frac{5}{16}$	$\frac{5}{32}$	$6\frac{1}{4}$ to $6\frac{1}{16}$	$1\frac{5}{8}$	$1\frac{3}{16}$
$1\frac{7}{16}$ to $1\frac{5}{8}$	$\frac{3}{8}$	$\frac{3}{16}$	$6\frac{3}{4}$ to $7\frac{3}{16}$	$1\frac{3}{4}$	$\frac{7}{8}$
$1\frac{11}{16}$ to $1\frac{7}{8}$	$\frac{7}{16}$	$\frac{7}{32}$	$7\frac{1}{4}$ to $7\frac{1}{16}$	$1\frac{7}{8}$	$1\frac{5}{16}$
$1\frac{15}{16}$ to $2\frac{1}{8}$	$\frac{1}{2}$	$\frac{1}{4}$	$7\frac{3}{4}$ to $8\frac{3}{16}$	2	1
$2\frac{3}{16}$ to $2\frac{1}{16}$	$\frac{5}{8}$	$\frac{5}{16}$	$8\frac{1}{4}$ to $8\frac{5}{16}$	$2\frac{1}{8}$	$1\frac{1}{16}$
$2\frac{3}{4}$ to $3\frac{3}{16}$	$\frac{3}{4}$	$\frac{3}{8}$	9 to 10	$2\frac{1}{4}$	$1\frac{1}{8}$

Reaming in the Lathe

Reamers are used in the lathe to finish a number of holes quickly and accurately to the same diameter. Usually the hole is first drilled or bored roughly to size, allowing sufficient stock for reaming. Two types of reamers are used, the rose reamer and the fluted reamer.


Rose reamers are ground for cutting on the end only and are intended for rough reaming as they do not produce a good finish or an accurate diameter.

Fluted reamers are ground for cutting on both the ends and the sides of the blades and are usually used after the rose reamer to obtain an exact size and produce a good smooth finish. Fluted reamers should be used only for light cuts, removing not over .010 in. from the hole.

DIMENSIONS OF STANDARD KEY- SEATS AND SETSCREWS FOR GEARS

IN INCHES

Diam. of Hole	Key- seat		Set- screw	Diam. of Hole	Key- seat		Set- screw
	W	d			W	d	
$\frac{1}{4}$ to $\frac{3}{8}$	$\frac{1}{16}$	$\frac{1}{32}$	10-32	$\frac{3}{8}$ to $\frac{5}{8}$	1	$\frac{1}{2}$	1-8
$\frac{7}{16}$ to $\frac{1}{2}$	$\frac{1}{8}$	$\frac{1}{16}$	$\frac{1}{4}$ -20	$\frac{5}{8}$ to $\frac{6}{7}$	$\frac{1}{8}$	$\frac{9}{16}$	$\frac{1}{8}$ -7
$\frac{1}{2}$ to $\frac{7}{8}$	$\frac{3}{16}$	$\frac{3}{32}$	$\frac{5}{8}$ -18	$\frac{6}{7}$ to $\frac{7}{8}$	$\frac{1}{4}$	$\frac{5}{8}$...
$\frac{15}{16}$ to $1\frac{1}{8}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{8}$ -16	$\frac{7}{8}$ to $1\frac{1}{8}$	$\frac{3}{8}$	$\frac{11}{16}$...
$1\frac{1}{8}$ to $1\frac{3}{8}$	$\frac{5}{16}$	$\frac{5}{32}$	$\frac{7}{8}$ -14	9 to $10\frac{3}{4}$	$\frac{1}{2}$	$\frac{3}{4}$...
$1\frac{3}{8}$ to $1\frac{1}{2}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{2}$ -13	$10\frac{3}{4}$ to $11\frac{1}{2}$	$\frac{5}{8}$	$\frac{13}{16}$...
$1\frac{1}{2}$ to $2\frac{1}{8}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{9}{16}$ -12	$11\frac{1}{2}$ to $12\frac{1}{2}$	$\frac{3}{4}$	$\frac{7}{8}$...
$2\frac{1}{8}$ to $2\frac{1}{2}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{3}{8}$ -11	$12\frac{1}{2}$ to $13\frac{1}{2}$	$1\frac{1}{8}$	$\frac{15}{16}$...
$2\frac{1}{2}$ to $3\frac{1}{8}$	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{1}{2}$ -10	14 to $14\frac{1}{2}$	2	1	...
$3\frac{1}{8}$ to $3\frac{1}{2}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{7}{8}$ -9				



Formula


$$X = \sqrt{\left(\frac{D}{2}\right)^2 - \left(\frac{W}{2}\right)^2} + d + \frac{D}{2}$$

$$X' = 2X - D$$

Example

Hole 1"; Keyway $\frac{1}{4}$ " wide by $\frac{5}{8}$ " deep.

$$X = \sqrt{\left(\frac{1}{2}\right)^2 - \left(\frac{1}{8}\right)^2} + \frac{1}{8} + \frac{1}{2} = 1.09"$$




**STANDARD KEYWAYS
FOR CUTTERS**

Diam. (D) of Hole, Inches	Width (W) of Keyway, In.	Depth (D') of Keyway, In.	Radius (R), Inches
1-2	3-32	3-64	1-64
5-8	1-8	1-16	1-32
3-4	1-8	1-16	1-32
7-8	1-8	1-16	1-32
1	1-4	3-32	3-64
1 1-4	5-16	1-8	3-64
1 1-2	3-8	5-32	1-16
1 3-4	7-16	3-16	1-16
2	1-2	3-16	1-16
2 1-4	5-8	7-32	1-16
2 1-2	5-8	7-32	1-16
2 3-4	3-4	1-4	1-16

HALF ROUND KEYWAY

Size Hole, H	$\frac{3}{8}$ - $\frac{5}{8}$	$\frac{1}{2}$ - $\frac{13}{16}$	$\frac{7}{8}$ - $1\frac{1}{8}$	$1\frac{1}{4}$ - $1\frac{7}{8}$	$1\frac{1}{2}$ -2	$2\frac{1}{8}$ - $2\frac{1}{2}$	$2\frac{1}{2}$ -3
Width, W	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{1}{4}$	$\frac{5}{16}$	$\frac{3}{8}$	$\frac{7}{16}$	$\frac{1}{2}$
Depth, D	$\frac{1}{16}$	$\frac{3}{32}$	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{1}{4}$



U. S. NAVY STANDARD KEYS

Keys and Keyways for Propellers

Proportions of Sunk Keys

Shaft Diam. Inch	Key Width Inch	Key Thickness Inch	Shaft Diam. Inch	Key Width Inch	Key Thickness Inch	Shaft Diam. Inch	Key Width Inch	Key Thickness Inch
$\frac{1}{2}$	$\frac{3}{8}$	$\frac{1}{8}$	3	$\frac{1}{2}$	$\frac{1}{8}$	6 $\frac{3}{4}$	1 $\frac{3}{8}$	$\frac{3}{4}$
$\frac{5}{8}$	$\frac{1}{2}$	$\frac{1}{8}$	3 $\frac{1}{4}$	$\frac{3}{4}$	$\frac{1}{8}$	7	1 $\frac{1}{8}$	$\frac{1}{2}$
$\frac{3}{4}$	$\frac{5}{8}$	$\frac{1}{8}$	3 $\frac{1}{2}$	$\frac{1}{2}$	$\frac{1}{8}$	7 $\frac{1}{4}$	1 $\frac{1}{2}$	$\frac{1}{2}$
$\frac{7}{8}$	$\frac{3}{4}$	$\frac{1}{8}$	3 $\frac{3}{4}$	$\frac{1}{2}$	$\frac{1}{8}$	7 $\frac{1}{2}$	1 $\frac{1}{8}$	$\frac{7}{8}$
1	$\frac{7}{8}$	$\frac{1}{8}$	4	$\frac{3}{4}$	$\frac{1}{8}$	7 $\frac{3}{4}$	1 $\frac{1}{8}$	$\frac{7}{8}$
1 $\frac{1}{8}$	$\frac{1}{2}$	$\frac{1}{4}$	4 $\frac{1}{4}$	$\frac{1}{2}$	$\frac{1}{8}$	8	1 $\frac{1}{8}$	$\frac{7}{8}$
1 $\frac{1}{4}$	$\frac{3}{8}$	$\frac{1}{4}$	4 $\frac{1}{2}$	1	$\frac{1}{8}$	8 $\frac{1}{4}$	1 $\frac{1}{8}$	$\frac{1}{2}$
1 $\frac{3}{8}$	$\frac{3}{8}$	$\frac{1}{4}$	4 $\frac{3}{4}$	1	$\frac{1}{8}$	8 $\frac{1}{2}$	1 $\frac{1}{8}$	$\frac{1}{2}$
1 $\frac{1}{2}$	$\frac{1}{2}$	$\frac{1}{4}$	5	1 $\frac{1}{8}$	$\frac{5}{8}$	8 $\frac{3}{4}$	1 $\frac{3}{4}$	$\frac{1}{2}$
1 $\frac{3}{4}$	$\frac{5}{8}$	$\frac{1}{8}$	5 $\frac{1}{4}$	1 $\frac{1}{8}$	$\frac{5}{8}$	9	1 $\frac{3}{4}$	1
2	$\frac{1}{2}$	$\frac{1}{8}$	5 $\frac{1}{2}$	1 $\frac{1}{4}$	$\frac{5}{8}$	9 $\frac{1}{4}$	1 $\frac{3}{4}$	1
2 $\frac{1}{4}$	$\frac{1}{8}$	$\frac{1}{8}$	5 $\frac{3}{4}$	1 $\frac{1}{2}$	$\frac{1}{2}$	9 $\frac{1}{2}$	1 $\frac{3}{4}$	1 $\frac{1}{8}$
2 $\frac{1}{2}$	$\frac{5}{8}$	$\frac{3}{8}$	6	1 $\frac{1}{4}$	$\frac{1}{2}$	9 $\frac{3}{4}$	2	1 $\frac{1}{8}$
2 $\frac{3}{4}$	$\frac{5}{8}$	$\frac{3}{8}$	6 $\frac{1}{4}$	1 $\frac{1}{8}$	$\frac{3}{4}$	10	2	1 $\frac{1}{8}$
			6 $\frac{1}{2}$	1 $\frac{1}{8}$	$\frac{3}{4}$			

Sunk Keys are generally proportioned with relation to the Shaft Diameter, instead of considering the torsional lead in each case, because rules which apply to sunk keys have been used widely. It is best however, to proportion keys according to an adopted standard.

RULE 1—The width of the key equals $\frac{1}{4}$ of the Shaft Diameter; the thickness $\frac{1}{6}$ of the Shaft Diameter; the minimum length $1\frac{1}{2}$ times the Shaft Diameter. In the following W = Key Width; T = Key Thickness; L = Key Length; and D = Shaft Diam.

$$W = \frac{D}{4} \qquad T = \frac{1}{6} D \qquad L = 1.5 D$$

$$\text{RULE 2} - W = \frac{1}{8} D + \frac{1}{8} \text{ inch; } T = \frac{1}{8} D + \frac{1}{8} \text{ inch; } L = \frac{3}{10} D + \frac{3}{10}$$

For Splines or Feather Keys, interchange the dimensions for width and thickness.

$$\text{RULE 3 (Unwin)} - W = \frac{1}{4} D + \frac{1}{8} \text{ inch; } T = \frac{1}{8} D + \frac{1}{8} \text{ inch.}$$


When gears or pulleys transmitting only a small amount of power are keyed to large shafts, these dimensions are excessive.

The taper of sunk keys is usually about $\frac{1}{8}$ or $\frac{1}{16}$ inch per foot. The depth of a taper keyseat at the deep end should be $\frac{3}{5}$ of the key thickness.


The U. S. Navy, in proportioning keys for Propellers, is to make the width of the key about $1\frac{1}{2}$ times its thickness. The thickness, in turn, is so determined that the side pressure on the propeller hub, calculated from the maximum turning moment on the shaft, does not exceed 25,000 pounds per square inch. The key is so proportioned that the pressure on the keyway will not exceed 22,000 pounds per square inch. With this pressure, if the key thickness is over $\frac{1}{4}$ of the Shaft Diameter, two keys, set opposite, are preferred.

The Hub of the Propeller is bored, tapered and fitted to a corresponding taper on the shaft, which is provided with a retaining nut.


Different Types of Keys used



Key Seat Clamps



For laying out keyways and scribing parallel lines on circular pieces. Easily put on and taken off of steel rules. Can be used also on combination square blades and straight edges (except Beveled Steel Straight Edges).



GIB KEYS DIMENSIONS

$G = B$, approximately;

$H = \frac{1}{8}$ times diam. of bore up to 6 inches; for larger sizes, $H = \frac{1}{8} \times \text{bore}$;

$h = \text{radius} = \frac{1}{8}$ times diam. of bore, approx., but minimum value = $\frac{3}{16}$ inch,

$L = \text{length of hub} + \frac{1}{2}$ inch.


Taper $\frac{1}{8}$ inch per foot.

$R = \text{radius of shaft}$;

$B = \text{breadth of key}$;

$S = \text{safe shearing strength of material in key}$;

$B = \frac{1}{4}$ times diam. of bore, up to 6 inches; for larger sizes, $B = 0.211 \times \text{bore}$, approximately;




Keys of proportions given below are weakest in shear.

The safe twisting moment per inch of length of keys $= R \times B \times S$

Bore and Shaft Diameter	Width of Key B	Height of Key H	Depth of Key-way $\frac{H}{2}$	Rad. h	G	Safe Twisting Moment on Key per Inch of Length f or $S =$		
						5000	7500	10,000
$\frac{15}{16}$ to $\frac{11}{8}$	$\frac{1}{4}$	$\frac{3}{16}$	$\frac{3}{32}$	$\frac{3}{16}$	$\frac{1}{4}$	630	940	1,250
$\frac{13}{16}$ to $\frac{13}{8}$	$\frac{3}{8}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{3}{8}$	1,170	1,760	2,340
$\frac{17}{16}$ to $\frac{15}{8}$	$\frac{3}{8}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{3}{8}$	1,410	2,110	2,810
$\frac{11}{16}$ to $\frac{17}{8}$	$\frac{1}{2}$	$\frac{5}{16}$	$\frac{5}{32}$	$\frac{1}{4}$	$\frac{1}{2}$	2,190	3,280	4,380
$\frac{15}{16}$ to $\frac{21}{8}$	$\frac{1}{2}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{4}$	$\frac{1}{2}$	2,500	3,750	5,000
$\frac{23}{16}$ to $\frac{23}{8}$	$\frac{5}{8}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{3}{8}$	$\frac{5}{8}$	3,520	5,270	7,030
$\frac{27}{16}$ to $\frac{25}{8}$	$\frac{5}{8}$	$\frac{7}{16}$	$\frac{7}{32}$	$\frac{3}{8}$	$\frac{5}{8}$	3,910	5,860	7,810
$\frac{21}{16}$ to $\frac{27}{8}$	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{8}$	$\frac{3}{4}$	5,160	7,730	10,313
$\frac{215}{16}$ to $\frac{31}{8}$	$\frac{3}{4}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{8}$	$\frac{3}{4}$	5,620	8,420	11,250
$\frac{33}{16}$ to $\frac{33}{8}$	$\frac{7}{8}$	$\frac{9}{16}$	$\frac{9}{32}$	$\frac{1}{2}$	$\frac{7}{8}$	7,110	10,660	14,220
$\frac{37}{16}$ to $\frac{35}{8}$	$\frac{7}{8}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{1}{2}$	$\frac{7}{8}$	7,660	11,480	15,310
$\frac{31}{16}$ to $\frac{37}{8}$	1	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{1}{2}$	1	9,380	14,060	18,750
$\frac{315}{16}$ to $\frac{41}{8}$	1	$\frac{11}{16}$	$\frac{11}{32}$	$\frac{1}{2}$	1	10,000	15,000	20,000
$\frac{43}{16}$ to $\frac{43}{8}$	$\frac{11}{8}$	$\frac{11}{16}$	$\frac{11}{32}$	$\frac{5}{8}$	1	11,950	17,930	23,910
$\frac{47}{16}$ to $\frac{43}{4}$	$\frac{11}{8}$	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{5}{8}$	1	12,660	18,980	25,310
$\frac{413}{16}$ to $\frac{51}{4}$	$\frac{11}{4}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{5}{8}$	$\frac{11}{4}$	15,620	23,440	31,250
$\frac{53}{16}$ to $\frac{53}{8}$	$\frac{13}{8}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{3}{4}$	$\frac{11}{4}$	18,910	28,360	37,810
$\frac{513}{16}$ to $\frac{61}{4}$	$\frac{11}{2}$	1	$\frac{1}{2}$	$\frac{3}{4}$	$\frac{11}{2}$	22,500	33,750	45,000
$\frac{63}{16}$ to $\frac{63}{8}$	$\frac{11}{2}$	1	$\frac{1}{2}$	$\frac{7}{8}$	$\frac{11}{2}$	24,380	36,560	48,750
$\frac{613}{16}$ to $\frac{71}{4}$	$\frac{11}{2}$	1	$\frac{1}{2}$	$\frac{7}{8}$	$\frac{13}{4}$	26,250	39,380	52,500
$\frac{75}{16}$ to $\frac{73}{8}$	$\frac{15}{8}$	1	$\frac{1}{2}$	1	$\frac{13}{4}$	30,470	45,700	60,940
$\frac{713}{16}$ to $\frac{83}{4}$	$\frac{13}{4}$	$\frac{11}{8}$	$\frac{9}{16}$	1	2	36,090	54,140	72,190
$\frac{813}{16}$ to $\frac{93}{4}$	2	$\frac{11}{4}$	$\frac{5}{8}$	$\frac{11}{8}$	2	46,250	69,380	92,500
$\frac{913}{16}$ to $\frac{103}{4}$	$\frac{21}{4}$	$\frac{11}{2}$	$\frac{3}{4}$	$\frac{11}{4}$	2	57,660	86,480	115,320
$\frac{1013}{16}$ to $\frac{113}{4}$	$\frac{21}{2}$	$\frac{11}{2}$	$\frac{3}{4}$	$\frac{11}{4}$	2	70,310	105,470	140,630
$\frac{1113}{16}$ to $\frac{123}{4}$	$\frac{21}{2}$	$\frac{11}{2}$	$\frac{3}{4}$	$\frac{11}{4}$	2	76,560	114,840	153,130


Machining Eccentrics

A simple eccentric can be machined on a straight mandrel having two sets of center holes as shown in Fig. 1. One set of centers is used for machining the concentric hub and the other set of centers is used for machining the eccentric part.



A Mandrel with Two Sets of Center Holes for Machining an Eccentric

KEYSEATS IN SHAFTING



DIMENSIONS

Shaft Diameter, Keyseat, Inches	Width Keyseat, Inches	Depth Keyseat, Inches		Shaft Diameter, Keyseat, Inches	Width Keyseat, Inches	Depth Keyseat, Inches	
		Square Key	Flat Key			Square Key	Flat Key
$\frac{1}{2}$	$\frac{1}{8}$	$\frac{1}{16}$	$\frac{3}{64}$	$2 \frac{3}{8}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{7}{32}$
$\frac{5}{16}$	$\frac{1}{8}$	$\frac{1}{16}$	$\frac{3}{64}$	$2 \frac{1}{16}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{7}{32}$
$\frac{3}{8}$	$\frac{3}{16}$	$\frac{3}{32}$	$\frac{1}{16}$	$2 \frac{1}{2}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{7}{32}$
$1 \frac{1}{16}$	$\frac{3}{16}$	$\frac{3}{32}$	$\frac{1}{16}$	$2 \frac{5}{8}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{7}{32}$
$\frac{3}{4}$	$\frac{3}{16}$	$\frac{3}{32}$	$\frac{1}{16}$	$2 \frac{3}{4}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{7}{32}$
$1 \frac{1}{16}$	$\frac{3}{16}$	$\frac{3}{32}$	$\frac{1}{16}$	$2 \frac{7}{8}$	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{1}{4}$
$\frac{7}{8}$	$\frac{3}{16}$	$\frac{3}{32}$	$\frac{1}{16}$	$2 \frac{15}{16}$	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{1}{4}$
$1 \frac{1}{16}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{32}$	3	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{1}{4}$
1	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{32}$	$3 \frac{1}{8}$	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{1}{4}$
$1 \frac{1}{16}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{32}$	$3 \frac{1}{4}$	$\frac{3}{4}$	$\frac{3}{8}$	$\frac{1}{4}$
$1 \frac{1}{8}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{32}$	$3 \frac{3}{8}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{5}{16}$
$1 \frac{3}{16}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{32}$	$3 \frac{1}{16}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{5}{16}$
$1 \frac{1}{4}$	$\frac{1}{4}$	$\frac{1}{8}$	$\frac{3}{32}$	$3 \frac{1}{2}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{5}{16}$
$1 \frac{5}{16}$	$\frac{3}{8}$	$\frac{5}{32}$	$\frac{1}{8}$	$3 \frac{5}{8}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{5}{16}$
$1 \frac{3}{8}$	$\frac{5}{16}$	$\frac{5}{32}$	$\frac{1}{8}$	$3 \frac{3}{4}$	$\frac{7}{8}$	$\frac{7}{16}$	$\frac{5}{16}$
$1 \frac{1}{16}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{8}$	$3 \frac{7}{8}$	1	$\frac{1}{2}$	$\frac{3}{8}$
$1 \frac{1}{2}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{8}$	$3 \frac{15}{16}$	1	$\frac{1}{2}$	$\frac{3}{8}$
$1 \frac{5}{16}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{8}$	4	1	$\frac{1}{2}$	$\frac{3}{8}$
$1 \frac{3}{8}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{8}$	$4 \frac{1}{4}$	1	$\frac{1}{2}$	$\frac{3}{8}$
$1 \frac{1}{16}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{8}$	$4 \frac{1}{16}$	1	$\frac{1}{2}$	$\frac{3}{8}$
$1 \frac{3}{4}$	$\frac{3}{8}$	$\frac{3}{16}$	$\frac{1}{8}$	$4 \frac{1}{2}$	1	$\frac{1}{2}$	$\frac{3}{8}$
$1 \frac{13}{16}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	$4 \frac{3}{4}$	$1 \frac{1}{4}$	$\frac{5}{8}$	$\frac{7}{16}$
$1 \frac{3}{8}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	$4 \frac{5}{16}$	$1 \frac{1}{4}$	$\frac{5}{8}$	$\frac{7}{16}$
$1 \frac{15}{16}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	5	$1 \frac{1}{4}$	$\frac{5}{8}$	$\frac{7}{16}$
2	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	$5 \frac{1}{4}$	$1 \frac{1}{4}$	$\frac{5}{8}$	$\frac{7}{16}$
$2 \frac{1}{16}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	$5 \frac{1}{16}$	$1 \frac{1}{4}$	$\frac{5}{8}$	$\frac{7}{16}$
$2 \frac{1}{8}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	$5 \frac{1}{2}$	$1 \frac{1}{4}$	$\frac{5}{8}$	$\frac{7}{16}$
$2 \frac{3}{16}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	$5 \frac{3}{4}$	$1 \frac{1}{2}$	$\frac{3}{4}$	$\frac{1}{2}$
$2 \frac{1}{4}$	$\frac{1}{2}$	$\frac{1}{4}$	$\frac{3}{16}$	$5 \frac{15}{16}$	$1 \frac{1}{2}$	$\frac{3}{4}$	$\frac{1}{2}$
$2 \frac{5}{16}$	$\frac{5}{8}$	$\frac{5}{16}$	$\frac{7}{32}$	6	$1 \frac{1}{2}$	$\frac{3}{4}$	$\frac{1}{2}$

Unless otherwise specified all Keyseats will be made with Cutter Runouts. Round End Keyseats will be furnished only when designated. Be sure to specify Round End for Keyseat ends coming next to bearings.

U. S. STANDARD STEAM, GAS AND WATER PIPE

Size of Pipe Tap	Threads per Inch	Outside Diam. of Pipe	Inside Diam. of Pipe	Total Length of Thread	Length of Perfect Thread	Size of Tap Drill	Diam. at End of Pipe	
							Outside of	At Bott. of Thd.
1/8	27	.405	.270	.41	.19	21-64	.393	.342
1/8	18	.540	.364	.62	.29	29-64	.522	.445
1/8	18	.675	.494	.63	.30	19-32	.656	.579
1/4	14	.840	.623	.83	.39	23-32	.816	.717
1/4	14	1.050	.824	.84	.40	15-16	1.025	.926
1	11 1/2	1.315	1.048	1.03	.51	1 3-16	1.283	1.162
1 1/4	11 1/2	1.660	1.380	1.06	.54	1 15-32	1.626	1.505
1 1/2	11 1/2	1.900	1.611	1.07	.55	1 23-32	1.866	1.745
2	11 1/2	2.375	2.067	1.10	.58	2 3-16	2.339	2.218
2 1/2	8	2.875	2.468	1.64	.89	2 11-16	2.819	2.646
3	8	3.500	3.067	1.70	.95	3 5-16	3.441	3.268
3 1/2	8	4.000	3.548	1.75	1.00	3 13-16	3.938	3.765
4	8	4.500	4.026	1.80	1.05	4 7-32	4.434	4.261
4 1/2	8	5.000	4.508	1.85	1.10	4 21-32	4.931	4.758
5	8	5.563	5.045	1.91	1.16	5 15-64	5.491	5.318
6	8	6.625	6.065	2.01	1.26	6 1-4	6.546	6.373
7	8	7.625	7.023	2.11	1.36	7 5-16	7.540	7.367
8	8	8.625	7.982	2.21	1.46	8 5-16	8.534	8.361
9	8	9.625	8.937	2.32	1.57	9 5-16	9.527	9.354
10	8	10.750	10.019	2.43	1.68	10 5-16	10.645	10.472

Note—The Taper of the Threaded Part is 1 in 16

STANDARD DIMENSIONS OF COUPLINGS

Nom. Inside Dia. of Pipe	Inside Diam.	Outside Diam.	Length	Threads Per Inch	Nom. Inside Dia. of Pipe	Inside Diam.	Outside Diam.	Length	Threads Per Inch
1/8	11/32	19/32	13/16	27	4	4 11/64	5	3 5/8	8
1/4	15/32	23/32	15/16	18	4 1/2	4 3/4	5 1/2	3 5/8	8
3/8	37/64	27/32	1 1/16	18	5	5 9/32	6 7/32	4 1/8	8
1/2	23/32	1	1 5/16	14	6	6 11/32	7 5/16	4 1/8	8
3/4	63/64	1 21/64	1 9/16	14	7	7 3/8	8 9/16	4 1/8	8
1	1 11/64	1 9/16	1 13/16	11 1/2	8	8 3/8	9 5/16	4 5/8	8
1 1/4	1 1/2	1 61/64	2 1/8	11 1/2	9	9 7/16	10 3/8	5 1/8	8
1 1/2	1 3/4	2 7/32	2 3/8	11 1/2	10	10 7/16	11 21/32	6 1/8	8
2	2 1/32	2 3/4	2 5/8	11 1/2	11	11 15/32	12 21/32	6 1/8	8
2 1/2	2 21/32	3 3/32	2 7/8	8	12	12 7/16	13 7/8	6 1/8	8
3	3 1/4	3 15/16	3 1/8	8	13	13 11/16	15 1/16	6 1/8	8
3 1/2	3 25/32	4 7/16	3 5/8	8	14	14 23/32	16 3/8	6 1/8	8
					15	15 11/16	17 3/8	6 1/8	8

BRIGGS PIPE STANDARD

Size of Tap, No.	Size of Drill, No.	Size of Tap, No.	Size of Drill, No.	Size of Tap, No.	Size of Drill, No.	Size of Tap, No.	Size of Drill, No.
1/8-27	R	1/2-14	23/32	1 1/4-11 1/2	1 1/2	2 1/2-8	2 5/8
1/4-18	7/16	3/4-14	59/64	1 1/2-11 1/2	1 17/64	3 -8	3 1/4
3/8-18	37/64	1 -11 1/2	1 5/8	2 -11 1/2	2 27/32		

Standard Dimensions for Nipples

CAST IRON PIPES

Nominal Weight of a Lineal Foot, Without Flanges

Pipe Size	Length in Inches		
	Close	Short	Long
1	1 1/2	1 1/2	3
1 1/4	1 1/2	1 1/2	3 1/2
1 1/2	1 1/2	1 1/2	3 1/2
2	2 1/2	2 1/2	4
2 1/4	2 1/2	2 1/2	4 1/2
2 1/2	2 1/2	2 1/2	4 1/2
3	3 1/2	3 1/2	5
3 1/4	3 1/2	3 1/2	5 1/2
3 1/2	3 1/2	3 1/2	5 1/2
4	4 1/2	4 1/2	6
4 1/4	4 1/2	4 1/2	6 1/2
4 1/2	4 1/2	4 1/2	6 1/2
5	5 1/2	5 1/2	6 1/2
5 1/4	5 1/2	5 1/2	6 1/2
5 1/2	5 1/2	5 1/2	6 1/2
6	6 1/2	6 1/2	6 1/2
6 1/4	6 1/2	6 1/2	6 1/2
6 1/2	6 1/2	6 1/2	6 1/2
7	7 1/2	7 1/2	7 1/2
7 1/4	7 1/2	7 1/2	7 1/2
7 1/2	7 1/2	7 1/2	7 1/2
8	8 1/2	8 1/2	8 1/2
8 1/4	8 1/2	8 1/2	8 1/2
8 1/2	8 1/2	8 1/2	8 1/2
9	9 1/2	9 1/2	9 1/2
9 1/4	9 1/2	9 1/2	9 1/2
9 1/2	9 1/2	9 1/2	9 1/2
10	10 1/2	10 1/2	10 1/2
10 1/4	10 1/2	10 1/2	10 1/2
10 1/2	10 1/2	10 1/2	10 1/2
11	11 1/2	11 1/2	11 1/2
11 1/4	11 1/2	11 1/2	11 1/2
11 1/2	11 1/2	11 1/2	11 1/2
12	12 1/2	12 1/2	12 1/2

Bore in Inches	THICKNESS OF METAL IN INCHES									
	1/4	3/8	1/2	5/8	3/4	7/8	1	1 1/4	1 1/2	1 3/4
2	1.52	1.74	1.87	1.91	2.05	2.10	2.17	2.35	2.42	2.48
2 1/4	6.75	10.58	14.73	19.18	23.95	28.99	34.36	40.04	46.02	
3	7.93	12.43	17.18	22.24	27.61	32.29	39.27	45.56	52.18	
3 1/4	9.20	14.27	19.64	25.31	31.29	37.53	41.18	51.08	58.29	
4	10.43	16.11	22.09	28.33	34.93	41.88	49.09	56.60	64.43	
4 1/4	11.66	17.95	24.54	31.43	38.66	46.18	54.00	62.13	70.56	
5	12.89	19.79	27.00	34.52	42.34	50.47	58.91	67.65	76.70	
5 1/4	14.11	21.63	29.45	37.53	46.02	54.76	63.81	73.17	82.84	
6	15.34	23.47	31.91	40.65	49.70	59.05	68.72	78.69	88.97	
7	17.79	27.15	36.82	46.79	57.06	67.65	78.54	89.74	101.24	
8	20.25	30.63	41.72	52.92	64.43	76.24	88.36	100.78	113.52	
9	22.70	34.52	46.63	59.06	71.79	84.83	98.18	111.83	125.79	
10	25.16	38.50	51.54	65.19	79.13	93.42	107.99	122.87	138.06	
11	27.61	41.88	56.45	71.33	86.52	102.01	117.81	133.92	150.33	
12	30.07	46.56	61.36	77.47	93.88	110.60	127.63	144.96	162.60	
13	32.52	49.24	66.27	83.60	101.24	119.19	137.45	155.01	174.85	
14	34.98	52.02	71.18	89.74	108.61	127.78	147.26	167.06	187.15	
15		56.00	76.09	96.87	115.97	136.37	167.08	178.10	199.42	
16		60.29	80.99	102.01	123.33	144.96	166.90	189.14	211.69	
18		67.65	90.81	114.28	138.06	162.14	186.53	211.23	236.23	
20		100.63	126.55	152.79	179.32	206.17	233.32	260.78		
22		110.45	138.83	167.51	196.50	225.80	255.41	285.32		
24		120.28	151.10	182.74	213.68	245.44	277.50	309.47		

LEAD PIPE AND CALKING LEAD

For several years buyers of lead pipe and lead for calking have had the same protection as buyers of lead fittings. Rigid industry standards and control the manufacture of these items and the Lead Industries' Seal of Approval readily identifies products meeting the standard. The purity of metal is carefully guarded by definite limitation of impurities and manufacturing defects are prohibited. Specific tolerances are provided for wall thickness and

Lead Pipe Diameter in.	Classification		Outside Diameter in.	Weight Per Foot	
	East	West		lb.	oz.
3/8	XL	XS	1 1/4	6	12
	XL	XS	1 1/2	7	8
	XL	XS	1 3/4	8	12
	XL	XS	2	10	10
1/2	XL	XS	1 1/4	7	8
	XL	XS	1 1/2	8	12
	XL	XS	1 3/4	9	12
	XL	XS	2	11	12
5/8	XL	XS	1 1/4	8	12
	XL	XS	1 1/2	9	12
	XL	XS	1 3/4	10	12
	XL	XS	2	12	12
3/4	XL	XS	1 1/4	9	12
	XL	XS	1 1/2	10	12
	XL	XS	1 3/4	11	12
	XL	XS	2	13	12
1	XL	XS	1 1/4	10	12
	XL	XS	1 1/2	11	12
	XL	XS	1 3/4	12	12
	XL	XS	2	14	12
1 1/4	XL	XS	1 1/4	11	12
	XL	XS	1 1/2	12	12
	XL	XS	1 3/4	13	12
	XL	XS	2	15	12

CALKING LEAD STANDARD

Lead for calking purposes shall contain not less than 99.75 per cent pure lead. Impurities shall not exceed the following limits:

Arsenic, Antimony and Tin together	0.015 per cent
Copper	0.008 per cent
Zinc	0.005 per cent
Iron	0.005 per cent
Lead	0.005 per cent
Unburnt	0.005 per cent
Shred	0.005 per cent

RECOMMENDED PIPE WEIGHTS

For plumbing soil, waste and vent. D or R C XL or L

For chemical waste pipes	A	XS
For cold water pressures	A	XS
For hot water pressures	A	XS
For steam pressures	A	XS
For gas pressures	A	XS
For air pressures	A	XS
For oil pressures	A	XS
For acid pressures	A	XS
For alkali pressures	A	XS
For other pressures	A	XS

In a pipe, the lighter of the two weights listed in each column shall be used. In a pipe, the heavier weight for chemical wastes.

WEIGHT COMPUTING FORMULAS

Round Hot Rolled or Cold Drawn Seamless Steel Tubing

To determine the average wall weight of a tube:

$$W = 10.68 (D - t) t$$

To determine the minimum wall weight of a tube:

$$W = 10.68 (D - \frac{t}{.875}) \frac{t}{.875}$$

Where W = Weight in pounds per foot (carried to 4 digits)

D = Outside Diameter in inches (to 3 decimal places)

t = Wall thickness in decimals (to 3 decimal places)

All weights are carried to four digits only, the fifth digit being carried forward if five or over, or dropped if under five.

Outside diameters and wall thicknesses are carried to three decimal places, the fourth decimal being carried forward if five or over, or dropped if under five.

Hot Rolled and Cold Finished Steel Products

Product	When Shown As			Single Weight Formulas
Structurals and Bar Shapes	Thickness	Width	Length	
	Wt. per Ft.	Inches	Feet	$Wt./Lin. Ft \times L$
	Inches	Inches	Feet	$Wt./Lin. Ft \times L$
Plates, Strip and Flats	Inches	Inches	Inches	$.2833 \times T \times W \times L$
	Inches	Inches	Feet	$3.4 \times T \times W \times L$
	Inches	Feet	Feet	$40.8 \times T \times W \times L$
	USS. Ga. No.	Feet	Feet	$Wt./Sq.Ft. \times W \times L$
	Wt. per Sq. Ft.	Feet	Feet	$Wt./Sq.Ft. \times W \times L$
Hot and C.R. Sheets	Inches	Inches	Inches	$.2904 \times T \times W \times L$
	Inches	Inches	Feet	$3.485 \times T \times W \times L$
	Inches	Feet	Feet	$41.82 \times T \times W \times L$
	USS. Ga. No.	Feet	Feet	$Wt./Sq.Ft. \times W \times L$
	Wt. per Sq. Ft.	Feet	Feet	$Wt./Sq.Ft. \times W \times L$
Plate Circles	Thickness	Diameter		
	Inches	Inches		$.2225 \times T \times D^2$
	Inches	Feet		$32.05 \times T \times D^2$
Sheet Circles	Inches	Inches		$.228 \times T \times D^2$
	Inches	Feet		$32.85 \times T \times D^2$
Bars { Square Round Hexagon Octagon	Diameter	Length		
	Inches	Feet		$3.4 \times D^2 \times L$
	Inches	Feet		$2.67 \times D^2 \times L$
	Inches	Feet		$2.945 \times D^2 \times L$
	Inches	Feet		$2.817 \times D^2 \times L$
Tubing	Thickness	Outer Diameter	Length	
	Inches	Inches	Feet	$10.68 \times (D - T) \times T \times L$

Symbols Used in Above Formulas Refer to the Following:

T Thickness L Length
 W Width D Diameter
 $Wt./Sq. Ft.$ Weight per Square Foot in Pounds

BRITISH STANDARD PIPE FLANGES

As Published by the ENGINEERING STANDARDS COMMITTEE

For Steam Pressure Up to 55 Lbs.

For Water Pressure Up to 200 Lbs. Sq. Inch

Internal Diameter of Pipe	Diameter of Flange	Diameter of Bolt Circle	Number of Bolts	Diameter of Bolts	THICKNESS OF FLANGE			Stamped or Forged Wrought Iron or Steel
					Cast Iron and Steel or Iron Welded on	Cast Steel and Bronze		
Inch	In.	In.		In.	In.	In.		In.
1/2	3 3/4	2 5/8	4	1/2	1/2	3/8		3/16
3/4	4	2 7/8	4	1/2	1/2	3/8		5/16
1	4 1/2	3 1/4	4	1/2	1/2	3/8		3/16
1 1/4	4 3/4	3 7/8	4	1/2	5/8	1/2		1/4
1 1/2	5 1/4	3 3/8	4	1/2	5/8	1/2		1/4
2	6	4 1/2	4	5/8	3/4	9/16		5/16
2 1/2	6 1/2	5	4	5/8	3/4	9/16		5/16
3	7 1/4	5 3/4	4	5/8	3/4	9/16		3/8
3 1/2	8	6 1/2	4	5/8	3/4	9/16		3/8
4	8 1/2	7	4	5/8	7/8	1 1/16		3/8
4 1/2	9	7 1/2	8	5/8	7/8	1 1/16		7/16
5	10	8 1/4	8	5/8	7/8	1 1/16		1/2
6	11	9 1/4	8	5/8	7/8	1 1/16		1/2
7	12	10 1/4	8	5/8	1	3/4		1/2
8	13 1/4	11 1/2	8	5/8	1	3/4		1/2
9	14 1/2	12 3/4	8	5/8	1	3/4		5/8
10	16	14	8	3/4	1	3/4		5/8
11	17	15	8	3/4	1 1/8	7/8		5/8
12	18	16	12	3/4	1 1/8	7/8		5/8

Bolt Holes, for 1/2 inch and 5/8 inch, the diameter of the holes to be 1/4 inch larger than the diameter of the bolts, and for the larger sizes of bolts 3/8 inch. Bolt holes to be drilled off center lines.

The above table does not apply to boiler feed pipes, or to other water pipes subject to exceptional shocks.

For Steam Pressures Up to 125 Lbs., 225 Lbs. and 325 Lbs. per Square Inch

Internal Diameter of Pipe	Diam. of Flange	Diam. of Bolt Circle	Number of Bolts	Diameter of Bolts		THICKNESS OF FLANGES					
						Cast Iron and Steel or Iron Welded on			Steel (Cast or Riveted on) and Bronze		
				125 lb.	325 lb.	125 lb.	225 lb.	325 lb.	125 lb.	225 lb.	325 lb.
1/2	3 3/4	2 5/8	4	1/2	1/2	1/2	1/2	5/8	3/8	7/16	5/8
3/4	4	2 7/8	4	1/2	1/2	1/2	1/2	5/8	3/8	7/16	5/8
1	4 1/2	3 1/4	4	5/8	5/8	1/2	5/8	3/4	3/8	1/2	1 1/16
1 1/4	5 1/4	3 7/8	4	5/8	5/8	5/8	5/8	3/4	1/2	1/2	1 1/16
1 1/2	5 1/2	4 1/8	4	5/8	5/8	5/8	3/4	7/8	1/2	9/16	3/4
2	6 1/2	5	4	5/8	3/4	3/4	7/8	1	5/8	1 1/16	7/8
2 1/2	7 1/4	5 3/4	8	5/8	3/4	3/4	7/8	1	5/8	1 1/16	7/8
3	8	6 1/2	8	5/8	3/4	3/4	1	1 1/4	5/8	3/4	1
3 1/2	8 1/2	7	8	5/8	3/4	7/8	1	1 1/4	3/4	3/4	1
4	9	7 1/2	8	5/8	3/4	7/8	1 1/8	1 3/8	3/4	7/8	1 1/8
4 1/2	10	8 1/4	8	3/4	7/8	7/8	1 1/8	1 3/8	3/4	7/8	1 1/8
5	11	9 1/4	8	3/4	7/8	1	1 1/4	1 1/2	7/8	1	1 1/4
6	12	10 1/4	12	3/4	7/8	1	1 1/4	1 1/2	7/8	1	1 1/4
7	13 1/4	11 1/2	12	3/4	7/8	1	1 3/8	1 5/8	7/8	1 1/8	1 3/8
8	14 1/2	12 3/4	12	3/4	7/8	1 1/8	1 3/8	1 5/8	1	1 1/8	1 3/8
9	16	14	12	7/8	1	1 1/8	1 1/2	1 3/4	1	1 1/4	1 1/2
10	17	15	12	7/8	1	1 1/8	1 1/2	1 7/8	1	1 1/4	1 1/8
11	18	16	16	7/8	1	1 1/4	1 5/8	1 7/8	1 1/8	1 3/8	1 5/8
12	19 1/4	17 1/4	16	7/8	1	1 1/4	1 5/8	2	1 1/8	1 3/8	1 1/4

The expansion for any length of pipe may be found by taking the difference in increased length at the minimum and maximum temperatures, dividing by 100 and multiplying by the length in feet of the line under consideration.

NATIONAL (AMERICAN) STANDARD FIRE HOSE COUPLING SCREW THREAD

Having Nominal Inside Diameters of 2½, 3, 3½, and 4½ Inches




Fig. 1 Typical Form of Standard Coupling

Characteristics of the National Standard Fire-Hose Coupling Screw Thread

1	Nominal inside diameter of hose coupling (C)	2½	3	3½	4½
2	Number of threads per inch	7½	6	6	4
3	Total length of threaded part of coupling and hydrant nipple, external thread (See L, Fig. 1)	1	1⅛	1⅛	1¼
4	Distance from face of nipple to start of second turn (See I, Fig. 1)	¼	⅝	⅝	⅞
5	Depth of coupling swivel to washer seat (See H, Fig. 1)	1⅝	1⅞	1⅞	1⅞
6	Distance from face of coupling swivel to start of second turn (See J, Fig. 1)	⅝	¾	¾	⅞
7	Depth of thread of coupling swivel (See T, Fig. 1)	1⅞	1⅞	1⅞	1⅞
8	Nipple (external thread) cylindrical to base of thread
9	Coupling (internal thread) cylindrical to base of thread
10	Outer ends of external and internal thread should be terminated by the "Higbee Cut" on full thread to avoid crossing and mutilation of thread
11	American (National) Form of thread must be used

All dimensions given in inches.

Limiting Dimensions for Threads of Coupling Swivels and Hydrant Caps (Internal)

Nominal Size	No. of Threads Per Inch	Min. Major Diameter	Pitch Diameter		Minor Diameter	
			Max.	Min.	Max.	Min.
2.500	7.5	3.0836	3.0130	2.9970	2.9424	2.9104
3.000	6.0	3.6389	3.5486	3.5306	3.4583	3.4223
3.500	6.0	4.2639	4.1736	4.1556	4.0833	4.0473
4.500	4.0	5.7859	5.6485	5.6235	5.5111	5.4611

All dimensions given in inches.

Limiting Dimensions of Threads of Coupling and Hydrant Nipples (External)

Nominal Size	No. of Threads Per Inch	Major Diameter		Pitch Diameter		Max. Minor Diameter
		Max.	Min.	Max.	Min.	
2.500	7.5	3.0686	4.0366	2.9820	2.9660	2.8954
3.000	6.0	3.6239	3.5879	3.5156	3.4976	3.4073
3.500	6.0	4.2439	4.2079	4.1356	4.1176	4.0273
4.500	4.0	5.7609	5.7109	5.5985	5.5735	5.4361

All dimensions given in inches.

STANDARD MANUFACTURING TOLERANCES

ROUND WELDED STAINLESS STEEL TUBING
Diameter Tolerances

Dimensions of Tube			Ornamental Flash-In Tube			Full Finished Tube			O.D. Up to 25% Closer than Std. I.D. Up to 40% Closer than Std.							
Size of Tube, Inches	B.W. Gauge	O.D.		I.D.		Flash	Ovality		I.D.	Ovality		O.D.	O.D. Up to 25% Closer than Std. I.D. Up to 40% Closer than Std.			
		O.D.	I.D.	Ovality	Ovality		O.D.	Ovality		O.D.	Ovality					
3/8	16 to 23															
1/2	16 to 23	±.004	3/4						±.003	±.009	.004	±.002	±.003	±.0025	.003	
1/2	13 to 14								±.003	±.009	.004	±.002	.003	±.002	±.0035	.003
5/8	16 to 22	±.005	3/4	.005					±.003	±.013	.004	±.002	.003	±.003		
5/8	13 to 14								±.004	±.005	.004	±.003	.003	±.003	±.003	.003
3/4 to 7/8	18 to 23	±.005	3/4	.008					±.005	±.014	.006	±.004	.005			
3/4 to 7/8	14 to 16	±.004	3/4	.006					±.004	±.005	.004	±.003	.004	±.003	±.003	.004
3/4 to 7/8	12 to 13								±.005	±.006	.005	±.004	.005	±.004	±.0035	.005
1	18 to 23	±.005	3/4	.008					±.004	±.005	.005	±.003	.005	±.003	±.003	.005
1	13 to 16	±.004	3/4	.008					±.004	±.005	.004	±.003	.004	±.003	±.003	.004
1	11 to 12								±.005	±.006	.005	±.004	.005	±.004	±.0035	.005
1 1/8 to 1 1/4	18 to 23	±.005	3/4	.008					±.005	±.005	.008	±.004	.006	±.004	±.003	.006
1 1/8 to 1 1/4	14 to 16	±.005	3/4	.006					±.005	±.0075	.005	±.004	.005	±.004	±.0045	.005
1 1/8 to 1 1/4	11 to 13	±.006	3/4	.007					±.006	±.006	.007	±.0045	.0055	±.0045	±.0035	.0055

(Continued)

STANDARD MANUFACTURING TOLERANCES

ROUND WELDED STAINLESS STEEL TUBING—(Cont'd)
Diameter Tolerances

Dimensions of Tube		Ornamental Flash-In Tube		Full Finished Tube		O.D. Up to 25% Closer than Std. I.D. Up to 40% Closer than Std.	
Size of Tube, Inches	B.W. Gauge	O.D.	I.D. Flash	Ovality	O.D.	I.D.	Ovality
(Continued)							
1 3/8	18 to 23	± .005	3/4	.008	± .005	± .006	.008
1 1/8	14 to 16	± .005	3/4	.006	± .005	± .0075	.006
1 3/8	10 to 13	± .006	3/4	.008	± .006	± .0085	.008
1 1/2 to 2	18 to 23	± .006	3/4	.008	± .006	± .006	.008
1 1/2 to 2	14 to 16	± .005	3/4	.008	± .005	± .006	.006
1 1/2 to 2	10 to 13	± .005	3/4	.008	± .005	± .0075	.006
2 1/8 to 2 1/2	18 to 20	± .008	1	.010	± .008	± .008	.010
2 1/8 to 2 1/2	14 to 16	± .008	1	.010	± .008	± .008	.010
2 1/8 to 2 1/2	10 to 13	± .008	1	.010	± .008	± .008	.010
2 5/8 to 3	16 to 20	± .010	1	.020	± .010	± .010	.020
2 5/8 to 3	12 to 14	± .010	1	.015	± .010	± .010	.015
2 5/8 to 3	10 to 11	± .010	1	.015	± .010	± .010	.015
3 1/8 to 3 1/2	14 to 19	± .012	1	.020	± .012	± .012	.020
3 1/8 to 3 1/2	11 to 13	± .010	1	.020	± .010	± .012	.020
3 5/8 to 4	14 to 18	± .016	1	.025	± .016	± .012	.025
3 5/8 to 4	11 to 13	± .012	1	.025	± .016	± .012	.025
4 1/8 to 5	14 to 18	± .022	1	.032	± .022	± .016	.032
4 1/8 to 5	11 to 13	± .016	1	.032	± .016	± .016	.032

SPECIAL STRAIGHT FIXTURE PIPE THREADS**EXTERNAL THREADS**

SIZES—DIMENSIONS IN INCHES

Pipe Size Inches	Number of Threads to Inch	Major Diameter		Pitch Diameter		Toler- ance P. D.	Minor Diam. Max.	Min. Length of Thread
		Max.	Min.	Max. (Basic)	Min.			
$\frac{1}{8}$	27	0.3989	0.3868	0.3748	0.3708	0.004	0.3507	0.2638
$\frac{1}{4}$	18	0.5260	0.5089	0.4899	0.4849	0.005	0.4538	0.4018
$\frac{3}{8}$	18	0.6631	0.6460	0.6270	0.6220	0.005	0.5909	0.4078
$\frac{1}{2}$	14	0.8248	0.8033	0.7784	0.7724	0.006	0.7320	0.5337
$\frac{3}{4}$	14	1.0353	1.0138	0.9889	0.9829	0.006	0.9425	0.5457
1	11½	1.2951	1.2692	1.2386	1.2316	0.007	1.1821	0.6828

SPECIAL STRAIGHT FIXTURE PIPE THREADS**INTERNAL THREADS**

SIZES— DIMENSIONS IN INCHES

Pipe Size Inches	Number of Threads to Inch	Minor Diameter		Pitch Diameter		Toler- ance P. D.	Major Diam. Min.	Min. Length of Thread
		Min.	Max.	Min. (Basic)	Max.			
$\frac{1}{8}$	27	0.3507	0.3628	0.3748	0.3788	0.004	0.3989	0.2638
$\frac{1}{4}$	18	0.4538	0.4709	0.4899	0.4949	0.005	0.5260	0.4018
$\frac{3}{8}$	18	0.5909	0.6080	0.6270	0.6320	0.005	0.6631	0.4078
$\frac{1}{2}$	14	0.7320	0.7535	0.7784	0.7844	0.006	0.8248	0.5337
$\frac{3}{4}$	14	0.9425	0.9640	0.9889	0.9949	0.006	1.0353	0.5457
1	11½	1.1821	1.2080	1.2386	1.2456	0.007	1.2951	0.6828

ALUMINUM PIPE SIZES


Seamless Drawn Aluminum Tubes made to correspond with Iron Tubes and to fit Iron Tube Fittings.

List of Sizes, Lengths, etc.

WEIGHTS PER FOOT

Same as Iron, Size	Outside Diameter	Inside Diameter	Aluminum lbs.	Brass lbs.	Copper lbs.
$\frac{1}{8}$.405	.270	.083	.27	.29
$\frac{1}{4}$.540	.364	.145	.37	.39
$\frac{3}{8}$.675	.494	.193	.60	.64
$\frac{1}{2}$.840	.623	.290	.76	.80
$\frac{3}{4}$	1.050	.824	.387	1.22	1.28
1	1.315	1.048	.577	1.63	1.74
$1\frac{1}{4}$	1.660	1.380	.777	2.52	2.65
$1\frac{1}{2}$	1.900	1.611	.928	2.94	3.12
2	2.375	2.067	1.24	4.28	4.53
$2\frac{1}{2}$	2.875	2.468	1.98	5.58	5.92
3	3.500	3.067	2.59	8.35	8.84
$3\frac{1}{2}$	4.000	3.548	3.11	10.30	10.90
4	4.500	4.026	3.69	12.24	12.96

Brown & Sharpe Taper Shanks



No. of Taper	Diam. of Plug at Small End	Diam. at End of Socket	Standard Plug Depth	Whole Length of Shank	Depth of Hole	End of Socket to Keyway	Length of Keyway	Width of Keyway	Length of Tongue	Diam. of Tongue	Thickness of Tongue	Radius of Mill for Tongue	Radius of Tongue	Shank Depth	Taper per Foot	Taper per Inch
	D	A	P	B	H	K	L	W	T	d	t	R	a	S		
4	.35	.402	1 3/4	1 3/4	1 3/8	1 1/16	1 1/8	.228	1 1/8	.326	1/16	3/16	.056	1 1/8	.500	.0416
5	.45	.5229	1 3/4	2 1/2	1 7/8	1 1/16	3/4	.260	3/8	.420	1/8	1/8	.060	2 1/8	.500	.0416
6	.50	.599	2 3/8	2 3/4	2 1/2	2 1/16	7/8	.291	1/2	.460	1/4	1/8	.060	2 7/8	.500	.0416
7	.60	.725	3	3 3/8	3 1/8	2 3/8	1 1/2	.322	1 1/2	.560	1/2	3/8	.070	3 1/4	.500	.0416
8	.75	.8985	3 1/2	4 1/4	3 11/16	3 3/8	1	.353	1 1/2	.710	1 1/2	3/8	.080	4 1/8	.500	.0416
9	.90	1.0667	4	4 3/4	4 1/8	3 7/8	1 1/8	.385	1 1/2	.860	3/8	1/2	.100	4 5/8	.500	.0416
10	1.0446	1.289	5 1/16	6 3/4	5 11/16	5 1/2	1 3/8	.447	2 1/2	1.01	1/2	1/2	.110	6 1/8	.5161	.043
11	1.25	1.53	6 3/4	7 11/16	6 7/8	6 1/16	1 5/8	.447	2 1/2	1.21	1/2	1/2	.130	7 1/8	.500	.0416
12	1.50	1.797	7 7/8	8 5/8	7 7/4	6 11/16	1 1/2	.510	3/4	1.46	1/2	1/2	.150	7 11/16	.500	.0416
13	1.75	2.0729	7 3/4	8 3/4	7 7/8	7 7/16	1 1/2	.510	3/4	1.710	1/2	5/8	.170	8 1/8	.500	.0416
14	2.00	2.3437	8 3/4	9 1/2	8 3/8	8 1/2	1 11/16	.572	2 1/2	1.960	1/2	3/4	.190	9 1/2	.500	.0416
15	2.25	2.6145	8 3/4	10	8 7/8	8 11/16	1 11/16	.572	2 1/2	2.210	1/2	7/8	.210	9 3/4	.500	.0416
16	2.50	2.8855	9 3/4	10 1/2	9 3/8	9	1 3/8	.635	1 1/2	2.450	5/8		.230	10 1/4	.500	.0416

Brown & Sharpe Standard Tapers

FOR SPINDLES, ARBORS, COLLETS, etc.

No. of Taper	Diam. at Small End, Inches	No. of Taper	Diam. at Small End, Inches	No. of Taper	Diam. at Small End, Inches
1	.200	7	.600	13	1.750
2	.250	8	.750	14	2.000
3	.312	9	.900	15	2.250
4	.350	10	1.0446	16	2.500
5	.450	11	1.250	17	2.750
6	.500	12	1.500	18	3.000

Standard Taper Pin Reamers*

Taper, $\frac{1}{4}$ inch per foot.

No. of Taper Pin Reamer	Diameter at Large End of Reamer E	Diameter at Small End of Reamer D	Total Length of Reamer A	Length of Cutting Edges B	Length of Shank C	No. of Flutes
00000	0.0984	0.075	1-5/8	1-1/8	1/2	4
0000	0.1140	0.088	1-3/4	1-1/4	1/2	4
000	0.1296	0.101	2	1-3/8	5/8	4
00	0.1452	0.114	2-1/4	1-1/2	3/4	4
0	0.1608	0.127	2-3/8	1-5/8	3/4	6
1	0.1824	0.146	2-1/2	1-3/4	3/4	6
2	0.2036	0.162	3	2	1	6
3	0.2298	0.183	3-1/2	2-1/4	1-1/4	6
4	0.2600	0.208	4	2-1/2	1-1/2	6
5	0.3024	0.240	4-1/2	3	1-1/2	6
6	0.3544	0.279	5	3-5/8	1-1/2	6
7	0.4246	0.331	6	4-1/2	1-1/2	6
8	0.5072	0.398	6-3/4	5-1/4	1-1/2	8
9	0.6094	0.482	8	6-1/8	1-7/8	8
10	0.7266	0.581	9	7	2	8
11	0.8776	0.706	11-1/4	8-1/4	3	8
12	1.050	0.842	13-3/8	10	3-3/8
13	1.2586	1.009	16	12	4
14	1.5412	1.250	18-1/4	14	4-1/4

*Adopted by manufacturers of reamers and taper pins.

Standard Taper Pins

No. of Taper Pin	Diameter F at Large End of Pin	Approx. Fractional Size F	Maximum Length L
3	0.219	7/32	1-3/4
4	0.250	1/4	2
5	0.289	19/64	2-1/4
6	0.341	11/32	3
7	0.409	13/32	3-3/4
8	0.492	1/2	4-1/2
9	0.591	19/32	5-1/4
10	0.706	23/32	6
11	0.860	55/64	7-1/4
12	1.032	1-1/32	9
13	1.241	1-15/64	11
14	1.523	1-33/64	13

While filing and polishing try work in gauge and use rub test with Prussian Blue to insure proper taper and fit.

A cut of 8 thousandths will allow the gauge to go approximately $\frac{3}{8}$ " farther on the work on either Jarno or Morse taper and approximately $\frac{5}{16}$ " on a Brown & Sharpe taper.

Rules for Figuring Tapers

Given	To Find	Rule
The taper per foot.....	The taper per inch.....	Divide the taper per foot by 12.
The taper per inch.....	The taper per foot.....	Multiply the taper per inch by 12.
End diameters and length of taper in inches.....	The taper per foot.....	Subtract small diameter from large; divide by length of taper, and multiply quotient by 12.
Large diameter and length of taper in inches and taper per foot.....	Diameter at small end in inches.....	Divide taper per foot by 12; multiply by length of taper, and subtract result from large diameter.
Small diameter and length of taper in inches, and taper per foot.....	Diameter at large end in inches.....	Divide taper per foot by 12; multiply by length of taper, and add result to small diameter.
The taper per foot and two diameters in inches.....	Distance between two given diameters in inches.....	Subtract small diameter from large; divide remainder by taper per foot, and multiply quotient by 12.
The taper per foot.....	Amount of taper in a certain length given in inches.....	Divide taper per foot by 12; multiply by given length of tapered part.

TAPERS PER FOOT, AND CORRESPONDING ANGLES

Taper Per Foot	Included Angle			Angle With Center Line			Taper Per Foot	Included Angle			Angle With Center Line		
	Deg.	Min.	Sec.	Deg.	Min.	Sec.		Deg.	Min.	Sec.	Deg.	Min.	Sec.
1/64	0	4	28	0	2	14	17 1/2	8	56	2	4	28	1
1/32	0	8	58	0	4	29	1 15/16	9	13	50	4	36	55
1/16	0	17	54	0	8	57	2	9	31	36	4	45	48
3/32	0	26	52	0	13	26	2 1/8	10	7	10	5	3	35
1/8	0	35	48	0	17	54	2 1/4	10	42	42	5	21	21
5/32	0	44	44	0	22	22	2 3/8	11	18	10	5	39	5
3/16	0	53	44	0	26	52	2 1/2	11	53	36	5	56	48
7/32	1	2	34	0	31	17	2 5/8	12	29	2	6	14	31
1/4	1	11	36	0	35	48	2 3/4	13	4	24	6	32	12
5/16	1	20	30	0	40	15	2 7/8	13	39	42	6	49	51
3/8	1	29	30	0	44	45	3	14	15	0	7	7	30
7/16	1	38	22	0	49	11	3 1/8	14	50	14	7	25	7
1/2	1	47	24	0	53	42	3 1/4	15	25	24	7	42	42
5/8	1	50	24	0	58	12	3 3/8	16	0	34	8	0	17
3/4	2	5	18	1	2	39	3 1/2	16	35	40	8	17	50
7/8	2	14	16	1	7	8	3 5/8	17	10	40	8	35	20
15/16	2	23	10	1	11	35	3 3/4	17	45	40	8	52	50
1	2	32	4	1	16	2	3 7/8	18	20	34	9	10	17
1 1/16	2	41	4	1	20	32	4	18	55	28	9	27	44
1 1/8	2	50	2	1	25	1	4 1/8	19	30	18	9	45	9
1 1/4	2	59	42	1	29	51	4 1/4	20	5	2	10	2	31
1 1/2	3	7	56	1	33	58	4 3/8	20	39	44	10	19	52
1 3/4	3	16	54	1	38	27	4 1/2	21	14	2	10	37	1
1 7/8	3	25	50	1	42	55	4 5/8	21	48	54	10	54	27
2	3	34	44	1	47	22	4 3/4	22	23	22	11	11	41
2 1/16	3	43	44	1	51	52	4 7/8	22	57	48	11	28	54
2 1/8	3	52	38	1	56	19	5	23	32	12	11	46	6
2 1/4	4	1	36	2	0	48	5 1/8	24	6	28	12	3	14
2 1/2	4	10	32	2	5	16	5 1/4	24	40	42	12	20	21
2 3/4	4	19	34	2	9	47	5 3/8	25	14	48	12	37	24
2 7/8	4	28	24	2	14	12	5 1/2	25	48	48	12	54	24
3	4	37	20	2	18	40	5 5/8	26	22	52	13	11	26
3 1/16	4	46	18	2	23	9	5 3/4	26	56	46	13	28	23
3 1/8	5	5	4	2	32	6	5 7/8	27	30	34	13	45	17
3 1/4	5	21	44	2	40	52	6	28	4	2	14	2	1
3 1/2	5	39	54	2	49	57	6 1/8	28	37	58	14	18	39
3 3/4	5	57	48	2	58	54	6 1/4	29	11	34	14	35	47
3 7/8	6	15	38	3	7	49	6 3/8	29	45	18	14	52	39
4	6	33	26	3	16	43	6 1/2	30	18	26	15	9	13
4 1/16	6	51	20	3	25	40	6 5/8	30	51	48	15	25	54
4 1/8	7	9	10	3	34	35	6 3/4	31	25	2	15	42	31
4 1/4	7	26	58	3	43	29	6 7/8	31	58	10	15	59	5
4 1/2	7	44	48	3	52	24	7	32	31	12	15	15	36
4 3/4	8	2	38	4	1	19	7 1/8	33	4	8	16	32	4
4 7/8	8	20	26	4	10	13	7 1/4	33	36	40	16	48	20
5	8	38	16	4	19	8	7 3/8	34	9	50	16	4	55

Arthur Morgan Trucking Co.

TRANSFER, DRAYAGE AND FORWARDING
Machinery Moving, Hoisting and Erecting



We are authorized to Operate by the
 Interstate Commerce Commission
 and
 Public Service Commission
 over the highways of
 MISSOURI, ILLINOIS, TENNESSEE
 AND KENTUCKY.

"Our Watchword"



*"For Any Load That Fits
 the Road"*

Call **ARTHUR MORGAN**

2923 NORTH BROADWAY

Saint Louis, Missouri

C E n t r a l 6 3 9 1

Arthur L. Morgan, Jr., Gen. Mgr.

This method cannot be used for boring tapers.

The amount the tailstock top must be set over depends on the amount of the taper per foot and the over-all length of the work. With the same amount of setover, pieces of different lengths will be machined with different tapers, as shown in Fig. 1. Notice that the tailstock center is set over one-half the total amount of the taper for the entire length of the work.




Fig. 1 Machining a Taper with the Tailstock Top Set Over





Fig. 2 With the Tailstock Set Over the Same Amount, Pieces of Different Lengths are Machined with Different Tapers

Morse Tapers



Number of Taper	Diam. of Plug at Small End, Inches	Diam. at End of Socket, Inches	SHANK		Depth of Hole, Inches	Standard Plug Depth, Inches	TONGUE					KEYWAY			Taper per Foot	Taper per Inch	Number of Key
			Whole Length of Shank, Inches	Shank Depth, Inches			Thickness of Tongue, Inches	Length of Tongue, Inches	Rad. of Mill for Tongue, Inches	Diameter of Tongue, Inches	Radius of Tongue, Inches	Width of Keyway, Inches	Length of Keyway, Inches	End of Socket to Keyway, Inches			
0	.252	.3561	2 1/16	2 1/2	2 1/2	2	1/2	1/4	1/16	.235	.04	.160	1/16	1 1/2	.62460	.05205	0
1	.369	.475	2 1/8	2 1/4	2 1/4	2 1/8	13/64	3/8	1/16	.343	.05	.213	3/4	2 1/8	.59858	.04988	1
2	.572	.700	3 1/8	2 13/16	2 3/8	2 3/8	1/4	1/2	1/4	.11	.06	.260	7/8	2 1/2	.59941	.04995	2
3	.778	.938	3 7/8	3 11/16	3 1/4	3 1/4	5/16	5/8	3/4	.23	.08	.322	1 1/2	3 1/8	.60235	.05019	3
4	1.020	1.231	4 7/8	4 3/8	4 1/2	4 1/2	15/32	3/4	3/8	.31	.10	.478	1 3/4	3 7/8	.62326	.05193	4
5	1.475	1.748	6 3/8	5 7/8	5 3/4	5 3/4	3/8	3/4	3/8	.11	.12	.635	1 1/2	4 1/8	.63151	.05262	5
6	2.116	2.494	8 1/8	8 1/4	7 3/8	7 3/4	3/4	1 1/8	1/2	2	.15	.760	1 3/4	7	.62565	.05213	6
7	2.750	3.270	11 3/8	11 3/4	10 3/8	10	1 1/8	1 3/8	3/4	2 3/8	.18	1.135	2 3/8	9 1/2	.62400	.05200	7


Brown & Sharpe Standard Taper Holes FOR SPINDLES, COLLETS, ETC.

No of Taper	Approx. Diam. at Large End, Inches	No. of Taper	Approx. Diam. at Large End, Inches	No of Taper	Approx. Diam. at Large End, Inches
6	19-32	10	1 1-4	14	2 11-32
7	23-32	11	1 1-2	16	2 7-8
9	1 1-16	12	1 13-16	18	3 7-16

COMPOUND FOR WELDING CAST STEEL.

Mix 41 parts of boracic acid, 35 parts of pure, dried common salt, 20 parts of ferrocyanide of potassium, 8 parts rosin and 4 parts carbonate of sodium. When this compound is to be used, a sufficient quantity is scattered upon the article to be welded, which has been heated to a light red heat. It is then heated to a strong yellow heat and the welding accomplished in the usual manner.


S. A. E. TAPER DIMENSIONS

TAPER PER FOOT = 1.500 ± 0.005 IN.

Nominal Diameter Inches	A Diam. of Shaft		B Diam. of Hole		C Length Shaft	D Length Hole
	Max.	Min.	Max.	Min.		
$\frac{1}{4}$	0.250	0.249	0.248	0.247	$\frac{5}{16}$	$\frac{3}{8}$
$\frac{3}{8}$	0.375	0.374	0.373	0.372	$\frac{7}{16}$	$\frac{1}{2}$
$\frac{1}{2}$	0.500	0.499	0.498	0.497	$\frac{9}{16}$	$\frac{3}{4}$
$\frac{5}{8}$	0.625	0.624	0.623	0.622	$\frac{11}{16}$	$\frac{3}{4}$
$\frac{3}{4}$	0.750	0.749	0.748	0.747	$\frac{13}{16}$	1
$\frac{7}{8}$	0.875	0.874	0.873	0.872	$1\frac{1}{8}$	$1\frac{1}{4}$
1	1.001	0.999	0.997	0.995	$1\frac{3}{8}$	$1\frac{1}{2}$
$1\frac{1}{8}$	1.126	1.124	1.122	1.120	$1\frac{3}{8}$	$1\frac{1}{2}$
$1\frac{1}{4}$	1.251	1.249	1.247	1.245	$1\frac{3}{8}$	$1\frac{1}{2}$
$1\frac{3}{8}$	1.376	1.374	1.372	1.370	$1\frac{7}{8}$	2
$1\frac{1}{2}$	1.501	1.499	1.497	1.495	$1\frac{7}{8}$	2
$1\frac{5}{8}$	1.626	1.624	1.622	1.620	$2\frac{1}{8}$	$2\frac{1}{4}$
$1\frac{3}{4}$	1.751	1.749	1.747	1.745	$2\frac{1}{8}$	$2\frac{1}{4}$
$1\frac{7}{8}$	1.876	1.874	1.872	1.870	$2\frac{3}{8}$	$2\frac{1}{2}$
2	2.001	1.999	1.997	1.995	$2\frac{3}{8}$	3
$2\frac{1}{4}$	2.252	2.248	2.245	2.242	$2\frac{3}{8}$	3
$2\frac{1}{2}$	2.502	2.498	2.495	2.492	$3\frac{3}{8}$	$3\frac{1}{2}$
$2\frac{3}{4}$	2.752	2.748	2.745	2.742	$3\frac{3}{8}$	$3\frac{1}{2}$
3	3.002	2.998	2.995	2.992	$3\frac{7}{8}$	4
$3\frac{1}{4}$	3.252	3.248	3.245	3.242	$4\frac{3}{8}$	$4\frac{1}{4}$
$3\frac{1}{2}$	3.502	3.498	3.495	3.492	$4\frac{3}{8}$	$4\frac{1}{2}$
4	4.002	3.998	3.995	3.992	$5\frac{3}{8}$	$5\frac{1}{2}$

Jarno Taper Shanks

Num- ber of Taper	Diameter at End of Socket Inches A	Diameter of Plug at Small End Inches B	Standard Plug Depth Inches C
1	0.125	0.10	$\frac{1}{2}$
2	0.250	0.20	$1\frac{1}{2}$
3	0.375	0.30	2
4	0.500	0.40	$2\frac{1}{2}$
5	0.625	0.50	3
6	0.750	0.60	$3\frac{1}{2}$
7	0.875	0.70	4
8	1.000	0.80	$4\frac{1}{2}$
9	1.125	0.90	5
10	1.250	1.00	$5\frac{1}{2}$
11	1.375	1.10	6
12	1.500	1.20	$6\frac{1}{2}$
13	1.625	1.30	7
14	1.750	1.40	$7\frac{1}{2}$
15	1.875	1.50	8
16	2.000	1.60	$8\frac{1}{2}$
17	2.125	1.70	9
18	2.250	1.80	$9\frac{1}{2}$
19	2.375	1.90	10
20	2.500	2.00	



**TAPERS FROM 1-16 TO 1 1-4 INCH PER FOOT
AMOUNT OF TAPER FOR LENGTHS UP TO 24 INCHES**

Length Tapered Inches	TAPER PER FOOT									
	1-16	3-32	1-8	1-4	3-8	1-2	5-8	3-4	1	1 1-4
1-32	.0002	.0002	.0003	.0007	.0010	.0013	.0016	.0020	.0026	.0033
1-16	.0003	.0005	.0007	.0013	.0020	.0026	.0033	.0039	.0052	.0065
1-8	.0007	.0010	.0013	.0026	.0039	.0052	.0065	.0078	.0104	.0130
3-16	.0010	.0015	.0020	.0039	.0059	.0078	.0098	.0117	.0156	.0195
1-4	.0013	.0020	.0026	.0052	.0078	.0104	.0130	.0156	.0208	.0260
5-16	.0016	.0024	.0033	.0065	.0098	.0130	.0163	.0195	.0260	.0326
3-8	.0020	.0029	.0039	.0078	.0117	.0156	.0195	.0234	.0312	.0391
7-16	.0023	.0034	.0046	.0091	.0137	.0182	.0228	.0273	.0365	.0456
1-2	.0026	.0039	.0052	.0104	.0156	.0208	.0260	.0312	.0417	.0521
9-16	.0029	.0044	.0059	.0117	.0176	.0234	.0293	.0352	.0469	.0586
5-8	.0033	.0049	.0065	.0130	.0195	.0260	.0326	.0391	.0521	.0651
11-16	.0036	.0054	.0072	.0143	.0215	.0286	.0358	.0430	.0573	.0716
3-4	.0039	.0059	.0078	.0156	.0234	.0312	.0391	.0469	.0625	.0781
13-16	.0042	.0063	.0085	.0169	.0254	.0339	.0423	.0508	.0677	.0846
7-8	.0046	.0068	.0091	.0182	.0273	.0365	.0456	.0547	.0729	.0911
15-16	.0049	.0073	.0098	.0195	.0293	.0391	.0488	.0586	.0781	.0977
1	.0052	.0078	.0104	.0208	.0312	.0417	.0521	.0625	.0833	.1042
2	.0104	.0156	.0208	.0417	.0625	.0833	.1042	.125	.1667	.2083
3	.0156	.0234	.0312	.0625	.0937	.1250	.1562	.1875	.250	.3125
4	.0208	.0312	.0417	.0833	.125	.1667	.2083	.250	.3333	.4167
5	.0260	.0391	.0521	.1042	.1562	.2083	.2604	.3125	.4167	.5208
6	.0312	.0469	.0625	.125	.1875	.250	.3125	.375	.500	.625
7	.0365	.0547	.0729	.1458	.2187	.2917	.3616	.4375	.5833	.7292
8	.0417	.0625	.0833	.1667	.250	.3333	.4167	.500	.6667	.8333
9	.0469	.0703	.0937	.1875	.2812	.375	.4687	.5625	.750	.9375
10	.0521	.0781	.1042	.2083	.3125	.4167	.5208	.625	.8333	1.0417
11	.0573	.0859	.1146	.2292	.3437	.4583	.5729	.6875	.9167	1.1458
12	.0625	.0937	.125	.250	.375	.500	.625	.750	1.000	1.250
13	.0677	.1016	.1354	.2708	.4062	.5417	.6771	.8125	1.0833	1.3542
14	.0729	.1091	.1458	.2917	.4375	.5833	.7292	.875	1.1667	1.4583
15	.0781	.1172	.1562	.3125	.4687	.625	.7812	.9375	1.250	1.5625
16	.0833	.125	.1667	.3333	.500	.6667	.8333	1.000	1.3333	1.6667
17	.0885	.1328	.1771	.3542	.5312	.7083	.8851	1.0625	1.4167	1.7708
18	.0937	.1406	.1875	.3750	.5625	.750	.9375	1.125	1.500	1.875
19	.0990	.1481	.1979	.3958	.5937	.7917	.9896	1.1875	1.5833	1.9792
20	.1042	.1562	.2083	.4167	.625	.8333	1.0417	1.250	1.6667	2.0833
21	.1091	.1611	.2187	.4375	.6562	.875	1.0937	1.3125	1.750	2.1875
22	.1116	.1719	.2292	.4583	.6875	.9167	1.1458	1.375	1.8333	2.2917
23	.1198	.1797	.2396	.4792	.7187	.9583	1.1970	1.4375	1.9167	2.3958
24	.125	.1875	.250	.500	.750	1.000	1.250	1.500	2.000	2.500

Milling Machine Standard Tapers

as adopted by the Milling Machine Manufacturers of the
National Machine Tool Builders' Association

TO SHARP CORNER TAPER 3 1/2 IN PER FOOT	No. of Taper	A	B	*Threaded End of Draw-In Bolt
	10	5-8	3-8	
	20	7-8	1-2	
	30	1 1-4	5-8	
	40	1 3-4	1	{ 1-2" 13 N.C., R.H. 5-8" 11 N.C., R.H.
	50	2 3-4	1 9-16	{ 5-8" 11 N.C., R.H. 1" 8 N.C., R.H.

Adapters where possible, but limitations on certain Adapters require the use of a threaded hole to fit the smaller Threaded End of the Draw-In Bolt.

How to Calculate Amount of Setover for Tailstock


Tapers are usually specified in "inches per foot." For example some Brown & Sharpe tapers are $\frac{1}{2}$ in. per foot. To machine a Brown & Sharpe taper of $\frac{1}{2}$ in. per foot on a shaft exactly one foot long, the center should be set over $\frac{1}{4}$ in. or .250 in. If the piece is only 10 in. long, then the amount of setover would be $\frac{1}{2}$ of .250 in. or .125 in. The following rules may be used for calculating the amount of setover:

TAPER IN INCHES PER FOOT GIVEN—Divide the total length of the stock in inches by twelve and multiply this quotient by one-half the amount of taper per foot specified. The result is the amount of setover in inches.

DIAMETERS AT ENDS OF TAPER GIVEN—Divide the total length of the stock by the length of the portion to be tapered and multiply this quotient by one-half the difference in diameters; the result is the amount of the setover.

Adjusting the Tailstock Center


To set over the tailstock center for taper turning, loosen clamping nut of tailstock and back off set screw "G," illustrated the distance required; then screw in set screw "F" a like distance until it is tight, and clamp the tailstock to the lathe bed.



Measuring the Setover

To measure the setover of the tailstock center, place a scale having graduations on both edges between the two centers, as shown.

This will give an approximate measurement.




Measuring the Setover

Fitting Tapers to Gauges


The best way to machine an accurate taper is to fit the taper to a standard gauge. To test the taper, make a chalk mark along the entire length of the taper, place the work in the taper it is to fit and turn carefully by hand. Then remove the work and the chalk mark will show where the taper is bearing.

If the taper is a perfect fit, it will show along the entire length of the chalk mark. If the taper is not perfect, make the necessary adjustment, take another light chip and test again. Be sure the taper is correct before turning to the finished diameter.



Morse Standard Taper Plug Gauge and Socket Gauge

Table of Bevels



A Height, Inches	0°		1°		2°		3°		4°		5°		6°		7°		8°		9°		10°		11°	
	Angle		Angle		Angle		Angle		Angle		Angle		Angle		Angle		Angle		Angle		Angle		Angle	
	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.	Deg.	Min.
0	4	45	9	28	14	03	18	26	22	37	26	34	30	15	33	42	36	52	39	48	42	31
$\frac{1}{32}$	0	09	4	55	9	37	14	11	18	35	22	45	26	41	30	22	33	48	36	58	39	54	42	36
$\frac{1}{16}$	0	18	5	04	9	45	14	19	18	43	22	53	26	49	30	29	33	54	37	04	39	59	42	40
$\frac{3}{32}$	0	27	5	12	9	54	14	28	18	50	23	00	26	55	30	35	34	00	37	10	40	05	42	45
$\frac{1}{8}$	0	36	5	20	10	02	14	36	18	59	23	08	27	02	30	42	34	07	37	15	40	10	42	50
$\frac{5}{32}$	0	45	5	31	10	12	14	45	19	07	23	15	27	10	30	49	34	13	37	20	40	15	42	55
$\frac{3}{16}$	0	54	5	39	10	20	14	53	19	15	23	23	27	17	30	56	34	18	37	26	40	20	43	00
$\frac{7}{32}$	1	02	5	48	10	29	15	01	19	23	23	30	27	24	31	02	34	24	37	32	40	25	43	05
$\frac{1}{4}$	1	11	5	57	10	38	15	09	19	30	23	38	27	30	31	09	34	30	37	38	40	30	43	10
$\frac{5}{16}$	1	20	6	06	10	46	15	18	19	38	23	46	27	38	31	15	34	37	37	43	40	35	43	14
$\frac{3}{8}$	1	30	6	15	10	55	15	26	19	46	23	53	27	45	31	22	34	43	37	49	40	40	43	19
$\frac{7}{16}$	1	38	6	24	11	04	15	34	19	54	24	00	27	52	31	28	34	49	37	55	40	46	43	24
$\frac{1}{2}$	1	47	6	32	11	12	15	42	20	02	24	08	27	58	31	35	34	55	38	00	40	51	43	28
$\frac{5}{8}$	1	57	6	41	11	20	15	51	20	10	24	16	28	06	31	41	35	00	38	05	40	56	43	33
$\frac{3}{4}$	2	06	6	50	11	29	16	00	20	18	24	23	28	13	31	48	35	07	38	11	41	01	43	38
$\frac{7}{8}$	2	15	6	59	11	38	16	08	20	26	24	30	28	20	31	54	35	13	38	16	41	06	43	42
$\frac{15}{16}$	2	24	7	08	11	46	16	16	20	34	24	38	28	27	32	00	35	19	38	22	41	11	43	47
$\frac{1}{8}$	2	33	7	16	11	55	16	24	20	41	24	45	28	34	32	07	35	25	38	27	41	16	43	51
$\frac{3}{16}$	2	41	7	25	12	03	16	32	20	49	24	53	28	41	32	14	35	31	38	33	41	21	43	56
$\frac{1}{4}$	2	50	7	34	12	12	16	40	20	57	25	00	28	48	32	20	35	36	38	39	41	26	44	01
$\frac{5}{16}$	2	59	7	43	12	20	16	49	21	05	25	08	28	55	32	26	35	42	38	44	41	31	44	06
$\frac{3}{8}$	3	08	7	52	12	30	16	57	21	12	25	15	29	02	32	32	35	48	38	50	41	37	44	10
$\frac{7}{16}$	3	17	8	00	12	38	17	05	21	20	25	22	29	08	32	38	35	55	38	55	41	41	44	15
$\frac{1}{2}$	3	26	8	09	12	46	17	13	21	28	25	29	29	15	32	45	36	00	39	00	41	46	44	20
$\frac{5}{8}$	3	35	8	18	12	55	17	21	21	35	25	37	29	22	32	51	36	06	39	06	41	51	44	24
$\frac{3}{4}$	3	44	8	27	13	04	17	30	21	44	25	44	29	28	32	58	36	12	39	11	41	56	44	29
$\frac{7}{8}$	3	52	8	35	13	12	17	38	21	52	25	51	29	35	33	04	36	17	39	16	42	01	44	33
$\frac{15}{16}$	4	01	8	44	13	20	17	46	21	59	25	58	29	42	33	10	36	24	39	21	42	06	44	38
$\frac{1}{8}$	4	10	8	53	13	29	17	54	22	07	26	05	29	48	33	17	36	30	39	27	42	11	44	42
$\frac{3}{16}$	4	20	9	02	13	37	18	02	22	15	26	13	29	55	33	23	36	35	39	32	42	16	44	47
$\frac{1}{4}$	4	28	9	11	13	45	18	10	22	22	26	20	30	02	33	29	36	40	39	38	42	21	44	51
$\frac{5}{16}$	4	37	9	20	13	54	18	18	22	30	26	27	30	09	33	35	36	46	39	43	42	26	44	56

Metric Threads

Metric threads can be cut through the quick change gear box by the addition of compound gears between the drive gear on the head and the gear on the feed box.

Size Lathe	Compound Gears	Range of Threads
10"	127T—90T	$\frac{1}{4}$ M. M. Pitch to $3\frac{3}{4}$ M. M. Pitch
13"—15"	127T—120T	$\frac{1}{8}$ M. M. Pitch to 7 M. M. Pitch
17"—19"	127T—120T	$\frac{1}{16}$ M. M. Pitch to 16 M. M. Pitch
21"—24"	127T—120T	203 M. M. Pitch to 24 M. M. Pitch

Lengths of Circular Arcs

Degrees and Radius of Circle Being Given.

Formula:—Length of Arcs = $\frac{3.1416}{180} \times \text{Radius} \times$

Rule:—Multiply the factor in the table for any given number of degrees by the radius.

Example:—Given, a curve of a radius of 55 ft. and an angle of $78^{\circ} 20'$, what is the length of the Arc?

Factor in the table for $78^\circ = 1.361356$

Factor in the table for $20' = .005817$

Factor = 1.367173
$$1.367173 \times 55 \text{ ft.} = 75.19 \text{ ft.}$$

Degrees													Min.		
1	.017453	31	.541052	61	1.064650	91	1.588249	121	2.111848	151	2.635447	1	.000290	31	.009017
2	.034906	32	.558505	62	1.082104	92	1.605702	122	2.129301	152	2.652900	2	.000581	32	.009308
3	.052359	33	.575958	63	1.099557	93	1.623156	123	2.146755	153	2.670353	3	.000872	33	.009599
4	.069813	34	.593411	64	1.117010	94	1.640609	124	2.164208	154	2.687807	4	.001163	34	.009890
5	.087266	35	.610865	65	1.134464	95	1.658062	125	2.181661	155	2.705260	5	.001454	35	.010181
6	.104719	36	.628318	66	1.151917	96	1.675516	126	2.199114	156	2.722713	6	.001745	36	.010472
7	.122173	37	.645771	67	1.169370	97	1.692969	127	2.216568	157	2.740166	7	.002036	37	.010762
8	.139626	38	.663225	68	1.186823	98	1.710422	128	2.234021	158	2.757620	8	.002327	38	.011053
9	.157079	39	.680678	69	1.204277	99	1.727876	129	2.251474	159	2.775073	9	.002618	39	.011344
10	.174532	40	.698131	70	1.221730	100	1.745329	130	2.268928	160	2.792526	10	.002908	40	.011635
11	.191986	41	.715583	71	1.239183	101	1.762782	131	2.286381	161	2.809980	11	.003199	41	.011926
12	.209439	42	.733038	72	1.256637	102	1.780235	132	2.303834	162	2.827433	12	.003490	42	.012217
13	.226892	43	.750491	73	1.274090	103	1.797689	133	2.321287	163	2.844886	13	.003781	43	.012508
14	.244346	44	.767944	74	1.291543	104	1.815142	134	2.338741	164	2.862340	14	.004072	44	.012799
15	.261799	45	.785398	75	1.308996	105	1.832595	135	2.356194	165	2.879793	15	.004363	45	.013090
16	.279252	46	.802851	76	1.326450	106	1.850049	136	2.373647	166	2.897246	16	.004654	46	.013380
17	.296706	47	.820304	77	1.343903	107	1.867502	137	2.391101	167	2.914699	17	.004945	47	.013671
18	.314159	48	.837758	78	1.361356	108	1.884955	138	2.408554	168	2.932153	18	.005236	48	.013962
19	.331612	49	.855211	79	1.378810	109	1.902408	139	2.426007	169	2.949606	19	.005526	49	.014253
20	.349065	50	.872664	80	1.396263	110	1.919862	140	2.443461	170	2.967059	20	.005817	50	.014544
21	.366519	51	.890117	81	1.413716	111	1.937318	141	2.460914	171	2.984513	21	.006108	51	.014835
22	.383972	52	.907571	82	1.431170	112	1.954768	142	2.478367	172	3.001966	22	.006399	52	.015126
23	.401425	53	.925024	83	1.448623	113	1.972222	143	2.495820	173	3.019419	23	.006690	53	.015417
24	.418879	54	.942477	84	1.466076	114	1.989675	144	2.513274	174	3.036872	24	.006981	54	.015708
25	.436332	55	.959931	85	1.483529	115	2.007128	145	2.530727	175	3.054326	25	.007272	55	.015998
26	.453785	56	.977384	86	1.500983	116	2.024581	146	2.548180	176	3.071779	26	.007563	56	.016289
27	.471238	57	.994837	87	1.518436	117	2.042035	147	2.565634	177	3.089232	27	.007854	57	.016580
28	.488692	58	1.012291	88	1.535889	118	2.059488	148	2.583087	178	3.106686	28	.008144	58	.016871
29	.506145	59	1.029744	89	1.553343	119	2.076941	149	2.600540	179	3.124139	29	.008435	59	.017162
30	.523598	60	1.047197	90	1.570796	120	2.094395	150	2.617993	180	3.141592	30	.008726	60	.017453

Decimals of a Foot for Each $\frac{1}{32}$ of an Inch

[illegible]

Areas and Volumes Plane Surfaces

CIRCLES

Let R = radius,
 D = diameter,




Fig. 500-517.

L = length of arc,
 V = Rise, or height of arc,

C = chord of the arc,
 c = chord of $\frac{1}{2}$ the arc

$$L = \frac{8c - C}{3} \text{ very nearly}$$

$$C = 2\sqrt{c^2 - V^2} = 2\sqrt{(D-V) \times V}$$

$$c = \sqrt{D \times V} = \frac{3L + C}{8}$$

$$D = \frac{c^2}{V} = \frac{C^2}{4V} + V \quad V = \frac{c^2}{D}$$

$$\text{Area of a circle} = \pi R^2 = 3.1416 R^2$$

$$\text{Area of sector of circle} = \text{Arc of sector} \times \frac{1}{2} \text{ radius} = \frac{1}{2} L R$$

SPHERES: Area of Sphere = $4 \times \text{Area of a great circle} = \pi D^2$

$$\text{Volume of Sphere} = \text{Area} \times \text{one third radius} = \frac{\pi D^3}{6}$$

ELLIPSE: Area = $\frac{1}{4} \pi AB$, A and B being length and breadth respectively.

TRIANGLES: Area = $\frac{1}{2} \text{ Base} \times \text{altitude}$

$$= \sqrt{S(S-A)(S-B)(S-C)} \quad S = \frac{1}{2} \text{ Sum of 3 sides, } A, B \text{ and } C.$$


TRAPEZIUM: Area = Sum of area of its 2 triangles.

TRAPEZOID: Area = $\frac{1}{2}$ sum of parallel sides \times perpendicular height.

PARALLELOGRAM: Area = Base \times perpendicular height.

REGULAR POLYGON: Area = $\frac{1}{2}$ Sum of Sides \times Inside-radius.

Lateral Surfaces (S) and Volumes (V) of Miscellaneous Solids




Parallelopiped.

$$S = [\text{perimeter, } P, \text{ perpendicular to sides} \times \text{lateral length, } l] = Pl$$

$$V = [\text{area of base, } B, \times \text{perpendicular height, } h] = Bh$$

$$V = [\text{area of section, } A, \text{ perpendicular to sides} \times \text{lateral length, } l] = Al$$



Prism, Right or Oblique, Regular or Irregular.

$$S = [\text{perimeter, } P, \text{ perpendicular to sides} \times \text{lateral length, } l] = Pl$$

$$V = [\text{area of base, } B, \times \text{perpendicular height, } h] = Bh$$

$$V = [\text{area of section, } A, \text{ perpendicular to sides} \times \text{lateral length, } l] = Al$$



Cylinder, Right or Oblique, Circular or Elliptical.

$$S = [\text{perimeter of base, } P, \times \text{perpendicular height, } h] = Ph$$

$$S = [\text{perimeter, } P, \text{ perpendicular to sides} \times \text{lateral length, } l] = Pl$$

$$V = [\text{area of base, } B, \times \text{perpendicular height, } h] = Bh$$


$$V = [\text{area of section, } A, \text{ perpendicular to sides} \times \text{lateral length, } l] = Al$$



Frustum of Any Prism or Cylinder.

$$V = [\text{area of base, } B, \times \text{perpendicular distance, } h, \text{ from base to center of gravity of opposite face}] = Bh$$

$$\text{For cylinder: } V = \frac{1}{2} A (l_1 + l_2)$$



Pyramid or Cone, Right and Regular


$$S = [\text{perimeter of base, } P, \times \frac{1}{2} \text{ slant height, } l] = \frac{1}{2} Pl$$

$$V = [\text{area of base, } B, \times \frac{1}{3} \text{ perpendicular height, } h] = \frac{1}{3} Bh$$



Pyramid or Cone, Regular or Irreg.

$$V = [\frac{1}{3} \text{ volume of prism or cylinder of same base and perpendicular height}]$$




Frustum of Pyramid or Cone, Right and Regular, Parallel Ends.

$$S = [(\text{sum of perimeter of base, } P, \text{ and top, } p) \times \frac{1}{2} \text{ slant height, } l] = \frac{1}{2} l (P + p)$$

$$V = [(\text{sum of areas of base, } B, \text{ and top, } b, \text{ + square root of their products}) \times \frac{1}{3} \text{ perpendicular height, } h]$$

$$= \frac{1}{3} h (B + b + \sqrt{Bb})$$



Frustum of Any Pyramid or Cone, Parallel Ends.

$$V = [(\text{sum of areas of base, } B, \text{ and top, } b, \text{ + square root of their products}) \times \frac{1}{3} \text{ perpendicular height, } h]$$

$$= \frac{1}{3} h (B + b + \sqrt{Bb})$$



Wedge, Parallelogram Face

$$V = [\frac{1}{6} (\text{sum of three edges, } a, b, c, \times \text{perpendicular height, } h, \times \text{perpendicular width, } d)] = \frac{1}{6} d h (2a + b)$$

("Kent" and "Carnegie")

TABLE FOR CONVERTING MINUTES INTO DECIMALS OF A DEGREE

Min.	Dec. of Degree	Min.	Dec. of Degree	Min.	Dec. of Degree	Min.	Dec. of Degree	Min.	Dec. of Degree
1/4	0.00416	12 1/4	0.20416	24 1/4	0.40416	36 1/4	0.60416	48 1/4	0.80416
1/2	0.00833	12 1/2	0.20833	24 1/2	0.40833	36 1/2	0.60833	48 1/2	0.80833
3/4	0.01250	12 3/4	0.21250	24 3/4	0.41250	36 3/4	0.61250	48 3/4	0.81250
1	0.01666	13	0.21666	25	0.41666	37	0.61666	49	0.81666
1 1/4	0.02083	13 1/4	0.22083	25 1/4	0.42083	37 1/4	0.62083	49 1/4	0.82083
1 1/2	0.02500	13 1/2	0.22500	25 1/2	0.42500	37 1/2	0.62500	49 1/2	0.82500
1 3/4	0.02916	13 3/4	0.22916	25 3/4	0.42916	37 3/4	0.62916	49 3/4	0.82916
2	0.03333	14	0.23333	26	0.43333	38	0.63333	50	0.83333
2 1/4	0.03750	14 1/4	0.23750	26 1/4	0.43750	38 1/4	0.63750	50 1/4	0.83750
2 1/2	0.04166	14 1/2	0.24166	26 1/2	0.44166	38 1/2	0.64166	50 1/2	0.84166
2 3/4	0.04583	14 3/4	0.24583	26 3/4	0.44583	38 3/4	0.64583	50 3/4	0.84583
3	0.05000	15	0.25000	27	0.45000	39	0.65000	51	0.85000
3 1/4	0.05416	15 1/4	0.25416	27 1/4	0.45416	39 1/4	0.65416	51 1/4	0.85416
3 1/2	0.05833	15 1/2	0.25833	27 1/2	0.45833	39 1/2	0.65833	51 1/2	0.85833
3 3/4	0.06250	15 3/4	0.26250	27 3/4	0.46250	39 3/4	0.66250	51 3/4	0.86250
4	0.06666	16	0.26666	28	0.46666	40	0.66666	52	0.86666
4 1/4	0.07083	16 1/4	0.27083	28 1/4	0.47083	40 1/4	0.67083	52 1/4	0.87083
4 1/2	0.07500	16 1/2	0.27500	28 1/2	0.47500	40 1/2	0.67500	52 1/2	0.87500
4 3/4	0.07916	16 3/4	0.27916	28 3/4	0.47916	40 3/4	0.67916	52 3/4	0.87916
5	0.08333	17	0.28333	29	0.48333	41	0.68333	53	0.88333
5 1/4	0.08750	17 1/4	0.28750	29 1/4	0.48750	41 1/4	0.68750	53 1/4	0.88750
5 1/2	0.09166	17 1/2	0.29166	29 1/2	0.49166	41 1/2	0.69166	53 1/2	0.89166
5 3/4	0.09583	17 3/4	0.29583	29 3/4	0.49583	41 3/4	0.69583	53 3/4	0.89583
6	0.10000	18	0.30000	30	0.50000	42	0.70000	54	0.90000
6 1/4	0.10416	18 1/4	0.30416	30 1/4	0.50416	42 1/4	0.70416	54 1/4	0.90416
6 1/2	0.10833	18 1/2	0.30833	30 1/2	0.50833	42 1/2	0.70833	54 1/2	0.90833
6 3/4	0.11250	18 3/4	0.31250	30 3/4	0.51250	42 3/4	0.71250	54 3/4	0.91250
7	0.11666	19	0.31666	31	0.51666	43	0.71666	55	0.91666
7 1/4	0.12083	19 1/4	0.32083	31 1/4	0.52083	43 1/4	0.72083	55 1/4	0.92083
7 1/2	0.12500	19 1/2	0.32500	31 1/2	0.52500	43 1/2	0.72500	55 1/2	0.92500
7 3/4	0.12916	19 3/4	0.32916	31 3/4	0.52916	43 3/4	0.72916	55 3/4	0.92916
8	0.13333	20	0.33333	32	0.53333	44	0.73333	56	0.93333
8 1/4	0.13750	20 1/4	0.33750	32 1/4	0.53750	44 1/4	0.73750	56 1/4	0.93750
8 1/2	0.14166	20 1/2	0.34166	32 1/2	0.54166	44 1/2	0.74166	56 1/2	0.94166
8 3/4	0.14583	20 3/4	0.34583	32 3/4	0.54583	44 3/4	0.74583	56 3/4	0.94583
9	0.15000	21	0.35000	33	0.55000	45	0.75000	57	0.95000
9 1/4	0.15416	21 1/4	0.35416	33 1/4	0.55416	45 1/4	0.75416	57 1/4	0.95416
9 1/2	0.15833	21 1/2	0.35833	33 1/2	0.55833	45 1/2	0.75833	57 1/2	0.95833
9 3/4	0.16250	21 3/4	0.36250	33 3/4	0.56250	45 3/4	0.76250	57 3/4	0.96250
10	0.16666	22	0.36666	34	0.56666	46	0.76666	58	0.96666
10 1/4	0.17083	22 1/4	0.37083	34 1/4	0.57083	46 1/4	0.77083	58 1/4	0.97083
10 1/2	0.17500	22 1/2	0.37500	34 1/2	0.57500	46 1/2	0.77500	58 1/2	0.97500
10 3/4	0.17916	22 3/4	0.37916	34 3/4	0.57916	46 3/4	0.77916	58 3/4	0.97916
11	0.18333	23	0.38333	35	0.58333	47	0.78333	59	0.98333
11 1/4	0.18750	23 1/4	0.38750	35 1/4	0.58750	47 1/4	0.78750	59 1/4	0.98750
11 1/2	0.19166	23 1/2	0.39166	35 1/2	0.59166	47 1/2	0.79166	59 1/2	0.99166
11 3/4	0.19583	23 3/4	0.39583	35 3/4	0.59583	47 3/4	0.79583	59 3/4	0.99583
12	0.20000	24	0.40000	36	0.60000	48	0.80000	60	1.00000

RECIPROCAL OF COMMON UNITS

Unit Number Reciprocal

Dozen12.....	0833333	Ream480.....	0020833
Gross	144	.0069445	Ream	500	.0020000
Square Foot	144	.0069445	Year (days)	360	.0027778
Cubic Foot	1728	.0005787	Year (days)	365	.0027397
Mile	5280	.00018939	Months (days)	28	.0357140
Ton	2000	.0005000	Months (days)	29	.0344830
Long Ton	2240	.0004643	Months (days)	30	.0333330
			Months (days)	31	.0322580

Decimal Equivalents

$\frac{1}{64}$.015625	$\frac{33}{64}$.515625
$\frac{1}{32}$.03125	$\frac{17}{32}$.53125
$\frac{3}{64}$.046875	$\frac{35}{64}$.546875
$\frac{1}{16}$.0625	$\frac{9}{16}$.5625
$\frac{5}{64}$.078125	$\frac{37}{64}$.578125
$\frac{3}{32}$.09375	$\frac{19}{32}$.59375
$\frac{7}{64}$.109375	$\frac{39}{64}$.609375
$\frac{1}{8}$.125	$\frac{5}{8}$.625
$\frac{9}{64}$.140625	$\frac{41}{64}$.640625
$\frac{5}{32}$.15625	$\frac{21}{32}$.65625
$\frac{11}{64}$.171875	$\frac{43}{64}$.671875
$\frac{3}{16}$.1875	$\frac{11}{16}$.6875
$\frac{13}{64}$.203125	$\frac{45}{64}$.703125
$\frac{7}{32}$.21875	$\frac{23}{32}$.71875
$\frac{15}{64}$.234375	$\frac{47}{64}$.734375
$\frac{1}{4}$.25	$\frac{3}{4}$.75
$\frac{17}{64}$.265625	$\frac{49}{64}$.765625
$\frac{9}{32}$.28125	$\frac{25}{32}$.78125
$\frac{19}{64}$.296875	$\frac{51}{64}$.796875
$\frac{5}{16}$.3125	$\frac{13}{16}$.8125
$\frac{21}{64}$.328125	$\frac{53}{64}$.828125
$\frac{11}{32}$.34375	$\frac{27}{32}$.84375
$\frac{23}{64}$.359375	$\frac{55}{64}$.859375
$\frac{3}{8}$.375	$\frac{7}{8}$.875
$\frac{25}{64}$.390625	$\frac{57}{64}$.890625
$\frac{13}{32}$.40625	$\frac{29}{32}$.90625
$\frac{27}{64}$.421875	$\frac{59}{64}$.921875
$\frac{7}{16}$.4375	$\frac{15}{16}$.9375
$\frac{29}{64}$.453125	$\frac{61}{64}$.953125
$\frac{15}{32}$.46875	$\frac{31}{32}$.96875
$\frac{31}{64}$.484375	$\frac{63}{64}$.984375
$\frac{1}{2}$.5	1		1.

Tables of Decimal Equivalents

Of 7ths, 14ths, and 28ths of an Inch								Of 6ths, 12ths, and 24ths of an Inch							
7th	14th	28th	Decimal	7th	14th	28th	Decimal	6th	12th	24th	Decimal	6th	12th	24th	Decimal
1	1	1	.035714	4		15	.535714	1	1	1	.041667	4	7	13	.541666
			.071429			17	.571429			3	.083333			15	.583333
		3	.107143			19	.607143			5	.125			17	.625
2	3	5	.142857	5	9	21	.642857	3	7	7	.166666	9	19	19	.666666
			.178571			23	.678571			9	.208333			21	.708333
		7	.214286			25	.714286			11	.25			23	.75
3	5	9	.25	6	11	27	.75	5	11	11	.291666	11	23	23	.791666
			.285714			29	.785714			13	.333333				.833333
		11	.321429			31	.821429			15	.375				.875
4	7	13	.357143	13	27	33	.857143	3	11	17	.416666				.916666
			.392857			35	.892857			19	.458333				.958333
		15	.428571			37	.928571			21	.5				
5	13	17	.464286	27		39	.964286			23					
						41				25					
		19	.5			43				27					

Shields Decimal

Decimal Equivalents of an Inch of 128ths, 64ths, 32nds, 16ths, 8ths.																	
Decimal	128	64	32	16	8th	Decimal	128	64	32	16	8th	Decimal	128	64	32	16	8th
.0078125	1					.343750	44	22	11			.6796875	87				
.015625	2	1				.3515625	45					.687500	88	44	22	11	
.0234375	3					.359375	46	23				.6953125	89				
.031250	4	2	1			.3671875	47					.703125	90	45			
.0390625	5					.375000	48	24	12	6	$\frac{3}{8}$.7109375	91				
.046875	6	3				.3828125	49					.718750	92	46	23		
.0546875	7					.390625	50	25				.7265625	93				
.062500	8	4	2	1		.3984375	51					.734375	94	47			
.0703125	9					.406250	52	26	13			.7421875	95				
.078125	10	5				.4140625	53					.750000	96	48	24	12	$\frac{3}{4}$
.0859375	11					.421875	54	27				.7578125	97				
.093750	12	6	3			.4296875	55					.765625	98	49			
.1015625	13					.437500	56	28	14	7		.7734375	99				
.109375	14	7				.4453125	57					.781250	100	50	25		
.1171875	15					.453125	58	29				.7890625	101				
.125000	16	8	4	2	$\frac{1}{2}$.4609375	59					.796875	102	51			
.1328125	17					.468750	60	30	15			.8047875	103				
.140625	18	9				.4765625	61					.812500	104	52	26	13	
.1484375	19					.484375	62	31				.8203125	105				
.156250	20	10	5			.4921875	63					.828125	106	53			
.1640625	21					.500000	64	32	16	8	$\frac{1}{2}$.8359375	107				
.171875	22	11				.5078125	65					.843750	108	54	27		
.1796875	23					.515625	66	33				.8515625	109				
.187500	24	12	6	3		.5234375	67					.859375	110	55			
.1953125	25					.531250	68	34	17			.8671875	111				
.203125	26	13				.5390625	69					.875000	112	56	28	14	$\frac{3}{8}$
.2109375	27					.546875	70	35				.8828125	113				
.218750	28	14	7			.5546875	71					.890625	114	57			
.2265625	29					.562500	72	36	18	9		.8984375	115				
.234375	30	15				.5703125	73					.906250	116	58	29		
.2421875	31					.578125	74	37				.9140625	117				
.250000	32	16	8	4	$\frac{1}{4}$.5859375	75					.921875	118	59			
.2578125	33					.593750	76	38	19			.9296875	119				
.265625	34	17				.6015625	77					.937500	120	60	30	15	
.2734375	35					.609375	78	39				.9453125	121				
.281250	36	18	9			.6171875	79					.953125	122	61			
.2890625	37					.625000	80	40	20	10	$\frac{5}{8}$.9609375	123				
.296875	38	19				.6328125	81					.968750	124	62	31		
.3046875	39					.640625	82	41				.9765625	125				
.312500	40	20	10	5		.6484375	83					.984375	126	63			
.3203125	41					.656250	84	42	21			.9921875	127				
.328125	42	21				.6640625	85					1.000000	128	64	32	16	1 in.
.3359375	43					.671875	86	43									

Copyright 1916 by Chas. J. Shields, St. Louis, Mo

TABLE FOR CONVERTING NAUTICAL MILES TO STATUTE MILES

Nautical Miles	Statute Miles	Nautical Miles	Statute Miles	Nautical Miles	Statute Miles	Nautical Miles	Statute Miles
1	1.152	14	16.122	27	31.092	40	46.063
2	2.303	15	17.274	28	32.244	41	47.214
3	3.455	16	18.425	29	33.396	42	48.366
4	4.606	17	19.577	30	34.547	43	49.518
5	5.758	18	20.728	31	35.699	44	50.670
6	6.909	19	21.880	32	36.850	45	51.821
7	8.061	20	23.031	33	38.002	46	52.972
8	9.213	21	24.183	34	39.153	47	54.124
9	10.364	22	25.335	35	40.305	48	55.275
10	11.516	23	26.486	36	41.457	49	56.427
11	12.667	24	27.638	37	42.608	50	57.578
12	13.819	25	28.789	38	43.760		
13	14.970	26	29.941	39	44.911		

EVAPORATIVE POWER OF ONE POUND OF VARIOUS FUELS
AT ATMOSPHERIC PRESSURE (15 POUNDS)

1 lb. good coal will evaporate 10 lbs. of water. 1 lb. crude petroleum will evaporate 16 lbs. of water. 1 lb. natural gas (25 cubic feet) will evaporate 20 lbs. of water.

22,450 cubic feet of natural gas (atmospheric pressure) is equal to 1 ton of good soft coal.

DECIMAL EQUIVALENTS


OF MILLIMETERS AND FRACTIONS OF MILLIMETERS

1/100 mm.=.0003937"

Inches		Inches	mm	Inches		Inches	mm	
1-32	1-64	.01563	.397	17-32	33-64	.51563	13.097	
		.03125	.791				.53125	13.494
	3-64	.04688	1.191			35-64	.54688	13.890
1-16		.0625	1.587	9-16		.5625	14.287	
3-32	5-64	.07813	1.984	19-32	37-64	.57813	14.681	
		.09375	2.381				.59375	15.081
	7-64	.10938	2.778			39-64	.60938	15.478
1-8		.125	3.175	5-8		.625	15.875	
5-32	9-64	.14063	3.572	21-32	41-64	.64063	16.272	
		.15625	3.969				.65625	16.669
	11-64	.17188	4.366			43-64	.67188	17.065
3-16		.1875	4.762	11-16		.6875	17.462	
7-32	13-64	.20313	5.159	23-32	45-64	.70313	17.859	
		.21875	5.556				.71875	18.256
	15-64	.23438	5.953			47-64	.73438	18.653
1-4		.25	6.350	3-4		.75	19.050	
9-32	17-64	.26563	6.747	25-32	49-64	.76563	19.447	
		.28125	7.144				.78125	19.844
	19-64	.29688	7.541			51-64	.79688	20.240
5-16		.3125	7.937	13-16		.8125	20.637	
11-32	21-64	.32813	8.334	27-32	53-64	.82813	21.034	
		.34375	8.731				.84375	21.431
	23-64	.35938	9.128			55-64	.85938	21.828
3-8		.375	9.525	7-8		.875	22.225	
13-32	25-64	.39063	9.922	29-32	57-64	.89063	22.622	
		.40625	10.319				.90625	23.019
	27-64	.42188	10.716			59-64	.92188	23.415
7-16		.4375	11.113	15-16		.9375	23.812	
15-32	29-64	.45313	11.509	31-32	61-64	.95313	24.209	
		.46875	11.906				.96875	24.606
	31-64	.48438	12.303			63-64	.98438	25.003
1-2		.5	12.700	1		1.00000	25.400	

Metric and English Linear Measure

The measuring rules shown below are graduated, in the Metric system and in the English system. This shows at a glance the comparison of the fractions of the Metric and English units, the meter and the inch.



Comparison of English and Metric Scales, Actual Size

TABLE

USEFUL NUMBERS

Square yards,	×.0002067	=acres.
Acres,	×.4840	=square yds.
Cubic inches,	×.00058	=cubic feet.
" feet,	×.03704	= " yds.
Circular inches,	×.00546	=square feet.
Cylindrical inches,	×.0004546	=cubic feet.
feet,	×.02909	= " yds.
Links,	×.22	=yards.
" "	×.66	=feet.
Feet,	×1.5	=links.
Width in chains,	×8.	=acres p. mile.
183,346 circular inches,		=1 square ft.
2200 cylindrical inches,		=1 cubic foot.
Cubic feet,	×748	=U. S. galls.
" inches,	×.004329	= " "
Cylindrical feet,	×5.874	= " "
" inches,	×.0034	= " "
U. S. Gallons,	×.13367	=cubic feet.
" "	×.231	= " inches.
Cubic feet,	×.8036	=U. S. bushel.
" inches,	×.000466	= " "
U. S. bushel,	×.9495	=cubic yds.
" "	×1.2446	= " feet.
" "	×2150.42	= " inches.
Cylin. feet of water,	×6.	=U. S. gal's.
Lbs. avoirdupois,	×.009	=cwt. (112.)
" "	×.00045	=tons (2240).
Cubic ft. of water	×62.5	=lbs. avoird.
" ins.	×.03617	= " "
Cylin. ft. of water,	×49.1	= " "
" ins.	×.02842	= " "
13.44 U. S. gal's of water,		=1 cwt.
268.8		=1 ton.
1.8 cubic feet of water,		=1 cwt.
35.88 " "		=1 ton.
Column of water 12 inches high,		
1 inch diameter,		=.341 lbs.

TABLE

Decimal Equivalents of Inches, Feet, and Yards

Frac. of an Inch	Dec. of an Inch	Dec. of a Foot	Ins.	Feet	Yards
$\frac{1}{16}$	= .0625	= .00521	1	= .0833	= .0277
$\frac{1}{8}$	= .125	= .01041	2	= .1668	= .0555
$\frac{3}{16}$	= .1875	= .01562	3	= .25	= .0833
$\frac{1}{4}$	= .25	= .02083	4	= .3333	= .1111
$\frac{5}{16}$	= .3125	= .02604	5	= .4166	= .1389
$\frac{3}{8}$	= .375	= .03125	6	= .5	= .1666
$\frac{7}{16}$	= .4375	= .03645	7	= .5833	= .1944
$\frac{1}{2}$	= .5	= .04166	8	= .666	= .2222
$\frac{9}{16}$	= .5625	= .04688	9	= .75	= .25
$\frac{5}{8}$	= .625	= .05208	10	= .8333	= .2778
$\frac{11}{16}$	= .6875	= .05729	11	= .9166	= .3055
$\frac{3}{4}$	= .75	= .06250	12	= 1.	= .3333
$\frac{13}{16}$	= .8125	= .06771			
$\frac{7}{8}$	= .875	= .07291			

TABLE

Decimal Equivalents of Ounces and Pounds

Oz.	Lbs.	Oz.	Lbs.	Oz.	Lbs.
$\frac{1}{4}$	= .015625	4	= .25	$8\frac{1}{2}$	= .5313
$\frac{1}{2}$	= .03125	$4\frac{1}{2}$	= .2813	9	= .5625
$\frac{3}{4}$	= .046875	5	= .3125	10	= .625
1	= .0625	$5\frac{1}{2}$	= .3438	11	= .6875
$1\frac{1}{4}$	= .09375	6	= .375	12	= .75
2	= .125	$6\frac{1}{2}$	= .4063	13	= .8125
$2\frac{1}{2}$	= .15625	7	= .4375	14	= .875
3	= .1875	$7\frac{1}{2}$	= .4688	15	= .9375
$3\frac{1}{2}$	= .21875	8	= .5	16	= 1.

Angles Corresponding with Parts of a Circle

Parts	Angle	Parts	Angle	Parts	Angle	Parts	Angle
1	360°	22	16.36°	43	8.37°	78	4.62°
2	180°	23	15.65°	44	8.18°	80	4.5°
3	120°	24	15°	45	8°	82	4.34°
4	90°	25	14.4°	46	7.83°	84	4.29°
5	72°	26	13.85°	47	7.66°	86	4.19°
6	60°	27	13.33°	48	7.5°	88	4.09°
7	51.43°	28	12.86°	49	7.35°	90	4°
8	45°	29	12.41°	50	7.2°	92	3.91°
9	40°	30	12°	52	6.92°	94	3.83°
10	36°	31	11.61°	54	6.67°	96	3.75°
11	32.73°	32	11.25°	56	6.43°	98	3.67°
12	30°	33	10.91°	58	6.21°	100	3.6°
13	27.69°	34	10.59°	60	6°	102	3.53°
14	25.71°	35	10.29°	62	5.81°	104	3.46°
15	24°	36	10°	64	5.63°	106	3.40°
16	22.5°	37	9.73°	66	5.46°	108	3.33°
17	21.18°	38	9.47°	68	5.29°	110	3.27°
18	20°	39	9.23°	70	5.14°	120	3°
19	18.95°	40	9°	72	5°	130	2.77°
20	18°	41	8.78°	74	4.86°	140	2.57°
21	17.14°	42	8.57°	76	4.74°	150	2.4°

Area of Circles — in Square Feet

Diameter	0 in.	1 in.	2 in.	3 in.	4 in.	5 in.	6 in.	7 in.	8 in.	9 in.	10 in.	11 in.
0 ft.	.0000	.0055	.0218	.0491	.0873	.1364	.1964	.2670	.3491	.4418	.5454	.6600
1 "	.7854	.922	1.07	1.23	1.40	1.58	1.77	1.97	2.18	2.41	2.64	2.89
2 "	3.14	3.41	3.69	3.98	4.28	4.59	4.91	5.24	5.59	5.94	6.30	6.68
3 "	7.07	7.47	7.88	8.30	8.73	9.17	9.62	10.08	10.56	11.04	11.54	12.05
4 "	12.57	13.10	13.64	14.19	14.75	15.32	15.90	16.50	17.10	17.72	18.35	18.99
5 ft.	19.64	20.29	20.97	21.65	22.34	23.04	23.76	24.48	25.20	25.97	26.73	27.49
6 "	28.27	29.07	29.87	30.68	31.50	32.34	33.18	34.04	34.91	35.78	36.67	37.57
7 "	38.48	39.41	40.34	41.28	42.24	43.20	44.18	45.17	46.16	47.17	48.19	49.22
8 "	50.27	51.32	52.38	53.46	54.54	55.64	56.75	57.86	58.99	60.13	61.28	62.44
9 "	63.62	64.80	66.00	67.20	68.42	69.64	70.88	72.13	73.39	74.66	75.94	77.24
10 "	78.54	79.85	81.18	82.52	83.86	85.22	86.59	87.97	89.36	90.76	92.18	93.69

NOTE: To find the area of a given circle use the figures at the intersection of the columns (representing feet and inches) which, when combined, equal the diameter of the circle.

Decimal Parts of a Foot in Square Inches

Hundredths of a Sq. Ft.	Square Inches	Hundredths of a Sq. Ft.	Square Inches	Hundredths of a Sq. Ft.	Square Inches	Hundredths of a Sq. Ft.	Square Inches
1	1.44	26	37.4	51	73.4	76	109.4
2	2.88	27	38.9	52	74.9	77	110.9
3	4.32	28	40.3	53	76.3	78	112.3
4	5.76	29	41.8	54	77.8	79	113.8
5	7.20	30	43.2	55	79.2	80	115.2
6	8.64	31	44.6	56	80.6	81	116.6
7	10.1	32	46.1	57	82.1	82	118.1
8	11.5	33	47.5	58	83.5	83	119.5
9	13.0	34	49.0	59	85.0	84	121.0
10	14.4	35	50.4	60	86.4	85	122.4
11	15.8	36	51.8	61	87.8	86	123.8
12	17.3	37	53.3	62	89.3	87	125.3
13	18.7	38	54.7	63	90.7	88	126.7
14	20.2	39	56.2	64	92.2	89	128.2
15	21.6	40	57.6	65	93.6	90	129.6
16	23.0	41	58.0	66	95.0	91	131.0
17	24.5	42	60.5	67	96.5	92	132.5
18	25.9	43	61.9	68	97.4	93	133.9
19	27.4	44	63.4	69	99.9	94	135.4
20	28.8	45	64.8	70	100.	95	136.8
21	30.2	46	66.2	71	102.2	96	138.2
22	31.7	47	67.7	72	103.7	97	139.7
23	33.1	48	69.1	73	105.1	99	141.1
24	34.6	49	70.6	74	106.6	99	142.6
25	36.0	50	72.0	75	108.0	100	144.0

Angles and Distances

Angles and Distances corresponding to the opening of the 2-foot rule.

Ang.	Dis.	Ang.	Dis.	Ang.	Dis.	Ang.	Dis.	Ang.	Dis.	Ang.	Dis.
°	in.	°	in.	°	in.	°	in.	°	in.	°	in.
1	.2	16	3.34	31	6.41	46	9.38	61	12.18	76	14.78
2	.42	17	3.55	32	6.62	47	9.57	62	12.36	77	14.94
3	.63	18	3.75	33	6.82	48	9.76	63	12.54	78	15.11
4	.84	19	3.96	34	7.02	49	9.95	64	12.72	79	15.27
5	1.05	20	4.17	35	7.22	50	10.14	65	12.9	80	15.43
6	1.26	21	4.37	36	7.42	51	10.33	66	13.07	81	15.59
7	1.47	22	4.58	37	7.61	52	10.52	67	13.25	82	15.75
8	1.67	23	4.78	38	7.81	53	10.71	68	13.42	83	15.9
9	1.88	24	4.99	39	8.01	54	10.9	69	13.59	84	16.06
10	2.09	25	5.19	40	8.2	55	11.08	70	13.77	85	16.21
11	2.3	26	5.4	41	8.4	56	11.27	71	13.94	86	16.37
12	2.51	27	5.6	42	8.6	57	11.45	72	14.11	87	16.52
13	2.72	28	5.81	43	8.8	58	11.64	73	14.28	88	16.67
14	2.92	29	6.01	44	8.99	59	11.82	74	14.44	89	16.82
15	3.13	30	6.21	45	9.18	60	12.	75	14.61	90	16.97

Useful Multipliers, Etc.

Diameter of circle $\times 3.1416$ = circumference.

Radius of circle $\times 6.283185$ = circumference.

Square of radius of circle $\times 3.1416$ = area.

Square of diameter of circle $\times .7854$ = area.

Square of circumference $\times .07958$ = area.

Half the circumference $\times \frac{1}{2}$ diameter = area.

Circumference of circle $\times .159155$ = radius.

Circumference of circle $\times .31831$ = diameter.

Diameter of circle $\times .86$ = side of inscribed equilateral triangle.

Diameter of circle $\times .7071$ = side of inscribed square.

Circumference of circle $\times .225$ = side of inscribed square.

Circumference of circle $\times .282$ = side of equal square.

Diameter of circle $\times .8861$ = side of equal square.

Base of triangle $\times \frac{1}{2}$ altitude = area.

Both diameters $\times .7854$ = area of ellipse.

Surface of sphere $\times \frac{1}{6}$ diameter = solidity.

Square of diameter of sphere $\times 3.1416$ = surface.

Square of circumference of sphere $\times .3183$ = surface.

Cube of diameter of sphere $\times .5236$ = solidity.

Cube of radius of sphere $\times 4.1888$ = solidity.

Cube of circumference of sphere $\times .016887$ = solidity.

Radius of sphere $\times 1.1547$ = side of inscribed cube.

Area of one of its sides $\times 6$ = surface of cube.

Area of its base $\times 1\text{-}3$ altitude = solidity of cone, or pyramid, whether round, square or triangular.

The circumference of a circle multiplied by .282 equals side of a square of same area. Useful in turning round tanks into square.

To find contents in gallons of a square vessel: Multiply number of cylindrical inches by .0034 for wine gallons, by .002785 for ale gallons.

To find contents in gallons of a vessel whose diameter is larger at one end than at the other: Multiply the largest diameter by the smallest in inches. Add one-third of the square of their difference, multiply that sum by the height, and multiply that product by .0034 for wine, or .002785 for ale gallons.

To find capacity of a four sided vessel in gallons: Find cubical contents by multiplying the length, breadth and height in inches and divide product by 231.

The square root of the area of a circle times .56419 equals the radius.

The square root of the area of a circle times 1.12838 equals the diameter.

Doubling the diameter of a pipe increases its capacity four times.

A gallon of water (U. S. Standard) weighs $8\frac{1}{2}$ pounds and contains 231 cubic inches. A cubic foot of water contains $7\frac{1}{2}$ gallons, 1728 cubic inches, and weighs $62\frac{1}{2}$ pounds at a temperature of about 39 degrees Fahrenheit. The weight changes slightly above and below this temperature.

To find the pressure in pounds per square inch of a column of water, multiply the height of the column in feet by .434.

To find the area of a triangle, multiply the base by the altitude and divide the product by 2.

To find the area of a surface, having only two of its sides parallel, multiply one-half sum of the parallel sides by the altitude.

To find the area of a surface whose opposite sides are parallel, multiply the base by the altitude.

To find the diagonal of a square, multiply the length of one side by 1.41421.

To find the diagonal of a cube or the diameter of its circumscribed sphere, multiply the length of a side by 1.7320508.

If a circle is divided by a diameter, each half is called a semicircle, and each half circumference is called a semicircumference.

To find the side of the greatest square that can be inscribed in a given circle, take $7/10$ of the diameter and increase it by one per cent of itself.

BARS AND PLATES

Iron	Multiply contents in cu. in. by .27777 result will be weight in lbs.							
Steel	"	"	"	"	.28332	"	"	"
Copper	"	"	"	"	.32118	"	"	"
Brass	"	"	"	"	.3112	"	"	"
Lead	"	"	"	"	.41015	"	"	"
Zinc	"	"	"	"	.25318	"	"	"
Tin	"	"	"	"	.36562	"	"	"
Alu nimum	"	"	"	"	.09375	"	"	"

Steam rising from water at its boiling point (212 degrees F.) has a pressure equal to that of the atmosphere at sea level (14.7 pounds per square inch).

$24\frac{3}{4}$ cu. ft. equals 1 perch stone. A perch of stone or brick is $16\frac{1}{2}$ feet long, $1\frac{1}{2}$ feet wide, and 1 foot high.

One acre equals 10 square chains equals 4840 square yards equals 43,560 sq. ft. An acre is equal to a square the side of which is 208.7 feet.

To make a casting of precisely the same size of a broken casting without the original pattern. Put the pieces of broken casting together and cast from them a new casting. Then anneal the new casting, it will expand to the original size of the pattern and thus remain in that expanded state.

To anneal cast iron, heat it in a slow charcoal fire to a dull red heat. Then cover it over, about two inches with fine charcoal; then cover with ashes. Let it lay until cold. Hard cast iron can be softened enough in this way to be filed or drilled.

DEFINITION OF ANGLES

(ALTITUDE.) The perpendicular distance between the bases, or between the vertex and the base, of a solid or plane figure.

(ANGLE.) The difference in direction of two lines which meet or tend to meet. The lines are called sides, and point of meeting, the vertex of the angle.

A right angle is one which is formed by the radius moving, through $\frac{1}{4}$ of the circumference. It is an angle of 90° .

A straight angle is formed when the radius has moved over $\frac{1}{2}$ of the circumference: It is an angle of 180° .

Acute angle. An angle less than a right angle.

Obtuse angle. An angle greater than a right angle.

Oblique angle. On which is not a right or a straight angle.

Reflex angle. One which is greater than 180° .

Adjacent angle. Two angles are adjacent when they have the same vertex and a common side.

Solid angle. One formed by planes which meet at a point.

Dihedral angle. The opening between two intersecting planes.

Apex. The summit or highest point of an object.

Bisect. To divide into two equal parts.

Bisector. A line which bisects.

Cinquefoil. A figure composed of five leaf-like parts.

Contour. The outline of the general appearance of an object.

Contour Element. An element which is in the contour of an object.

Convergence. Lines extending toward a common point, or planes extending toward a common line.

Circumferences and Areas of Circles

Dia.	Circum.	Area	Dia.	Circum.	Area	Dia.	Circum.	Area
$\frac{1}{16}$.1963	.00307	8	25.132	50.265	55	172.788	2375.83
$\frac{1}{8}$.3927	.01227	9	28.274	63.617	56	175.929	2463.01
$\frac{3}{16}$.5890	.02761	10	31.416	78.540	57	179.071	2551.76
$\frac{1}{4}$.7854	.04909	11	34.558	95.033	58	182.212	2642.08
$\frac{5}{16}$.9817	.07670	12	37.699	113.097	59	185.354	2733.97
$\frac{3}{8}$	1.1781	.1104	13	40.840	132.732	60	188.496	2827.43
$\frac{7}{16}$	1.3744	.1503	14	43.982	153.938	61	191.637	2922.47
$\frac{1}{2}$	1.5708	.1963	15	47.124	176.715	62	194.779	3019.07
$\frac{9}{16}$	1.7671	.2485	16	50.265	201.062	63	197.920	3117.25
$\frac{5}{8}$	1.9635	.3068	17	53.407	226.980	64	201.062	3216.99
$\frac{11}{16}$	2.1598	.3712	18	56.548	254.469	65	204.204	3318.31
$\frac{3}{4}$	2.3562	.4418	19	59.690	283.529	66	207.345	3421.19
$\frac{13}{16}$	2.5525	.5185	20	62.832	314.160	67	210.487	3525.66
$\frac{7}{8}$	2.7489	.6013	21	65.973	346.361	68	213.628	3631.68
$\frac{15}{16}$	2.9452	.6903	22	69.115	380.133	69	216.770	3739.28
1	3.1416	.7854	23	72.256	415.476	70	219.912	3848.45
$1\frac{1}{16}$	3.3379	.8866	24	75.398	452.390	71	223.053	3959.19
$1\frac{1}{8}$	3.5343	.9940	25	78.540	490.875	72	226.195	4071.50
$1\frac{3}{16}$	3.7306	1.1075	26	81.681	530.930	73	229.336	4185.39
$1\frac{1}{4}$	3.9270	1.2271	27	84.823	572.556	74	232.478	4300.84
$1\frac{5}{16}$	4.1233	1.3530	28	87.964	615.753	75	235.620	4417.86
$1\frac{3}{8}$	4.3197	1.4848	29	91.106	660.521	76	238.761	4536.46
$1\frac{7}{16}$	4.5160	1.6229	30	94.248	706.860	77	241.903	4656.63
$1\frac{1}{2}$	4.7124	1.7671	31	97.389	754.769	78	245.044	4778.36
$1\frac{5}{8}$	5.0151	2.0739	32	100.531	804.249	79	248.186	4901.68
$1\frac{3}{4}$	5.4978	2.4052	33	103.672	855.30	80	251.328	5026.55
$1\frac{7}{8}$	5.8905	2.7611	34	106.814	907.92	81	254.469	5153.00
2	6.2832	3.1416	35	109.956	962.11	82	257.611	5281.02
$2\frac{1}{8}$	6.6759	3.5465	36	113.097	1017.88	83	260.752	5410.61
$2\frac{1}{4}$	7.0686	3.9760	37	116.239	1075.21	84	263.894	5541.77
$2\frac{3}{8}$	7.4613	4.4302	38	119.380	1134.11	85	267.035	5674.51
$2\frac{1}{2}$	7.8540	4.9087	39	122.522	1194.59	86	270.177	5808.80
$2\frac{3}{4}$	8.6394	5.9395	40	125.664	1256.64	87	273.319	5944.68
3	9.4248	7.0686	41	128.805	1320.25	88	276.460	6082.12
$3\frac{1}{4}$	10.210	8.2957	42	131.947	1385.44	89	279.602	6221.14
$3\frac{1}{2}$	10.995	9.6211	43	135.088	1452.20	90	282.744	6361.73
$3\frac{3}{4}$	11.781	11.044	44	138.230	1520.53	91	285.885	6503.88
4	12.566	12.566	45	141.372	1590.43	92	289.027	6647.61
$4\frac{1}{4}$	13.351	14.186	46	144.513	1661.90	93	292.168	6792.91
$4\frac{1}{2}$	14.137	15.904	47	147.655	1734.94	94	295.310	6939.78
$4\frac{3}{4}$	14.922	17.720	48	150.796	1809.56	95	298.452	7088.22
5	15.708	19.635	49	153.938	1885.74	96	301.593	7238.23
$5\frac{1}{4}$	16.493	21.647	50	157.080	1963.50	97	304.734	7389.81
$5\frac{1}{2}$	17.278	23.758	51	160.221	2042.82	98	307.876	7542.96
$5\frac{3}{4}$	18.064	25.967	52	163.363	2123.72	99	311.018	7697.69
6	18.849	28.274	53	166.504	2206.18	100	314.159	7853.98
7	21.991	38.484	54	169.646	2290.22			

To find the circumference and area of any diameter greater than any in the above table:

RULE.—Multiply any diameter given above by the factor 2, 3, 4 or 5, etc., the product of which will be the diameter whose circumference and area is wanted. **EXAMPLE:** What is the circumference of 140? Tabular diameter of $35 \times 4 = 140$. Tabular circumference of 35 = $109.9 \times 4 = 439.6$ circumference wanted.

RULE FOR THE AREA.—Multiply the tabular area of tabular diameter by the square of the factor. **EXAMPLE:** What is the area of 140? Tabular area of 35 = 962.11×16 (16 is the square of the factor 4) = 15,393.76, area wanted.

THE CIRCLE.—The circumference of a circle is equal to the diameter multiplied by 3.1416. The area of a circle is equal to the square of the diameter multiplied by .7854.

TO HARDEN CAST IRON

Mix 2 pounds of concentrated sulphuric acid and 2 ounces of nitric acid with $2\frac{1}{2}$ gallons of water. Immerse the article at a cherry red heat in this mixture. The surface becomes very hard.

Convenient Multipliers


Inches	$\times 0.08333$	= feet	Sq. inches	$\times 0.00695$	= Sq. feet
Inches	$\times 0.02778$	= yards	Sq. inches	$\times 0.0007716$	= Sq. yards
Inches	$\times 0.00001578$	= miles	Cu. inches	$\times 0.00058$	= Cu. feet
			Cu. inches	$\times 0.0000214$	= Cu. yards
Feet	$\times 0.3334$	= yards	Sq. feet	$\times 144$	= Sq. inches
Feet	$\times 0.00019$	= miles	Sq. feet	$\times 0.1112$	= Sq. yards
Yards	$\times 36$	= inches	Cu. feet	$\times 1728$	= Cu. inches
Yards	$\times 3$	= feet	Cu. feet	$\times 0.03701$	= Cu. yards
Yards	$\times 0.0005681$	= miles	Sq. yards	$\times 1296$	= Sq. inches
Miles	$\times 63360$	= inches	Sq. yards	$\times 9$	= Sq. feet
Miles	$\times 5280$	= feet	Cu. yards	$\times 46656$	= Cu. inches
Miles	$\times 1760$	= yards	Cu. yards	$\times 27$	= Cu. feet
Avoir. oz.	$\times 0.0625$	= pounds	Avoir. lbs.	$\times 0.0005$	= tons
Avoir. oz.	$\times 0.00003125$	= tons	Avoir. tons	$\times 32000$	= ounces
Avoir. lbs.	$\times 16$	= ounces	Avoir. tons	$\times 2000$	= pounds

Useful Rules for Finding Dimensions of Circles, Squares, Etc.

D is diameter of stock necessary to turn shape desired.


A is distance "across flats."

C is depth of cut into stock turned to correct diameter.




TRIANGLE

$$\begin{aligned} A &= \text{side} \times .57735 \\ D &= \text{side} \times 1.1547 = 2A \\ \text{Side} &= D \times .866 \\ C &= A \times .5 = D \times .25 \end{aligned}$$



SQUARE

$$\begin{aligned} A &= \text{side} = D \times .7071 \\ D &= \text{side} \times 1.4142 = \text{diagonal} \\ \text{Side} &= D \times .7071 \\ C &= D \times .14645 \end{aligned}$$



PENTAGON

$$\begin{aligned} A &= \text{side} \times 1.3764 = D \times .809 \\ D &= \text{side} \times 1.7013 = A \times 1.2361 \\ \text{Side} &= D \times .5878 \\ C &= D \times .0955 \end{aligned}$$



HEXAGON


$$\begin{aligned} A &= \text{side} \times 1.7321 = D \times .866 \\ D &= \text{side} \times 2 = A \times 1.1547 \\ \text{Side} &= D \times .5 \\ C &= D \times .067 \end{aligned}$$



OCTAGON

$$\begin{aligned} A &= \text{side} \times 2.4142 = D \times .9239 \\ D &= \text{side} \times 2.6131 = A \times 1.0824 \\ \text{Side} &= D \times .3827 \\ C &= D \times .038 \end{aligned}$$




STANDARD ROUND-CORNERED SQUARE HOLES



No. of Square	Size of Square	Size of Shaft
	A	B
1	1	1 $\frac{1}{4}$
2	1 $\frac{1}{16}$	1 $\frac{5}{16}$
3	1 $\frac{1}{8}$	1 $\frac{3}{8}$
4	1 $\frac{1}{4}$	1 $\frac{1}{2}$
5	1 $\frac{1}{4}$	1 $\frac{9}{16}$
6	1 $\frac{1}{4}$	1 $\frac{5}{8}$
7	1 $\frac{3}{8}$	1 $\frac{3}{4}$
8	1 $\frac{1}{2}$	1 $\frac{13}{16}$
10	1 $\frac{9}{16}$	1 $\frac{15}{16}$
11	1 $\frac{5}{8}$	2
12	1 $\frac{11}{16}$	2 $\frac{1}{8}$
13	1 $\frac{3}{4}$	2 $\frac{1}{4}$
14	1 $\frac{13}{16}$	2 $\frac{3}{16}$
15	1 $\frac{7}{8}$	2 $\frac{3}{8}$
16	1 $\frac{15}{16}$	2 $\frac{7}{16}$
17	2	2 $\frac{1}{2}$

Distance Across Corners

HEXAGONS AND SQUARES

Distance Across Flats "F"	 Sharp Hexagon F× 1.155	 Pratt & Whitney Practice F× 1.333	 Sharp Corners F× 1.414
$\frac{1}{4}$.29	.33	.36
$\frac{5}{16}$.36	.41	.44
$\frac{3}{8}$.43	.50	.53
$\frac{7}{16}$.50	.58	.62
$\frac{1}{2}$.57	.66	.71
$\frac{9}{16}$.65	.75	.80
$\frac{5}{8}$.72	.83	.88
$\frac{11}{16}$.79	.91	.97
$\frac{3}{4}$.86	1.00	1.06
$\frac{13}{16}$.93	1.08	1.15
$\frac{7}{8}$	1.01	1.16	1.24
$\frac{15}{16}$	1.08	1.25	1.33
1	1.15	1.33	1.41
$1 \frac{1}{16}$	1.22	1.42	1.50
$1 \frac{1}{8}$	1.29	1.50	1.59
$1 \frac{3}{16}$	1.37	1.58	1.68
$1 \frac{1}{4}$	1.44	1.66	1.77
$1 \frac{5}{16}$	1.51	1.75	1.86
$1 \frac{3}{8}$	1.58	1.83	1.94
$1 \frac{7}{16}$	1.66	1.92	2.03
$1 \frac{1}{2}$	1.73	2.00	2.12
$1 \frac{9}{16}$	1.80	2.08	2.21
$1 \frac{5}{8}$	1.88	2.16	2.30
$1 \frac{11}{16}$	1.95	2.25	2.39
$1 \frac{3}{4}$	2.02	2.33	2.47
$1 \frac{13}{16}$	2.09	2.42	2.56
$1 \frac{7}{8}$	2.17	2.50	2.65
$1 \frac{15}{16}$	2.24	2.58	2.74
2	2.31	2.66	2.83

The Electro-Chemical Series of Elements

In the table given below, the elements are electro-positive to the ones which follow them, and will displace them from solutions of their salts.

- | | | |
|--------------|--------------|----------------|
| 1. Sodium | 13. Bismuth | 25. Tungsten |
| 2. Barium | 14. Copper | 26. Molybdenum |
| 3. Calcium | 15. Silver | 27. Chromium |
| 4. Magnesium | 16. Mercury | 28. Arsenic |
| 5. Beryllium | 17. Platinum | 29. Phosphorus |
| 6. Aluminum | 18. Iridium | 30. Iodine |
| 7. Manganese | 19. Gold | 31. Bromine |
| 8. Zinc | 20. Hydrogen | 32. Chlorine |
| 9. Iron | 21. Tin | 33. Nitrogen |
| 10. Nickel | 22. Silicon | 34. Sulphur |
| 11. Cobalt | 23. Antimony | 35. Oxygen |
| 12. Lead | 24. Carbon | |

Shields Definitions of Angles — Triangles

An angle is the portion of a plane included between two straight lines which meet at a common point. The part of the plane included between AB and AC is called an Angle. AB and AC are its sides, and A is its vertex.

Triangles are divided into classes with reference both to their sides and their angles.

Fig. A—An "Equilateral" Triangle is one which has its three sides equal.



Fig. B—An "Isosceles" triangle is one which has only two of its sides equal.



Fig. C—A "Scalene" triangle is one which has its three sides unequal.



Fig. D—An "Acute-angled" triangle is one which has its three angles acute; that is, less than a right angle.



Fig. E—A "Right Angled" triangle is one which has a right angle. The side opposite the right angle is called the hypotenuse, and the other two sides the base and perpendicular.



Fig. F—An "Obtuse-angled" triangle is one which has an obtuse angle; that is, an angle greater than a right angle.



Fig. G—An "Oblique" angle with the plane of the horizon; a sloping plane, or inclined plane.



APPROXIMATE CUTTING SPEEDS

Turning and Boring

MATERIAL	Roughing Cutting Speed, Feet per Minute	Finishing Cutting Speed, Feet per Minute	Chasing Cutting Speed, Feet per Minute
Cast-Iron.....	60	120	50
Mild Machine Steel.....	80	150	60
Alloy Steel*.....	50	90	40
Bronze.....	100	150	70
Brass.....	200	300	80
Aluminum.....	250	400	90

Shields Measurements of Angles and Circles

The greatest line which can be inscribed in a circle is a diameter, hence every chord is less than a diameter.

Fig. A—Let AD be any chord. Draw the radii CA and CD to its extremities. We shall then have AD is less than AC + CD, but AC plus CD is equal to AB; hence AD is less than AB.

A radius which is perpendicular to a chord bisects the chord, and also bisects the subtended arc of the chord.

Fig. B—Let AB be any chord, and CG a radius perpendicular to it; then AD will be equal to DB, and the arc AG to the arc GB. For, draw the radii CA, CB and the two right-angled triangles ADC and CDB will have AC equal to CB, and CD common, hence AD is equal to DB.

Again, since AD and DB are equal, CG is a perpendicular erected from the middle of AB; and since G is a point of this perpendicular, the chords AG and GB are equal. And if the chord AG is equal to the chord GB, the arc AG is equal to the arc GB.

The center C, the middle point D of the chord AB, and the middle point G of the subtended arc, are three points of the same straight line, perpendicular to the chord.

Fig. C—All the angles, BAC, BDC and BEC, inscribed in the same segment, are equal; because they are each measured by half of the same arc, BOC.

Fig. D—Every angle, BAD, inscribed in a semicircle, is a right angle; because it is measured by half the semicircumference, BOD, that is, by the fourth part of the whole circumference.

Fig. E—Every angle, BAC, inscribed in a segment greater than a semicircle, is an acute angle; for it is measured by half the arc BOC, which is less than a semicircle. Hence, every angle, BOC, inscribed in a segment less than a semicircle, is an obtuse angle; for it is measured by half the arc BAC, which is greater than a semicircle,

Fig. F—The opposite angles, A and C, of an inscribed quadrilateral, ABCD, are together equal to two right angles; for the angle, BAD, is measured by half the arc BCD, and the angle, BCD, is measured by half the arc BAD; hence the two angles, BAD and BCD, taken together, are measured by half the circumference, therefore their sum is equal to two right angles.



Fig. A.




Fig. B.




Fig. C.




Fig. D.




Fig. E.




Fig. F.

Shields Inscribed Angles



Fig. A.



Fig. B.




Fig. C.

Fig. A—An inscribed angle is one which has its vertex in a circumference, and is included by two chords of the circle. An inscribed triangle is one which has the vertices of its three angles in the circumference.

Fig. B—A Polygon is said to be inscribed in a circle when the vertices of all the angles are in the circumference. The circumference of the circle is then said to circumscribe the polygon.

Fig. C—The top line is a Secant, a line which meets the circumference in two points, and lies partly within and partly without the circle. The lower line is a Tangent, a line which has but one point in common with the circumference. The point where the tangent touches the circumference is called the point of contact.

Fig. D—Two circumferences touch each other when they have but one point in common. The common point is called the point of tangency.

Fig. E—A Polygon is circumscribed about a circle when all its sides are tangents to the circumference. In the same case, the circle is said to be inscribed in the polygon.

The circumference of a circle may be described from any center, and with any radius.




Fig. D.




Fig. E.


Shields Definitions of Polygons

A POLYGON, or rectilinear figure, is a portion of a plane terminated on all sides by straight lines. The sum of the bounding lines is called the perimeter of the polygon.


The polygon of three sides, the simplest of all, is called a Triangle; that of four sides, a Quadrilateral; five sides, a Pentagon; six sides, a Hexagon; seven sides, a Heptagon; eight sides, an Octagon; nine sides, a Nonagon; ten sides, a Decagon; twelve sides, a Dodecagon.

An Equilateral Polygon is one which has all its sides equal. An Equiangular Polygon is one which has all its angles equal.


Two Polygons are mutually equilateral when they have their sides equal, each to each and placed in the same order; that is to say, when following their bounding lines in the same direction, the first side of one is equal to the first side of the other, the second to the second, the third to the third, and so on. Likewise, two polygons are mutually equiangular when every angle of the one is equal to a corresponding angle of the other, each to each.



Pentagon.



Hexagon.



Octagon.

Shields Definitions of Quadrilaterals



Fig. A.




Fig. B.



Fig. C.




Fig. D.



Fig. E.




Fig. F.



Fig. G.




Fig. H.

There are three kinds of Quadrilaterals;

Fig. A—The Trapezium, which has none of its sides parallel.

Fig. B—The Trapezoid, which has only two of its sides parallel. The altitude of a Trapezoid is the perpendicular distance between its two parallel sides.

Fig. C—The Parallelogram, which has its opposite sides parallel.

There are four kinds of Parallelograms;

Fig. D—The Rhomboid, has no right angle.

Fig. E—The Rhombus (lozenge), which is an equilateral rhomboid.

Fig. F—The Rectangle, which is equiangular but not equilateral.

Fig. G—The Square, which is both equilateral and equiangular.

The altitude of a parallelogram is the perpendicular distance between two opposite sides. These sides are called bases.

A "Diagonal" of a figure is a line which joins the vertices of two angles not adjacent (Fig. H.)

Shields Definitions of Polyhedrons



Fig. A.




Fig. B.




Fig. C.




Fig. D.

Polyhedron is a name given to any solid, bounded by Polygons. The bounding polygons are called faces of the polyhedron; and the straight line in which any two adjacent faces meet each other, is called an edge of the polyhedron.

Fig. A—A Prism is a polyhedron in which two of the faces are equal polygons, with their planes and homologous sides parallel, and all the other faces parallelograms.

Fig. B—A Rectangular Parallelepipedon is one whose faces are all rectangles. When all the faces are squares, it is called a Cube, or regular Hexahedron.

Fig. C—A Pyramid is a solid bounded by a polygon, and by triangles meeting at a common point called the Vertex. The Polygon is called the Base; and the triangles, taken together, the convex or lateral surface.

The Pyramid, like the Prism, takes different names according to the form of its base; it may be Triangular, Quadrangular, Pentangular, etc.

Fig. D—If a pyramid is cut by a plane parallel to its base, forming a second base, it is called a Truncated Pyramid, or Frustum of a pyramid.

Shields Definitions of Three Round Bodies

The Cylinder, the Cone and the Sphere, are the three round bodies treated of in the Elements of Geometry.

Fig. A—A Cylinder is a solid which may be generated by the revolution of a rectangle, ABCD, turning about the fixed side AB. In this movement, the sides AD and BC, continuing always perpendicular to AB, describe the equal circles, DPH and CGQ, which are called the bases of the cylinder, the sides CD, describing at the same time, the convex surface.




Fig. A.

The fixed line, AB, is called the axis of the Cylinder, and any section, MNKL, in the cylinder, made by a plane at right angles to the axis, is a circle equal to either of the bases.

While the rectangle ABCD turns about AB, the line KI, perpendicular to AB, describes a circle equal to the base, and this circle is the same as the plane MNKL, perpendicular to the axis at the point I. Every section, QPHG, made by a plane passing through the axis, is a rectangle double the generating rectangle ABCD.




Fig. B.

Fig. B—A Cone is a solid which may be generated by the revolution of a right-angled triangle, SAB, turning about the fixed side SA. In this movement the side AB describes the circle BDCE, called the Base of the cone; and the Hypotenuse SB, describes the convex surface of the cone.

The point S is called the Vertex of the cone, SA the Axis, or the Altitude, and SB the Slant Height. Every section, HKFI, made by a plane at right angles to the axis, is a circle. Every section, EDS, made by a plane passing through the axis, is an Isosceles Triangle double the generating triangle SAB.

Fig. C—The Sphere is a solid terminated by a curved surface, all points of which are equally distant from a point within, called the center.

The sphere may be generated by the revolution of a semicircle, DAE, about its diameter DE; for the surface described in this movement, by the semicircumference DAE, will have all its points equally distant from its center C.




Fig. C.

While the semicircle DAE, revolving around its diameter, DE, describes the Sphere, any circular sector DCF or FCA, describes a solid called a spherical sector.

SAFETY PLUGS — COMPOSITION AND MELTING POINTS

Tin	Lead	Melts °F.	Tin	Lead	Bismuth	Melts °F.
6	1	381	4	4	1	320
5	1	378	3	3	1	310
4	1	365	2	2	1	292
3	1	340	1	1	1	254
2	1	334	3	5	8	212
1½	1	320	1	1	2	201
			2	3	5	199

MENSURATION

Square

A = Area

S = Height

d = Diagonal

AREA •

$$A = S^2$$

$$A = \frac{1}{2}d^2$$

$$S = .7071d = \sqrt{A}$$

$$D = 1.414S = 1.414\sqrt{A}$$

Rectangle

A = Area

a = Height

b = Width

d = Diagonal

$$A = a \times b$$

$$A = a\sqrt{d^2 - a^2} = b\sqrt{d^2 - b^2}$$

$$d = \sqrt{a^2 + b^2}$$

$$a = \sqrt{d^2 - b^2} = A \div b$$

$$b = \sqrt{d^2 - a^2} = A \div a$$

Hexagon

A = Area

R = Radius of Circumscribed Circle $R = s = 1.55 \times r$

r = Radius of Inscribed Circle

s = Width of Side

$$A = 2.598 \times S^2 = 2.598 \cdot R^2 = 3.464r^2$$

$$R = s = 1.55 \times r$$

$$r = .866 \times s = .866 R$$

$$s = R = 1.55 \times r$$

Octagon

A = Area

R = Radius of Circumscribed Circle $R = 1.307 \times s = 1.082 \times r$

r = Radius of Inscribed Circle

s = Width of Side

$$A = 4.828 \times s^2 = 2.828 \cdot R^2 = 3.314 r^2$$

$$R = 1.307 \times s = 1.082 \times r$$

$$r = 1.207 \times s = .924R$$

$$s = .765 \times R = .828 \times r$$

Circle

A = Area

C = Circumference

r = Radius

d = Diameter

$$A = \pi r^2 = 3.1416 \times r^2 = .7854d^2$$

$$C = 2\pi r = 6.2832 \times r = 3.1416d$$

$$r = \frac{C}{6.2832} = \sqrt{\frac{A}{3.1416}} = .564\sqrt{A}$$

$$d = \frac{C}{3.1416} = \sqrt{\frac{A}{.7854}} = 1.128\sqrt{A}$$

Circular Sector

L = Length of arc

A = Area

a = Angle in degrees

r = Radius

$$L = \frac{ra \cdot 3.1416}{180} = .01745 \times r \times a = \frac{2A}{r}$$

$$A = \frac{1}{2}r \times L = .008727 \times a \times r^2$$

$$a = \frac{57.296 \times L}{r}$$

$$r = \frac{2A}{L} = \frac{57.296L}{a}$$

Circular Ring

A = Area

D = Outside diameter

d = Inside diameter

R = Outside radius

$$A = \pi(R^2 - r^2) = 3.1416(R^2 - r^2) = 3.1416(R + r)(R - r)$$

$$= 7.854(D_2 - d_2) = 7.854(D + d)(D - d)$$

VOLUME

Cube

S = Dimension of one side

V = Volume

$$V = S^3$$

$$S = \sqrt[3]{V}$$

AREA—Continued

Square Prism

V = Volume

a = Length

b = Height

c = Width

$$V = abc$$

$$a = \frac{V}{bc} \quad b = \frac{V}{ac} \quad c = \frac{V}{ab}$$

Cylinder

V = Volume

S = Area of cylindrical surface

A = Area of cylindrical surface
and end surfaces

R = Radius of circle

D = Diameter of circle

h = Length of cylinder

$$V = 3.1416 \times R^2 h = .7854 D^2 h$$

$$S = 6.2832 R h = 3.1416 D h$$

$$A = 6.2832 R (R + h) = 3.1416 \times D (1/2 D + h)$$

Hollow Cylinder

V = Volume

R = Radius of outer cylinder

r = Radius of inner cylinder

t = Thickness of wall

D = Outside diameter of cylinder

d = Inside diameter of cylinder

h = Length

$$V = 3.1416 \times h (R^2 - r^2) = .7854 h (D^2 - d^2)$$

$$= 3.1416 \times h t (2R - t) = 3.1416 h t (D - t)$$

$$= 3.1416 \times h t (2r + t) = 3.1416 h t (d + t)$$

$$= 3.1416 \times h t (R + r) = 1.5708 h t (D + d)$$

Sphere

V = Volume

A = Area of surface

r = Radius

d = Diameter

$$V = \frac{4\pi r^3}{3} = \frac{\pi d^3}{6} = 4.1888 \times r^3$$

$$= .5236 d^3$$

$$A = 4\pi r^2 = \pi d^2 = 12.5664 r^2$$

$$= 3.1416 d^2$$

$$r = \sqrt[3]{\frac{3V}{4\pi}} = .6204 \sqrt[3]{V}$$

Hollow Sphere

V = Volume

r = Inside radius

R = Outer radius

d = Inside diameter

D = Outside diameter

$$V = \frac{4\pi}{3} (R^3 - r^3) = 4.1888 (R^3 - r^3)$$

$$= \frac{\pi}{6} (D^3 - d^3) = .5236 (D^3 - d^3)$$

$$V = \frac{3.1416 \times R^2 \times H}{3} =$$

Cone

V = Volume

A = Area of conical surface

D = Diameter of base

R = Radius of base

H = Height

S = Length of side

$$1.0472 \times R^2 \times H =$$

$$.2618 \times D^2 \times H$$

$$A = 3.1416 \times R \times \sqrt{R^2 + H^2}$$

$$= 3.1416 \times R \times S$$

$$= 1.5708 \times D \times S$$

$$S = \sqrt{R^2 + H^2} = \sqrt{\frac{D^2}{4} + H^2}$$

VOLUME—Continued

Frustum of Cone

V = Volume

A = Area of Conical Surface

D = Diameter of base

d = Diameter of top

H = Height

S = Length of side

R = Radius of base

r = Radius of top


a = R - r

$$V = 1.0472 \times H(R^2 + R \times r + r^2) = .2618 \times h(D^2 + D \times d + d^2).$$


$$A = 3.1416 \times S(R + r) =$$

$$1.5708 \times S(D + d)$$

$$S = \sqrt{a^2 + H^2} = \sqrt{(R - r)^2 + H^2}$$

Table for Solving Right Angled Triangles

PARTS GIVEN	PARTS TO BE FOUND				
	Hyp.	Adj.	Opp.	Angle	Opp. Angle
Hyp. & Adj.	_____	_____	$\sqrt{\text{Hyp.}^2 - \text{Adj.}^2}$	$\text{Cos.} = \frac{\text{Adj.}}{\text{Hyp.}}$	$\text{Sin.} = \frac{\text{Adj.}}{\text{Hyp.}}$
Hyp. & Opp.	_____	$\sqrt{\text{Hyp.}^2 - \text{Opp.}^2}$	_____	$\text{Sin.} = \frac{\text{Opp.}}{\text{Hyp.}}$	$\text{Cos.} = \frac{\text{Opp.}}{\text{Hyp.}}$
Hyp. & Angle	_____	Hyp. x Cos.	Hyp. x Sin.	_____	90°-Angle
Adj. & Opp.	$\sqrt{\text{Adj.}^2 + \text{Opp.}^2}$	_____	_____	$\text{Tan.} = \frac{\text{Opp.}}{\text{Adj.}}$	$\text{Cot.} = \frac{\text{Opp.}}{\text{Adj.}}$
Adj. & Angle	$\frac{\text{Adj.}}{\text{Cos.}}$	_____	Adj. x Tan.	_____	90°-Angle
Opp. & Angle	$\frac{\text{Opp.}}{\text{Sin.}}$	Opp. x Cot.	_____	_____	90°-Angle



When A, B & D
Are Given $X = \frac{D^2 + A^2 - B^2}{2D}$

REGULAR POLYGONS

Let the areas of the regular polygons whose sides are unity, or 1, be calculated and arranged in the following table.

Names	Sides	Areas	Names	Sides	Areas
Triangle	3	0.4330127	Octagon	8	4.8284271
Square	4	1.0000000	Nonagon	9	6.1818242
Pentagon	5	1.7204774	Decagon	10	7.6942088
Hexagon	6	2.5980762	Undecagon	11	9.3656399
Heptagon	7	3.6339124	Dodecagon	12	11.1961524

POLYHEDRONS

We have subjoined the computation of these polygons, carried on till they agree as far as the seventh place of decimals.

Number of Sides	Inscribed Polygons	Circumscribed Polygons
4	2.0000000	4.0000000
8	2.8284271	3.3137085
16	3.0314674	3.1825979
32	3.1214451	3.1517249
64	3.1365485	3.1441184
128	3.1403311	3.1422236
256	3.1412772	3.1417504
512	3.1415138	3.1416321
1024	3.1415729	3.1416025
2048	3.1415877	3.1415951
4096	3.1415914	3.1415933
8192	3.1415923	3.1415928
16384	3.1415925	3.1415927
32768	3.1415926	3.1415926

A Table of Regular Polyhedrons Whose Edges Are 1

NAMES.	NO. OF FACES.	SURFACE.	SOLIDITY.
Tetraedron	4	1.7320508	0.1178513
Hexaedron	6	6.0000000	1.0000000
Octaedron	8	3.4641016	0.4714045
Dodecaedron	12	20.6457288	7.6631189
Icosaedron	20	8.6602540	2.1816950

Solution of Triangles by Natural Lines

Parts Given	TO OBTAIN				
	Angle	Adj. Side	Op. Side	Hypoth.	Op. Angle
Op. & Hyp.	$\text{Sin.} = \frac{\text{Op.}}{\text{Hyp.}}$	$\sqrt{\text{Hyp.}^2 - \text{Op.}^2}$			$\text{Cos.} = \frac{\text{Op.}}{\text{Hyp.}}$
Op. & Adj.	$\text{Tan.} = \frac{\text{Op.}}{\text{Adj.}}$			$\sqrt{\text{Op.}^2 + \text{Adj.}^2}$	$\text{Cot.} = \frac{\text{Op.}}{\text{Adj.}}$
Adj. & Hyp.	$\text{Cos.} = \frac{\text{Adj.}}{\text{Hyp.}}$				
Ang. & Op.		$\text{Op.} \times \text{Cot.}$		$\text{Op.} \div \text{Sin.}$	$90^\circ - \text{Ang.}$
Ang. & Adj.			$\text{Adj.} \times \text{Tan.}$	$\text{Adj.} \div \text{Cos.}$	$90^\circ - \text{Ang.}$
Ang. & Hyp.		$\text{Hyp.} \times \text{Cos.}$	$\text{Hyp.} \times \text{Sin.}$		$90^\circ - \text{Ang.}$

TRIGONOMETRIC FUNCTIONS

QUICK REFERENCE TABLE

Degrees	Sine	Tangent	Cotangent	Cosine	Degrees
0	.0000	.0000	1.000	90
1	.0175	.0175	57.29	.9998	89
2	.0349	.0349	28.636	.9994	88
3	.0523	.0524	19.081	.9986	87
4	.0698	.0699	14.301	.9976	86
5	.0872	.0875	11.430	.9962	85
6	.1045	.1051	9.5144	.9945	84
7	.1219	.1228	8.1443	.9925	83
8	.1392	.1405	7.1154	.9903	82
9	.1564	.1584	6.3138	.9877	81
10	.1736	.1763	5.6713	.9848	80
11	.1908	.1944	5.1446	.9816	79
12	.2079	.2126	4.7046	.9781	78
13	.2250	.2309	4.3315	.9744	77
14	.2419	.2493	4.0108	.9703	76
15	.2588	.2679	3.7321	.9659	75
16	.2756	.2867	3.4874	.9613	74
17	.2924	.3057	3.2709	.9563	73
18	.3090	.3249	3.0777	.9511	72
19	.3256	.3443	2.9042	.9455	71
20	.3420	.3640	2.7475	.9397	70
21	.3584	.3839	2.6051	.9336	69
22	.3746	.4040	2.4751	.9272	68
23	.3907	.4245	2.3559	.9205	67
24	.4067	.4452	2.2460	.9135	66
25	.4226	.4663	2.1445	.9063	65
26	.4384	.4877	2.0503	.8988	64
27	.4540	.5095	1.9626	.8910	63
28	.4695	.5317	1.8807	.8829	62
29	.4848	.5543	1.8040	.8746	61
30	.5000	.5774	1.7321	.8660	60
31	.5150	.6009	1.6643	.8572	59
32	.5299	.6249	1.6003	.8480	58
33	.5446	.6494	1.5399	.8387	57
34	.5592	.6745	1.4826	.8290	56
35	.5736	.7002	1.4281	.8192	55
36	.5878	.7265	1.3764	.8090	54
37	.6018	.7536	1.3270	.7986	53
38	.6157	.7813	1.2799	.7880	52
39	.6293	.8098	1.2349	.7771	51
40	.6428	.8391	1.1918	.7660	50
41	.6561	.8693	1.1504	.7547	49
42	.6691	.9004	1.1106	.7431	48
43	.6820	.9325	1.0724	.7314	47
44	.6947	.9657	1.0355	.7193	46
45	.7071	1.0000	1.0000	.7071	45
Degrees	Cosine	Cotangent	Tangent	Sine	Degrees

AN "ATMOSPHERE," $14.7 \frac{10}{100}$ lbs. at 62° F., is equal to a column of mercury $30''$ high, or a column of water $33\frac{9}{10}$ feet high. Approximately each foot of elevation = $\frac{1}{2}$ lb. pressure per square inch, but to find the **exact** pressure in lbs. per square inch of a column of water \times the height in feet by $\frac{434}{1000}$. $\frac{434}{1000}$ is the decimal fraction of the lb. pressure per square inch of a column of water 1 foot high at 62° F. **Example:** 100 feet height of column $\times .434 = 43\frac{4}{10}$ lb. pressure.

TRIGONOMETRIC FUNCTIONS

NATURAL COSINES AND SINES

Degrees	COSINE						SINE						Degrees		
	0°	10°	20°	30°	40°	50°	60°	0°	10°	20°	30°	40°		50°	60°
0	1.00000	1.00000	0.99980	0.99960	0.99930	0.99880	0.99810	0	0.00000	0.17365	0.34202	0.50000	0.64279	0.76604	80
1	0.99985	0.99979	0.99959	0.99939	0.99909	0.99869	0.99810	1	0.00015	0.17350	0.34187	0.49985	0.64264	0.76589	81
2	0.99970	0.99964	0.99944	0.99924	0.99894	0.99854	0.99805	2	0.00030	0.17335	0.34172	0.49970	0.64249	0.76574	82
3	0.99955	0.99949	0.99929	0.99909	0.99879	0.99839	0.99790	3	0.00045	0.17320	0.34157	0.49955	0.64234	0.76559	83
4	0.99940	0.99934	0.99914	0.99894	0.99864	0.99824	0.99775	4	0.00060	0.17305	0.34142	0.49940	0.64219	0.76544	84
5	0.99925	0.99919	0.99899	0.99879	0.99849	0.99809	0.99760	5	0.00075	0.17290	0.34127	0.49925	0.64204	0.76529	85
6	0.99910	0.99904	0.99884	0.99864	0.99834	0.99794	0.99745	6	0.00090	0.17275	0.34112	0.49910	0.64189	0.76514	86
7	0.99895	0.99889	0.99869	0.99849	0.99819	0.99779	0.99730	7	0.00105	0.17260	0.34097	0.49895	0.64174	0.76499	87
8	0.99880	0.99874	0.99854	0.99834	0.99804	0.99764	0.99715	8	0.00120	0.17245	0.34082	0.49880	0.64159	0.76484	88
9	0.99865	0.99859	0.99839	0.99819	0.99789	0.99749	0.99700	9	0.00135	0.17230	0.34067	0.49865	0.64144	0.76469	89
10	0.99850	0.99844	0.99824	0.99804	0.99774	0.99734	0.99685	10	0.00150	0.17215	0.34052	0.49850	0.64129	0.76454	90
11	0.99835	0.99829	0.99809	0.99789	0.99759	0.99719	0.99670	11	0.00165	0.17200	0.34037	0.49835	0.64114	0.76439	91
12	0.99820	0.99814	0.99794	0.99774	0.99744	0.99704	0.99655	12	0.00180	0.17185	0.34022	0.49820	0.64099	0.76424	92
13	0.99805	0.99799	0.99779	0.99759	0.99729	0.99689	0.99640	13	0.00195	0.17170	0.34007	0.49805	0.64084	0.76409	93
14	0.99790	0.99784	0.99764	0.99744	0.99714	0.99674	0.99625	14	0.00210	0.17155	0.33992	0.49790	0.64069	0.76394	94
15	0.99775	0.99769	0.99749	0.99729	0.99699	0.99659	0.99610	15	0.00225	0.17140	0.33977	0.49775	0.64054	0.76379	95
16	0.99760	0.99754	0.99734	0.99714	0.99684	0.99644	0.99595	16	0.00240	0.17125	0.33962	0.49760	0.64039	0.76364	96
17	0.99745	0.99739	0.99719	0.99699	0.99669	0.99629	0.99580	17	0.00255	0.17110	0.33947	0.49745	0.64024	0.76349	97
18	0.99730	0.99724	0.99704	0.99684	0.99654	0.99614	0.99565	18	0.00270	0.17095	0.33932	0.49730	0.64009	0.76334	98
19	0.99715	0.99709	0.99689	0.99669	0.99639	0.99599	0.99550	19	0.00285	0.17080	0.33917	0.49715	0.63994	0.76319	99
20	0.99700	0.99694	0.99674	0.99654	0.99624	0.99584	0.99535	20	0.00300	0.17065	0.33902	0.49700	0.63979	0.76304	100

NATURAL SINES AND COSINES

Degrees	SINE						COSINE						Degrees		
	0°	10°	20°	30°	40°	50°	60°	0°	10°	20°	30°	40°		50°	60°
0	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	1.00000	0.99985	0.99970	0.99955	0.99940	0.99925	0.99910	80
1	0.01745	0.03036	0.04362	0.05618	0.06799	0.07894	0.08899	0.99985	0.99979	0.99959	0.99939	0.99909	0.99869	0.99810	81
2	0.03490	0.05781	0.08017	0.10197	0.12319	0.14382	0.16386	0.99970	0.99964	0.99944	0.99924	0.99894	0.99854	0.99795	82
3	0.05234	0.07524	0.09760	0.11939	0.14061	0.16124	0.18130	0.99955	0.99949	0.99929	0.99909	0.99879	0.99839	0.99780	83
4	0.06978	0.09268	0.11504	0.13673	0.15786	0.17843	0.19847	0.99940	0.99934	0.99914	0.99894	0.99864	0.99824	0.99765	84
5	0.08722	0.11012	0.13248	0.15417	0.17530	0.19587	0.21591	0.99925	0.99919	0.99899	0.99879	0.99849	0.99809	0.99750	85
6	0.10466	0.12756	0.14992	0.17161	0.19274	0.21331	0.23335	0.99910	0.99904	0.99884	0.99864	0.99834	0.99794	0.99735	86
7	0.12210	0.14500	0.16736	0.18905	0.21018	0.23075	0.25079	0.99895	0.99889	0.99869	0.99849	0.99819	0.99779	0.99720	87
8	0.13954	0.16244	0.18480	0.20649	0.22762	0.24819	0.26823	0.99880	0.99874	0.99854	0.99834	0.99804	0.99764	0.99705	88
9	0.15698	0.17988	0.20224	0.22393	0.24506	0.26563	0.28567	0.99865	0.99859	0.99839	0.99819	0.99789	0.99749	0.99690	89
10	0.17442	0.19732	0.21968	0.24137	0.26250	0.28307	0.30311	0.99850	0.99844	0.99824	0.99804	0.99774	0.99734	0.99675	90
11	0.19186	0.21476	0.23712	0.25881	0.27994	0.29951	0.31855	0.99835	0.99829	0.99809	0.99789	0.99759	0.99719	0.99660	91
12	0.20930	0.23220	0.25456	0.27625	0.29738	0.31795	0.33799	0.99820	0.99814	0.99794	0.99774	0.99744	0.99704	0.99645	92
13	0.22674	0.24964	0.27200	0.29369	0.31482	0.33539	0.35543	0.99805	0.99799	0.99779	0.99759	0.99729	0.99689	0.99630	93
14	0.24418	0.26708	0.28944	0.31113	0.33226	0.35283	0.37287	0.99790	0.99784	0.99764	0.99744	0.99714	0.99674	0.99615	94
15	0.26162	0.28452	0.30688	0.32853	0.34966	0.37023	0.39027	0.99775	0.99769	0.99749	0.99729	0.99699	0.99659	0.99600	95
16	0.27906	0.30196	0.32432	0.34597	0.36710	0.38767	0.40771	0.99760	0.99754	0.99734	0.99714	0.99684	0.99644	0.99585	96
17	0.29650	0.31940	0.34176	0.36341	0.38454	0.40511	0.42515	0.99745	0.99739	0.99719	0.99699	0.99669	0.99629	0.99570	97
18	0.31394	0.33684	0.35920	0.38085	0.40198	0.42255	0.44259	0.99730	0.99724	0.99704	0.99684	0.99654	0.99614	0.99555	98
19	0.33138	0.35428	0.37664	0.39829	0.41942	0.44000	0.46004	0.99715	0.99709	0.99689	0.99669	0.99639	0.99599	0.99540	99
20	0.34882	0.37172	0.39408	0.41573	0.43686	0.45743	0.47747	0.99700	0.99694	0.99674	0.99654	0.99624	0.99584	0.99525	100

NATURAL COTANGENTS AND TANGENTS

Degrees	COTANGENT							Degrees
	0°	10°	20°	30°	40°	50°	60°	
0	∞	343.77371	171.88540	114.58865	85.93979	68.75009	57.28996	89
1	57.28996	49.10388	42.96498	38.18846	34.36777	31.21528	28.68015	88
2	28.68015	24.47761	21.07958	18.80604	17.10691	15.55706	14.11196	87
3	14.11196	12.70768	11.47631	10.37109	9.37109	8.44343	7.57128	86
4	7.57128	6.80405	6.13135	5.54508	5.02584	4.56190	4.14300	85
5	4.14300	3.72674	3.39370	3.10385	2.85709	2.64886	2.46435	84
6	2.46435	2.25370	2.07943	1.92808	1.79633	1.68086	1.58781	83
7	1.58781	1.49135	1.40934	1.33984	1.28084	1.23111	1.19037	82
8	1.19037	1.15037	1.11111	1.07258	1.03553	1.00000	0.96569	81
9	0.96569	0.93252	0.90000	0.86813	0.83688	0.80613	0.77587	80
10	0.77587	0.74613	0.71691	0.68813	0.65979	0.63190	0.60445	79
11	0.60445	0.57728	0.55063	0.52450	0.49888	0.47376	0.44914	78
12	0.44914	0.42450	0.40037	0.37674	0.35361	0.33096	0.30886	77
13	0.30886	0.28628	0.26424	0.24274	0.22176	0.20128	0.18138	76
14	0.18138	0.16096	0.14159	0.12324	0.10590	0.08946	0.07392	75
15	0.07392	0.05937	0.04580	0.03320	0.02161	0.01101	0.00140	74
16	0.00140	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	73
17	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	72
18	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	71
19	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	70
20	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	69
21	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	68
22	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	67
23	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	66
24	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	65
25	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	64
26	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	63
27	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	62
28	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	61
29	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	60
30	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	59
31	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	58
32	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	57
33	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	56
34	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	55
35	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	54
36	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	53
37	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	52
38	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	51
39	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	50
40	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	49
41	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	48
42	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	47
43	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	46
44	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	45

NATURAL TANGENTS AND COTANGENTS

Degrees	TANGENT							Degrees
	0°	10°	20°	30°	40°	50°	60°	
0	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	0.00000	89
1	0.01746	0.02036	0.02338	0.02659	0.02999	0.03358	0.03736	88
2	0.03736	0.04154	0.04591	0.05046	0.05519	0.06000	0.06490	87
3	0.06490	0.06999	0.07528	0.08076	0.08643	0.09228	0.09831	86
4	0.09831	0.10454	0.11099	0.11765	0.12452	0.13159	0.13886	85
5	0.13886	0.14534	0.15196	0.15881	0.16589	0.17319	0.18070	84
6	0.18070	0.18744	0.19432	0.20134	0.20858	0.21594	0.22341	83
7	0.22341	0.23000	0.23674	0.24361	0.25061	0.25783	0.26526	82
8	0.26526	0.27192	0.27873	0.28568	0.29277	0.29999	0.30734	81
9	0.30734	0.31400	0.32077	0.32764	0.33462	0.34171	0.34891	80
10	0.34891	0.35520	0.36159	0.36807	0.37464	0.38130	0.38806	79
11	0.38806	0.39444	0.40091	0.40746	0.41409	0.42080	0.42759	78
12	0.42759	0.43396	0.44041	0.44694	0.45354	0.46021	0.46694	77
13	0.46694	0.47329	0.47971	0.48620	0.49276	0.49938	0.50606	76
14	0.50606	0.51239	0.51879	0.52526	0.53179	0.53837	0.54499	75
15	0.54499	0.55139	0.55786	0.56439	0.57097	0.57759	0.58425	74
16	0.58425	0.59079	0.59738	0.60401	0.61068	0.61739	0.62414	73
17	0.62414	0.63079	0.63748	0.64420	0.65095	0.65773	0.66454	72
18	0.66454	0.67129	0.67806	0.68486	0.69168	0.69852	0.70538	71
19	0.70538	0.71214	0.71891	0.72569	0.73248	0.73928	0.74609	70
20	0.74609	0.75280	0.75952	0.76624	0.77297	0.77971	0.78646	69
21	0.78646	0.79319	0.79992	0.80665	0.81338	0.82011	0.82684	68
22	0.82684	0.83357	0.84030	0.84702	0.85374	0.86046	0.86718	67
23	0.86718	0.87389	0.88060	0.88731	0.89401	0.90071	0.90741	66
24	0.90741	0.91411	0.92080	0.92749	0.93417	0.94085	0.94752	65
25	0.94752	0.95419	0.96085	0.96750	0.97414	0.98077	0.98740	64
26	0.98740	0.99401	1.00061	1.00720	1.01378	1.02035	1.02691	63
27	1.02691	1.03346	1.04000	1.04652	1.05303	1.05953	1.06602	62
28	1.06602	1.07250	1.07897	1.08543	1.09188	1.09831	1.10473	61
29	1.10473	1.11114	1.11753	1.12390	1.13025	1.13658	1.14289	60
30	1.14289	1.14919	1.15547	1.16173	1.16796	1.17417	1.18036	59
31	1.18036	1.18653	1.19268	1.19881	1.20491	1.21098	1.21703	58
32	1.21703	1.22307	1.22908	1.23507	1.24103	1.24696	1.25286	57
33	1.25286	1.25877	1.26465	1.27050	1.27632	1.28211	1.28787	56
34	1.28787	1.29361	1.29932	1.30500	1.31065	1.31627	1.32186	55
35	1.32186	1.32742	1.33295	1.33845	1.34391	1.34934	1.35474	54
36	1.35474	1.36012	1.36546	1.37076	1.37602	1.38125	1.38644	53
37	1.38644	1.39162	1.39676	1.40186	1.40692	1.41194	1.41692	52
38	1.41692	1.42187	1.42678	1.43165	1.43648	1.44127	1.44602	51
39	1.44602	1.45073	1.45539	1.46000	1.46457	1.46910	1.47359	50
40	1.47359	1.47804	1.48244	1.48679	1.49110	1.49537	1.49960	49
41	1.49960	1.50382	1.50799	1.51211	1.51619	1.52023	1.52423	48
42	1.52423	1.52819	1.53210	1.53596	1.53977	1.54354	1.54727	47
43	1.54727	1.55095	1.55458	1.55816	1.56169	1.56517	1.56860	46
44	1.56860	1.57203	1.57541	1.57874	1.58202	1.58525	1.58843	45

NATURAL SECANTS AND COSECANTS

NATURAL COSECANTS AND SECANTS

Degrees	SECANT						Degrees
	0'	10'	20'	30'	40'	50'	60'
0	1.00000	1.00001	1.00002	1.00004	1.00007	1.00011	1.00015
1	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
2	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
3	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
4	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
5	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
6	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
7	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
8	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
9	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
10	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
11	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
12	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
13	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
14	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
15	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
16	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
17	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
18	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
19	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
20	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
21	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
22	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
23	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
24	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
25	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
26	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
27	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
28	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
29	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
30	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
31	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
32	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
33	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
34	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
35	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
36	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
37	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
38	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
39	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
40	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
41	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
42	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
43	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
44	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015
45	1.00001	1.00002	1.00003	1.00005	1.00008	1.00011	1.00015

Degrees	COSECANT						Degrees
	0'	10'	20'	30'	40'	50'	60'
0	∞	343.7516	171.8883	114.5030	85.9456	68.7526	57.2869
1	57.2869	49.1144	42.9757	38.2255	34.7348	32.0000	29.5401
2	28.6537	26.4501	24.5621	22.9259	21.4936	20.2308	19.1072
3	19.1072	18.1026	17.1984	16.3801	15.6379	14.9588	14.3359
4	14.3359	13.7632	13.2347	12.7450	12.2915	11.8683	11.4731
5	11.4731	11.1045	10.7589	10.4343	10.1275	9.8391	9.5667
6	9.5667	9.3091	9.0651	8.8367	8.6139	8.4066	8.2051
7	8.2051	8.0165	7.8443	7.6830	7.5321	7.3908	7.2580
8	7.2580	7.0962	6.9479	6.8023	6.6603	6.5225	6.3887
9	6.3887	6.2719	6.1607	6.0548	5.9536	5.8569	5.7647
10	5.7647	5.6633	5.5673	5.4760	5.3894	5.3074	5.2299
11	5.2299	5.1539	5.0833	5.0181	4.9581	4.9031	4.8531
12	4.8531	4.7923	4.7367	4.6861	4.6404	4.5994	4.5631
13	4.5631	4.5215	4.4841	4.4507	4.4212	4.3956	4.3728
14	4.3728	4.3481	4.3273	4.3103	4.2969	4.2869	4.2799
15	4.2799	4.2723	4.2673	4.2647	4.2631	4.2623	4.2621
16	4.2621	4.2623	4.2631	4.2647	4.2673	4.2723	4.2799
17	4.2799	4.2869	4.2969	4.3074	4.3181	4.3294	4.3412
18	4.3412	4.3531	4.3656	4.3787	4.3923	4.4064	4.4212
19	4.4212	4.4361	4.4512	4.4664	4.4817	4.4971	4.5128
20	4.5128	4.5286	4.5445	4.5604	4.5764	4.5925	4.6087
21	4.6087	4.6249	4.6412	4.6575	4.6739	4.6904	4.7070
22	4.7070	4.7236	4.7402	4.7569	4.7736	4.7904	4.8072
23	4.8072	4.8241	4.8410	4.8579	4.8748	4.8918	4.9088
24	4.9088	4.9258	4.9428	4.9598	4.9768	4.9938	5.0108
25	5.0108	5.0278	5.0448	5.0618	5.0788	5.0958	5.1128
26	5.1128	5.1298	5.1468	5.1638	5.1808	5.1978	5.2148
27	5.2148	5.2318	5.2488	5.2658	5.2828	5.2998	5.3168
28	5.3168	5.3338	5.3508	5.3678	5.3848	5.4018	5.4188
29	5.4188	5.4358	5.4528	5.4698	5.4868	5.5038	5.5208
30	5.5208	5.5378	5.5548	5.5718	5.5888	5.6058	5.6228
31	5.6228	5.6398	5.6568	5.6738	5.6908	5.7078	5.7248
32	5.7248	5.7418	5.7588	5.7758	5.7928	5.8098	5.8268
33	5.8268	5.8438	5.8608	5.8778	5.8948	5.9118	5.9288
34	5.9288	5.9458	5.9628	5.9798	5.9968	6.0138	6.0308
35	6.0308	6.0478	6.0648	6.0818	6.0988	6.1158	6.1328
36	6.1328	6.1498	6.1668	6.1838	6.2008	6.2178	6.2348
37	6.2348	6.2518	6.2688	6.2858	6.3028	6.3198	6.3368
38	6.3368	6.3538	6.3708	6.3878	6.4048	6.4218	6.4388
39	6.4388	6.4558	6.4728	6.4898	6.5068	6.5238	6.5408
40	6.5408	6.5578	6.5748	6.5918	6.6088	6.6258	6.6428
41	6.6428	6.6598	6.6768	6.6938	6.7108	6.7278	6.7448
42	6.7448	6.7618	6.7788	6.7958	6.8128	6.8298	6.8468
43	6.8468	6.8638	6.8808	6.8978	6.9148	6.9318	6.9488
44	6.9488	6.9658	6.9828	6.9998	7.0168	7.0338	7.0508
45	7.0508	7.0678	7.0848	7.1018	7.1188	7.1358	7.1528

FUNCTIONS OF NUMBERS

1

49

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
1	1	1	1.0000	1.0000	0.00000	1000.000	3.1416	0.7854
2	4	8	1.4142	1.2599	0.30103	500.000	6.2832	3.1416
3	9	27	1.7321	1.4422	0.47712	333.333	9.4248	7.0686
4	16	64	2.0000	1.5874	0.60206	250.000	12.5664	17.6825
5	25	125	2.2361	1.7100	0.69897	200.000	15.7080	28.2743
6	36	216	2.4495	1.8171	0.77815	166.667	18.8500	38.4845
7	49	343	2.6458	1.9129	0.84510	142.857	21.9811	48.6945
8	64	512	2.8284	2.0000	0.90309	125.000	25.1327	58.9050
9	81	729	3.0000	2.0801	0.95424	111.111	28.2743	69.1155
10	100	1000	3.1623	2.1584	1.00000	100.000	31.4159	78.5398
11	121	1331	3.3166	2.2240	1.04139	90.909	34.5584	88.0032
12	144	1728	3.4641	2.2894	1.07918	83.333	37.6991	97.7245
13	169	2197	3.6056	2.3513	1.11394	76.923	40.8307	107.7032
14	196	2744	3.7417	2.4102	1.14613	70.588	43.9822	117.9175
15	225	3375	3.8730	2.4682	1.17609	66.667	47.124	128.2743
16	256	4096	4.0000	2.5198	1.20412	62.5000	50.265	138.8045
17	289	4913	4.1231	2.5713	1.23045	58.8235	53.407	149.4845
18	324	5832	4.2426	2.6207	1.25527	55.5556	56.549	160.3133
19	361	6859	4.3589	2.6684	1.27957	52.6316	59.692	171.2980
20	400	8000	4.4721	2.7144	1.30310	50.0000	62.832	182.4775
21	441	9261	4.5826	2.7589	1.32222	47.6190	65.973	193.861
22	484	10648	4.6904	2.8020	1.34242	45.4545	69.115	205.359
23	529	12167	4.7958	2.8439	1.36173	43.4783	72.369	217.074
24	576	13824	4.8990	2.8840	1.38103	41.6667	75.694	228.905
25	625	15625	5.0000	2.9240	1.39754	40.0000	79.087	240.854
26	676	17576	5.0990	2.9625	1.41497	38.4615	81.681	252.929
27	729	19683	5.1962	3.0000	1.43136	37.0370	84.283	265.133
28	784	21952	5.2915	3.0356	1.44716	35.7143	86.891	277.468
29	841	24389	5.3852	3.0702	1.46240	34.4828	89.506	289.920
30	900	27000	5.4772	3.1072	1.47712	33.3333	92.133	302.499
31	961	29791	5.5678	3.1414	1.49136	32.2581	94.784	315.199
32	1024	32768	5.6569	3.1748	1.50515	31.2500	97.369	328.029
33	1089	35937	5.7446	3.2068	1.51848	30.3030	100.000	340.887
34	1156	39304	5.8312	3.2378	1.53134	29.4118	102.681	353.874
35	1225	42875	5.9161	3.2711	1.54407	28.5714	105.395	366.999
36	1296	46656	6.0000	3.3019	1.55630	27.7778	108.146	380.263
37	1369	50653	6.0828	3.3322	1.56820	27.0270	110.934	393.668
38	1444	54872	6.1644	3.3612	1.57978	26.3158	113.759	407.215
39	1521	59319	6.2446	3.3892	1.59106	25.6410	116.619	420.905
40	1600	64000	6.3246	3.4200	1.60206	25.0000	119.514	434.739
41	1681	68921	6.4031	3.4482	1.61278	24.3902	122.444	448.710
42	1764	74088	6.4807	3.4760	1.62325	23.8095	125.408	462.819
43	1849	79507	6.5572	3.5033	1.63348	23.2323	128.408	477.068
44	1936	85184	6.6328	3.5303	1.64345	22.6667	131.444	491.459
45	2025	91125	6.7083	3.5569	1.65317	22.2222	134.514	505.994
46	2116	97336	6.7823	3.5830	1.66276	21.7391	137.619	520.675
47	2209	103823	6.8557	3.6088	1.67214	21.2643	140.759	535.504
48	2304	110592	6.9284	3.6343	1.68134	20.8000	143.934	550.484
49	2401	117649	7.0000	3.6593	1.69020	20.4082	147.144	565.615

FUNCTIONS OF NUMBERS

.01

.49

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
.01	.0001	.000001	0.1000	0.2154	2.00000	10000.000	.03142	.00079
.02	.0004	.000008	0.1414	0.2714	2.30103	5000.000	.06283	.00314
.03	.0009	.000027	0.1732	0.3307	2.47712	3333.333	.09425	.00707
.04	.0016	.000064	0.2000	0.3420	2.60206	2500.000	.12566	.01257
.05	.0025	.000125	0.2236	0.3684	2.69897	2000.000	.15708	.01964
.06	.0036	.000216	0.2449	0.3915	2.77815	1666.667	.18850	.02827
.07	.0049	.000343	0.2646	0.4121	2.84510	1428.571	.21981	.03849
.08	.0064	.000512	0.2828	0.4309	2.90309	1250.000	.25133	.05027
.09	.0081	.000729	0.3000	0.4462	2.95424	1111.111	.28274	.06362
.10	.0100	.001000	0.3162	0.4641	3.00000	1000.000	.31416	.07854
.11	.0121	.001331	0.3317	0.4791	3.04139	909.090	.34558	.09503
.12	.0144	.001728	0.3464	0.4932	3.07918	833.333	.37699	.01130
.13	.0169	.002197	0.3606	0.5066	3.11394	769.230	.40841	.01323
.14	.0196	.002744	0.3742	0.5192	3.14613	714.286	.43982	.01534
.15	.0225	.003375	0.3873	0.5313	3.17609	666.667	.47124	.01762
.16	.0256	.004096	0.4000	0.5429	3.20412	625.000	.50265	.02016
.17	.0289	.004913	0.4123	0.5540	3.23045	588.235	.53407	.02268
.18	.0324	.005832	0.4243	0.5646	3.25527	555.556	.56549	.02544
.19	.0361	.006859	0.4359	0.5749	3.27957	526.316	.59692	.02833
.20	.0400	.008000	0.4472	0.5848	3.30310	500.000	.62832	.03146
.21	.0441	.009261	0.4583	0.5944	3.32222	476.190	.65973	.03463
.22	.0484	.010648	0.4690	0.6037	3.34242	454.545	.69115	.03803
.23	.0529	.012167	0.4796	0.6127	3.36173	434.783	.72257	.04158
.24	.0576	.013824	0.4899	0.6214	3.38103	416.667	.75398	.04529
.25	.0625	.015625	0.5000	0.6300	3.39754	400.000	.78540	.04907
.26	.0676	.017576	0.5099	0.6383	3.41497	384.615	.81681	.05303
.27	.0729	.019683	0.5196	0.6463	3.43136	370.370	.84823	.05726
.28	.0784	.021952	0.5292	0.6542	3.44716	357.143	.88025	.06175
.29	.0841	.024389	0.5385	0.6619	3.46240	344.828	.91106	.06650
.30	.0900	.027000	0.5477	0.6694	3.47712	333.333	.94248	.07068
.31	.0961	.029791	0.5568	0.6768	3.49136	322.581	.97369	.07517
.32	.1024	.032768	0.5657	0.6840	3.50515	312.500	1.00531	.08042
.33	.1089	.035937	0.5745	0.6910	3.51848	303.030	1.0373	.08550
.34	.1156	.039304	0.5831	0.6980	3.53134	294.118	1.06814	.09079
.35	.1225	.042875	0.5916	0.7047	3.54407	285.714	1.09956	.09621
.36	.1296	.046656	0.6000	0.7114	3.55630	277.778	1.13097	.10188
.37	.1369	.050653	0.6083	0.7179	3.56820	270.270	1.16239	.10752
.38	.1444	.054872	0.6164	0.7243	3.57978	263.158	1.19381	.11341
.39	.1521	.059319	0.6245	0.7306	3.59106	256.410	1.22522	.11949
.40	.1600	.064000	0.6325	0.7366	3.60206	250.000	1.25664	.12566
.41	.1681	.068921	0.6403	0.7429	3.61278	243.902	1.2881	.13202
.42	.1764	.074088	0.6480	0.7489	3.62325	238.095	1.3195	.13854
.43	.1849	.079507	0.6557	0.7548	3.63348	232.581	1.3509	.14522
.44	.1936	.085184	0.6633	0.7605	3.64345	227.272	1.3823	.15203
.45	.2025	.091125	0.6708	0.7663	3.65317	222.222	1.4137	.15903
.46	.2116	.097336	0.6782	0.7719	3.66276	217.391	1.4451	.16619
.47	.2209	.103823	0.6856	0.7775	3.67214	212.660	1.4765	.17349
.48	.2304	.110592	0.6928	0.7830	3.68134	208.000	1.5080	.18096
.49	.2401	.117649	0.7000	0.7884	3.69020	204.082	1.5394	.18854

FUNCTIONS OF NUMBERS

50

99

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 Reciprocal	No. = Diameter	
							Circum.	Area
50	2500	125000	7.0711	3.6840	1.69897	20.0000	157.08	1963.50
51	2601	132651	7.1114	3.7084	1.70557	19.6082	160.22	2042.82
52	2704	140608	7.2111	3.7325	1.71600	19.2308	163.36	2123.77
53	2809	148877	7.2801	3.7563	1.72428	18.8679	166.50	2206.18
54	2916	157464	7.3485	3.7798	1.73339	18.5185	169.65	2290.22
55	3025	166375	7.4162	3.8030	1.74306	18.1818	172.79	2375.83
56	3136	175616	7.4839	3.8259	1.75349	17.8571	175.93	2463.01
57	3249	185193	7.5512	3.8485	1.76467	17.5439	179.07	2551.76
58	3364	195112	7.6181	3.8709	1.77653	17.2414	182.21	2642.08
59	3481	205379	7.6841	3.8930	1.77085	16.9492	185.35	2733.97
60	3600	216000	7.7460	3.9149	1.77815	16.6667	188.50	2827.43
61	3721	226981	7.8061	3.9365	1.78533	16.3934	191.64	2922.47
62	3844	238328	7.8640	3.9579	1.79239	16.1290	194.78	3019.07
63	3969	250047	7.9193	3.9791	1.79934	15.8720	197.92	3117.25
64	4096	262144	8.0000	4.0000	1.80518	15.6250	201.06	3216.99
65	4225	274625	8.0632	4.0207	1.81291	15.3846	204.20	3318.31
66	4356	287496	8.1264	4.0412	1.82154	15.1504	207.35	3421.19
67	4489	300763	8.1884	4.0615	1.83007	14.9214	210.49	3525.65
68	4624	314432	8.2492	4.0817	1.83851	14.7059	213.63	3631.68
69	4761	328509	8.3095	4.1016	1.84685	14.4928	216.77	3739.28
70	4900	343000	8.3685	4.1213	1.85510	14.2857	219.91	3848.45
71	5041	357911	8.4261	4.1408	1.86326	14.0845	223.05	3959.19
72	5184	373248	8.4834	4.1602	1.87133	13.8889	226.19	4071.50
73	5329	389017	8.5404	4.1793	1.87932	13.6985	229.34	4185.39
74	5476	405224	8.6024	4.1983	1.88723	13.5135	232.48	4300.84
75	5625	421875	8.6593	4.2172	1.89506	13.3333	235.62	4417.86
76	5776	438976	8.7161	4.2359	1.90281	13.1579	238.76	4536.46
77	5929	456533	8.7728	4.2545	1.91048	12.9870	241.90	4656.63
78	6084	474552	8.8294	4.2727	1.91809	12.8205	245.04	4778.36
79	6241	493039	8.8858	4.2908	1.92563	12.6582	248.19	4901.67
80	6400	512000	8.9430	4.3089	1.93309	12.5000	251.33	5026.55
81	6561	531441	8.9999	4.3268	1.94048	12.3457	254.47	5153.00
82	6724	551368	9.0566	4.3445	1.94781	12.1951	257.61	5281.02
83	6889	571787	9.1131	4.3621	1.95508	12.0482	260.75	5410.52
84	7056	592704	9.1695	4.3795	1.96228	11.9048	263.89	5541.77
85	7225	614125	9.2258	4.3968	1.96942	11.7647	267.04	5674.50
86	7396	636056	9.2819	4.4139	1.97650	11.6279	270.18	5808.80
87	7569	658493	9.3378	4.4310	1.98352	11.4943	273.32	5944.68
88	7744	681432	9.3936	4.4480	1.99048	11.3636	276.46	6082.12
89	7921	704879	9.4493	4.4647	1.99739	11.2360	279.59	6221.14
90	8100	729900	9.5049	4.4814	1.95404	11.1111	282.74	6361.73
91	8281	755481	9.5604	4.4979	1.96064	10.9900	285.88	6503.88
92	8464	781632	9.6158	4.5143	1.96719	10.8696	289.03	6647.61
93	8649	808357	9.6711	4.5307	1.97368	10.7527	292.17	6792.91
94	8836	835664	9.7262	4.5468	1.97913	10.6383	295.31	6939.78
95	9025	863575	9.7811	4.5629	1.98454	10.5263	298.45	7088.22
96	9216	892096	9.8358	4.5789	1.98991	10.4167	301.59	7238.23
97	9409	921233	9.8903	4.5947	1.99523	10.3093	304.73	7389.81
98	9604	950992	9.9446	4.6104	1.99123	10.2041	307.88	7542.96
99	9801	970299	9.9989	4.6261	1.99564	10.1010	311.02	7697.69

FUNCTIONS OF NUMBERS

50

99

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 Reciprocal	No. = Diameter	
							Circum.	Area
50	2500	125000	0.7071	0.7937	1.69897	2000.000	1.5708	1.9635
51	2601	132651	0.7111	0.7970	1.70557	1950.784	1.6022	2.0428
52	2704	140608	0.7211	0.8041	1.71600	1923.077	1.6336	2.1237
53	2809	148877	0.7348	0.8093	1.72428	1886.793	1.6650	2.2062
54	2916	157464	0.7416	0.8143	1.73239	1851.852	1.6965	2.2902
55	3025	166375	0.7516	0.8193	1.74036	1818.182	1.7279	2.3758
56	3136	175616	0.7593	0.8243	1.74819	1785.714	1.7593	2.4630
57	3249	185193	0.7653	0.8291	1.75587	1754.386	1.7907	2.5518
58	3364	195112	0.7696	0.8340	1.76343	1724.138	1.8221	2.6421
59	3481	205379	0.7731	0.8387	1.77085	1694.915	1.8535	2.7340
60	3600	216000	0.7746	0.8434	1.77815	1666.667	1.8850	2.8274
61	3721	226981	0.7781	0.8481	1.78533	1639.344	1.9164	2.9225
62	3844	238328	0.7810	0.8527	1.79239	1612.903	1.9478	3.0191
63	3969	250047	0.7837	0.8573	1.79934	1587.302	1.9792	3.1173
64	4096	262144	0.8000	0.8618	1.80518	1562.500	2.0106	3.2170
65	4225	274625	0.8062	0.8662	1.81291	1538.462	2.0420	3.3183
66	4356	287496	0.8114	0.8705	1.82154	1515.152	2.0735	3.4212
67	4489	300763	0.8164	0.8748	1.83007	1492.537	2.1049	3.5257
68	4624	314432	0.8216	0.8794	1.83851	1470.588	2.1363	3.6317
69	4761	328509	0.8267	0.8837	1.84685	1449.275	2.1677	3.7393
70	4900	343000	0.8317	0.8879	1.85510	1428.571	2.1991	3.8485
71	5041	357911	0.8365	0.8919	1.86326	1408.451	2.2305	3.9592
72	5184	373248	0.8412	0.8956	1.87133	1388.869	2.2620	4.0715
73	5329	389017	0.8454	0.9004	1.87932	1369.863	2.2934	4.1854
74	5476	405224	0.8502	0.9045	1.88723	1351.351	2.3248	4.3008
75	5625	421875	0.8548	0.9086	1.89506	1333.333	2.3562	4.4170
76	5776	438976	0.8593	0.9126	1.90281	1315.790	2.3876	4.5355
77	5929	456533	0.8637	0.9165	1.91048	1298.701	2.4190	4.6566
78	6084	474552	0.8680	0.9205	1.91809	1282.051	2.4504	4.7784
79	6241	493039	0.8722	0.9244	1.92563	1265.823	2.4819	4.9017
80	6400	512000	0.8764	0.9283	1.93309	1250.000	2.5133	5.0265
81	6561	531441	0.8805	0.9322	1.94048	1234.568	2.5447	5.1530
82	6724	551368	0.8845	0.9361	1.94781	1219.512	2.5761	5.2810
83	6889	571787	0.8884	0.9398	1.95508	1204.819	2.6075	5.4105
84	7056	592704	0.8922	0.9435	1.96228	1190.476	2.6389	5.5418
85	7225	614125	0.8959	0.9473	1.96942	1176.471	2.6704	5.6745
86	7396	636056	0.8996	0.9510	1.97650	1162.791	2.7018	5.8088
87	7569	658493	0.9031	0.9546	1.98352	1149.425	2.7332	5.9447
88	7744	681432	0.9065	0.9581	1.99048	1136.364	2.7646	6.0821
89	7921	704879	0.9098	0.9619	1.99739	1123.596	2.7960	6.2211
90	8100	729900	0.9130	0.9655	1.95424	1111.111	2.8274	6.3617
91	8281	755481	0.9161	0.9691	1.96064	1099.001	2.8589	6.5039
92	8464	781632	0.9191	0.9726	1.96719	1086.957	2.8903	6.6476
93	8649	808357	0.9220	0.9761	1.97368	1075.260	2.9217	6.7929
94	8836	835664	0.9248	0.9795	1.97913	1063.830	2.9531	6.9398
95	9025	863575	0.9274	0.9829	1.98454	1052.632	2.9845	7.0882
96	9216	892096	0.9300	0.9861	1.98991	1041.673	3.0159	7.2389
97	9409	921233	0.9325	0.9893	1.99523	1030.928	3.0473	7.3908
98	9604	950992	0.9350	0.9924	1.99123	1020.408	3.0788	7.5437
99	9801	970299	0.9375	0.9956	1.99564	1010.101	3.1102	7.6977

FUNCTIONS OF NUMBERS

 150
199

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
150	22500	3375000	150.000	5.3010	2.2793	6.6667	471.24	17671.5
151	22801	3442951	151.000	5.3133	2.2801	6.6255	474.38	17907.9
152	23104	3511808	152.000	5.3261	2.2814	6.5895	477.56	18154.8
153	23409	3581577	153.000	5.3394	2.2828	6.5539	480.77	18405.4
154	23716	3652264	154.000	5.3531	2.2842	6.5184	484.01	18660.5
155	24025	3723875	155.000	5.3672	2.2857	6.4831	487.28	18920.2
156	24336	3796416	156.000	5.3817	2.2872	6.4480	490.58	19184.4
157	24649	3869893	157.000	5.3966	2.2887	6.4131	493.91	19453.3
158	24964	3944312	158.000	5.4118	2.2902	6.3784	497.27	19726.9
159	25281	4019679	159.000	5.4274	2.2917	6.3439	500.66	20005.2
160	25600	4096000	160.000	5.4433	2.2932	6.3096	504.08	20288.2
161	25921	4173281	161.000	5.4595	2.2947	6.2755	507.53	20575.8
162	26244	4251528	162.000	5.4761	2.2962	6.2416	511.01	20868.2
163	26569	4330747	163.000	5.4930	2.2977	6.2078	514.52	21164.4
164	26896	4410944	164.000	5.5102	2.2992	6.1742	518.06	21464.4
165	27225	4492125	165.000	5.5277	2.3007	6.1408	521.63	21769.0
166	27556	4574296	166.000	5.5455	2.3022	6.1076	525.23	22078.2
167	27889	4657463	167.000	5.5635	2.3037	6.0746	528.86	22392.0
168	28224	4741632	168.000	5.5817	2.3052	6.0418	532.52	22710.4
169	28561	4826809	169.000	5.6002	2.3067	6.0092	536.21	23033.4
170	28900	4913000	170.000	5.6189	2.3082	5.9768	539.93	23361.0
171	29241	5000211	171.000	5.6379	2.3097	5.9446	543.68	23694.2
172	29584	5088448	172.000	5.6571	2.3112	5.9126	547.46	24033.0
173	29929	5177717	173.000	5.6765	2.3127	5.8808	551.27	24377.4
174	30276	5268024	174.000	5.6961	2.3142	5.8492	555.11	24727.4
175	30625	5359375	175.000	5.7159	2.3157	5.8178	558.98	25083.0
176	30976	5451776	176.000	5.7359	2.3172	5.7866	562.88	25444.2
177	31329	5545233	177.000	5.7561	2.3187	5.7556	566.81	25811.0
178	31684	5639752	178.000	5.7765	2.3202	5.7248	570.77	26183.4
179	32041	5735339	179.000	5.7971	2.3217	5.6942	574.76	26561.4
180	32400	5832000	180.000	5.8179	2.3232	5.6638	578.78	26945.0
181	32761	5929741	181.000	5.8389	2.3247	5.6336	582.83	27334.2
182	33124	6028568	182.000	5.8600	2.3262	5.6036	586.91	27729.0
183	33489	6128487	183.000	5.8813	2.3277	5.5738	591.02	28129.4
184	33856	6229504	184.000	5.9027	2.3292	5.5442	595.16	28535.4
185	34225	6331625	185.000	5.9243	2.3307	5.5148	599.33	28947.0
186	34596	6434856	186.000	5.9461	2.3322	5.4856	603.53	29364.2
187	34969	6539203	187.000	5.9681	2.3337	5.4566	607.76	29787.0
188	35344	6644672	188.000	5.9902	2.3352	5.4278	612.02	30215.4
189	35721	6751269	189.000	5.9999	2.3367	5.3992	616.31	30649.4
190	36100	6859000	190.000	6.0200	2.3382	5.3708	620.63	31089.0
191	36481	6967881	191.000	6.0403	2.3397	5.3426	625.00	31534.2
192	36864	7077928	192.000	6.0608	2.3412	5.3146	629.41	31985.0
193	37249	7189155	193.000	6.0815	2.3427	5.2868	633.86	32441.4
194	37636	7301568	194.000	6.1023	2.3442	5.2592	638.35	32903.4
195	38025	7415275	195.000	6.1233	2.3457	5.2318	642.88	33371.0
196	38416	7530288	196.000	6.1444	2.3472	5.2046	647.45	33844.2
197	38809	7646613	197.000	6.1657	2.3487	5.1776	652.06	34323.0
198	39204	7764264	198.000	6.1872	2.3502	5.1508	656.71	34807.4
199	39601	7883259	199.000	6.2089	2.3517	5.1242	661.40	35297.4

FUNCTIONS OF NUMBERS

 100
149

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
100	10000	1000000	100.000	4.6416	2.0000	10.0000	314.16	7853.98
101	10201	1060301	101.000	4.6570	2.0042	9.9099	317.30	8011.85
102	10404	1122672	102.000	4.6725	2.0084	9.8209	320.44	8172.23
103	10609	1187227	103.000	4.6881	2.0126	9.7329	323.58	8335.29
104	10816	1254064	104.000	4.7037	2.0167	9.6458	326.73	8499.87
105	11025	1323187	105.000	4.7194	2.0209	9.5596	329.87	8667.01
106	11236	1393616	106.000	4.7352	2.0251	9.4743	333.03	8836.73
107	11449	1465361	107.000	4.7511	2.0293	9.3898	336.19	9009.04
108	11664	1538432	108.000	4.7671	2.0334	9.3061	339.37	9182.98
109	11881	1612839	109.000	4.7832	2.0375	9.2232	342.56	9358.56
110	12100	1688580	110.000	4.7994	2.0416	9.1406	345.77	9535.87
111	12321	1765667	111.000	4.8157	2.0457	9.0585	348.99	9714.93
112	12544	1844112	112.000	4.8321	2.0498	8.9769	352.23	9895.73
113	12769	1924027	113.000	4.8486	2.0539	8.8958	355.48	10078.27
114	12996	1995414	114.000	4.8652	2.0580	8.8152	358.74	10262.56
115	13225	2068285	115.000	4.8819	2.0621	8.7351	362.01	10448.60
116	13456	2142640	116.000	4.8987	2.0662	8.6555	365.29	10636.40
117	13689	2218489	117.000	4.9156	2.0703	8.5764	368.58	10825.95
118	13924	2294832	118.000	4.9326	2.0744	8.4978	371.87	11017.25
119	14161	2372669	119.000	4.9497	2.0785	8.4196	375.18	11210.30
120	14400	2452000	120.000	4.9669	2.0826	8.3419	378.50	11405.10
121	14641	2532831	121.000	4.9842	2.0867	8.2646	381.83	11601.65
122	14884	2615168	122.000	4.9999	2.0908	8.1878	385.17	11800.00
123	15129	2698017	123.000	5.0157	2.0949	8.1114	388.52	12000.15
124	15376	2782384	124.000	5.0317	2.0990	8.0354	391.87	12202.10
125	15625	2868275	125.000	5.0478	2.1031	7.9598	395.23	12405.85
126	15876	2954704	126.000	5.0640	2.1072	7.8846	398.60	12611.30
127	16129	3042687	127.000	5.0803	2.1113	7.8098	401.98	12818.45
128	16384	3132232	128.000	5.0967	2.1154	7.7354	405.37	13027.20
129	16641	3223359	129.000	5.1132	2.1195	7.6614	408.77	13237.65
130	16900	3316080	130.000	5.1298	2.1236	7.5878	412.18	13449.80
131	17161	3410401	131.000	5.1465	2.1277	7.5146	415.60	13663.65
132	17424	3506328	132.000	5.1633	2.1318	7.4418	419.03	13879.20
133	17689	3603867	133.000	5.1802	2.1359	7.3694	422.47	14096.45
134	17956	3703024	134.000	5.1972	2.1400	7.2974	425.92	14315.40
135	18225	3803805	135.000	5.2143	2.1441	7.2258	429.38	14536.05
136	18496	3906216	136.000	5.2315	2.1482	7.1546	432.85	14758.40
137	18769	4010263	137.000	5.2488	2.1523	7.0838	436.33	14982.45
138	19044	4115952	138.000	5.2662	2.1564	7.0134	439.82	15208.20
139	19321	4223289	139.000	5.2837	2.1605	6.9434	443.33	15435.65
140	19600	4332280	140.000	5.3013	2.1646	6.8738	446.85	15664.80
141	19881	4442931	141.000	5.3190	2.1687	6.8046	450.38	15895.65
142	20164	4555248	142.000	5.3368	2.1728	6.7358	453.93	16128.20
143	20449	4669237	143.000	5.3547	2.1769	6.6674	457.48	16362.45
144	20736	4784904	144.000	5.3727	2.1810	6.5994	461.04	16598.40
145	21025	4902255	145.000	5.3908	2.1851	6.5318	464.61	16836.05
146	21316	5021304	146.000	5.4090	2.1892	6.4646	468.19	17075.40
147	21609	5142057	147.000	5.4273	2.1933	6.3978	471.78	17317.45
148	21904	5264520	148.000	5.4457	2.1974	6.3314	475.38	17562.10
149	22201	5388709	149.000	5.4642	2.2015	6.2654	479.00	17809.45

FUNCTIONS OF NUMBERS

250

299

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 Reciprocal	No. = Diameter	
							Circum.	Area
250	62500	15625000	250.00	237.97	4.00000	785.40	49087.4	49087.4
251	63001	15813251	251.00	238.96	4.00006	786.40	49480.9	49480.9
252	63504	16003008	252.00	239.97	4.00012	787.40	49875.6	49875.6
253	64009	16192277	253.00	240.98	4.00018	788.40	50272.9	50272.9
254	64516	16381064	254.00	241.99	4.00024	789.40	50672.6	50672.6
255	65025	16570275	255.00	243.00	4.00030	790.40	51075.0	51075.0
256	65536	16760016	256.00	244.01	4.00036	791.40	51479.9	51479.9
257	66049	16950293	257.00	245.02	4.00042	792.40	51887.4	51887.4
258	66564	17141112	258.00	246.03	4.00048	793.40	52297.2	52297.2
259	67081	17332479	259.00	247.04	4.00054	794.40	52709.3	52709.3
260	67600	17524390	260.00	248.05	4.00060	795.40	53123.6	53123.6
261	68121	17716851	261.00	249.06	4.00066	796.40	53540.1	53540.1
262	68644	17910868	262.00	250.07	4.00072	797.40	53958.8	53958.8
263	69169	18105437	263.00	251.08	4.00078	798.40	54379.7	54379.7
264	69696	18300564	264.00	252.09	4.00084	799.40	54802.9	54802.9
265	70225	18496255	265.00	253.10	4.00090	800.40	55228.4	55228.4
266	70756	18692506	266.00	254.11	4.00096	801.40	55656.2	55656.2
267	71289	18889323	267.00	255.12	4.00102	802.40	56086.3	56086.3
268	71824	19086702	268.00	256.13	4.00108	803.40	56518.6	56518.6
269	72361	19284649	269.00	257.14	4.00114	804.40	56953.1	56953.1
270	72900	19483170	270.00	258.15	4.00120	805.40	57389.8	57389.8
271	73441	19682271	271.00	259.16	4.00126	806.40	57828.7	57828.7
272	73984	19881958	272.00	260.17	4.00132	807.40	58269.8	58269.8
273	74529	20082227	273.00	261.18	4.00138	808.40	58713.1	58713.1
274	75076	20283084	274.00	262.19	4.00144	809.40	59158.6	59158.6
275	75625	20484535	275.00	263.20	4.00150	810.40	59606.3	59606.3
276	76176	20686586	276.00	264.21	4.00156	811.40	60056.2	60056.2
277	76729	20889243	277.00	265.22	4.00162	812.40	60508.3	60508.3
278	77284	21092512	278.00	266.23	4.00168	813.40	60962.6	60962.6
279	77841	21296399	279.00	267.24	4.00174	814.40	61419.2	61419.2
280	78400	21500910	280.00	268.25	4.00180	815.40	61878.0	61878.0
281	78961	21706051	281.00	269.26	4.00186	816.40	62339.0	62339.0
282	79524	21911828	282.00	270.27	4.00192	817.40	62802.2	62802.2
283	80089	22118247	283.00	271.28	4.00198	818.40	63267.6	63267.6
284	80656	22325304	284.00	272.29	4.00204	819.40	63735.2	63735.2
285	81225	22532915	285.00	273.30	4.00210	820.40	64205.0	64205.0
286	81796	22741086	286.00	274.31	4.00216	821.40	64677.1	64677.1
287	82369	22949823	287.00	275.32	4.00222	822.40	65151.4	65151.4
288	82944	23159132	288.00	276.33	4.00228	823.40	65627.9	65627.9
289	83521	23369019	289.00	277.34	4.00234	824.40	66106.6	66106.6
290	84100	23579490	290.00	278.35	4.00240	825.40	66587.6	66587.6
291	84681	23790551	291.00	279.36	4.00246	826.40	67070.9	67070.9
292	85264	23992208	292.00	280.37	4.00252	827.40	67556.4	67556.4
293	85849	24194467	293.00	281.38	4.00258	828.40	68044.1	68044.1
294	86436	24397324	294.00	282.39	4.00264	829.40	68534.0	68534.0
295	87025	24600785	295.00	283.40	4.00270	830.40	69026.1	69026.1
296	87616	24804856	296.00	284.41	4.00276	831.40	69520.4	69520.4
297	88209	25009533	297.00	285.42	4.00282	832.40	70016.9	70016.9
298	88804	25214812	298.00	286.43	4.00288	833.40	70515.6	70515.6
299	89401	25420700	299.00	287.44	4.00294	834.40	71016.6	71016.6

FUNCTIONS OF NUMBERS

200

249

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
200	40000	8000000	200.00	5.8480	2.30103	5.00000	628.32	31415.9
201	40401	8120601	201.00	5.8578	2.30320	4.97512	631.46	31730.9
202	40804	8242408	202.00	5.8675	2.30535	4.95050	634.79	32047.4
203	41209	8365427	203.00	5.8771	2.30749	4.92611	638.11	32366.4
204	41616	8488664	204.00	5.8868	2.30963	4.90195	641.48	32687.9
205	42025	8613125	205.00	5.8964	2.31175	4.87805	644.83	33011.0
206	42436	8738816	206.00	5.9059	2.31387	4.85437	648.17	33336.6
207	42849	8865743	207.00	5.9155	2.31597	4.83092	651.50	33664.7
208	43264	8993912	208.00	5.9250	2.31807	4.80769	654.82	33994.4
209	43681	9123329	209.00	5.9345	2.32015	4.78469	658.15	34326.6
210	44100	9254000	210.00	5.9440	2.32222	4.76190	661.46	34660.4
211	44521	9385931	211.00	5.9535	2.32428	4.73934	664.79	34996.8
212	44944	9519128	212.00	5.9630	2.32633	4.71699	668.11	35334.8
213	45369	9653597	213.00	5.9725	2.32838	4.69484	671.42	35674.4
214	45796	9789344	214.00	5.9820	2.33042	4.67289	674.72	36015.6
215	46225	9926375	215.00	5.9915	2.33244	4.65116	678.01	36358.4
216	46656	10064706	216.00	6.0010	2.33445	4.62963	681.29	36702.8
217	47089	10204163	217.00	6.0105	2.33646	4.60830	684.56	37048.8
218	47524	10344752	218.00	6.0200	2.33846	4.58716	687.82	37396.4
219	47961	10486489	219.00	6.0295	2.34046	4.56621	691.07	37745.6
220	48400	10629380	220.00	6.0390	2.34244	4.54545	694.31	38096.4
221	48841	10773431	221.00	6.0485	2.34439	4.52489	697.54	38448.8
222	49284	10918648	222.00	6.0580	2.34633	4.50452	700.77	38802.8
223	49729	11065037	223.00	6.0675	2.34826	4.48434	704.00	39158.4
224	50176	11212604	224.00	6.0770	2.35019	4.46434	707.22	39515.6
225	50625	11361365	225.00	6.0865	2.35211	4.44444	710.44	39874.4
226	51076	11511326	226.00	6.0960	2.35402	4.42478	713.65	40234.8
227	51529	11662493	227.00	6.1055	2.35592	4.40535	716.86	40596.8
228	51984	11814872	228.00	6.1150	2.35782	4.38614	720.07	40960.4
229	52441	11968469	229.00	6.1245	2.35971	4.36714	723.27	41326.6
230	52900	12124200	230.00	6.1340	2.36159	4.34834	726.47	41694.4
231	53361	12281181	231.00	6.1435	2.36346	4.32974	729.67	42063.8
232	53824	12439416	232.00	6.1530	2.36533	4.31134	732.86	42434.8
233	54289	12600000	233.00	6.1625	2.36719	4.29314	736.05	42807.4
234	54756	12761939	234.00	6.1720	2.36904	4.27514	739.24	43181.6
235	55225	12925230	235.00	6.1815	2.37088	4.25734	742.43	43557.4
236	55696	13089975	236.00	6.1910	2.37271	4.23974	745.62	43934.8
237	56169	13257180	237.00	6.2005	2.37454	4.22234	748.81	44313.8
238	56644	13425840	238.00	6.2100	2.37636	4.20514	752.00	44694.4
239	57121	13595960	239.00	6.2195	2.37818	4.18814	755.19	45076.6
240	57600	13767540	240.00	6.2290	2.38000	4.17134	758.38	45460.4
241	58081	13940581	241.00	6.2385	2.38181	4.15474	761.57	45846.8
242	58564	14115188	242.00	6.2480	2.38362	4.13834	764.76	46234.8
243	59049	14291367	243.00	6.2575	2.38542	4.12214	767.95	46624.4
244	59536	14469124	244.00	6.2670	2.38722	4.10614	771.14	47015.6
245	60025	14648475	245.00	6.2765	2.38902	4.09034	774.33	47408.4
246	60516	14829426	246.00	6.2860	2.39081	4.07474	777.52	47802.8
247	61009	15011983	247.00	6.2955	2.39261	4.05934	780.71	48198.8
248	61504	15196152	248.00	6.3050	2.39440	4.04414	783.90	48596.4
249	62001	15381939	249.00	6.3145	2.39619	4.02914	787.09	49000.0

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 Reciprocal	No. = Diameter	
							Circum.	Area
300	90000	27000000	300.000	6.9328	2.47712	3.33333	942.48	70685.8
301	90601	27270001	301.667	6.9371	2.47757	3.32226	945.62	71157.9
302	91204	27540008	303.333	6.9414	2.47801	3.31126	948.76	71631.0
303	91809	27810017	305.000	6.9457	2.47846	3.30033	951.90	72105.0
304	92416	28080028	306.667	6.9500	2.47891	3.28944	955.04	72583.4
305	93025	28350041	308.333	6.9543	2.47936	3.27855	958.19	73061.7
306	93636	28620056	310.000	6.9586	2.47981	3.26766	961.33	73541.0
307	94249	28890073	311.667	6.9629	2.48026	3.25677	964.47	74021.0
308	94864	29160092	313.333	6.9672	2.48071	3.24588	967.61	74501.0
309	95481	29430113	315.000	6.9715	2.48116	3.23499	970.75	74981.0
310	96100	29700136	316.667	6.9758	2.48161	3.22410	973.89	75461.0
311	96721	30000161	318.333	6.9801	2.48206	3.21321	977.03	75941.0
312	97344	30300188	320.000	6.9844	2.48251	3.20232	980.17	76421.0
313	97969	30600217	321.667	6.9887	2.48296	3.19143	983.31	76901.0
314	98596	30900248	323.333	6.9930	2.48341	3.18054	986.45	77381.0
315	99225	31200281	325.000	6.9973	2.48386	3.16965	989.59	77861.0
316	99856	31500316	326.667	6.9999	2.48431	3.15876	992.73	78341.0
317	100489	31800353	328.333	7.0042	2.48476	3.14787	995.87	78821.0
318	101124	32100392	330.000	7.0085	2.48521	3.13698	999.01	79301.0
319	101761	32400433	331.667	7.0128	2.48566	3.12609	1002.15	79781.0
320	102400	32700476	333.333	7.0171	2.48611	3.11520	1005.29	80261.0
321	103041	33000521	335.000	7.0214	2.48656	3.10431	1008.43	80741.0
322	103684	33300568	336.667	7.0257	2.48701	3.09342	1011.57	81221.0
323	104329	33600617	338.333	7.0300	2.48746	3.08253	1014.71	81701.0
324	104976	33900668	340.000	7.0343	2.48791	3.07164	1017.85	82181.0
325	105625	34200721	341.667	7.0386	2.48836	3.06075	1021.00	82661.0
326	106276	34500776	343.333	7.0429	2.48881	3.04986	1024.14	83141.0
327	106929	34800833	345.000	7.0472	2.48926	3.03897	1027.28	83621.0
328	107584	35100892	346.667	7.0515	2.48971	3.02808	1030.42	84101.0
329	108241	35400953	348.333	7.0558	2.49016	3.01719	1033.56	84581.0
330	108900	35701016	350.000	7.0601	2.49061	3.00630	1036.70	85061.0
331	109561	36001081	351.667	7.0644	2.49106	3.01541	1039.84	85541.0
332	110224	36301148	353.333	7.0687	2.49151	3.01452	1042.98	86021.0
333	110889	36601217	355.000	7.0730	2.49196	3.00363	1046.12	86501.0
334	111556	36901288	356.667	7.0773	2.49241	2.99274	1049.26	86981.0
335	112225	37201361	358.333	7.0816	2.49286	2.98185	1052.40	87461.0
336	112896	37501436	360.000	7.0859	2.49331	2.97096	1055.54	87941.0
337	113569	37801513	361.667	7.0902	2.49376	2.96007	1058.68	88421.0
338	114244	38101592	363.333	7.0945	2.49421	2.94918	1061.82	88901.0
339	114921	38401673	365.000	7.0988	2.49466	2.93829	1064.96	89381.0
340	115600	38701756	366.667	7.1031	2.49511	2.92740	1068.10	89861.0
341	116281	39001841	368.333	7.1074	2.49556	2.91651	1071.24	90341.0
342	116964	39301928	370.000	7.1117	2.49601	2.90562	1074.38	90821.0
343	117649	39602017	371.667	7.1160	2.49646	2.89473	1077.52	91301.0
344	118336	40002108	373.333	7.1203	2.49691	2.88384	1080.66	91781.0
345	119025	40302201	375.000	7.1246	2.49736	2.87295	1083.80	92261.0
346	119716	40602296	376.667	7.1289	2.49781	2.86206	1086.94	92741.0
347	120409	40902393	378.333	7.1332	2.49826	2.85117	1090.08	93221.0
348	121104	41202492	380.000	7.1375	2.49871	2.84028	1093.22	93701.0
349	121801	41502593	381.667	7.1418	2.49916	2.82939	1096.36	94181.0

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 Reciprocal	No. = Diameter	
							Circum.	Area
350	122500	42875000	350.000	7.0473	2.54407	2.85714	1099.6	96211.3
351	123201	43243551	351.667	7.0516	2.54452	2.84625	1102.7	96691.8
352	123904	43612608	353.333	7.0559	2.54497	2.83536	1105.8	97171.0
353	124609	43982177	355.000	7.0602	2.54542	2.82447	1108.9	97651.0
354	125316	44352252	356.667	7.0645	2.54587	2.81358	1112.0	98131.0
355	126025	44722335	358.333	7.0688	2.54632	2.80269	1115.1	98611.0
356	126736	45092424	360.000	7.0731	2.54677	2.79180	1118.2	99091.0
357	127449	45462519	361.667	7.0774	2.54722	2.78091	1121.3	99571.0
358	128164	45832616	363.333	7.0817	2.54767	2.77002	1124.4	100051.0
359	128881	46202717	365.000	7.0860	2.54812	2.75913	1127.5	100531.0
360	129600	46572824	366.667	7.0903	2.54857	2.74824	1130.6	101011.0
361	130321	46942933	368.333	7.0946	2.54902	2.73735	1133.7	101491.0
362	131044	47313048	370.000	7.0989	2.54947	2.72646	1136.8	101971.0
363	131769	47683169	371.667	7.1032	2.54992	2.71557	1140.0	102451.0
364	132496	48053296	373.333	7.1075	2.55037	2.70468	1143.1	102931.0
365	133225	48423429	375.000	7.1118	2.55082	2.69379	1146.2	103411.0
366	133956	48793568	376.667	7.1161	2.55127	2.68290	1149.3	103891.0
367	134689	49163713	378.333	7.1204	2.55172	2.67201	1152.4	104371.0
368	135424	49533864	380.000	7.1247	2.55217	2.66112	1155.5	104851.0
369	136161	50004021	381.667	7.1290	2.55262	2.65023	1158.6	105331.0
370	136900	50474184	383.333	7.1333	2.55307	2.63934	1161.7	105811.0
371	137641	50944353	385.000	7.1376	2.55352	2.62845	1164.8	106291.0
372	138384	51414528	386.667	7.1419	2.55397	2.61756	1167.9	106771.0
373	139129	51884709	388.333	7.1462	2.55442	2.60667	1171.0	107251.0
374	139876	52354896	390.000	7.1505	2.55487	2.59578	1174.1	107731.0
375	140625	52825089	391.667	7.1548	2.55532	2.58489	1177.2	108211.0
376	141376	53295288	393.333	7.1591	2.55577	2.57400	1180.3	108691.0
377	142129	53765493	395.000	7.1634	2.55622	2.56311	1183.4	109171.0
378	142884	54235704	396.667	7.1677	2.55667	2.55222	1186.5	109651.0
379	143641	54705921	398.333	7.1720	2.55712	2.54133	1189.6	110131.0
380	144400	55176144	400.000	7.1763	2.55757	2.53044	1192.7	110611.0
381	145161	55646373	401.667	7.1806	2.55802	2.51955	1195.8	111091.0
382	145924	56116608	403.333	7.1849	2.55847	2.50866	1198.9	111571.0
383	146689	56586849	405.000	7.1892	2.55892	2.49777	1202.0	112051.0
384	147456	57057096	406.667	7.1935	2.55937	2.48688	1205.1	112531.0
385	148225	57527349	408.333	7.1978	2.55982	2.47599	1208.2	113011.0
386	149000	58000000	410.000	7.2021	2.56027	2.46510	1211.3	113491.0
387	149776	58472657	411.667	7.2064	2.56072	2.45421	1214.4	113971.0
388	150564	58945320	413.333	7.2107	2.56117	2.44332	1217.5	114451.0
389	151353	59417989	415.000	7.2150	2.56162	2.43243	1220.6	114931.0
390	152144	59890664	416.667	7.2193	2.56207	2.42154	1223.7	115411.0
391	152936	60363345	418.333	7.2236	2.56252	2.41065	1226.8	115891.0
392	153729	60836032	420.000	7.2279	2.56297	2.40000	1229.9	116371.0
393	154524	61308725	421.667	7.2322	2.56342	2.38911	1233.0	116851.0
394	155321	61781424	423.333	7.2365	2.56387	2.37822	1236.1	117331.0
395	156120	62254129	425.000	7.2408	2.56432	2.36733	1239.2	117811.0
396	156921	62726840	426.667	7.2451	2.56477	2.35644	1242.3	118291.0
397	157724	63200057	428.333	7.2494	2.56522	2.34555	1245.4	118771.0
398	158529	63673280	430.000	7.2537	2.56567	2.33466	1248.5	119251.0
399	159336	64146509	431.667	7.2580	2.56612	2.32377	1251.6	119731.0

FUNCTIONS OF NUMBERS

450
499

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
450	202500	91125000	21.2132	7.6631	2.5531	2.22222	1413.7	159043
451	203401	9173381	21.2368	7.6688	2.65418	2.21729	1416.9	159751
452	204304	92345408	21.2603	7.6744	2.65514	2.21239	1420.1	160461
453	205209	92959677	21.2837	7.6801	2.65610	2.20750	1423.3	161171
454	206116	93576694	21.3073	7.6857	2.65706	2.20264	1426.5	161883
455	207025	94196375	21.3307	7.6914	2.65801	2.19780	1429.7	162597
456	207936	94818816	21.3542	7.6970	2.65896	2.19298	1432.9	163313
457	208849	95443993	21.3776	7.7026	2.65992	2.18816	1436.1	164030
458	209764	96071917	21.4010	7.7082	2.66087	2.18334	1439.3	164748
459	210681	96702659	21.4243	7.7138	2.66181	2.17853	1442.5	165468
460	211600	97336000	21.4476	7.7194	2.66276	2.17371	1445.7	166190
461	212521	97972181	21.4709	7.7250	2.66370	2.16890	1448.9	166914
462	213444	98611128	21.4942	7.7305	2.66465	2.16408	1452.1	167639
463	214369	99252861	21.5175	7.7360	2.66559	2.15926	1455.3	168365
464	215296	99897344	21.5407	7.7415	2.66652	2.15445	1458.5	169093
465	216225	100546625	21.5639	7.7473	2.66745	2.14963	1461.7	169823
466	217156	101194966	21.5870	7.7529	2.66839	2.14482	1464.9	170554
467	218089	101847553	21.6102	7.7585	2.66932	2.14000	1468.1	171286
468	219024	102504387	21.6333	7.7640	2.67026	2.13518	1471.3	172019
469	219961	103161709	21.6564	7.7695	2.67117	2.13036	1474.5	172757
470	220900	103820000	21.6795	7.7750	2.67210	2.12554	1477.7	173494
471	221841	104487111	21.7025	7.7805	2.67302	2.12072	1480.9	174234
472	222784	105154244	21.7255	7.7860	2.67395	2.11590	1484.1	174976
473	223729	105821397	21.7485	7.7915	2.67486	2.11108	1487.3	175716
474	224676	106488564	21.7715	7.7970	2.67578	2.10626	1490.5	176460
475	225625	107154735	21.7945	7.8025	2.67669	2.10144	1493.7	177205
476	226576	107820916	21.8174	7.8079	2.67761	2.10004	1496.9	177952
477	227529	108487107	21.8403	7.8133	2.67852	2.09522	1500.1	178699
478	228484	109153302	21.8632	7.8188	2.67943	2.09040	1503.3	179451
479	229441	109819503	21.8861	7.8243	2.68034	2.08558	1506.5	180203
480	230400	110485700	21.9089	7.8297	2.68124	2.08076	1509.7	180956
481	231361	111151903	21.9316	7.8352	2.68215	2.07594	1512.9	181717
482	232325	111818116	21.9543	7.8406	2.68305	2.07112	1516.1	182478
483	233290	112484331	21.9770	7.8460	2.68395	2.06630	1519.3	183239
484	234256	113150544	22.0000	7.8514	2.68485	2.06148	1522.5	183994
485	235225	113816759	22.0227	7.8568	2.68574	2.05666	1525.7	184745
486	236196	114482976	22.0454	7.8622	2.68664	2.05184	1528.9	185496
487	237169	115149197	22.0681	7.8676	2.68753	2.04702	1532.1	186247
488	238144	115815420	22.0907	7.8730	2.68843	2.04220	1535.3	186998
489	239121	116481645	22.1133	7.8784	2.68932	2.03738	1538.5	187750
490	240100	117147872	22.1359	7.8837	2.69021	2.03256	1541.7	188501
491	241081	117814101	22.1584	7.8891	2.69110	2.02774	1544.9	189252
492	242064	118480332	22.1809	7.8944	2.69198	2.02292	1548.1	190003
493	243049	119146565	22.2034	7.8997	2.69287	2.01810	1551.3	190754
494	244036	119812800	22.2259	7.9050	2.69375	2.01328	1554.5	191505
495	245025	120479037	22.2484	7.9103	2.69464	2.00846	1557.7	192256
496	246016	121145276	22.2709	7.9156	2.69552	2.00364	1560.9	193007
497	247009	121811517	22.2934	7.9209	2.69641	2.00000	1564.1	193758
498	248004	122477760	22.3159	7.9262	2.69729	2.00000	1567.3	194509
499	249001	123144005	22.3383	7.9315	2.69817	2.00000	1570.5	195260

FUNCTIONS OF NUMBERS

400
449

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
400	160000	64000000	20.0000	7.3681	2.60206	2.50000	1256.6	125664
401	160801	64481201	20.0250	7.3742	2.60314	2.49777	1259.8	126293
402	161604	64962408	20.0500	7.3803	2.60423	2.49554	1263.0	126923
403	162409	65443617	20.0749	7.3864	2.60531	2.49331	1266.2	127553
404	163216	65924824	20.0998	7.3925	2.60639	2.49108	1269.4	128183
405	164025	66406035	20.1246	7.3986	2.60746	2.48886	1272.6	128813
406	164836	66887246	20.1494	7.4047	2.60854	2.48664	1275.8	129443
407	165649	67368457	20.1742	7.4108	2.60962	2.48442	1279.0	130073
408	166464	67849668	20.1990	7.4169	2.61070	2.48220	1282.2	130703
409	167281	68330879	20.2237	7.4229	2.61178	2.48000	1285.4	131333
410	168100	68812090	20.2485	7.4290	2.61286	2.47778	1288.6	131963
411	168921	69293301	20.2731	7.4350	2.61394	2.47556	1291.8	132593
412	169744	69774512	20.2978	7.4410	2.61502	2.47334	1295.0	133223
413	170569	70255723	20.3224	7.4470	2.61610	2.47112	1298.2	133853
414	171396	70736934	20.3470	7.4530	2.61718	2.46890	1301.4	134483
415	172225	71218145	20.3715	7.4590	2.61826	2.46668	1304.6	135113
416	173056	71699356	20.3961	7.4650	2.61934	2.46446	1307.8	135743
417	173889	72180567	20.4206	7.4710	2.62042	2.46224	1311.0	136373
418	174724	72661778	20.4450	7.4770	2.62150	2.46002	1314.2	137003
419	175561	73142989	20.4695	7.4829	2.62258	2.45780	1317.4	137633
420	176400	73624200	20.4939	7.4889	2.62366	2.45558	1320.6	138263
421	177241	74105411	20.5183	7.4948	2.62474	2.45336	1323.8	138893
422	178084	74586622	20.5426	7.5007	2.62582	2.45114	1327.0	139523
423	178929	75067833	20.5670	7.5067	2.62690	2.44892	1330.2	140153
424	179776	75549044	20.5913	7.5126	2.62798	2.44670	1333.4	140783
425	180625	76030255	20.6155	7.5185	2.62906	2.44448	1336.6	141413
426	181476	76511466	20.6398	7.5244	2.63014	2.44226	1339.8	142043
427	182329	77002677	20.6640	7.5303	2.63122	2.44004	1343.0	142673
428	183184	77493888	20.6882	7.5362	2.63230	2.43782	1346.2	143303
429	184041	77985099	20.7123	7.5421	2.63338	2.43560	1349.4	143933
430	184900	78476310	20.7364	7.5479	2.63446	2.43338	1352.6	144563
431	185761	78967521	20.7605	7.5538	2.63554	2.43116	1355.8	145193
432	186624	79458732	20.7846	7.5597	2.63662	2.42894	1359.0	145823
433	187489	79949943	20.8087	7.5656	2.63770	2.42672	1362.2	146453
434	188356	80441154	20.8327	7.5715	2.63878	2.42450	1365.4	147083
435	189225	80932365	20.8567	7.5774	2.63986	2.42228	1368.6	147713
436	190096	81423576	20.8806	7.5833	2.64094	2.42006	1371.8	148343
437	190969	81914787	20.9045	7.5892	2.64202	2.41784	1375.0	148973
438	191844	82405998	20.9284	7.5951	2.64310	2.41562	1378.2	149603
439	192721	82897209	20.9523	7.6010	2.64418	2.41340	1381.4	150233
440	193600	83388420	20.9762	7.6069	2.64526	2.41118	1384.6	150863
441	194481	83879631	21.0000	7.6128	2.64634	2.40896	1387.8	151493
442	195364	84370842	21.0238	7.6187	2.64742	2.40674	1391.0	152123
443	196249	84862053	21.0476	7.6246	2.64850	2.40452	1394.2	152753
444	197136	85353264	21.0713	7.6305	2.64958	2.40230	1397.4	153383
445	198025	85844475	21.0950	7.6364	2.65066	2.40008	1400.6	154013
446	198916	86335686	21.1187	7.6423	2.65174	2.39786	1403.8	154643
447	199809	86826897	21.1424	7.6482	2.65282	2.39564	1407.0	155273
448	200704	87318108	21.1660	7.6541	2.65390	2.39342	1410.2	155903
449	201601	87809319	21.1896	7.6600	2.65498	2.39120	1413.4	156533

FUNCTIONS OF NUMBERS

550
599

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
550	302500	166375000	23.4521	8.1932	2.74036	1.81818	1727.9	237583
551	303601	167284151	23.4734	8.2037	2.74036	1.81488	1731.0	238448
552	304704	168193304	23.4947	8.2142	2.74194	1.81159	1734.2	239314
553	305809	169102459	23.5160	8.2247	2.74273	1.80832	1737.3	240182
554	306916	170011616	23.5372	8.2351	2.74351	1.80505	1740.4	241051
555	308025	170920775	23.5584	8.2456	2.74429	1.80178	1743.5	241922
556	309136	171830036	23.5796	8.2561	2.74507	1.79851	1746.6	242795
557	310249	172739299	23.6008	8.2666	2.74585	1.79524	1749.7	243669
558	311364	173648564	23.6220	8.2771	2.74663	1.79197	1752.8	244545
559	312481	174557831	23.6432	8.2876	2.74741	1.78870	1755.9	245422
560	313600	175467090	23.6644	8.2981	2.74819	1.78543	1759.0	246300
561	314721	176376351	23.6856	8.3086	2.74897	1.78216	1762.1	247181
562	315844	177285612	23.7068	8.3191	2.74975	1.77889	1765.2	248063
563	316969	178194875	23.7280	8.3296	2.75053	1.77562	1768.3	248947
564	318096	179104140	23.7492	8.3401	2.75131	1.77235	1771.4	249832
565	319225	180013405	23.7704	8.3506	2.75209	1.76908	1774.5	250719
566	320356	180922672	23.7916	8.3611	2.75287	1.76581	1777.6	251607
567	321489	181831941	23.8128	8.3716	2.75365	1.76254	1780.7	252497
568	322624	182741212	23.8340	8.3821	2.75443	1.75927	1783.8	253388
569	323761	183650485	23.8552	8.3926	2.75521	1.75600	1786.9	254281
570	324900	184559760	23.8764	8.4031	2.75600	1.75273	1790.0	255176
571	326041	185469037	23.8976	8.4136	2.75678	1.74946	1793.1	256072
572	327184	186378316	23.9188	8.4241	2.75756	1.74619	1796.2	256970
573	328329	187287597	23.9400	8.4346	2.75834	1.74292	1799.3	257869
574	329476	188196880	23.9612	8.4451	2.75912	1.73965	1802.4	258770
575	330625	189106165	23.9824	8.4556	2.75990	1.73638	1805.5	259672
576	331776	190015452	24.0036	8.4661	2.76068	1.73311	1808.6	260576
577	332929	190924741	24.0248	8.4766	2.76146	1.72984	1811.7	261482
578	334084	191834032	24.0460	8.4871	2.76224	1.72657	1814.8	262389
579	335241	192743325	24.0672	8.4976	2.76302	1.72330	1817.9	263298
580	336400	193652620	24.0884	8.5081	2.76380	1.72003	1821.0	264208
581	337561	194561917	24.1096	8.5186	2.76458	1.71676	1824.1	265120
582	338724	195471216	24.1308	8.5291	2.76536	1.71349	1827.2	266033
583	339889	196380517	24.1520	8.5396	2.76614	1.71022	1830.3	266948
584	341056	197289820	24.1732	8.5501	2.76692	1.70695	1833.4	267865
585	342225	198199125	24.1944	8.5606	2.76770	1.70368	1836.5	268783
586	343400	199108432	24.2156	8.5711	2.76848	1.70041	1839.6	269703
587	344579	200017741	24.2368	8.5816	2.76926	1.69714	1842.7	270624
588	345760	200927052	24.2580	8.5921	2.77004	1.69387	1845.8	271547
589	346941	201836365	24.2792	8.6026	2.77082	1.69060	1848.9	272471
590	348124	202745680	24.3004	8.6131	2.77160	1.68733	1852.0	273397
591	349309	203655000	24.3216	8.6236	2.77238	1.68406	1855.1	274325
592	350496	204564321	24.3428	8.6341	2.77316	1.68079	1858.2	275254
593	351684	205473644	24.3640	8.6446	2.77394	1.67752	1861.3	276184
594	352873	206382969	24.3852	8.6551	2.77472	1.67425	1864.4	277117
595	354064	207292296	24.4064	8.6656	2.77550	1.67098	1867.5	278051
596	355256	208201625	24.4276	8.6761	2.77628	1.66771	1870.6	278986
597	356449	209110956	24.4488	8.6866	2.77706	1.66444	1873.7	279923
598	357644	210020289	24.4700	8.6971	2.77784	1.66117	1876.8	280862
599	358841	210929624	24.4912	8.7076	2.77862	1.65790	1879.9	281802

FUNCTIONS OF NUMBERS

500
549

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
500	250000	125000000	22.3607	7.9370	2.68897	2.00000	1653.50	196350
501	251001	125915101	22.3820	7.9473	2.68975	1.99923	1657.8	197136
502	252004	126830204	22.4032	7.9576	2.69053	1.99846	1662.1	197923
503	253009	127745309	22.4245	7.9679	2.69131	1.99769	1666.4	198710
504	254016	128660416	22.4457	7.9782	2.69209	1.99692	1670.7	199497
505	255025	129575525	22.4670	7.9885	2.69287	1.99615	1675.0	200284
506	256036	130490636	22.4882	7.9988	2.69365	1.99538	1679.3	201071
507	257049	131405749	22.5095	8.0091	2.69443	1.99461	1683.6	201858
508	258064	132320864	22.5307	8.0194	2.69521	1.99384	1687.9	202645
509	259081	133235981	22.5520	8.0297	2.69599	1.99307	1692.2	203432
510	260100	134151100	22.5732	8.0400	2.69677	1.99230	1696.5	204219
511	261121	135066221	22.5945	8.0503	2.69755	1.99153	1700.8	205006
512	262144	135981344	22.6157	8.0606	2.69833	1.99076	1705.1	205793
513	263169	136896469	22.6370	8.0709	2.69911	1.99000	1709.4	206580
514	264196	137811596	22.6582	8.0812	2.69989	1.98923	1713.7	207367
515	265225	138726725	22.6795	8.0915	2.70067	1.98846	1718.0	208154
516	266256	139641856	22.7007	8.1018	2.70145	1.98769	1722.3	208941
517	267289	140556989	22.7220	8.1121	2.70223	1.98692	1726.6	209728
518	268324	141472124	22.7432	8.1224	2.70301	1.98615	1730.9	210515
519	269361	142387261	22.7645	8.1327	2.70379	1.98538	1735.2	211302
520	270400	143302390	22.7857	8.1430	2.70457	1.98461	1739.5	212089
521	271441	144217521	22.8070	8.1533	2.70535	1.98384	1743.8	212876
522	272484	145132652	22.8282	8.1636	2.70613	1.98307	1748.1	213663
523	273529	146047785	22.8495	8.1739	2.70691	1.98230	1752.4	214450
524	274576	146962920	22.8707	8.1842	2.70769	1.98153	1756.7	215237
525	275625	147878055	22.8920	8.1945	2.70847	1.98076	1761.0	216024
526	276676	148793192	22.9132	8.2048	2.70925	1.98000	1765.3	216811
527	277729	149708331	22.9345	8.2151	2.71003	1.97923	1769.6	217598
528	278784	150623472	22.9557	8.2254	2.71081	1.97846	1773.9	218385
529	279841	151538615	22.9770	8.2357	2.71159	1.97769	1778.2	219172
530	280900	152453760	23.0000	8.2460	2.71237	1.97692	1782.5	220000
531	281961	153368907	23.0212	8.2563	2.71315	1.97615	1786.8	220833
532	283024	154284056	23.0425	8.2666	2.71393	1.97538	1791.1	221666
533	284089	155199207	23.0637	8.2769	2.71471	1.97461	1795.4	222500
534	285156	156114360	23.0850	8.2872	2.71549	1.97384	1799.7	223333
535	286225	157029515	23.1062	8.2975	2.71627	1.97307	1804.0	224166
536	287296	157944672	23.1275	8.3078	2.71705	1.97230	1808.3	225000
537	288369	158859831	23.1487	8.3181	2.71783	1.97153	1812.6	225833
538	289444	159774992	23.1699	8.3284	2.71861	1.97076	1816.9	226666
539	290521	160690155	23.1912	8.3387	2.71939	1.97000	1821.2	227500
540	291600	161605320	23.2125	8.3490	2.72017	1.96923	1825.5	228333
541	292681	162520487	23.2337	8.3593	2.72095	1.96846	1829.8	229166
542	293764	163435656	23.2550	8.3696	2.72173	1.96769	1834.1	230000
543	294849	164350827	23.2762	8.3799	2.72251	1.96692	1838.4	230833
544	295936	165265992	23.2975	8.3902	2.72329	1.96615	1842.7	231666
545	297025	166181165	23.3187	8.4005	2.72407	1.96538	1847.0	232500
546	298116	167096340	23.3400	8.4108	2.72485	1.96461	1851.3	233333
547	299209	168011517	23.3612	8.4211	2.72563	1.96384	1855.6	234166
548	300304	168926696	23.3825	8.4314	2.72641	1.96307	1859.9	235000
549	301401	169841877	23.4037	8.4417	2.72719	1.96230	1864.2	235833

FUNCTIONS OF NUMBERS

650
699

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
650	422500	274625000	25.4951	8.6624	2.81291	1.53846	2042.0	331831
651	423801	275894401	25.5147	8.6668	2.81358	1.53810	2045.2	332853
652	425104	277176808	25.5343	8.6713	2.81425	1.53773	2048.5	333875
653	426409	278463264	25.5539	8.6758	2.81492	1.53736	2051.8	334897
654	427716	279753664	25.5734	8.6801	2.81558	1.53699	2055.1	335920
655	429025	281047000	25.5930	8.6845	2.81625	1.53662	2058.4	336942
656	430336	282343281	25.6125	8.6889	2.81691	1.53625	2061.7	337965
657	431649	283642512	25.6320	8.6933	2.81758	1.53588	2065.0	338987
658	432964	284944688	25.6515	8.6977	2.81825	1.53551	2068.3	340010
659	434281	286249800	25.6710	8.7022	2.81891	1.53514	2071.6	341032
660	435600	287557856	25.6905	8.7066	2.81958	1.53477	2074.9	342055
661	436921	288868861	25.7100	8.7110	2.82025	1.53440	2078.2	343077
662	438244	290182816	25.7295	8.7154	2.82092	1.53403	2081.5	344100
663	439569	291499721	25.7488	8.7198	2.82159	1.53366	2084.8	345122
664	440896	292819576	25.7682	8.7241	2.82227	1.53329	2088.1	346145
665	442225	294142381	25.7876	8.7285	2.82294	1.53292	2091.4	347167
666	443556	295468136	25.8069	8.7328	2.82362	1.53255	2094.7	348190
667	444889	296796841	25.8263	8.7371	2.82430	1.53218	2098.0	349212
668	446224	298128496	25.8457	8.7415	2.82497	1.53181	2101.3	350235
669	447561	299463100	25.8650	8.7458	2.82565	1.53144	2104.6	351257
670	448900	300800656	25.8844	8.7502	2.82632	1.53107	2107.9	352280
671	450241	302141161	25.9037	8.7545	2.82700	1.53070	2111.2	353302
672	451584	303484716	25.9230	8.7589	2.82767	1.53033	2114.5	354325
673	452929	304832221	25.9422	8.7633	2.82835	1.52996	2117.8	355347
674	454276	306183776	25.9615	8.7677	2.82902	1.52959	2121.1	356370
675	455625	307539281	25.9808	8.7721	2.82970	1.52922	2124.4	357392
676	456976	308898736	25.9999	8.7764	2.83037	1.52885	2127.7	358415
677	458329	310262241	26.0192	8.7807	2.83105	1.52848	2131.0	359437
678	459684	311629796	26.0384	8.7850	2.83173	1.52811	2134.3	360460
679	461041	313001300	26.0576	8.7893	2.83241	1.52774	2137.6	361482
680	462400	314376856	26.0769	8.7937	2.83309	1.52737	2140.9	362505
681	463761	315756361	26.0960	8.7980	2.83377	1.52700	2144.2	363527
682	465124	317139916	26.1151	8.8023	2.83445	1.52663	2147.5	364550
683	466489	318527421	26.1343	8.8066	2.83513	1.52626	2150.8	365572
684	467856	319919976	26.1534	8.8109	2.83581	1.52589	2154.1	366595
685	469225	321317481	26.1725	8.8152	2.83649	1.52552	2157.4	367617
686	470596	322719936	26.1916	8.8194	2.83717	1.52515	2160.7	368640
687	471969	324127441	26.2107	8.8237	2.83785	1.52478	2164.0	369662
688	473344	325539996	26.2298	8.8279	2.83853	1.52441	2167.3	370685
689	474721	326957500	26.2488	8.8323	2.83921	1.52404	2170.6	371707
690	476100	328380056	26.2679	8.8366	2.83989	1.52367	2173.9	372730
691	477481	329807561	26.2869	8.8408	2.84057	1.52330	2177.2	373752
692	478864	331240016	26.3059	8.8451	2.84125	1.52293	2180.5	374775
693	480249	332677471	26.3249	8.8493	2.84193	1.52256	2183.8	375797
694	481636	334119926	26.3439	8.8536	2.84261	1.52219	2187.1	376820
695	483025	335567381	26.3629	8.8578	2.84329	1.52182	2190.4	377842
696	484416	337018836	26.3818	8.8621	2.84397	1.52145	2193.7	378865
697	485809	338475291	26.4008	8.8663	2.84465	1.52108	2197.0	379887
698	487204	339926746	26.4197	8.8706	2.84533	1.52071	2200.3	380910
699	488601	341383200	26.4386	8.8748	2.84601	1.52034	2203.6	381932

FUNCTIONS OF NUMBERS

600
649

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
600	360000	216000000	60.0000	8.4333	2.77815	1.66667	1885.0	282743
601	361201	217081801	60.1000	8.4330	2.77887	1.66639	1888.1	283687
602	362404	218167208	60.2000	8.4327	2.77960	1.66611	1891.2	284631
603	363609	219256227	60.3000	8.4464	2.78032	1.66583	1894.3	285575
604	364816	220349864	60.4000	8.4530	2.78104	1.66555	1897.5	286520
605	366025	221448125	60.5000	8.4577	2.78176	1.66527	1900.7	287464
606	367236	222551001	60.6000	8.4623	2.78248	1.66500	1903.8	288409
607	368449	223658481	60.7000	8.4670	2.78319	1.66472	1907.0	289353
608	369664	224770576	60.8000	8.4717	2.78391	1.66444	1910.1	290298
609	370881	225887281	60.9000	8.4763	2.78462	1.66416	1913.2	291242
610	372100	226998500	61.0000	8.4809	2.78534	1.66388	1916.4	292187
611	373321	228114221	61.1000	8.4856	2.78605	1.66360	1919.5	293131
612	374544	229234444	61.2000	8.4902	2.78677	1.66332	1922.7	294075
613	375769	230359169	61.3000	8.4948	2.78748	1.66304	1925.8	295019
614	376996	231488396	61.4000	8.4994	2.78819	1.66276	1929.0	295963
615	378225	232622125	61.5000	8.5040	2.78890	1.66248	1932.1	296907
616	379456	233760456	61.6000	8.5086	2.78961	1.66220	1935.3	297851
617	380689	234903289	61.7000	8.5132	2.79032	1.66192	1938.4	298795
618	381924	236050624	61.8000	8.5178	2.79103	1.66164	1941.6	299739
619	383161	237202461	61.9000	8.5224	2.79174	1.66136	1944.7	300683
620	384400	238358800	62.0000	8.5270	2.79245	1.66108	1947.8	301627
621	385641	239520641	62.1000	8.5316	2.79316	1.66080	1951.0	302571
622	386884	240686984	62.2000	8.5361	2.79387	1.66052	1954.1	303515
623	388129	241857829	62.3000	8.5408	2.79458	1.66024	1957.2	304459
624	389376	243033176	62.4000	8.5453	2.79529	1.66000	1960.4	305403
625	390625	244213025	62.5000	8.5499	2.79600	1.65972	1963.5	306347
626	391876	245407376	62.6000	8.5544	2.79671	1.65944	1966.7	307291
627	393129	246606229	62.7000	8.5590	2.79742	1.65916	1969.8	308235
628	394384	247810584	62.8000	8.5635	2.79813	1.65888	1973.0	309179
629	395641	249020441	62.9000	8.5681	2.79884	1.65860	1976.1	310123
630	396900	250235800	63.0000	8.5726	2.79955	1.65832	1979.2	311067
631	398161	251456661	63.1000	8.5772	2.80026	1.65804	1982.4	312011
632	399424	252683024	63.2000	8.5817	2.80097	1.65776	1985.5	312955
633	400696	253914889	63.3000	8.5863	2.80168	1.65748	1988.7	313899
634	401969	255152256	63.4000	8.5908	2.80239	1.65720	1991.8	314843
635	403244	256395125	63.5000	8.5954	2.80310	1.65692	1995.0	315787
636	404521	257643496	63.6000	8.5999	2.80381	1.65664	1998.1	316731
637	405800	258897369	63.7000	8.6045	2.80452	1.65636	2001.3	317675
638	407081	260156744	63.8000	8.6090	2.80523	1.65608	2004.4	318619
639	408364	261421621	63.9000	8.6136	2.80594	1.65580	2007.6	319563
640	409650	262692000	64.0000	8.6182	2.80665	1.65552	2010.7	320507
641	410941	263967881	64.1000	8.6228	2.80736	1.65524	2013.9	321451
642	412164	265249264	64.2000	8.6273	2.80807	1.65496	2017.0	322395
643	413439	266536149	64.3000	8.6318	2.80878	1.65468	2020.2	323339
644	414716	267828536	64.4000	8.6363	2.80949	1.65440	2023.3	324283
645	416025	269126425	64.5000	8.6409	2.81020	1.65412	2026.5	325227
646	417336	270430816	64.6000	8.6454	2.81091	1.65384	2029.6	326171
647	418649	271741719	64.7000	8.6499	2.81162	1.65356	2032.8	327115
648	419964	273059124	64.8000	8.6545	2.81233	1.65328	2035.9	328059
649	421281	274383031	64.9000	8.6590	2.81304	1.65300	2039.1	329003

FUNCTIONS OF NUMBERS

750

799

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
750	562500	421875000	27.3861	9.0856	2.87506	1.33333	2356.2	441786
751	564001	423564751	27.4044	9.0896	2.87561	1.33156	2359.3	442965
752	565504	425254508	27.4226	9.0937	2.87616	1.32979	2362.5	444146
753	567009	426957777	27.4408	9.0977	2.87670	1.32802	2365.8	445328
754	568516	428665164	27.4591	9.1017	2.87724	1.32626	2369.0	446511
755	570025	430388875	27.4773	9.1057	2.87778	1.32450	2371.9	447697
756	571536	432128016	27.4955	9.1098	2.87832	1.32275	2375.0	448883
757	573049	433882609	27.5138	9.1138	2.87886	1.32100	2378.2	450072
758	574564	435652664	27.5318	9.1178	2.87940	1.31926	2381.5	451264
759	576081	437438199	27.5501	9.1218	2.88000	1.31752	2384.8	452459
760	577600	439239225	27.5681	9.1258	2.88061	1.31579	2387.6	453646
761	579121	441055751	27.5862	9.1298	2.88122	1.31406	2390.8	454834
762	580644	442887778	27.6043	9.1338	2.88183	1.31234	2393.9	456023
763	582169	444735305	27.6225	9.1378	2.88244	1.31062	2397.0	457214
764	583696	446598332	27.6405	9.1418	2.88305	1.30890	2400.2	458406
765	585225	448476859	27.6586	9.1458	2.88366	1.30719	2403.3	459599
766	586756	450370886	27.6767	9.1498	2.88427	1.30548	2406.5	460793
767	588289	452280413	27.6948	9.1537	2.88488	1.30378	2409.6	461988
768	589824	454205440	27.7128	9.1577	2.88549	1.30207	2412.7	463184
769	591361	456145967	27.7309	9.1617	2.88610	1.30036	2415.9	464381
770	592900	458102000	27.7489	9.1657	2.88671	1.29866	2419.0	465579
771	594441	460073527	27.7669	9.1696	2.88732	1.29700	2422.2	466778
772	595984	462060554	27.7849	9.1736	2.88793	1.29534	2425.3	467978
773	597529	464063081	27.8029	9.1775	2.88854	1.29368	2428.5	469179
774	599076	466081108	27.8209	9.1815	2.88915	1.29202	2431.6	470381
775	600625	468114635	27.8388	9.1855	2.88976	1.29036	2434.7	471584
776	602176	470163662	27.8567	9.1895	2.89037	1.28870	2437.9	472788
777	603729	472228189	27.8747	9.1935	2.89098	1.28704	2441.0	473993
778	605284	474308216	27.8927	9.1975	2.89159	1.28538	2444.2	475199
779	606841	476403743	27.9107	9.2015	2.89220	1.28372	2447.3	476406
780	608400	478514770	27.9285	9.2055	2.89281	1.28206	2450.4	477614
781	609961	480641297	27.9464	9.2095	2.89342	1.28040	2453.5	478823
782	611524	482783324	27.9643	9.2135	2.89403	1.27874	2456.7	480033
783	613090	484940851	27.9822	9.2175	2.89464	1.27708	2459.8	481244
784	614658	487113878	28.0001	9.2215	2.89525	1.27542	2463.0	482456
785	616225	489302405	28.0179	9.2255	2.89586	1.27376	2466.2	483669
786	617796	491506432	28.0357	9.2295	2.89647	1.27210	2469.3	484883
787	619369	493726459	28.0535	9.2335	2.89708	1.27044	2472.5	486098
788	620944	495962486	28.0713	9.2375	2.89769	1.26878	2475.7	487314
789	622521	498213513	28.0891	9.2415	2.89830	1.26712	2478.9	488531
790	624100	499480540	28.1069	9.2455	2.89891	1.26546	2482.0	489749
791	625681	501763567	28.1247	9.2495	2.89952	1.26380	2485.2	490968
792	627264	504062594	28.1425	9.2535	2.89999	1.26214	2488.3	492189
793	628849	506377621	28.1603	9.2575	2.90050	1.26048	2491.5	493411
794	630436	508708648	28.1780	9.2615	2.90101	1.25882	2494.6	494634
795	632025	511055675	28.1957	9.2655	2.90152	1.25716	2497.9	495858
796	633616	513418702	28.2135	9.2695	2.90203	1.25550	2501.0	497083
797	635209	515797729	28.2312	9.2735	2.90254	1.25384	2504.2	498309
798	636804	518192756	28.2489	9.2775	2.90305	1.25218	2507.3	499536
799	638401	520603783	28.2666	9.2815	2.90356	1.25052	2510.5	500764

FUNCTIONS OF NUMBERS

700

749

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
700	490000	343000000	26.4575	8.9790	2.84510	1.49887	2199.1	384845
701	492001	345920001	26.4757	8.9830	2.84571	1.49712	2202.3	386034
702	494004	348840008	26.4939	8.9870	2.84632	1.49538	2205.5	387224
703	496009	351760007	26.5121	8.9910	2.84693	1.49364	2208.7	388415
704	498016	354680008	26.5303	8.9950	2.84754	1.49190	2211.9	389606
705	499995	357600009	26.5485	8.9990	2.84815	1.49016	2215.1	390798
706	501976	360520012	26.5667	9.0030	2.84876	1.48842	2218.3	391991
707	503959	363440017	26.5849	9.0070	2.84937	1.48668	2221.5	393184
708	505944	366360024	26.6031	9.0110	2.84998	1.48494	2224.7	394378
709	507931	369280033	26.6213	9.0150	2.85059	1.48320	2227.9	395573
710	509920	372200044	26.6395	9.0190	2.85120	1.48146	2231.1	396768
711	511911	375120057	26.6577	9.0230	2.85181	1.47972	2234.3	397964
712	513904	378040072	26.6759	9.0270	2.85242	1.47798	2237.5	399161
713	515900	380960089	26.6941	9.0310	2.85303	1.47624	2240.7	400359
714	517899	383880108	26.7123	9.0350	2.85364	1.47450	2243.9	401558
715	519900	386800129	26.7305	9.0390	2.85425	1.47276	2247.1	402758
716	521903	389720152	26.7487	9.0430	2.85486	1.47102	2250.3	403959
717	523908	392640177	26.7669	9.0470	2.85547	1.46928	2253.5	405161
718	525915	395560204	26.7851	9.0510	2.85608	1.46754	2256.7	406364
719	527924	398480233	26.8033	9.0550	2.85669	1.46580	2259.9	407568
720	529935	401400264	26.8215	9.0590	2.85730	1.46406	2263.1	408773
721	531948	404320297	26.8397	9.0630	2.85791	1.46232	2266.3	409979
722	533963	407240332	26.8579	9.0670	2.85852	1.46058	2269.5	411186
723	535980	410160369	26.8761	9.0710	2.85913	1.45884	2272.7	412394
724	537999	413080408	26.8943	9.0750	2.85974	1.45710	2275.9	413603
725	539995	416000449	26.9125	9.0790	2.86035	1.45536	2279.1	414813
726	541996	418920492	26.9307	9.0830	2.86096	1.45362	2282.3	416024
727	543999	421840537	26.9489	9.0870	2.86157	1.45188	2285.5	417236
728	545996	424760584	26.9671	9.0910	2.86218	1.45014	2288.7	418449
729	547999	427680633	26.9853	9.0950	2.86279	1.44840	2291.9	419663
730	549995	430600684	27.0035	9.0990	2.86340	1.44666	2295.1	420878
731	551996	433520737	27.0217	9.1030	2.86401	1.44492	2298.3	422094
732	553999	436440792	27.0399	9.1070	2.86462	1.44318	2301.5	423311
733	555996	439360849	27.0581	9.1110	2.86523	1.44144	2304.7	424529
734	557999	442280908	27.0763	9.1150	2.86584	1.43970	2307.9	425748
735	559995	445200969	27.0945	9.1190	2.86645	1.43796	2311.1	426968
736	561996	448121032	27.1127	9.1230	2.86706	1.43622	2314.3	428189
737	563999	451041097	27.1309	9.1270	2.86767	1.43448	2317.5	429411
738	565996	453961164	27.1491	9.1310	2.86828	1.43274	2320.7	430634
739	567999	456881233	27.1673	9.1350	2.86889	1.43100	2323.9	431858
740	569995	459801304	27.1855	9.1390	2.86950	1.42926	2327.1	433083
741	571996	462721377	27.2037	9.1430	2.87011	1.42752	2330.3	434309
742	573999	465641452	27.2219	9.1470	2.87072	1.42578	2333.5	435536
743	575996	468561529	27.2401	9.1510	2.87133	1.42404	2336.7	436764
744	577999	471481608	27.2583	9.1550	2.87194	1.42230	2339.9	437993
745	579995	474401689	27.2765	9.1590	2.87255	1.42056	2343.1	439224
746	581996	477321772	27.2947	9.1630	2.87316	1.41882	2346.3	440456
747	583999	480241857	27.3129	9.1670	2.87377	1.41708	2349.5	441689
748	585996	483161944	27.3311	9.1710	2.87438	1.41534	2352.7	442923
749	587999	486082033	27.3493	9.1750	2.87499	1.41360	2355.9	444158
750	589995	489002124	27.3675	9.1790	2.87560	1.41186	2359.1	445394

FUNCTIONS OF NUMBERS

850

899

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 Reciprocal	No. = Diameter	
							Circum.	Area
850	723500	614125000	26.1548	9.4727	2.82942	1.7647	2670.4	567450
851	723200	613920000	26.1719	9.4764	2.82982	1.7650	2673.5	568788
852	722900	613715000	26.1890	9.4801	2.83022	1.7653	2676.6	570124
853	722600	613510000	26.2062	9.4838	2.83062	1.7656	2679.7	571463
854	722316	613305664	26.2233	9.4875	2.83102	1.7659	2682.8	572803
855	722032	613101328	26.2404	9.4912	2.83142	1.7662	2685.9	574146
856	721748	612896992	26.2575	9.4949	2.83182	1.7665	2689.0	575490
857	721464	612692656	26.2746	9.4986	2.83222	1.7668	2692.1	576835
858	721180	612488320	26.2916	9.5023	2.83262	1.7671	2695.2	578182
859	720896	612283984	26.3087	9.5060	2.83302	1.7674	2698.3	579530
860	720612	612079648	26.3258	9.5097	2.83342	1.7677	2701.4	580880
861	720328	611875312	26.3428	9.5134	2.83382	1.7680	2704.5	582232
862	720044	611670976	26.3599	9.5171	2.83422	1.7683	2707.6	583585
863	719760	611466640	26.3769	9.5207	2.83462	1.7686	2710.7	584940
864	719476	611262304	26.3939	9.5244	2.83502	1.7689	2713.8	586297
865	719192	611057968	26.4109	9.5281	2.83542	1.7692	2716.9	587655
866	718908	610853632	26.4279	9.5318	2.83582	1.7695	2720.0	589014
867	718624	610649296	26.4449	9.5354	2.83622	1.7698	2723.1	590375
868	718340	610444960	26.4618	9.5391	2.83662	1.7701	2726.2	591738
869	718056	610240624	26.4788	9.5427	2.83702	1.7704	2729.3	593102
870	717772	610036288	26.4958	9.5464	2.83742	1.7707	2732.4	594468
871	717488	609831952	26.5127	9.5501	2.83782	1.7710	2735.5	595835
872	717204	609627616	26.5296	9.5537	2.83822	1.7713	2738.6	597204
873	716920	609423280	26.5466	9.5574	2.83862	1.7716	2741.7	598575
874	716636	609218944	26.5635	9.5610	2.83902	1.7719	2744.8	599947
875	716352	609014608	26.5804	9.5647	2.83942	1.7722	2747.9	601320
876	716068	608810272	26.5973	9.5683	2.83982	1.7725	2751.0	602696
877	715784	608605936	26.6142	9.5719	2.84022	1.7728	2754.1	604073
878	715500	608401600	26.6311	9.5756	2.84062	1.7731	2757.2	605451
879	715216	608197264	26.6479	9.5792	2.84102	1.7734	2760.3	606831
880	714932	607992928	26.6648	9.5828	2.84142	1.7737	2763.4	608212
881	714648	607788592	26.6816	9.5865	2.84182	1.7740	2766.5	609595
882	714364	607584256	26.6985	9.5901	2.84222	1.7743	2769.6	610980
883	714080	607379920	26.7153	9.5937	2.84262	1.7746	2772.7	612366
884	713796	607175584	26.7321	9.5973	2.84302	1.7749	2775.8	613754
885	713512	606971248	26.7489	9.6010	2.84342	1.7752	2778.9	615143
886	713228	606766912	26.7658	9.6046	2.84382	1.7755	2782.0	616534
887	712944	606562576	26.7826	9.6082	2.84422	1.7758	2785.1	617927
888	712660	606358240	26.7994	9.6118	2.84462	1.7761	2788.2	619321
889	712376	606153904	26.8161	9.6154	2.84502	1.7764	2791.3	620717
890	712092	605949568	26.8329	9.6190	2.84542	1.7767	2794.4	622114
891	711808	605745232	26.8496	9.6226	2.84582	1.7770	2797.5	623511
892	711524	605540896	26.8664	9.6262	2.84622	1.7773	2800.6	624913
893	711240	605336560	26.8831	9.6298	2.84662	1.7776	2803.7	626315
894	710956	605132224	26.8998	9.6334	2.84702	1.7779	2806.8	627718
895	710672	604927888	26.9165	9.6370	2.84742	1.7782	2809.9	629124
896	710388	604723552	26.9332	9.6406	2.84782	1.7785	2813.0	630530
897	710104	604519216	26.9499	9.6442	2.84822	1.7788	2816.1	631938
898	709820	604314880	26.9666	9.6477	2.84862	1.7791	2819.2	633348
899	709536	604110544	26.9833	9.6513	2.84902	1.7794	2822.3	634760

FUNCTIONS OF NUMBERS

800

849

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
800	640000	512000000	28.2843	9.2832	2.90300	1.25000	2513.3	502655
801	641601	513922401	28.3019	9.2870	2.90363	1.24844	2516.4	503912
802	643204	515849608	28.3196	9.2909	2.90427	1.24688	2519.5	505171
803	644809	517781627	28.3373	9.2948	2.90491	1.24532	2522.6	506432
804	646416	519718664	28.3549	9.2986	2.90555	1.24376	2525.8	507694
805	648025	521660125	28.3725	9.3025	2.90618	1.24220	2528.9	508958
806	649636	523606616	28.3901	9.3063	2.90682	1.24064	2532.1	510223
807	651249	525559943	28.4077	9.3102	2.90745	1.23908	2535.2	511490
808	652864	527520112	28.4252	9.3140	2.90808	1.23752	2538.4	512758
809	654481	529486125	28.4427	9.3178	2.90871	1.23596	2541.5	514028
810	656100	531458000	28.4601	9.3217	2.90934	1.23440	2544.7	515300
811	657721	533435731	28.4776	9.3255	2.90997	1.23284	2547.8	516573
812	659344	535419424	28.4950	9.3293	2.91060	1.23128	2551.0	517848
813	660969	537409089	28.5124	9.3331	2.91123	1.22972	2554.1	519124
814	662596	539404716	28.5298	9.3369	2.91186	1.22816	2557.3	520402
815	664225	541406305	28.5472	9.3407	2.91249	1.22660	2560.4	521681
816	665856	543413856	28.5645	9.3445	2.91312	1.22504	2563.6	522962
817	667489	545427369	28.5818	9.3483	2.91375	1.22348	2566.7	524244
818	669124	547446944	28.6000	9.3521	2.91438	1.22192	2569.9	525528
819	670761	549472581	28.6182	9.3559	2.91501	1.22036	2573.0	526814
820	672400	551505200	28.6364	9.3597	2.91564	1.21880	2576.1	528102
821	674041	553543861	28.6537	9.3635	2.91627	1.21724	2579.2	529392
822	675684	555588564	28.6710	9.3673	2.91690	1.21568	2582.3	530684
823	677329	557639319	28.6882	9.3711	2.91753	1.21412	2585.5	531977
824	678976	559696126	28.7054	9.3749	2.91816	1.21256	2588.6	533272
825	680625	561759000	28.7228	9.3787	2.91879	1.21100	2591.8	534568
826	682276	563827956	28.7402	9.3825	2.91942	1.20944	2595.0	535866
827	683929	565902996	28.7576	9.3863	2.92005	1.20788	2598.1	537166
828	685584	567984120	28.7750	9.3901	2.92068	1.20632	2601.3	538466
829	687241	569972268	28.7924	9.3939	2.92131	1.20476	2604.4	539768
830	688900	571967500	28.8097	9.3977	2.92194	1.20320	2607.5	541061
831	690561	573968821	28.8271	9.4015	2.92257	1.20164	2610.7	542356
832	692224	575976240	28.8445	9.4053	2.92320	1.20008	2613.8	543652
833	693889	577989769	28.8618	9.4091	2.92383	1.19852	2617.0	544949
834	695556	580009400	28.8791	9.4129	2.92446	1.19696	2620.1	546248
835	697225	582035125	28.8964	9.4166	2.92509	1.19540	2623.2	547549
836	698896	584066856	28.9137	9.4204	2.92572	1.19384	2626.4	548851
837	700569	586104593	28.9310	9.4242	2.92635	1.19228	2629.5	550154
838	702244	588148336	28.9483	9.4279	2.92698	1.19072	2632.7	551458
839	703921	590198085	28.9655	9.4316	2.92761	1.18916	2635.8	552763
840	705600	592253840	28.9828	9.4354	2.92824	1.18760	2639.0	554068
841	707281	594315601	28.9999	9.4391	2.92887	1.18604	2642.1	555374
842	708964	596383368	29.0171	9.4429	2.92950	1.18448	2645.3	556681
843	710649	598457141	29.0342	9.4466	2.93013	1.18292	2648.4	557988
844	712336	599971100	29.0517	9.4503	2.93076	1.18136	2651.6	559296
845	714025	602035125	29.0689	9.4541	2.93139	1.17980	2654.7	560604
846	715716	604105216	29.0861	9.4578	2.93202	1.17824	2657.9	561913
847	717409	606181273	29.1032	9.4615	2.93265	1.17668	2661.0	563223
848	719104	608263396	29.1204	9.4652	2.93328	1.17512	2664.2	564534
849	720801	610351475	29.1376	9.4689	2.93391	1.17356	2667.3	565846

FUNCTIONS OF NUMBERS

950
999


No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
950	902500	857375000	30.8221	9.8305	2.9772	1.05263	2984.5	708922
951	904901	86138331	30.8343	9.8312	2.9775	1.05268	2985.2	709132
952	907304	86540690	30.8465	9.8319	2.9778	1.05273	2985.9	709342
953	909709	86943617	30.8587	9.8326	2.9781	1.05278	2986.6	709552
954	912116	87347112	30.8709	9.8333	2.9784	1.05283	2987.3	709762
955	914525	87751185	30.8831	9.8340	2.9787	1.05288	2988.0	710000
956	916936	88155836	30.8953	9.8347	2.9790	1.05293	2988.7	710238
957	919349	88561065	30.9075	9.8354	2.9793	1.05298	2989.4	710476
958	921764	88966872	30.9197	9.8361	2.9796	1.05303	2990.1	710714
959	924181	89373257	30.9319	9.8368	2.9799	1.05308	2990.8	710952
960	926600	89780220	30.9441	9.8375	2.9802	1.05313	2991.5	711190
961	929021	90187761	30.9563	9.8382	2.9805	1.05318	2992.2	711428
962	931444	90595880	30.9685	9.8389	2.9808	1.05323	2992.9	711666
963	933869	91004587	30.9807	9.8396	2.9811	1.05328	2993.6	711904
964	936296	91413882	30.9929	9.8403	2.9814	1.05333	2994.3	712142
965	938725	91823765	31.0051	9.8410	2.9817	1.05338	2995.0	712380
966	941156	92234236	31.0173	9.8417	2.9820	1.05343	2995.7	712618
967	943589	92645295	31.0295	9.8424	2.9823	1.05348	2996.4	712856
968	946024	93056942	31.0417	9.8431	2.9826	1.05353	2997.1	713094
969	948461	93469177	31.0539	9.8438	2.9829	1.05358	2997.8	713332
970	950900	93881900	31.0661	9.8445	2.9832	1.05363	2998.5	713570
971	953341	94295211	31.0783	9.8452	2.9835	1.05368	2999.2	713808
972	955784	94709010	31.0905	9.8459	2.9838	1.05373	3000.0	714046
973	958229	95123297	31.1027	9.8466	2.9841	1.05378	3000.7	714284
974	960676	95538172	31.1149	9.8473	2.9844	1.05383	3001.4	714522
975	963125	95953635	31.1271	9.8480	2.9847	1.05388	3002.1	714760
976	965576	96369686	31.1393	9.8487	2.9850	1.05393	3002.8	715000
977	968029	96786325	31.1515	9.8494	2.9853	1.05398	3003.5	715238
978	970484	97203562	31.1637	9.8501	2.9856	1.05403	3004.2	715476
979	972941	97620797	31.1759	9.8508	2.9859	1.05408	3004.9	715714
980	975399	98038130	31.1881	9.8515	2.9862	1.05413	3005.6	715952
981	977859	98455561	31.2003	9.8522	2.9865	1.05418	3006.3	716190
982	980320	98873090	31.2125	9.8529	2.9868	1.05423	3007.0	716428
983	982783	99290717	31.2247	9.8536	2.9871	1.05428	3007.7	716666
984	985248	99708442	31.2369	9.8543	2.9874	1.05433	3008.4	716904
985	987715	10018165	31.2491	9.8550	2.9877	1.05438	3009.1	717142
986	990184	10068882	31.2613	9.8557	2.9880	1.05443	3009.8	717380
987	992654	10119605	31.2735	9.8564	2.9883	1.05448	3010.5	717618
988	995126	10170328	31.2857	9.8571	2.9886	1.05453	3011.2	717856
989	997600	10221051	31.2979	9.8578	2.9889	1.05458	3011.9	718094
990	1000000	10271774	31.3101	9.8585	2.9892	1.05463	3012.6	718332
991	1002500	10322500	31.3223	9.8592	2.9895	1.05468	3013.3	718570
992	1005001	10373227	31.3345	9.8599	2.9898	1.05473	3014.0	718808
993	1007504	10423954	31.3467	9.8606	2.9901	1.05478	3014.7	719046
994	1010009	10474681	31.3589	9.8613	2.9904	1.05483	3015.4	719284
995	1012516	10525408	31.3711	9.8620	2.9907	1.05488	3016.1	719522
996	1015025	10576135	31.3833	9.8627	2.9910	1.05493	3016.8	719760
997	1017536	10626862	31.3955	9.8634	2.9913	1.05498	3017.5	720000
998	1020049	10677589	31.4077	9.8641	2.9916	1.05503	3018.2	720238
999	1022564	10728316	31.4199	9.8648	2.9919	1.05508	3018.9	720476

FUNCTIONS OF NUMBERS

900
949

No.	Square	Cube	Square Root	Cube Root	Logarithm	1000 X Reciprocal	No. = Diameter	
							Circum.	Area
900	810000	729000000	30.0000	9.6549	2.9544	1.11111	2827.4	636173
901	811801	731432701	30.0167	9.6585	2.9547	1.10988	2830.6	637587
902	813604	733870808	30.0333	9.6620	2.9551	1.10865	2833.9	639003
903	815409	736314327	30.0500	9.6656	2.9555	1.10742	2837.2	640421
904	817216	738763264	30.0666	9.6692	2.9557	1.10619	2840.5	641840
905	819025	741217625	30.0832	9.6727	2.9560	1.10497	2843.8	643261
906	820836	743677416	30.0998	9.6763	2.9563	1.10375	2847.1	644683
907	822649	746142643	30.1164	9.6799	2.9567	1.10254	2850.4	646107
908	824464	748613312	30.1330	9.6835	2.9570	1.10132	2853.7	647533
909	826281	751089429	30.1496	9.6871	2.9573	1.10011	2857.0	648960
910	828100	753571000	30.1662	9.6905	2.9576	1.09890	2860.3	650388
911	829921	756058031	30.1828	9.6941	2.9580	1.09769	2863.6	651818
912	831744	758550528	30.1993	9.6976	2.9583	1.09648	2866.9	653250
913	833569	761048497	30.2159	9.7012	2.9587	1.09527	2870.2	654683
914	835396	763551944	30.2324	9.7047	2.9590	1.09406	2873.5	656118
915	837225	766060875	30.2490	9.7082	2.9594	1.09285	2876.8	657555
916	839056	768575296	30.2655	9.7118	2.9597	1.09164	2880.1	658993
917	840889	771095213	30.2820	9.7153	2.9601	1.09043	2883.4	660433
918	842724	773620632	30.2985	9.7188	2.9604	1.08922	2886.7	661875
919	844561	776151559	30.3150	9.7224	2.9608	1.08801	2890.0	663317
920	846400	778688000	30.3315	9.7259	2.9611	1.08680	2893.3	664761
921	848241	781229961	30.3480	9.7294	2.9615	1.08559	2896.6	666207
922	850084	783777448	30.3645	9.7329	2.9618	1.08438	2900.0	667654
923	851929	786330467	30.3809	9.7364	2.9622	1.08317	2903.3	669103
924	853776	788889024	30.3974	9.7399	2.9625	1.08196	2906.6	670554
925	855625	791453125	30.4138	9.7435	2.9628	1.08075	2910.0	672006
926	857476	794022776	30.4302	9.7470	2.9632	1.07954	2913.3	673460
927	859329	796597983	30.4467	9.7505	2.9635	1.07833	2916.6	674916
928	861184	799178752	30.4631	9.7540	2.9639	1.07712	2920.0	676373
929	863041	801765089	30.4795	9.7575	2.9642	1.07591	2923.3	677831
930	864900	804357000	30.4959	9.7610	2.9646	1.07470	2926.6	679291
931	866761	806954491	30.5123	9.7645	2.9649	1.07349	2930.0	680752
932	868624	809557056	30.5287	9.7680	2.9653	1.07228	2933.3	682214
933	870489	812164689	30.5450	9.7715	2.9656	1.07107	2936.6	683680
934	872356	814780504	30.5614	9.7750	2.9659	1.06986	2940.0	685147
935	874225	817400375	30.5778	9.7785	2.9663	1.06865	2943.3	686616
936	876096	820026956	30.5942	9.7820	2.9666	1.06744	2946.6	688087
937	877969	822659665	30.6106	9.7855	2.9669	1.06623	2950.0	689559
938	879844	825298496	30.6270	9.7890	2.9673	1.06502	2953.3	691033
939	881721	827943619	30.6434	9.7925	2.9676	1.06381	2956.6	692509
940	883600	830595400	30.6598	9.7960	2.9680	1.06260	2960.0	693986
941	885481	833253888	30.6762	9.8000	2.9683	1.06139	2963.3	695465
942	887364	835918976	30.6926	9.8040	2.9687	1.06018	2966.6	696946
943	889249	838586800	30.7090	9.8080	2.9690	1.05897	2970.0	698429
944	891136	841257384	30.7254	9.8120	2.9694	1.05776	2973.3	699914
945	893025	843930825	30.7418	9.8160	2.9697	1.05655	2976.6	701401
946	894916	846607236	30.7582	9.8200	2.9701	1.05534	2980.0	702889
947	896809	849287812	30.7746	9.8240	2.9704	1.05413	2983.3	704379
948	898704	851971392	30.7910	9.8280	2.9708	1.05292	2986.6	705870
949	900601	854670349	30.8074	9.8320	2.9711	1.05171	2990.0	707363

EXTENSION SPRINGS



- (1) Free length (over all) _____
Maximum _____ Minimum _____
- (2) Controlling diameter: (a) Outside diameter Max. _____
(b) Inside diameter Min. _____
(c) Hooks inside _____
(d) Hooks over _____
- (3) Wire size (if known) _____
- (4) Material (kind and grade) _____
- (5) Number of coils _____
- (6) Style ends (for illustrations see back page) _____
- (7) *Winding (left or right hand optional) _____
(see above for directional drawing of right hand winding)
- (8) Finish (as specified) _____
- (9) Load required at _____
(if wire size not specified) Length inside hooks _____
Length of coil _____
- (10) Maximum length _____
- (11) Deflection or distance of travel _____
- (12) Frequency of extension _____
- (13) Is relative position of ends important?
(making the ends of springs bear a definite relation to each other usually adds to the cost of manufacture).


*NOTE: Extension springs made from tempered or hard-drawn wires can be and usually are wound with initial tension. Such tension may average 20% of the total safe stress of the springs, but will not increase the elastic limit.

TYPES OF ENDS


used on

EXTENSION SPRINGS

These drawings show only a few of the various types of ends used on Extension Springs




ALL THE ABOVE ENDS ARE STANDARD TYPES FOR WHICH NO SPECIAL TOOLS ARE REQUIRED!



THIS GROUP OF SPECIAL ENDS REQUIRE SPECIAL TOOLS


COMPRESSION SPRINGS

MANUFACTURING VARIATIONS
for coil springs made of wire up to
and including 1-inch



- (1) Free length _____ Maximum _____ Minimum _____
- (2) Controlling diameter: (c) Outside diameter Max. _____
(b) Inside diameter Min. _____
(e) Pitch diameter _____
(d) Works inside hole _____
(e) Works over _____
- (3) Wire size (if known) _____
- (4) Material (kind and grade) _____
- (5) Load _____ at deflected position of _____
- (6) Style ends (see below) _____
- (7) Winding (left or right hand optional) _____
(see above for directional drawing of right hand winding)
- (8) Finish (as specified) _____
- (9) Maximum solid length _____
- (10) Frequency of compression _____

Additional information:



ALLOWABLE TOLERANCES
IN


COMPRESSION SPRING SPECIFICATIONS

Outside Diameter O.D.	Diameter of Coil	Variation
Less than 1/8"		.003
1/8 - 3/4		.005
3/4 - 1 1/2		.008
1 1/2 - 2		1/64
2 - 3		1/32
3 and Larger		1/16


SPLINE FITTINGS

FOUR-SPLINE FITTINGS

(S. A. E. Standard)




4A
 $W=0.241D$
 $h=0.075D$
 $d=0.850D$




4B
 $W=0.241D$
 $h=0.125D$
 $d=0.750D$

SIX-SPLINE FITTINGS


(S. A. E. Standard)



6A
 $W=0.250D$
 $h=0.050D$
 $d=0.900D$




6B
 $W=0.250D$
 $h=0.075D$
 $d=0.850D$




6C
 $W=0.250D$
 $h=0.100D$
 $d=0.800D$

TEN-SPLINE FITTINGS


(S. A. E. Standard)



10A
 $W=0.156D$
 $h=0.045D$
 $d=0.910D$



10B
 $W=0.156D$
 $h=0.070D$
 $d=0.860D$



10C
 $W=0.156D$
 $h=0.095D$
 $d=0.810D$

COMPOUND
 FOR WELDING
 CAST STEEL.

Mix 41 parts of boracic acid, 35 parts of pure, dried common salt, 20 parts of ferrocyanide of potassium, 8 parts rosin and 4 parts carbonate of sodium. When this compound is to be used, a sufficient quantity is scattered upon the article to be welded, which has been heated to a light red heat. It is then heated to a strong yellow heat and the welding accomplished in the usual manner.

Limits for Turning and Grinding—The limits given in the table below are recommended for use in the manufacture of machine parts, to produce satisfactory commercial work. These limits should only be followed under ordinary conditions. For special cases, it may be necessary to increase or decrease the limits given in the table. The allowance to be used when rough turning parts to be ground varies from 0.010 to 0.030 inch; that is, a part to be ground to a diameter of 1 inch would be rough turned in the lathe to a diameter of from 1.010 to 1.015 inch, while a 3-inch shaft may have an allowance of from 0.015 to 0.025 inch. The allowance depends largely on the class of work.

Allowances for Fits

Grinding Limits for Cylindrical Parts

(+ Designates larger than nominal size; — Smaller than nominal size.)

Diameter, Inches	Limits, Inches	Diameter, Inches	Limits, Inches
Running Fits—Ordinary Speed		Driving Fits—Ordinary	
Up to $\frac{1}{2}$	— 0.00025 to — 0.00075	Up to $\frac{1}{2}$	+ 0.00075 to + 0.0015
$\frac{1}{2}$ to 1	— 0.00075 to — 0.0015	$\frac{1}{2}$ to 1	+ 0.001 to + 0.002
1 to 2	— 0.0015 to — 0.0025	1 to 2	+ 0.002 to + 0.003
2 to $3\frac{1}{2}$	— 0.0025 to — 0.0035	2 to $3\frac{1}{2}$	+ 0.003 to + 0.004
$3\frac{1}{2}$ to 6	— 0.0035 to — 0.005	$3\frac{1}{2}$ to 6	+ 0.004 to + 0.005
Running Fits—High-Speed, Heavy Pressure and Rocker Shafts		Forced Fits	
Up to $\frac{1}{2}$	— 0.0005 to — 0.001	Up to $\frac{1}{2}$	+ 0.00025 to + 0.0005
$\frac{1}{2}$ to 1	— 0.001 to — 0.002	$\frac{1}{2}$ to 1	+ 0.0015 to + 0.0025
1 to 2	— 0.002 to — 0.003	1 to 2	+ 0.0025 to + 0.004
2 to $3\frac{1}{2}$	— 0.003 to — 0.0045	2 to $3\frac{1}{2}$	+ 0.004 to + 0.006
$3\frac{1}{2}$ to 6	— 0.0045 to — 0.0065	$3\frac{1}{2}$ to 6	+ 0.006 to + 0.009
Sliding Fits		Driving Fits—For such Pieces as are Required to be Readily Taken Apart	
Up to $\frac{1}{2}$	— 0.00025 to — 0.0005	Up to $\frac{1}{2}$	0 to + 0.00025
$\frac{1}{2}$ to 1	— 0.0005 to — 0.001	$\frac{1}{2}$ to 1	+ 0.00025 to + 0.0005
1 to 2	— 0.001 to — 0.002	1 to 2	+ 0.0005 to + 0.00075
2 to $3\frac{1}{2}$	— 0.002 to — 0.0035	2 to $3\frac{1}{2}$	+ 0.00075 to + 0.001
$3\frac{1}{2}$ to 6	— 0.003 to — 0.005	$3\frac{1}{2}$ to 6	+ 0.001 to + 0.0015

How to Anneal Tool Steel


Carbon tool steel may be annealed by heating slowly and evenly to a cherry red and then placing in a box of lime or ashes to cool slowly. The steel should be completely covered and when it is cooled to room temperature will be ready for machining.

How to Anneal Brass

Brass that has been hardened through cold working may be annealed by heating to a dull red when held in dark shadow and plunging into cold water. Care must be taken not to overheat the brass.

To Remove Dry Paint from Iron or Steel — Dip a swab with a handle in a strong solution of oxalic acid. It softens at once upon being moistened

PROPORTIONS OF SQUARE SHAFTS AND FIT ALLOWANCES



Nominal Diam.	Permanent Fit — =0.80 $\frac{B}{D}$							Sliding Fit — =0.73 $\frac{B}{D}$				
	A	B	C	D	E	F	G	A	B	C	D	E
$\frac{1}{4}$	0.193	0.189 0.188	0.187 0.186	0.250 0.245	0.260 0.252	$\frac{5}{16}$	$\frac{3}{8}$	0.257	0.248 0.247	0.250 0.249	0.344 0.339	0.354 0.346
$\frac{3}{8}$	0.290	0.283 0.282	0.281 0.280	0.375 0.370	0.385 0.377	$\frac{7}{16}$	$\frac{1}{2}$	0.386	0.373 0.372	0.375 0.374	0.516 0.511	0.526 0.518
$\frac{1}{2}$	0.386	0.377 0.376	0.375 0.374	0.500 0.495	0.510 0.502	$\frac{11}{16}$	$\frac{3}{4}$	$\frac{33}{64}$	0.498 0.497	0.500 0.499	0.687 0.682	0.697 0.689
$\frac{5}{8}$	$\frac{33}{64}$	0.502 0.501	0.500 0.499	0.625 0.620	0.635 0.627	$\frac{11}{16}$	$\frac{3}{4}$	$\frac{41}{64}$	0.623 0.622	0.625 0.624	0.844 0.839	0.854 0.846
$\frac{3}{4}$	$\frac{37}{64}$	0.564 0.563	0.562 0.561	0.750 0.745	0.760 0.752	$\frac{15}{16}$	1	$\frac{49}{64}$	0.748 0.747	0.750 0.749	1.031 1.026	1.051 1.036
$\frac{7}{8}$	$\frac{45}{64}$	0.689 0.688	0.687 0.686	0.875 0.870	0.885 0.877	$1\frac{1}{8}$	$1\frac{1}{4}$	$\frac{29}{32}$	0.873 0.872	0.875 0.874	1.187 1.182	1.207 1.192
1	$\frac{21}{32}$	0.815 0.814	0.812 0.811	1.000 0.995	1.020 1.005	$1\frac{1}{8}$	$1\frac{1}{2}$	$1\frac{1}{32}$	0.998 0.997	1.000 0.999	1.375 1.370	1.395 1.380
$1\frac{1}{8}$	$\frac{29}{32}$	0.878 0.877	0.875 0.874	1.125 1.120	1.145 1.130	$1\frac{1}{8}$	$1\frac{1}{4}$	$1\frac{5}{32}$	1.123 1.122	1.125 1.124	1.562 1.557	1.582 1.567
$1\frac{1}{4}$	$1\frac{1}{32}$	1.103 1.102	1.000 0.999	1.250 1.245	1.270 1.255	$1\frac{1}{8}$	$1\frac{1}{2}$	$1\frac{9}{32}$	1.248 1.247	1.250 1.249	1.687 1.682	1.707 1.692
$1\frac{3}{8}$	$1\frac{5}{32}$	1.128 1.127	1.125 1.124	1.375 1.370	1.395 1.380	$1\frac{1}{8}$	2	$1\frac{27}{64}$	1.373 1.372	1.375 1.374	1.875 1.870	1.895 1.880
$1\frac{1}{2}$	$1\frac{5}{16}$	1.128 1.127	1.125 1.124	1.500 1.495	1.520 1.505	$1\frac{1}{8}$	2	$1\frac{35}{64}$	1.498 1.497	1.500 1.499	2.062 2.057	2.082 2.067
$1\frac{3}{4}$	$1\frac{27}{64}$	1.378 1.377	1.375 1.374	1.750 1.745	1.770 1.755	$2\frac{1}{8}$	$2\frac{1}{4}$	$1\frac{15}{16}$	1.748 1.747	1.750 1.749	2.375 2.370	2.395 2.380
2	$1\frac{35}{64}$	1.504 1.503	1.500 1.498	2.000 1.995	2.020 2.005	$2\frac{1}{8}$	3	$2\frac{1}{16}$	1.997 1.996	2.000 1.998	2.750 2.745	2.770 2.755
$2\frac{1}{4}$	$1\frac{15}{16}$	1.754 1.753	1.750 1.748	2.250 2.245	2.270 2.255	$2\frac{1}{8}$	3	$2\frac{5}{16}$	2.247 2.246	2.250 2.248	3.062 3.057	3.082 3.067
$2\frac{1}{2}$	$2\frac{1}{16}$	2.004 2.003	2.000 1.998	2.500 2.495	2.520 2.505	$3\frac{1}{8}$	$3\frac{1}{2}$	$2\frac{37}{64}$	2.497 2.496	2.500 2.498	3.437 3.432	3.457 3.442
$2\frac{3}{4}$	$2\frac{5}{16}$	2.254 2.253	2.250 2.248	2.750 2.745	2.770 2.755	$3\frac{1}{8}$	$3\frac{1}{2}$	$2\frac{55}{64}$	2.747 2.746	2.750 2.748	3.750 3.745	3.770 3.755
3	$2\frac{27}{64}$	2.504 2.503	2.500 2.498	3.000 2.995	3.020 3.005	$3\frac{1}{8}$	4	$3\frac{3}{32}$	2.997 2.996	3.000 2.998	4.125 4.120	4.145 4.130
$3\frac{1}{2}$	$2\frac{55}{64}$	2.754 2.753	2.750 2.748	3.500 3.495	3.520 3.505	$4\frac{1}{8}$	$4\frac{1}{2}$	$3\frac{39}{64}$	3.497 3.496	3.500 3.498	4.750 4.745	4.770 4.755
4	$3\frac{25}{64}$	3.254 3.253	3.250 3.248	4.000 3.995	4.020 4.005	$5\frac{1}{8}$	$5\frac{1}{2}$	$4\frac{1}{8}$	3.997 3.996	4.000 3.998	5.500 5.495	5.520 5.505

TEMPERING OF TOOL STEEL

The following table gives the temperature in degrees Fahrenheit necessary to produce the required color, when tempering hardened steel:

Lathe, Shaper and Planer Tools:
430°—Very light straw color.
450°—Light straw color.

Taps, Dies, and Wood Turning Tools:
470°—Dark straw color.
490°—Very dark straw color.

Hatchets, Chisels, etc.:
500°—Brownish yellow.
520°—Yellow tinged with purple.
530°—Light purple.

Springs, etc.:
550°—Dark purple.
570°—Dark blue.

Proportional parts of lead to one pound of pure block tin, which when melted will have the temperature in degrees Fahrenheit necessary to produce the required color on hardened steel, by simple immersion:

COLOR	Temperature	Pounds of Lead to One of Tin
Very light straw color.....	430°	1¾ lbs. to 1 lb. Tin
Light straw color.....	450°	2¼ lbs. to 1 lb. Tin
Dark straw color.....	470°	2½ lbs. to 1 lb. Tin
Very dark straw color.....	490°	3½ lbs. to 1 lb. Tin
Brownish yellow.....	500°	4¾ lbs. to 1 lb. Tin
Light purple.....	530°	7½ lbs. to 1 lb. Tin
Dark purple.....	550°	12 lbs. to 1 lb. Tin
Dark blue.....	570°	25 lbs. to 1 lb. Tin

CASE HARDENING WROUGHT IRON

This process gives to wrought iron, a surface having the properties of steel, and parts subjected to friction are enabled to withstand considerably more wear. The depth to which the hardening may extend is from 1/16 to 1/8 inch. To case-harden, the polished surface is heated to a cherry red and then placed in a mixture of charcoal and soda ash, or ferro-cyanide of potassium and pieces of leather.

PREVENTION OF RUSTING IN OF SCREWS

The screws in machines exposed to heat and moist air soon rust in, even if oil is used, which makes the taking apart of a machine a difficult task. By dipping the screws before putting them in place in a thin paste of graphite and oil, they can be removed without difficulty, even after being in use for several years.

POUND RIVETS

(Flat Head)


IN STOCK IN 200 POUND KEGS

Size Weight per M	Dimen.		Pr. per lb.	Size Weight per M	Dimen.		Pr. per lb.	Size Weight per M	Dimen.		Pr. per lb.
	Dia.	L'gth			Dia.	L'gth			Dia.	L'gth	
2 lbs.	.140	17 ¹ / ₆₄	28	6 lbs.	.200	25 ⁵ / ₆₄	20	10 lbs.	.233	15 ¹ / ₃₂	19
2½ "	.147	9 ⁹ / ₃₂	25	7 "	.215	13 ¹ / ₃₂	20	12 "	.253	1½	17
3 "	.160	5 ⁵ / ₁₆	24	8 "	.225	7 ⁷ / ₁₆	20	14 "	.275	33 ³ / ₆₄	17
4 "	.173	11 ¹ / ₃₂	22	9 "	.230	29 ⁵ / ₆₄	19	16 "	.293	17 ¹ / ₃₂	17
5 "	.185	3 ³ / ₈	21								

Crankshaft Turning

Crankshaft turning is an adaptation of eccentric machining. A single throw crankshaft mounted in the lathe for machining the throw bearing is shown in Fig.


The adapters attached to each end of the crankshaft have offset center holes corresponding to the throw of the crankshaft.




A Crankshaft Mounted in the Lathe for Machining the Throw Bearing

MELTING POINTS AND COLOR SCALE

MELTING POINTS



MELTING POINT RANGES



BRIDGEPORT BRASS COMPANY

Testing Crankshafts

Crankshafts may be tested between the lathe centers, as shown in Fig. 1. The dial indicator mounted in the tool post of the lathe reads in thousandths of an inch and will show exactly how much the crankshaft is sprung and will also disclose any out-of-round condition of the bearing. Straightening a crankshaft is a delicate job and should be attempted only by an experienced mechanic.




Fig. 1. Testing a Crankshaft in the Lathe

COLOR AND TEMPERATURE IN HEATING STEEL

THE average blacksmith and repair shop is not equipped with pyrometers with which to accurately determine the heat temperature of iron or steel. They have to depend upon the human eye, and in vision the idea of color frequently varies, but for all practical purposes color can be used as a fairly accurate gauge in heating and tempering steel.

Solid bodies which are heated to a point so that they glow with the intensity of their own heat will emit certain colors, depending on the temperature and this independently of the nature of the heated material. In other words, a piece of iron or steel heated to 1500 degrees F., will have practically the same brightness and color as a piece of firebrick which has been heated to the same temperature.

Consequently, providing that the eye of the individual and his keenness of vision are true, the following table will enable the mechanic who has not a pyrometer to determine approximately the temperatures of iron or steel from the following colors:

Color	Approximate Temperature Deg. Fahr.
Lowest red visible in the dark	800
Lowest red visible in twilight	900
Lowest red visible in daylight	950
Faint red	1000
Blood, medium	1050
Dull red	1100
Dark cherry red	1250
Full cherry red	1300
Bright cherry red	1450
Salmon	1550
Light red	1600
Dark orange	1625
Orange	1700
Full yellow	1800
Lemon	1900
Light yellow	2250
White	2400
Brilliant white	2600
Dazzling (blueish) white	2800

When the temperature is too low for the material to glow — as in tempering — it is sometimes possible to estimate it by placing a piece of polished steel at a point where it can come approximately to the temperature of the article to be determined upon. After taking the steel away it will be found to have a "temper" color corresponding to the highest temperature reached by it. These colors for the various temperatures are given below and are only for the range between 430 deg. and 600 deg. F.

Color	Temperature Deg. Fahr.
Very pale yellow	430
Light yellow	440
Pale straw yellow	450
Straw yellow	460
Deep straw yellow	470
Dark yellow	480
Yellow brown	490
Brown yellow	500
Spotted red yellow	510
Brown purple	520
Light purple	530
Full purple	540
Dark purple	550
Full blue	560
Dark blue	570
Very dark blue	600

From the foregoing table on high heats it is possible to consider the heating and cooling cycles of 0.20 per cent carbon steel, for example. This is about the average carbon content of the steel most widely encountered in the trade.

Refer to the heat colors in the above chart, and you can then determine the temperatures at which the changes take place in the composition of the steel due to the heat or cooling applied. By this means you can make heat treatment closely accurate in the blacksmith shop.

Stress Relieving, 1150 deg. F. —
Around this temperature, there is no change in grain size or composition of the steel. But there is a change in

COLOR AND TEMPERATURE (Continued)

grain structure resulting in plastic flow of the material. In this manner, any internal stresses induced by welding are to all intents and purposes nullified. But if the material has received a permanent set after welding, stress relieving will not return it to normal.

The material should be held at this temperature for an hour per inch thickness. Cooling in still air is recommended.

Critical Temperature, 1330 deg. F. — No change in grain size of steel but change in composition starts. Iron carbides begin to dissolve and austenitic iron makes its appearance. Below this temperature, quenching has no effect on hardness. Above this temperature, quenching increases the hardness but lowers the ductility of the steel.

Critical Temperature, 1520 deg. F. — At this high-critical temperature, full austenitic iron is obtained. Quick cooling just above this temperature results in a fine grained, hardened steel. As the temperature increases, however, grain growth begins and quenching results in large coarse grains with a corresponding loss in ductility. For welds in this state subsequent annealing is strongly recommended.

Hardened steels may be tempered by reheating to a temperature just below the critical range and followed by a convenient rate of cooling.

Top Annealing Temperature, 1625 deg. F. — For full annealing, the steel should be held around this temperature for one hour per inch of thickness and cooled very slowly in the furnace or in some medium such as lime that will prolong the rate of cooling as compared to that of air.

Top Quenching in Water, 1640 deg. F. — Above this temperature (a dark orange), the steel should be quenched in oil or lead.

Top Normalizing Temperature, 1770 deg. F. — The steel is heated at this temperature and cooled in still air at ordinary temperatures. The steel is thus given a grain of known structure, size and composition. Normalizing is always followed by some desired heat treatment.

Top Forging Temperature, 2380 deg. F. — Above this temperature, the steel should not be forged.

At 2710 deg. F. liquid iron appears in the steel, and at 2770 deg. F., iron becomes completely liquid.

Melting Points of Metals

Some metals seem to melt more easily than others, which I presume means they melt at lower temperatures. Where can I obtain a table showing the approximate melting points of the principal metals used in welding?

As this is a subject of general interest we have compiled such a table and it is given below. It must be remembered, however, that pure metals melt at the temperature given, whereas alloys, that is combinations of 2 or more metals, have a melting range, and not a single melting temperature.

By a melting range we mean that there may be a difference of 10 or 15 or even more degrees during which some of the crystals of the alloy are molten, while others still remain solid or in a plastic condition. As the temperature increases finally the whole mass becomes molten.

MELTING POINTS (Approximate, of Pure Metals and Alloys)

Degrees F.

Iron (Pure)	2786
Steel (Mild) (Alloy)	2700
Nickel (Pure)	2646
Steel (Medium Carbon) (Alloy) ..	2600
Steel (High Carbon) (Alloy) ..	2500
Monel Metal (Alloy)	2480
Iron (Cast) (Alloy)	2300
Iron (Malleable) (Alloy)	2300

MELTING POINTS (Continued)

Copper (Pure)	1981
Bronze (Phosphor) (Alloy) ...	1922
Brass (Common Yellow) (Alloy)	1652
Bronze (Tobin) (Alloy)	1625
Silver Brazing Alloys..	1175 to 1600
Aluminum (Pure)	1218
Aluminum (Cast) (8% Copper)	
(Alloy)	1175
Aluminum (5% silicon) (Alloy)	1117
Antimony (Pure)	1166
Zinc (Pure)	786
Babbitt (Alloy)	500 to 700
Lead (Pure)	620
Solder (Alloy)	350 to 550
Tin (Pure)	450

Blow Holes In Cast Iron

What causes the molten metal in welding cast iron to be full of blow holes? When I first start to make a weld in a casting I seem to get along fairly well, but the puddle soon develops a lot of blow holes, which I cannot get rid of. Is the trouble with the rod, or flux?

The reason why you do not have difficulty when the metal is first molten is because the metal is hot enough to melt, but not too hot to produce gas. If the puddle of molten metal is overheated certain constituents are burned producing gases, which will bubble from the molten iron. In other words, the puddle will "boil" as it is often called. If the molten metal is allowed to cool quickly the gas is entrapped as the metal solidifies and "blow holes" result.

To avoid this condition it is only necessary to heat the puddle to a lower temperature. This can be done by using a smaller tip, or preferably by reducing the pressure of the two gases, oxygen and acetylene to prevent what is sometimes called a "blowing" or harsh flame. Some welders get into the habit of using too large a torch for the job and sometimes they turn the pressures up too high for a soft neutral flame at the tip. When this is done a casting, or

any other job, which is being welded is likely to be overheated. Perhaps one of the difficulties lies in trying to heat a casting too rapidly and failing to preheat the casting before starting to weld.

Cast iron should be heated very slowly and if the casting is of any size it should be protected by fire brick, asbestos, or other means during heating and the heat should be slowly applied until the casting has reached a dull red heat.

When the torch is used, with a properly adjusted flame, the puddle may be kept just hot enough, but not too hot. Good rods and fluxes are of course essential, but ordinarily blow holes are not caused by these, but are the result of too much heat, as described above. We would suggest that you take a scrap casting and experiment with these thoughts in mind. We believe you will solve the trouble.

Difference Between Sheet and Cast Aluminum — Method of Welding Each

Cast Aluminum is usually an alloy of Approx. 8% copper and the balance aluminum. In some instances a small amount of zinc is added. Approx. melting point is 1175 F.

Aluminum Sheets (for tanks, etc.) are usually Pure Aluminum. Melting point Approx. 1215 F.

Cast Aluminum is ordinarily welded with a cast aluminum flux and cast aluminum welding rods made of the same alloy. Some preheating is usually necessary and can be done with city or natural gas burner without air. Care must be exercised to avoid overheating, and casting well supported to prevent warping.

Aluminum Sheets (pure aluminum) is usually welded with pure aluminum welding rod and a good sheet-aluminum flux. Very thin sheets may be flanged (edges bent at right angle to sheet) and flanges held securely together in a jig. Flux may be pasted on the seam and flanges melted down to make the weld. In this case, welding rod is not required except at start — or to repair hole accidentally melted in the metal.

RYERSON COLOR MARKS FOR STAINLESS STEEL

Grade	Type No.	Color Mark	Grade	Type No.	Color Mark
18-8	302	Yellow	18-8-M	316	Purple
18-8-EZ	303	Black	18-8M Spec.	317	Orange
18-8-S	304	Green	18-8-C	347	Pink
25-12	309	Brown	12-EZ	416	Blue
25-20	310	Red			

HEAT TREATMENTS FOR CARBON
AND ALLOY STEELS—1

(Recommended for various steels conforming to S. A. E. specifications)

Heat Treatment A

After forging or machining:

1. Carbonize between 1600° F. and 1750° F. (1650°–1700° F. desired).
2. Cool slowly or quench.
3. Reheat to 1450°–1500° F. and quench.

Heat Treatment B

After forging or machining:

1. Carbonize between 1600° F. and 1750° F. (1650°–1700° F. desired).
2. Cool slowly in the carbonizing mixture.
3. Reheat to 1550°–1625° F.
4. Quench.
5. Reheat to 1400°–1450° F.
6. Quench.
7. Draw in hot oil varying from 300°–450° F., depending upon hardness desired.

Heat Treatment D

After forging or machining:

1. Heat to 1500°–1600° F.
2. Quench.
3. Reheat to 1450°–1500° F.
4. Quench.
5. Reheat to 600°–1200° F. and cool slowly.

Heat Treatment E

After forging or machining:

1. Heat to 1500°–1550° F.
2. Cool slowly.
3. Reheat to 1450°–1500° F.
4. Quench.
5. Reheat to 600°–1200° F. and cool slowly.

Heat Treatment F

After shaping or coiling:

1. Heat to 1425°–1475° F.
2. Quench in oil.
3. Reheat to 400°–900° F., according to temper desired, and cool slowly.

Heat Treatment G

After forging or machining:

1. Carbonize between 1600° F. and 1750° F. (1650°–1700° F. desired).
2. Cool slowly in the carbonizing material.
3. Reheat to 1500°–1550° F.
4. Quench.
5. Reheat to 1300°–1400° F.
6. Quench.
7. Reheat to 250°–500° F. (depending upon work) and cool slowly.

Heat Treatment H

After forging or machining:

1. Heat to 1500°–1600° F.
2. Quench.
3. Reheat to 600°–1200° F. and cool slowly.

Heat Treatment K

After forging or machining:

1. Heat to 1500°–1550° F.
2. Quench.
3. Reheat to 1300°–1400° F.
4. Quench.
5. Reheat to 600°–1200° F. and cool slowly.

Heat Treatment L

After forging or machining:

1. Carbonize at a temperature between 1600° F. and 1750° F. (1650°–1700° F. desired).
2. Cool slowly in the carbonizing mixture.
3. Reheat to 1400°–1500° F.
4. Quench.
5. Reheat to 1300°–1400° F.
6. Quench.
7. Reheat to 250°–500° F. and cool slowly.

Heat Treatment M

After forging or machining:

1. Heat to 1450°–1500° F.
2. Quench.
3. Reheat to 500°–1250° F. and cool slowly.

HEAT TREATMENTS FOR CARBON AND ALLOY STEELS—2

(Recommended for Various Steels conforming to S. A. E. specifications)

Heat Treatment P

After forging or machining:

1. Heat to 1450°–1500° F.
2. Quench.
3. Reheat to 1375°–1450° F.
4. Quench.
5. Reheat to 500°–1250° F. and cool slowly.

Heat Treatment Q

After forging:

1. Heat to 1475°–1525° F. (Hold at this temperature one-half hour to insure thorough heating.)
2. Cool slowly.
3. Machine.
4. Reheat to 1375°–1425° F.
5. Quench.
6. Reheat to 250°–550° F. and cool slowly.

Heat Treatment R

After forging:

1. Heat to 1500°–1550° F.
2. Quench in oil
3. Reheat to 1200°–1300° F. (Hold at this temperature three hours.)
4. Cool slowly.
5. Machine.
6. Reheat to 1350°–1450° F.
7. Quench in oil.
8. Reheat to 250°–500° F. and cool slowly.

Heat Treatment S

After forging or machining:

1. Carbonize at a temperature between 1600° F. and 1750° F (1650°–1700° F. desired).
2. Cool slowly in the carbonizing mixture.
3. Reheat to 1650°–1750° F.
4. Quench.
5. Reheat to 1475°–1550° F.
6. Quench.
7. Reheat to 250°–550° F. and cool slowly.

Heat Treatment T

After forging or machining:

1. Heat to 1650°–1750° F.
2. Quench.
3. Reheat to 500°–1300° F. and cool slowly.

Heat Treatment U

After forging:

1. Heat to 1525°–1600° F. (Hold for about one-half hour.)
2. Cool slowly.
3. Machine.
4. Reheat to 1650°–1700° F.
5. Quench.
6. Reheat to 350°–550° F. and cool slowly.

Heat Treatment V

After forging or machining:

1. Heat to 1650°–1750° F.
2. Quench.
3. Reheat to 400°–1200° F. and cool slowly.

DRILL ROD

Standard Tolerances for Size

ROUNDS

1.500" to .500"001"	+ or -
.499" to .125"0005"	+ or -
.124" and smaller0003"	+ or -

FLATS, SQUARES, HEXAGONS, OCTAGONS

1" to 3/4"0015"	+ or -
3/4" to 1/4"001"	+ or -
Smaller than 1/4"0005"	+ or -

COLD ROLLED LOW CARBON SHEETS AND STRIP

Rockwell B	Brinell	Shore Scleroscope	Rockwell B	Brinell	Shore Scleroscope
100.....	216.....	40	65.....	106.....	20
95.....	186.....	35	60.....	98.....	19
90.....	163.....	30	55.....	91.....	18
85.....	147.....	28	50.....	84.....	16
80.....	134.....	26	45.....	78.....	15
75.....	124.....	24	40.....	71.....	14
70.....	115.....	22	35.....	65.....	14

Molybdenum Steels

S. A. E. No.	Carbon Range	Manganese Range	Phosphorus, Max.	Sulfur, Max.	Chromium Range	Nickel Range	Molybdenum Range
4130	0.25-0.35	0.50-0.80	0.040	0.050	0.50-0.80	0.15-0.25
X4130	0.25-0.35	0.40-0.60	0.040	0.050	0.80-1.10	0.15-0.25
4135	0.30-0.40	0.60-0.90	0.040	0.050	0.80-1.10	0.15-0.25
4140	0.35-0.45	0.60-0.90	0.040	0.050	0.80-1.10	0.15-0.25
4150	0.45-0.55	0.60-0.90	0.040	0.050	0.80-1.10	0.15-0.25
4320	0.15-0.25	0.40-0.70	0.040	0.050	0.30-0.60	1.65-2.00	0.20-0.30
4340	0.35-0.45	0.50-0.80	0.040	0.050	0.50-0.80	1.50-2.00	0.30-0.40
X4340	0.35-0.45	0.50-0.80	0.040	0.050	0.60-0.90	1.50-2.00	0.20-0.30
4615	0.10-0.20	0.40-0.70	0.040	0.050	1.65-2.00	0.20-0.30
4620	0.15-0.25	0.40-0.70	0.040	0.050	1.65-2.00	0.20-0.30
4640	0.35-0.45	0.50-0.80	0.040	0.050	1.65-2.00	0.20-0.30
4815	0.10-0.20	0.40-0.60	0.040	0.050	3.25-3.75	0.20-0.30
4820	0.15-0.25	0.40-0.60	0.040	0.050	3.25-3.75	0.20-0.30

¹Silicon range of all S. A. E. basic open hearth alloy steels shall be 0.15-0.30. For electric and acid open hearth alloy steels, the silicon content shall be 0.15 minimum.

Silicon Manganese Steels

S. A. E. No.	Carbon Range	Manganese Range	Phosphorus, Max.	Sulfur, Max.	Silicon Range
9255	0.50-0.60	0.60-0.90	0.040	0.050	1.80-2.20
9260	0.55-0.65	0.60-0.90	0.040	0.050	1.80-2.20

Corrosion and Heat Resisting Alloys

S. A. E. No.	Carbon, Max.	Manganese, Max.	Silicon, Max.	Phosphorus, Max.	Sulfur, Max.	Chromium Range	Nickel Range
30905	0.08	0.20-0.70	0.75	0.030	0.030	17.00-20.00	8.00-10.00
30915	0.09-0.20	0.20-0.70	0.75	0.030	0.030	17.00-20.00	8.00-10.00
51210	0.12	0.50	0.50	0.030	0.030	11.50-13.00
X51410	0.12	0.60	0.50	0.030	0.15-0.50	13.00-15.00
51335	0.25-0.40	0.60	0.50	0.030	0.030	12.00-14.00
51510	0.12	0.60	0.50	0.030	0.030	14.00-16.00
51710	0.12	0.60	0.50	0.030	0.030	16.00-18.00

¹Silicon range of all S. A. E. basic open hearth alloy steels shall be 0.15-0.30. For electric and acid open hearth alloy steels, the silicon content shall be 0.15 minimum.

Free Cutting Steels

S. A. E. No.	Carbon Range	Manganese Range	Phosphorus Range	Sulfur Range
1112	0.08-0.16	0.60-0.90	0.09-0.13	0.10-0.20
X1112	0.08-0.16	0.60-0.90	0.09-0.13	0.20-0.30
1115	0.10-0.20	0.70-1.00	0.045 max.	0.075-0.15
1120	0.15-0.25	0.60-0.90	0.045 max.	0.075-0.15
X1314	0.10-0.20	1.00-1.30	0.045 max.	0.075-0.15
X1315	0.10-0.20	1.30-1.60	0.045 max.	0.075-0.15
X1330	0.25-0.35	1.35-1.65	0.045 max.	0.075-0.15
X1335	0.30-0.40	1.35-1.65	0.045 max.	0.075-0.15
X1340	0.35-0.45	1.35-1.65	0.045 max.	0.075-0.15

Manganese Steels¹

S. A. E. No.	Carbon Range	Manganese Range	Phosphorus, Max.	Sulfur, Max.
T1330	0.25-0.35	1.60-1.90	0.040	0.050
T1335	0.30-0.40	1.60-1.90	0.040	0.050
T1340	0.35-0.45	1.60-1.90	0.040	0.050
T1345	0.40-0.50	1.60-1.90	0.040	0.050
T1350	0.45-0.55	1.60-1.90	0.040	0.050

To Soften Cast-Iron for Drilling—Heat to a cherry red, having it lay level in the fire. Then with tongs, put on a piece of brimstone, a little less in size than the hole is to be. This softens the iron entirely through. Let it lie in the fire until slightly cooled, when it is ready to drill.

S. A. E. STANDARD SPECIFICATIONS

Nickel-Chromium Steels

S. A. E. Steel No.	Carbon Range	Manganese Range	Phosphorus Max.	Sulphur Max.	Nickel Range	Chromium Range
3115	0.10-0.20	0.30-0.60	0.04	0.05	1.00-1.50	0.45-0.75
3120	0.15-0.25	0.30-0.60	0.04	0.05	1.00-1.50	0.45-0.75
3125	0.20-0.30	0.50-0.80	0.04	0.05	1.00-1.50	0.45-0.75
3130	0.25-0.35	0.50-0.80	0.04	0.05	1.00-1.50	0.45-0.75
3135	0.30-0.40	0.50-0.80	0.04	0.05	1.00-1.50	0.45-0.75
3140	0.35-0.45	0.50-0.80	0.04	0.05	1.00-1.50	0.45-0.75
3145	0.40-0.50	0.50-0.80	0.04	0.05	1.00-1.50	0.45-0.75
3150	0.45-0.55	0.50-0.80	0.04	0.05	1.00-1.50	0.45-0.75
3215	0.10-0.20	0.30-0.60	0.04	0.045	1.50-2.00	0.90-1.25
3220	0.15-0.25	0.30-0.60	0.04	0.045	1.50-2.00	0.90-1.25
3230	0.25-0.35	0.30-0.60	0.04	0.045	1.50-2.00	0.90-1.25
3240	0.35-0.45	0.30-0.60	0.04	0.045	1.50-2.00	0.90-1.25
3245	0.40-0.50	0.30-0.60	0.04	0.045	1.50-2.00	0.90-1.25
3250	0.45-0.55	0.30-0.60	0.04	0.045	1.50-2.00	0.90-1.25
3312	max. 0.17	0.30-0.60	0.04	0.045	3.25-3.75	1.25-1.75
3325	0.20-0.30	0.30-0.60	0.04	0.045	3.25-3.75	1.25-1.75
3335	0.30-0.40	0.30-0.60	0.04	0.045	3.25-3.75	1.25-1.75
3340	0.35-0.45	0.30-0.60	0.04	0.045	3.25-3.75	1.25-1.75
3415	0.10-0.20	0.30-0.60	0.04	0.045	2.75-3.25	0.60-0.95
3435	0.30-0.40	0.30-0.60	0.04	0.045	2.75-3.25	0.60-0.95
3450	0.45-0.55	0.30-0.60	0.04	0.045	2.75-3.25	0.60-0.95

Chromium Steels

S. A. E. Steel No.	Carbon Range	Manganese Range	Phosphorus Max.	Sulphur Max.	Chromium Range
5120	0.15-0.25	0.30-0.60	0.04	0.05	0.60-0.90
5140	0.35-0.45	0.50-0.80	0.04	0.05	0.80-1.10
5150	0.45-0.55	0.50-0.80	0.04	0.05	0.80-1.10
52100	0.95-1.10	0.20-0.50	0.03	0.035	1.20-1.50

Chromium - Vanadium Steels

S. A. E. Steel No.	Carbon Range	Manganese Range	Phosphorus Max.	Sulphur Max.	Chromium Range	Vanadium	
						Min.	Desired
6115	0.10-0.20	0.30-0.60	0.04	0.045	0.80-1.10	0.15	0.18
6120	0.15-0.25	0.30-0.60	0.04	0.045	0.80-1.10	0.15	0.18
6125	0.20-0.30	0.50-0.80	0.04	0.045	0.80-1.10	0.15	0.18
6130	0.25-0.35	0.50-0.80	0.04	0.045	0.80-1.10	0.15	0.18
6135	0.30-0.40	0.50-0.80	0.04	0.045	0.80-1.10	0.15	0.18
6140	0.35-0.45	0.50-0.80	0.04	0.045	0.80-1.10	0.15	0.18
6145	0.40-0.50	0.50-0.80	0.04	0.045	0.80-1.10	0.15	0.18
6150	0.45-0.55	0.50-0.80	0.04	0.045	0.80-1.10	0.15	0.18
6195	0.90-1.05	0.20-0.45	0.03	0.035	0.80-1.10	0.15	0.18

Tungsten Steels

S. A. E. Steel No.	Carbon Range	Manganese Max.	Phosphorus Max.	Sulphur Max.	Chromium Range	Tungsten Range
71360	0.50-0.70	0.30	0.035	0.035	3.00-4.00	12.00-15.00
71660	0.50-0.70	0.30	0.035	0.035	3.00-4.00	15.00-18.00
7260	0.50-0.70	0.30	0.035	0.035	0.50-1.00	1.50-2.00

S. A. E. STANDARD SPECIFICATIONS

Carbon Steels

S. A. E. Steel No.	Carbon Range	Manganese Range	Phosphorus Max.	Sulphur Max.
1010	0.05—0.15	0.30—0.60	0.045	0.055
1015	0.10—0.20	0.30—0.60	0.045	0.055
1020	0.15—0.25	0.30—0.60	0.045	0.055
O.H.1020-90	0.15—0.25	0.75—1.05	0.045	0.055
1025	0.20—0.30	0.50—0.80	0.045	0.055
1030	0.25—0.35	0.50—0.80	0.045	0.055
1035	0.30—0.40	0.50—0.80	0.045	0.055
1040	0.35—0.45	0.50—0.80	0.045	0.055
1045	0.40—0.50	0.50—0.80	0.045	0.055
1050	0.45—0.55	0.50—0.80	0.045	0.055
1095	0.90—1.05	0.25—0.50	0.040	0.050
X-1314	0.10—0.20	1.00—1.30	0.050	0.08—0.13
X-1315	0.10—0.20	1.25—1.55	0.050	0.08—0.13
1335	0.30—0.40	1.60—1.90	0.040	0.050
*1350	0.45—0.55	0.90—1.20	0.040	0.050
*1360	0.55—0.70	0.90—1.20	0.040	0.050

* Silicon not to exceed 0.30.

Screw Stocks


S. A. E. Steel No.	Carbon Range	Manganese Range	Phosphorus Max.	Sulphur Max.
1112	0.08—0.16	0.60—0.90	0.09—0.13	0.10—0.18
1120	0.15—0.25	0.60—0.90	max. 0.06	0.075—0.15

Nickel Steels

S. A. E. Steel No.	Carbon Range	Manganese Range	Phosphorus Max.	Sulphur Max.	Nickel Range
2015	0.10—0.20	0.30—0.60	0.04	0.05	0.40—0.60
2115	0.10—0.20	0.30—0.60	0.04	0.05	1.25—1.75
2315	0.10—0.20	0.30—0.60	0.04	0.05	3.25—3.75
2320	0.15—0.25	0.30—0.60	0.04	0.05	3.25—3.75
2330	0.25—0.35	0.50—0.80	0.04	0.05	3.25—3.75
2335	0.30—0.40	0.50—0.80	0.04	0.05	3.25—3.75
2340	0.35—0.45	0.50—0.80	0.04	0.05	3.25—3.75
2345	0.40—0.50	0.50—0.80	0.04	0.05	3.25—3.75
2350	0.45—0.55	0.50—0.80	0.04	0.05	3.25—3.75
2512	max. 0.17	0.30—0.60	0.04	0.05	4.75—5.25


NOTES ON CORRUGATED SHEETS

To find the Rise when radius length of Span is given, use following formula:



$$V = R - \sqrt{R^2 - \frac{C^2}{4}} \text{ or nearly } \frac{C^2}{8R}$$

To find the Rise when radius and length of Arc is given, use following formula:




Rise = Radius
 $R \times \text{Cosine}$
of Angle X

$$Y = \frac{\text{Arc} \times 360^\circ}{\text{Cir. of Circle}}$$

$$Z = \text{Cosine of Angle } X$$

$$X = \frac{Y}{2}$$

$$Z = R \times \text{Cosine } X$$




To find length of Arc when Span and Small Chord are given:

L—Length of Arc
C—Span
c—Small Chord


$$L = \frac{8c - C}{3}$$

CORRUGATED SHEET DATA


Standard Details of Construction



Girths of 8", 10", 12" and 14", with corresponding Apron "L" of 2, 3, 4 and 5 inches. Diameter of roll, 2 inches. Girth is full width of sheet required to make ridge roll.




SIDING DETAIL




TYPICAL DETAIL OF ROOF SHEETING & RIDGE ROLL

(One end up, one down)



Roofing Sheet—Rolled from 30" flat sheet

(Both ends down)



Siding Sheet—Rolled from 28" flat sheet

NOTES ON CORRUGATED SHEETS—(Cont'd)

SAFE LOADS—PER SHEET

Supported at Ends Only. Sheets, 26 Inches Wide

	Gauge	28	27	26	24	22	20	18	16
2 1/2" Corrugations	6'0" Span..	88	97	106	141	176	211	282	352
	7'0" Span..	75	83	91	121	151	181	242	302
	8'0" Span..	66	73	79	106	132	158	211	264
	9'0" Span..	59	65	70	94	117	141	188	235
	10'0" Span..	53	58	63	85	106	127	169	211
1 1/4" Corrugations	6'0" Span..	53	58	63	85	106	127	169	211
	7'0" Span..	45	50	55	73	91	109	145	181
	8'0" Span..	40	44	47	64	79	95	127	158
	9'0" Span..	35	39	42	56	70	85	113	141
	10'0" Span..	32	34	38	51	64	76	101	127

5/8 inch is taken as depth of 2 1/2 inch corrugations, 3/8 inch as depth of 1 1/4 inch corrugations.

The following formula has been used: $W = \frac{99900 \cdot b \cdot d}{L}$

L —Supported length of sheet in inches. b —Thickness of sheet in inches. d —Depth of corrugations in inches.

W —Breaking weight distributed in pounds. $\frac{W}{4}$ —Safe loads per sheet between supports.

CORRUGATED SHEETS

TO ASCERTAIN LENGTH OF A CURVED SHEET BY THE FOLLOWING TABLE

TABLE FOR COMPUTING LENGTHS OF CURVED SHEETS—Continued

RULE.—Divide height (or size) by base (or span), find quotient in column of heights, take length for that height opposite to it in next column on the right hand. Multiply length thus obtained by base (or span) and product will give length of sheet.

EXAMPLE.—Find length of sheet, base (or span) being 100 inches, rise being 25 inches.

25 divided by 100 equals .25; and .25, per table, equals 1.5912, length of base, which multiplied by 100 equals 159.12 inches, length of sheet before curving.


TABLE FOR COMPUTING LENGTHS OF CURVED SHEETS

Height	Length	Height	Length	Height	Length	Height	Length
.001	1.00002	.128	1.04313	.176	1.08066	.224	1.12885
.005	1.00007	.129	1.04338	.177	1.08156	.225	1.12997
.01	1.00027	.13	1.04447	.178	1.08246	.226	1.13108
.015	1.00061	.131	1.04515	.179	1.08337	.227	1.13219
.02	1.00107	.132	1.04584	.18	1.08428	.228	1.13334
.025	1.00167	.133	1.04652	.181	1.08519	.229	1.13441
.03	1.0024	.134	1.04722	.182	1.08611	.23	1.13557
.035	1.00327	.135	1.04792	.183	1.08704	.231	1.13671
.04	1.00426	.136	1.04862	.184	1.08797	.232	1.13786
.045	1.00539	.137	1.04932	.185	1.0889	.233	1.13903
.05	1.00665	.138	1.05003	.186	1.08984	.234	1.1402
.055	1.00805	.139	1.05075	.187	1.09079	.235	1.14136
.06	1.00957	.14	1.05147	.188	1.09174	.236	1.14247
.065	1.01123	.141	1.0522	.189	1.09269	.237	1.14363
.07	1.01302	.142	1.05293	.19	1.09365	.238	1.1448
.075	1.01493	.143	1.05367	.191	1.09461	.239	1.14597
.08	1.01698	.144	1.05441	.192	1.09557	.24	1.14714
.085	1.01916	.145	1.05516	.193	1.09654	.241	1.14831
.09	1.02146	.146	1.05591	.194	1.09752	.242	1.14949
.095	1.02389	.147	1.05667	.195	1.0985	.243	1.15067
.1	1.02645	.148	1.05743	.196	1.09949	.244	1.15186
.101	1.02908	.149	1.05819	.197	1.10048	.245	1.15308
.102	1.02752	.15	1.05895	.198	1.10147	.246	1.15429
.103	1.02806	.151	1.05973	.199	1.10247	.247	1.15549
.104	1.0286	.152	1.06051	.2	1.10348	.248	1.1567
.105	1.02914	.153	1.0613	.201	1.10447	.249	1.15791
.106	1.0297	.154	1.06209	.202	1.10548	.25	1.15912
.107	1.03026	.155	1.06288	.203	1.1065	.251	1.16033
.108	1.03082	.156	1.06368	.204	1.10752	.252	1.16157
.109	1.03139	.157	1.06449	.205	1.10855	.253	1.16279
.110	1.03196	.158	1.0653	.206	1.10958	.254	1.16402
.111	1.03254	.159	1.06611	.207	1.11062	.255	1.16526
.112	1.03312	.16	1.06693	.208	1.11165	.256	1.16649
.113	1.03371	.161	1.06775	.209	1.11269	.257	1.16774
.114	1.0343	.162	1.06858	.21	1.11374	.258	1.16899
.115	1.0349	.163	1.06941	.211	1.11479	.259	1.17024
.116	1.03551	.164	1.07025	.212	1.11584	.26	1.1715
.117	1.03611	.165	1.07109	.213	1.11692	.261	1.17275
.118	1.03672	.166	1.07194	.214	1.11799	.262	1.17401
.119	1.03734	.167	1.07279	.215	1.11904	.263	1.17527
.12	1.03797	.168	1.07365	.216	1.12011	.264	1.17655
.121	1.0386	.169	1.07451	.217	1.12118	.265	1.17784
.122	1.03923	.17	1.07537	.218	1.12225	.266	1.17912
.123	1.03985	.171	1.07624	.219	1.12334	.267	1.1804
.124	1.04051	.172	1.07711	.22	1.12445	.268	1.18162
.125	1.04116	.173	1.07799	.221	1.12556	.269	1.18294
.126	1.04181	.174	1.07888	.222	1.12663	.27	1.18428
.127	1.04247	.175	1.07977	.223	1.12774	.271	1.18557


Height	Length	Height	Length	Height	Length	Height	Length
.272	1.18688	.33	1.26892	.387	1.36084	.444	1.46255
.273	1.18819	.331	1.27043	.388	1.36254	.445	1.46411
.274	1.18965	.332	1.27196	.389	1.36425	.446	1.46568
.275	1.19082	.333	1.27349	.39	1.36596	.447	1.46815
.276	1.19214	.334	1.27502	.391	1.36767	.448	1.47002
.277	1.19345	.335	1.27655	.392	1.36939	.449	1.47189
.278	1.19477	.336	1.2781	.393	1.37111	.45	1.47377
.279	1.1961	.337	1.27964	.394	1.37283	.451	1.47565
.28	1.19743	.338	1.28118	.395	1.37455	.452	1.47753
.281	1.19887	.339	1.28273	.396	1.37628	.453	1.47942
.282	1.2001	.34	1.28428	.397	1.37801	.454	1.48131
.283	1.20146	.341	1.28583	.398	1.37974	.455	1.4832
.284	1.20282	.342	1.28739	.399	1.38148	.456	1.48509
.285	1.20419	.343	1.28895	.4	1.38322	.457	1.48699
.286	1.20558	.344	1.29052	.401	1.38496	.458	1.48889
.287	1.20696	.345	1.29209	.402	1.38671	.459	1.49079
.288	1.20832	.346	1.29366	.403	1.38846	.46	1.49269
.289	1.20967	.347	1.29523	.404	1.39021	.461	1.4946
.29	1.21082	.348	1.29681	.405	1.39196	.462	1.49651
.291	1.21239	.349	1.29839	.406	1.39372	.463	1.49842
.292	1.21381	.35	1.29997	.407	1.39548	.464	1.50033
.293	1.2152	.351	1.30156	.408	1.39724	.465	1.50224
.294	1.21658	.352	1.30315	.409	1.399	.466	1.50416
.295	1.21794	.353	1.30474	.41	1.40077	.467	1.50608
.296	1.21926	.354	1.30634	.411	1.40254	.468	1.508
.297	1.22061	.355	1.30794	.412	1.40432	.469	1.50992
.298	1.22203	.356	1.30954	.413	1.4061	.47	1.51182
.299	1.22347	.357	1.31115	.414	1.40788	.471	1.51373
.3	1.22495	.358	1.31276	.415	1.40966	.472	1.51575
.301	1.22635	.359	1.31437	.416	1.41145	.473	1.51764
.302	1.22776	.36	1.31599	.417	1.41321	.474	1.51958
.303	1.22918	.361	1.31761	.418	1.41503	.475	1.52152
.304	1.23061	.362	1.31923	.419	1.41682	.476	1.52346
.305	1.23205	.363	1.32086	.42	1.41861	.477	1.52541
.306	1.23349	.364	1.32249	.421	1.42041	.478	1.52736
.307	1.23494	.365	1.32412	.422	1.42222	.479	1.52931
.308	1.23636	.366	1.32577	.423	1.42402	.48	1.53126
.309	1.2378	.367	1.32741	.424	1.42583	.481	1.53322
.31	1.23925	.368	1.32905	.425	1.42764	.482	1.53518
.311	1.2407	.369	1.33069	.426	1.42945	.483	1.53714
.312	1.24216	.37	1.33234	.427	1.43127	.484	1.5391
.313	1.2436	.371	1.33399	.428	1.43309	.485	1.54186
.314	1.24506	.372	1.33561	.429	1.43491	.486	1.54402
.315	1.24654	.373	1.3373	.43	1.43673	.487	1.54609
.316	1.24801	.374	1.33896	.431	1.43856	.488	1.54896
.317	1.24946	.375	1.34063	.432	1.44039	.489	1.55183
.318	1.25095	.376	1.34229	.433	1.44222	.49	1.5549
.319	1.25243	.377	1.34396	.434	1.44405	.491	1.55728
.32	1.25391	.378	1.34563	.435	1.44589	.492	1.55968
.321	1.25539	.379	1.34731	.436	1.44773	.493	1.56208
.322	1.25686	.38	1.34899	.437	1.44957	.494	1.56448
.323	1.25836	.381	1.35068	.438	1.45142	.495	1.56688
.324	1.25987	.382	1.35237	.439	1.45327	.496	1.56928
.325	1.26137	.383	1.35406	.44	1.45512	.497	1.57168
.326	1.26286	.384	1.35575	.441	1.45697	.498	1.57408
.327	1.26437	.385	1.35744	.442	1.45883	.499	1.57649
.328	1.26588	.386	1.35914	.443	1.46069	.5	1.5789
.329	1.2674						

MANUFACTURERS' STANDARD PRACTICE

Permissible Variations
for Standard Structural Beams, Channels,
Tees, Angles, Bulb Angles and Zees



Permissible Variations
for Wide Flange Structural Sections



APPROXIMATE WEIGHTS OF BOILER TUBES

External Diameter Inches	Standard Thickness, Minimum		Nominal Weight per Ft. Lbs. For Estimating Purposes (ASME)				
	B.W.G. Inches	Inches	Stand. Thick- ness	One Extra Gauge	Two Extra Gauges	Three Extra Gauges	Four Extra Gauges
1	13	.095	1.037	1.168	1.263	1.384	1.500
1 1/4	13	.095	1.328	1.502	1.628	1.793	1.951
1 1/2	13	.095	1.619	1.836	1.994	2.201	2.402
1 3/4	13	.095	1.910	2.169	2.360	2.610	2.854
2	13	.095	2.201	2.503	2.726	3.018	3.305
2 1/4	13	.095	2.492	2.837	3.092	3.427	3.756
2 1/2	12	.109	3.171	3.457	3.835	4.207	4.665
2 3/4	12	.109	3.504	3.823	4.244	4.658	5.169
3	12	.109	3.838	4.189	4.652	5.110	5.674
3 1/4	11	.120	4.555	5.061	5.561	6.179	6.697
3 1/2	11	.120	4.921	5.469	6.012	6.683	7.247
4	10	.134	6.286	6.915	7.693	8.347	9.336
4 1/2	10	.134	7.103	7.817	8.702	9.447	10.580
5	9	.148	8.720	9.711	10.550	11.810	12.730
6	7	.180	12.750	14.290	15.410	16.640	17.450

GALVANIZED AND STAINLESS STEEL GAUGES

Galvanized Sheets		Stainless Steel Sheets			
Galvanized Sheet Gauge	Wt. per Sq. Ft. Lbs.	Stainless Sheet Gauge	Approximate Decimal Parts of an Inch	Aver. Wt. per Sq. Ft. Lbs. for	
				Chrome Iron Alloys	Chrome Nickel C.R. Alloys
8.....	7.0312	8.....	.171875	7.0813	7.2187
9.....	6.4062	9.....	.156250	6.4375	6.5625
10.....	5.7812	10.....	.140625	5.7937	5.9062
11.....	5.1562	11.....	.125000	5.1500	5.2500
12.....	4.5312	12.....	.109375	4.5063	4.5937
13.....	3.9062	13.....	.093750	3.8625	3.9375
14.....	3.2812	14.....	.078125	3.2187	3.2812
15.....	2.9687	15.....	.070312	2.8968	2.9531
16.....	2.6562	16.....	.062500	2.5750	2.6250
17.....	2.4062	17.....	.056250	2.3175	2.3625
18.....	2.1562	18.....	.050000	2.0600	2.1000
19.....	1.9062	19.....	.043750	1.8025	1.8375
20.....	1.6562	20.....	.037500	1.5450	1.5750
21.....	1.5312	21.....	.034375	1.4160	1.4437
22.....	1.4062	22.....	.031250	1.2875	1.3125
23.....	1.2812	23.....	.028125	1.1587	1.1813
24.....	1.1562	24.....	.025000	1.0300	1.0500
25.....	1.0312	25.....	.021875	.9013	.9187
26.....	.9062	26.....	.018750	.7725	.7875
27.....	.8437	27.....	.017187	.7081	.7218
28.....	.7812	28.....	.015625	.6438	.6562
29.....	.7187	29.....	.014062	.5794	.5906
30.....	.6562	30.....	.012500	.5150	.5250

The Galvanized Sheet Gauge, established by custom, is based on the United States Standard Gauge, each galvanized sheet gauge weight being 2.5 oz. per sq. ft. heavier than the gauge weight of the same United States Standard Gauge number, regardless of coating weights.

APPROXIMATE WEIGHTS OF VARIOUS METALS

To find the weight of various metals, multiply the contents in cubic inches by the number shown below; the result will be the approximate weight in pounds.

Iron27777	Brass3112	Tin26562
Steel28332	Lead41015	Aluminum..	.09375
Copper32118	Zinc25318		

NOTES ON CORRUGATED SHEETS

NUMBER OF CORRUGATED SHEETS IN ONE SQUARE (100 sq. ft.—no allowance for laps)

Length of Sheet, Inches	2 1/2" Corrug. (Sheets 26" wide)	1 1/4" Corrug. (Sheets 25" wide)
60	9,231	9,600
72	7,692	8,000
84	6,593	6,857
96	5,769	6,000
108	5,128	5,333
120	4,416	4,800
144	3,846	4,000

NUMBER OF SQUARE FEET IN ONE CORRUGATED SHEET (Standard Lengths)

Length of Sheet, Inches	2 1/2" Corrug. (Sheets 26" wide)	1 1/4" Corrug. (Sheets 25" wide)
60	10.833	10.416
72	13.000	12.500
84	15.166	14.583
96	17.333	16.666
108	19.500	18.750
120	21.666	20.833
144	26.000	25.000

EXTRUDED BRONZE

ANGLES

Size in Inches	Thickness in Inches	Decimal Equivalent	Approx. Weight Lbs. per Lin. Ft.
$\frac{1}{2} \times \frac{1}{2}$	$\frac{1}{8}$.125	.40
$\frac{3}{4} \times \frac{3}{4}$	$\frac{1}{8}$.125	.63
1×1	$\frac{1}{8}$.125	.84
1×1	$\frac{1}{4}$.250	1.68
$1\frac{1}{4} \times 1\frac{1}{4}$	$\frac{1}{8}$.125	1.09
$1\frac{1}{2} \times 1\frac{1}{2}$	$\frac{1}{8}$.125	1.30
$1\frac{1}{2} \times 1\frac{1}{2}$	$\frac{3}{16}$.1875	1.90
$1\frac{1}{2} \times 1\frac{1}{2}$	$\frac{1}{4}$.250	2.60
2×2	$\frac{1}{8}$.125	1.78
2×2	$\frac{1}{4}$.250	3.40
$2\frac{1}{2} \times 2\frac{1}{2}$	$\frac{1}{4}$.250	4.37
3×3	$\frac{1}{4}$.250	5.30

SQUARE BRASS TUBING

Size in Inches	Stubs Gauge	Thickness Decimal Equivalent in Inches	Approx. Weight Lbs. per Ft.
$\frac{1}{4}$	21	.032	.107
$\frac{3}{8}$.040	.189
$\frac{1}{2}$.040	.270
$\frac{1}{2}$	21	.032	.231
$\frac{5}{8}$	21	.032	.293
$\frac{3}{4}$	21	.032	.355
1	21	.032	.478
$1\frac{1}{4}$	21	.032	.603

COPPER TUBING

OPEN ENDS

Soft Temper

Outside Diameter	Stubs Gauge	Thickness Decimal Equiv. in Inches	Lengths	Approx. Weight Lbs. per Ft.
$\frac{7}{16}$	22	.028	6 ft. straight	.144
$\frac{1}{2}$	22	.028	6 ft. straight	.165
$\frac{3}{4}$	16	.065	50 ft. coils	.542
1	16	.065	50 ft. coils	.740

ROUND SEAMLESS

BRASS TUBING

Soft Temper

Listed by Stubs Gauges

Outside Diameter	Stubs Gauge	Thickness Decimal Equivalent in Inches	Approx. Weight Lbs. per Ft.
$\frac{1}{4}$	16	.065	.139
$\frac{1}{4}$	20	.035	.0871
$\frac{5}{16}$	16	.065	.186
$\frac{5}{16}$	19	.042	.101
$\frac{5}{16}$	20	.035	.112
$\frac{5}{16}$	22	.028	.090
$\frac{3}{8}$	16	.065	.233
$\frac{3}{8}$	18	.049	.185
$\frac{3}{8}$	19	.042	.162
$\frac{3}{8}$	20	.035	.138

SPECIFIC GRAVITY—

The specific gravity of a substance is its weight as compared with the weight of an equal bulk of pure water.

For making specific gravity determinations the temperature of the water is usually taken at 62°F., when 1 cu. ft. of water weighs 62.355 lbs. Water is at its greatest density at 39.2°F. or 4° Centigrade.

MISCELLANEOUS.

IRON, LEAD, ETC.	BEEF, PORK, ETC.
14 pounds.....1 stone.	200 pounds.....1 barrel.
21½ stones.....1 pig.	196 lbs. (flour) 1 barrel.
8 pigs.....1 fother.	100 lbs. (fish) 1 quintal.

Stubs' Gages

The difference between the Stubs' Iron Wire Gage and the Stubs' Steel Wire Gage should be borne constantly in mind, the first, commonly being known as the English Standard Wire or Birmingham Gage which designates the Stubs' soft wire sizes, and the second, being used in measuring drawn steel wire or drill rods of Stubs' make.

STANDARD GAUGES AND WEIGHTS OF TIN PLATE

Approx. U. S. Gauge	Trade Term	Weight in Pounds Per Sq. Ft.	Base Weight	Approximate Thickness in Inches
38		.253	55	.0061
37		.276	60	.0068
36		.298	65	.0073
35		.321	70	.0079
34		.344	75	.0084
33		.367	80	.0090
32		.390	85	.0095
31		.413	90	.0101
31		.436	95	.0107
30 1/2	I.C.L.	.459	100	.0113
30	I.C.	.491	107	.0120
29 1/2		.528	115	
29		.542	118	.0133
29		.564	123	.0138
28	I.X.L.	.588	128	.0144
28	I.X.	.620	135	.0152
28	D.C.	.638	139	.0156
28 1/2		.666	145	
27	I.X.X.L.	.680	148	.0167
27		.688	150	.0169
27	I.X.X.	.712	155	.0175
26	I.X.X.X.L.	.771	168	.0189
26	I.X.X.X.	.804	175	.0197
25	D.X.	.827	180	.0203
25	I.X.X.X.X.L.	.863	188	.0211
25	I.X.X.X.X.	.895	195	.0220
25	I.X.X.X.X.X.L.	.955	208	.0238
25	D.X.X.	.964	210	.0241
25	I.X.X.X.X.X.	.987	215	.0246
24	I.X.X.X.X.X.X.L.	1.047	228	.0261
24	I.X.X.X.X.X.X.X.	1.079	235	.0269
24	D.X.X.X.	1.102	240	.0275
23	I.X.X.X.X.X.X.X.L.	1.139	248	.0284
23	I.X.X.X.X.X.X.X.X.	1.171	255	.0292
23	I.X.X.X.X.X.X.X.X.L.	1.231	268	.0307
23	D.X.X.X.X.	1.240	270	.0310
22	I.X.X.X.X.X.X.X.X.X.	1.263	275	.0315

DRAWN BRASS ANGLES

Size in Inches	B & S Gauge	Decimal Equivalent	Approx. Weight Lbs. per Lin. Ft.
1/2 x 1/2	18	.040	.147
3/4 x 3/4	14	.064	.402
3/4 x 3/4	18	.040	.220
1 x 1/4	20	.032	.146
1 x 1	14	.064	.470
1 x 1	18	.040	.294

TEMPERATURE—

The following equation will be found convenient for transforming temperature from one system to another:

Let F = degrees Fahrenheit; C = degree Centi- grade; R = degrees Reamur.

$$\frac{F - 32}{180} = \frac{C}{100} = \frac{R}{80}$$

Properties of Structural Shapes

Depth of Beam Inches	Weight, per Foot Pounds	Area of Section Sq. Ins.	Thickness of Web Inch	Width of Flange Inches	Depth of Beam Inches	Weight, per Foot Pounds	Area of Section Sq. Ins.	Thickness of Web Inch	Width of Flange Inches
Standard I-Beams					Standard Channels				
3	5.7	1.64	.170	2.330	3	4.1	1.19	.170	1.410
3	6.5	1.88	.251	2.411	3	5.0	1.46	.258	1.498
3	7.5	2.17	.349	2.509	3	6.0	1.75	.356	1.596
4	7.7	2.21	.190	2.660	4	5.4	1.56	.180	1.580
4	8.5	2.46	.253	2.723	4	6.25	1.82	.247	1.647
4	9.5	2.76	.326	2.796	4	7.25	2.12	.320	1.720
5	10.5	3.05	.400	2.870	5	6.7	1.95	.190	1.750
5	10.0	2.87	.210	3.000	5	9.0	2.63	.325	1.885
5	12.25	3.56	.347	3.137	5	11.5	3.36	.472	2.032
6	14.75	4.29	.494	3.284	6	8.2	2.39	.200	1.920
6	12.5	3.61	.230	3.330	6	10.5	3.07	.314	2.034
6	14.75	4.29	.343	3.443	6	13.0	3.81	.437	2.157
6	17.25	5.02	.465	3.565	6	15.5	4.54	.559	2.279
7	15.3	4.43	.250	3.660	7	9.8	2.85	.210	2.090
7	17.5	5.09	.345	3.755	7	12.25	3.58	.314	2.194
7	20.0	5.83	.450	3.860	7	14.75	4.32	.419	2.299
8	18.4	5.34	.270	4.000	7	17.25	5.05	.524	2.404
8	20.5	5.97	.349	4.079	7	19.75	5.79	.629	2.509
8	23.0	6.71	.441	4.171	8	11.5	3.36	.260	2.260
					8	13.75	4.02	.303	2.343
8	25.5	7.43	.532	4.262	8	16.25	4.76	.395	2.435
10	25.4	7.38	.447	4.660	8	18.75	5.49	.487	2.527
10	30.0	8.75	.447	4.797	8	21.25	6.23	.579	2.619
10	35.0	10.22	.594	4.944	9	13.4	3.89	.230	2.430
10	40.0	11.69	.741	5.091	9	15.0	4.39	.285	2.485
12	31.8	9.26	.350	5.000	9	20.0	5.86	.448	2.648
12	35.0	10.20	.428	5.078	9	25.0	7.33	.612	2.812
12	40.8	11.84	.460	5.250	10	15.3	4.47	.240	2.600
12	45.0	13.10	.565	5.355	10	20.0	5.86	.379	2.739
12	50.0	14.57	.687	5.477	10	25.0	7.33	.526	2.886
12	55.0	16.04	.810	5.600	10	30.0	8.80	.673	3.033
15	42.9	12.49	.410	5.500	10	35.0	10.27	.820	3.180
15	45.0	13.12	.452	5.542	12	20.7	6.03	.280	2.940
15	50.0	14.59	.550	5.640	12	25.0	7.32	.367	3.047
15	55.0	16.06	.648	5.738	12	30.0	8.79	.510	3.170
15	60.8	17.68	.590	6.000	12	35.0	10.26	.632	3.292
15	65.0	18.91	.672	6.082	12	40.0	11.73	.755	3.415
15	70.0	20.38	.770	6.180	15	33.9	9.90	.400	3.400
15	75.0	21.85	.868	6.278	15	35.0	10.23	.422	3.422
					15	40.0	11.70	.520	3.52
18	54.7	15.94	.460	6.000	15	45.0	13.17	.618	3.618
18	60.0	17.50	.547	6.087	15	50.0	14.64	.716	3.716
18	65.0	18.98	.629	6.169	15	55.0	16.11	.814	3.814
18	70.0	20.46	.711	6.251	18	42.7	12.48	.450	3.950
20	81.4	23.74	.600	7.000	18	45.8	13.38	.500	4.000
20	85.0	24.80	.653	7.053	18	51.9	15.18	.600	4.100
20	90.0	26.26	.726	7.126	18	58.0	16.98	.700	4.200
20	95.0	27.74	.800	7.200					
20	100.0	29.20	.873	7.273	Standard H-Beams				
24	79.9	23.33	.500	7.000	4	13.8	3.99	.313	4.000
24	85.0	24.84	.563	7.063	5	18.9	5.47	.313	5.000
24	90.0	26.30	.624	7.124	6	20.0	5.86	.250	5.938
24	95.0	27.79	.686	7.186	6	22.5	6.61	.375	6.063
24	100.0	29.25	.747	7.247	6	25.0	7.33	.313	5.938
24	105.9	30.98	.825	7.275	6	27.5	8.08	.438	6.063
24	110.0	32.18	.925	7.925	8	32.6	9.50	.313	7.938
24	115.0	33.67	.737	7.987	8	34.3	10.00	.375	8.000
24	120.0	35.13	.798	8.048	8	37.7	11.00	.500	8.125

THEORETICAL WEIGHT OF STEEL PLATES

Size in Inches	Wt. per Square Ft. Lbs.	Size in Inches	Wt. per Square Ft. Lbs.	Size in Inches	Wt. per Square Ft. Lbs.	Size in Inches	Wt. per Square Ft. Lbs.
$\frac{1}{8}$	7.65	1	40.80	2½	102.00	5	204.00
$\frac{1}{4}$	10.20	1½	45.90	2¾	112.20	5½	224.40
$\frac{3}{8}$	12.75	1¾	51.00	3	122.40	6	244.80
$\frac{1}{2}$	15.30	1¾	56.10	3½	132.60	6½	265.20
$\frac{5}{8}$	17.86	1½	61.20	3¾	142.80	7	285.60
$\frac{3}{4}$	20.40	1¾	66.30	4	153.00	7½	306.00
$\frac{7}{8}$	22.96	1¾	71.40	4	163.20	8	326.40
$\frac{1}{2}$	25.50	2	81.60	4¼	173.40	9	367.20
$\frac{3}{4}$	30.60	2¼	91.80	4½	183.60	10	408.00
$\frac{7}{8}$	35.70						

BUILDING MATERIALS

Material	Average Ultimate Stress Pounds per Square Inch			Safe Working Stress Pounds per Square Inch			Modulus of Elasticity Pounds per Sq. In.
	Compres- sion	Tension	Bending	Compres- sion	Tension	Bending	
Masonry, granite.....				420	600		
“ limestone, bluestone.....				350	500		
“ sandstone.....				280	400		
“ rubble.....				140	250		
“ brick, common.....	10000	200	600				
Ropes, cast steel hoisting.....		80000					
“ standing, derrick.....		70000					
“ manila.....		8000					
Stone, bluestone.....	12000	1200	2500	1200	1200	200	7,000,000
“ granite, gneiss.....	12000	1200	1600	1200	1200	200	7 000,000
“ limestone, marble.....	8000	800	1500	800	800	150	7,000,000
“ sandstone.....	5000	150	1200	500	500	150	3,000,000
“ slate.....	10000	3000	5000	1000	1000	175	14,000,000

Galvanized Steel Sheets—Approx. Weight Per Sheet in Pounds

Size of Sheet in Inches	U. S. Standard Gauge											
	10	12	14	16	18	20	22	24	26	27	28	30
24x96				42.5	34.5	26.5	22.5	18.5	14.5	13.5	12.5	10.5
24x120				53.1	43.1	33.1	28.1	23.1	18.1		15.6	13.1
26x96				46.0	37.4	28.7	24.4	20.0	15.7	14.6	13.5	11.4
26x120				57.5	46.7	35.9	30.5	25.0	19.6		16.9	14.2
28x72					30.2	23.2	19.7	16.2	12.7		10.9	
28x84					35.2	27.1	23.0	18.9	14.8		12.8	
28x96				49.6	40.2	30.9	26.2	21.6	16.9	15.7	14.6	12.3
28x108					45.3	34.8	29.5	24.3	19.0		16.4	
28x120				62.0	50.3	38.6	32.8	27.0	21.1	19.7	18.2	15.3
28x144						46.4	39.4	32.4	25.4		21.8	
30x96	115.6	90.6	65.6	53.1	43.1	33.1	28.1	23.1	18.1	16.9	15.6	13.1
30x120	144.5	113.3	82.0	66.4	53.9	41.4	35.2	28.9	22.7	21.1	19.5	16.4
36x96	138.8	108.8	78.8	63.8	51.8	39.8	33.8	27.8	21.8	20.3	18.7	15.8
36x120	173.4	135.9	98.4	79.7	64.7	49.7	42.2	34.7	27.2	25.3	23.4	19.7
42x96	161.8	126.8	91.9	74.4	60.4	46.4	39.4	32.4	25.4			
42x120	202.3	158.7	114.8	93.0	75.5	58.0	49.2	40.5	31.7			
48x96	185.0	145.0	105.0	85.0	69.0	53.0	45.0	37.0				
48x120	231.2	181.2	131.2	106.2	86.2	66.2	56.2	46.2				

Maximum Electrical Carrying Capacity of Pure Copper Wire

American Gauge No.	Circular Millimeters	Current in Amperes	American Gauge No.	Circular Millimeters	Current in Amperes	American Gauge No.	Circular Millimeters	Current in Amperes
0000	211.600	450	7	20.816	75	17	2,048.2	15
000	167.805	375	8	16.509	67.5	18	1,624.3	12
00	133.079.4	315	9	13.094	60	19	1,252.4	9
0	105.592.5	270	10	10.381	45	20	1,021.5	7.5
1	83.694.2	225	11	8.234	37.5	21	810.1	6.75
2	66.373	180	12	6.525.9	30	22	642.7	6
3	52.634	150	13	5.178.4	27	23	509.45	5.25
4	41.742	120	14	4.196.8	24	24	404.01	4.5
5	33.102	105	15	3.256.7	21	25	320.4	3.75
6	26.250.5	90	16	2.582.9	18			

To Compute the Weight of Steel — Divide the thickness expressed in thousands by 25. The result is the weight in pounds per square foot. For weight of sheet brass add 11 per cent. For weight of sheet copper, add 10 per cent.

BOARD MEASURE—

One foot board measure is a piece of wood 12 inches square by 1 inch thick, or 144 cu. ins. 1 cu. ft. therefore, equals 12 feet board measure.

Weights of Steel Angles With Fillet

Per Lineal Foot in Pounds

Size, Inches	1/8	3/16	1/4	5/16	3/8	7/16	1/2	9/16	5/8	11/16	3/4	13/16	7/8	15/16	1	1 1/16	1 1/8
3/4x3/4	.59	.84
1x1	.80	1.16	1.49
1 1/4x1 1/4	1.01	1.48	1.92
1 1/2x1 1/2	1.23	1.80	2.34	2.86	3.35
1 3/4x1 3/4	1.44	2.12	2.77	3.39	4.0
2x1 1/2	1.44	2.12	2.77	3.39	3.99
2x2	1.65	2.44	3.19	3.92	4.7	5.3	6.0
2 1/4x2 1/4	1.86	2.75	3.62	4.5	5.3	6.1
2 1/2x2 1/2	1.86	2.75	3.62	4.5	5.3	6.1	6.8
2 3/4x2 3/4	2.08	3.07	4.1	5.0	5.9	6.8	7.7
3x2	3.07	4.1	5.0	5.9	6.8	7.7
3x2 1/2	3.39	4.5	5.6	6.6	7.6	8.5	9.5
3x3	2.50	3.70	4.9	6.1	7.2	8.3	9.4	10.4	11.5
3 1/2x2 1/2	4.9	6.1	7.2	8.3	9.4	10.4	11.5	12.5
3 1/2x3	5.4	6.6	7.9	9.1	10.2	11.4	12.5	13.6	14.7	15.8	16.8
3 1/2x3 1/2	5.8	7.2	8.5	9.8	11.1	12.4	13.6	14.8	16.0	17.1	18.3
4x3	5.8	7.2	8.5	9.8	11.1	12.4	13.6	14.8	16.0	17.1	18.3
4x3 1/2	6.2	7.7	9.1	10.6	11.9	13.3	14.7	16.0
4x4	6.6	8.2	9.8	11.3	12.8	14.3	15.7	17.1	18.5	19.9	21.2
5x3	8.2	9.8	11.3	12.8	14.3	15.7	17.1	18.5	19.9	21.2
5x3 1/2	8.7	10.4	12.0	13.6	15.2	16.8	18.3	19.8	21.3	22.7	24.2
5x4	11.0	12.8	14.5	16.2	17.8	19.5
5x5	12.3	14.3	16.2	18.1	20.0	21.8
6x3 1/2	9.8	11.7	13.5	15.3	17.1	18.9	20.6	22.4	24.0	25.7	27.3	28.9
6x4	10.3	12.3	14.3	16.2	18.1	20.0	21.8	23.6	25.4	27.2	28.9	30.6
6x6	14.9	17.2	19.6	21.9	24.2	26.5	28.7	31.0	33.1	35.3	37.4
7x4	13.6	15.8	17.9	20.0	22.1	24.2	26.2	28.2	30.2	32.1	34.0
8x4	17.2	19.6	21.9	24.2	26.5	28.7	31.0	33.1	35.3	37.4
8x6	20.2	23.0	25.7	28.5	31.2	33.8	36.5	39.1	41.7	44.2
8x8	26.4	29.6	32.7	35.8	38.9	42.0	45.0	48.1	51.0	54.0	56.9

STANDARD WROUGHT WASHERS

Packed in 200-Pound Kegs

Outside Diameter	Size of Hole	Thickness Wire Gauge		Size of Bolt	Number Per 100 Pounds	Weight Per 1000 Pieces
		Number	Inches			Pounds
9/16	1/4	18	3/64	3/16	27,800	3.6
3/4	5/16	16	1/16	1/4	15,600	6.4
7/8	3/8	16	1/16	5/16	11,250	8.8
1	7/16	14	5/64	3/8	6,800	14.7
1 1/4	1/2	14	5/64	7/16	4,300	23.
1 3/8	9/16	12	3/32	1/2	2,600	38.4
1 1/2	5/8	12	3/32	9/16	2,250	44.4
1 3/4	11/16	10	1/8	5/8	1,300	77.
2	13/16	9	5/32	3/4	900	111.
2 1/4	15/16	8	11/64	7/8	782	130.
2 1/2	1 1/16	8	11/64	1	568	176.
2 3/4	1 1/4	8	11/64	1 1/8	473	211.
3	1 3/8	8	11/64	1 1/4	364	272.
3 1/4	1 1/2	7	3/16	1 3/8	275	364.
3 1/2	1 5/8	7	3/16	1 1/2	256	390.
3 3/4	1 3/4	7	3/16	1 5/8	220	454.
4	1 7/8	7	3/16	1 3/4	197	508.
4 1/4	2	7	3/16	1 7/8	174	575.
4 1/2	2 1/8	7	3/16	2	160	625.
4 3/4	2 3/8	5	7/32	2 1/4	122	820.
5	2 5/8	4	15/64	2 1/2	106	943

Weights of Materials

The weights given represent averages for standards of various states, as given in circulars issued by the United States Government, and are also compiled from those given by Cambria.

They represent, in many cases, the weights of materials as settled or packed in bins, while lower weights should generally be figured for materials as slightly agitated or fluffed by handling in elevators, screw conveyors, etc.

Material	Average Weight of One Cu. Ft., Pounds	Specific Gravity Water = 1.	Material	Average Weight of One Cu. Ft., Pounds	Specific Gravity Water = 1.
Alcohol, proof spirit.....	58	.79	Gold, pure cast, 24K.....	1206	19.32
Aluminum, cast, pure.....	160	2.55	Granite, solid.....	166	2.65
Anthracite, broken, loose.....	55	1.5	Granite, broken.....	96
Asbestos.....	175	2.8	Gravel.....	100	1.75
Ash, American White, dry (wood).....	47	.75	Gypsum, under 1" Crushed.....	80 to 100
Ashes of soft coal, solidly packed.....	40	Gypsum, powdered.....	60 to 80	2.2
Asphaltum.....	87	1.4	Hay, baled.....	24
Barley.....	38	Hemlock, perfectly dry.....	25	.40
Barytes.....	180	Hides green, 85 pounds each.....
Batch, Glass.....	90	Hickory, perfectly dry.....	50	.80
Beans.....	48	Ice.....	56	.90
Benzine.....	50	.85	Iron, cast.....	446	7.15
Bauxite, Crushed.....	80	Iron, wrought.....	480	7.69
Bran.....	16	Lead, commercial.....	709.6	11.38
Brass (copper and zinc), cast.....	519	(8.20 to 8.60)	Lignumvitae (dry).....	41 to 83	.66 to 1.3
Brick, best pressed.....	134	2.15	Limestone, loose.....	96	2.6
Brick, common and hard.....	112-125	Lime, quick.....	95	1.5
Brick, fire.....	144	Lime, quick, ground, well shaken.....	64
Brickwork, cement.....	112	Lime, hydrated.....	20 to 45
Bronze, copper 8, tin 1 (gun metal).....	552	8.85	Locust, dry.....	46	.73
Cedar.....	24	.57	Magnesium.....	109	1.75
Cement, Portland, per barrel, net, 376 pounds.....	100	1.6	Mahogany.....	56	.90
Cement, Portland, standard proportioning.....	100	1.6	Manganese.....	500
Chalk.....	156	2.5	Maple, dry.....	44	.70
Char.....	45	Marble, crushed.....	90	2.6
Charcoal of pines and oaks.....	20 to 38	Marl.....	79
Cherry, perfectly dry.....	44	.70	Oak, live, perfectly dry, .88 to 1.02.....	72	1.15
Chestnut wood, dry.....	38	.60	Oak, white, perfectly dry.....	50	.80
Cinder, blast furnace.....	57	Oats.....	26
Cinders (coal, ashes and clinkers).....	40	.64	Oil, linseed.....	59	.94
Clay, dry, in lump, loose.....	75	Oil, petroleum.....	51	.82
Clinker, cement.....	80 to 95	Oil, olive and whale.....	58	.92
Coal, bituminous, solid.....	84	1.27	Ore, zinc, crushed.....	160
Coal, Bituminous, broken, of any size, piled.....	44 to 52	Ore, soft iron.....	150
Coal, Steam.....	50	Oxide, Iron Sponge.....	28 to 50
Coke, Breeze.....	25-34	Phosphate acid.....	62
Coke, Refiners.....	35-40	Phosphate Pebble.....	100
Coke, loose, good quality.....	23 to 32	Phosphate rock.....	85
Concrete, conglomerate, with Portland cement.....	143-150	Pine, white, perfectly dry.....	32	.50
Concrete, gravel, with Portland cement.....	150	2.4	Pine, Yellow Southern, perfectly dry.....	41	.65
Concrete, loose, unrammed, weighs 5 to 25% lighter, varying with consistency.....	Poplar, dry.....	32	.50
Copper, cast.....	542	8.7	Quartz.....	90 to 100
Copper, rolled.....	555	8.9	Salt, coarse.....	45
Corn, Shelled.....	45	.64	Salt, dry, fines.....	80
Corn, meal.....	40	.64	Sand, damp.....	117 to 130
Cork, dry.....	15	.24	Sand, dry.....	90 to 110
Cotton seed.....	25	Sandstone, quarried and piled.....	86
Cotton seed cake, cracked.....	41	Sawdust.....	13
Cotton seed hulls.....	12	Shales.....	92
Cotton seed meal.....	35	Slag.....	160 to 180
Cullet.....	80 to 120	Slag, furnace, granulated.....	53
Cypress.....	38	.60	Slate.....	175	2.8
Earth, common loam, perfectly dry, loose.....	72 to 80	1.2	Slurry, cement.....	90
Earth, common loam, perfectly dry, shaken.....	82 to 92	1.2	Soda.....	42
Elm, perfectly dry.....	42	.67	Soda ash.....	32 to 67
Feldspar, powdered.....	75	Spruce, dry.....	25	.40
Fir.....	35	.55	Steel.....	486.5	7.80
Flax seed.....	45	Straw, baled.....	24
Flour, 196 pounds per barrel, net.....	35 to 40	Sugar, refined.....	55
Fullers earth.....	35 to 45	Sulphur.....	125	2.0
Glass.....	163	2.6	Tar.....	62.4	1.0
			Tin, cast, 72.....	455	7.29
			Trap rock, crushed.....	97 to 107	3.0
			Turpentine, 300 pounds per barrel.....87
			Walnut, Black, perfectly dry (see note below).....	41	.65
			Water, pure rain, distilled, at 32 degrees F., Bar. 30 inches.....	62.417	1.00
			Water, sea.....	64.08	1.03
			Wheat.....	48
			Zinc or Spelter, cast.....	428	6.86

Cotton Bales, Weight 500 lbs.

Full Bale, not compressed, size, 27"x54"x42".

Full Bale, compressed, size, 27"x54"x18".

The sizes of cotton bales vary according to the baling machine used, and amount of compression. A fair average is given above.

STRUCTURAL TIMBER COLUMNS

ALLOWABLE UNIT STRESSES

POUNDS PER SQUARE INCH

FOREST PRODUCTS LABORATORY, DEPARTMENT OF AGRICULTURE

Species of Timber	American Standard Grade	Ratio of Length to Least Dimension (L/d)									
		10 and Less	12	14	16	18	20	25	30	35	40
Ash, Commercial White.....	Select	1100	1076	1055	1023	978	913	656	457	336	267
	Common	880	868	857	810	784	747				
Cedar, Western Red Fir, Balsam.....	Select	700	686	674	656	629	592	538	384	224	171
	Common	560	553	547	538	524	505	425			
Cedar, Northern and Southern White.....	Select	550	540	530	516	496	468	351	244	179	137
	Common	440	435	430	425	412	398	338			
Chestnut, Pine, Northern White, Idaho White, Sugar, Calif. White, and Ponderosa.....	Select	750	733	718	695	663	617	538	364	224	171
	Common	600	591	583	572	556	532	434			
Cypress, Southern; Larch, Western.....	Select	1100	1063	1030	981	909	810	526	365	268	208
	Common	880	861	843	818	781	729				
Douglas Fir (Coast Region); Pine, Southern Yellow; Beech; Birch, Yellow and Sweet; Maple, Sugar.....	Dense } Select } Common	1285	1251	1222	1176	1112	1022	702	487	358	274
		1175	1149	1127	1093	1045	975	702	487	358	274
		880	870	861	847	826	796	675			
Douglas Fir (Rocky Mtn. Region); Spruce, Red, White, Sitka; Norway Pine; Alaska Cedar; Elm; Slippery and White; Sycamore; Gum, Red and Black; Tupelo	Select	800	786	774	753	726	688	526	365	268	208
	Common	640	632	627	617	602	582	500			
Hemlock, West Coast.....	Select	900	885	872	852	823	783	614	426	313	240
	Common	720	712	706	696	686	660	573			
Hemlock, Eastern; Fir, Commercial White.....	Select	700	689	678	664	641	611	482	335	246	188
	Common	560	554	549	542	530	515	449			
Oak, White and Red.....	Select	1000	982	967	943	908	860	658	457	336	267
	Common	800	790	783	771	753	728	625			
Redwood.....	Select	1000	972	947	910	856	781	526	365	268	208
	Common	800	786	773	754	726	688				
Spruce, Englemann.....	Select	680	586	574	556	530	494	351	244	179	137
	Common	480	473	466	457	444	426	347			
Tamarack.....	Select	1000	976	955	923	877	817	570	395	291	223
	Common	800	789	777	761	737	706	560			

No column shall be used in which the unsupported length is more than 50 times the least diameter of the column. For wet lumber, the allowable unit stresses should be reduced 25 per cent. The strength of wood is influenced considerably by its moisture content. The above values are based on the recommendations of the Forest Products Laboratory.

TIMBER

AMERICAN STANDARD SIZES

PROPERTIES FOR DESIGNING

NATIONAL LUMBER MANUFACTURERS ASSOCIATION

Nominal Size	American Standard Dressed Size	Area of Section	Weight per Foot	Moment of Inertia	Section Modulus	Nominal Size		American Standard Dressed Size	Area of Section	Weight per Foot	Moment of Inertia	Section Modulus
						In.	In.					
2 x 4	1 5/8 x 3 5/8	5.69	1.64	6.45	3.56	10x10	9 1/2 x 9 1/2	90.3	25.0	679	143	104
6 x 6	5 1/2 x 5 1/2	22.2	2.54	24.4	8.57	12	11 1/2 x 11 1/2	129	30.3	1204	209	136
8 x 8	7 1/2 x 7 1/2	42.4	4.29	42.4	15.3	14	13 1/2 x 13 1/2	188	35.6	1948	289	152
10 x 10	9 1/2 x 9 1/2	87.1	8.71	87.1	31.2	16	15 1/2 x 15 1/2	240	40.9	2948	380	168
12 x 12	11 1/2 x 11 1/2	144	14.4	144	46.1	18	17 1/2 x 17 1/2	324	46.1	4243	485	176
14 x 14	13 1/2 x 13 1/2	210	21.0	210	66.1	20	19 1/2 x 19 1/2	400	51.7	5870	602	184
16 x 16	15 1/2 x 15 1/2	281	28.1	281	88.4	22	21 1/2 x 21 1/2	484	56.7	7868	732	192
18 x 18	17 1/2 x 17 1/2	354	35.4	354	111	24	23 1/2 x 23 1/2	564	62.0	10274	874	200
20 x 20	19 1/2 x 19 1/2	434	43.4	434	136	26	25 1/2 x 25 1/2	648	67.7	12437	1058	208
22 x 22	21 1/2 x 21 1/2	518	51.8	518	162	28	27 1/2 x 27 1/2	732	73.5	15093	1283	216
24 x 24	23 1/2 x 23 1/2	606	60.6	606	188	30	29 1/2 x 29 1/2	816	79.9	17859	1483	224
26 x 26	25 1/2 x 25 1/2	698	69.8	698	214	32	31 1/2 x 31 1/2	900	86.2	20826	1708	232
28 x 28	27 1/2 x 27 1/2	794	79.4	794	240	34	33 1/2 x 33 1/2	984	92.7	23909	1943	240
30 x 30	29 1/2 x 29 1/2	894	89.4	894	266	36	35 1/2 x 35 1/2	1068	99.2	27100	2198	248
32 x 32	31 1/2 x 31 1/2	998	99.8	998	292	38	37 1/2 x 37 1/2	1152	106	30408	2463	256
34 x 34	33 1/2 x 33 1/2	1106	110.6	1106	318	40	39 1/2 x 39 1/2	1236	113	33824	2738	264
36 x 36	35 1/2 x 35 1/2	1218	121.8	1218	344	42	41 1/2 x 41 1/2	1320	120	37356	3023	272
38 x 38	37 1/2 x 37 1/2	1334	133.4	1334	370	44	43 1/2 x 43 1/2	1404	127	41004	3318	280
40 x 40	39 1/2 x 39 1/2	1454	145.4	1454	396	46	45 1/2 x 45 1/2	1488	134	44778	3623	288
42 x 42	41 1/2 x 41 1/2	1578	157.8	1578	422	48	47 1/2 x 47 1/2	1572	141	48678	3938	296
44 x 44	43 1/2 x 43 1/2	1706	170.6	1706	448	50	49 1/2 x 49 1/2	1656	148	52704	4263	304
46 x 46	45 1/2 x 45 1/2	1838	183.8	1838	474	52	51 1/2 x 51 1/2	1740	155	56856	4598	312
48 x 48	47 1/2 x 47 1/2	1974	197.4	1974	500	54	53 1/2 x 53 1/2	1824	162	61134	4943	320
50 x 50	49 1/2 x 49 1/2	2114	211.4	2114	526	56	55 1/2 x 55 1/2	1908	169	65538	5298	328
52 x 52	51 1/2 x 51 1/2	2258	225.8	2258	552	58	57 1/2 x 57 1/2	2000	176	70068	5663	336
54 x 54	53 1/2 x 53 1/2	2406	240.6	2406	578	60	59 1/2 x 59 1/2	2088	183	74724	6038	344
56 x 56	55 1/2 x 55 1/2	2558	255.8	2558	604	62	61 1/2 x 61 1/2	2176	190	79506	6423	352
58 x 58	57 1/2 x 57 1/2	2714	271.4	2714	630	64	63 1/2 x 63 1/2	2264	197	84414	6818	360
60 x 60	59 1/2 x 59 1/2	2874	287.4	2874	656	66	65 1/2 x 65 1/2	2352	204	89448	7223	368
62 x 62	61 1/2 x 61 1/2	3038	303.8	3038	682	68	67 1/2 x 67 1/2	2440	211	94608	7638	376
64 x 64	63 1/2 x 63 1/2	3206	320.6	3206	708	70	69 1/2 x 69 1/2	2528	218	99894	8063	384
66 x 66	65 1/2 x 65 1/2	3378	337.8	3378	734	72	71 1/2 x 71 1/2	2616	225	105306	8498	392
68 x 68	67 1/2 x 67 1/2	3554	355.4	3554	760	74	73 1/2 x 73 1/2	2704	232	110844	8943	400
70 x 70	69 1/2 x 69 1/2	3734	373.4	3734	786	76	75 1/2 x 75 1/2	2792	239	116508	9398	408
72 x 72	71 1/2 x 71 1/2	3918	391.8	3918	812	78	77 1/2 x 77 1/2	2880	246	122298	9863	416
74 x 74	73 1/2 x 73 1/2	4106	410.6	4106	838	80	79 1/2 x 79 1/2	2968	253	128214	10338	424
76 x 76	75 1/2 x 75 1/2	4298	429.8	4298	864	82	81 1/2 x 81 1/2	3056	260	134256	10813	432
78 x 78	77 1/2 x 77 1/2	4494	449.4	4494	890	84	83 1/2 x 83 1/2	3144	267	140424	11298	440
80 x 80	79 1/2 x 79 1/2	4694	469.4	4694	916	86	85 1/2 x 85 1/2	3232	274	146718	11793	448
82 x 82	81 1/2 x 81 1/2	4898	489.8	4898	942	88	87 1/2 x 87 1/2	3320	281	153138	12298	456
84 x 84	83 1/2 x 83 1/2	5106	510.6	5106	968	90	89 1/2 x 89 1/2	3408	288	159684	12813	464
86 x 86	85 1/2 x 85 1/2	5318	531.8	5318	994	92	91 1/2 x 91 1/2	3496	295	166356	13338	472
88 x 88	87 1/2 x 87 1/2	5534	553.4	5534	1020	94	93 1/2 x 93 1/2	3584	302	173154	13873	480
90 x 90	89 1/2 x 89 1/2	5754	575.4	5754	1046	96	95 1/2 x 95 1/2	3672	309	180078	14418	488
92 x 92	91 1/2 x 91 1/2	5978	597.8	5978	1072	98	97 1/2 x 97 1/2	3760	316	187128	14973	496
94 x 94	93 1/2 x 93 1/2	6206	620.6	6206	1100	100	99 1/2 x 99 1/2	3848	323	194304	15538	504
96 x 96	95 1/2 x 95 1/2	6438	643.8	6438	1126	102	101 1/2 x 101 1/2	3936	330	201606	16113	512
98 x 98	97 1/2 x 97 1/2	6674	667.4	6674	1152	104	103 1/2 x 103 1/2	4024	337	209034	16698	520
100 x 100	99 1/2 x 99 1/2	6914	691.4	6914	1178	106	105 1/2 x 105 1/2	4112	344	216688	17293	528
102 x 102	101 1/2 x 101 1/2	7158	715.8	7158	1204	108	107 1/2 x 107 1/2	4200	351	224460	17898	536
104 x 104	103 1/2 x 103 1/2	7406	740.6	7406	1230	110	109 1/2 x 109 1/2	4288	358	232350	18503	544
106 x 106	105 1/2 x 105 1/2	7658	765.8	7658	1256	112	111 1/2 x 111 1/2	4376	365	240360	19118	552
108 x 108	107 1/2 x 107 1/2	7914	791.4	7914	1282	114	113 1/2 x 113 1/2	4464	372	248490	19743	560
110 x 110	109 1/2 x 109 1/2	8174	817.4	8174	1308	116	115 1/2 x 115 1/2	4552	379	256740	20378	568
112 x 112	111 1/2 x 111 1/2	8438	843.8	8438	1334	118	117 1/2 x 117 1/2	4640	386	265110	21013	576
114 x 114	113 1/2 x 113 1/2	8706	870.6	8706	1360	120	119 1/2 x 119 1/2	4728	393	273600	21658	584
116 x 116	115 1/2 x 115 1/2	8978	897.8	8978	1386	122	121 1/2 x 121 1/2	4816	400	282210	22313	592
118 x 118	117 1/2 x 117 1/2	9254	925.4	9254	1412	124	123 1/2 x 123 1/2	4904	407	290940	22968	600
120 x 120	119 1/2 x 119 1/2	9534	953.4	9534	1438	126	125 1/2 x 125 1/2	4992	414	300000	23623	608
122 x 122	121 1/2 x 121 1/2	9818	981.8	9818	1464	128	127 1/2 x 127 1/2	5080	421	309210	24278	616
124 x 124	123 1/2 x 123 1/2	10106	1010.6	10106	1490	130	129 1/2 x 129 1/2	5168	428	318570	24933	624
126 x 126	125 1/2 x 125 1/2	10398	1039.8	10398	1516	132	131 1/2 x 131 1/2	5256	435	328080	25598	632
128 x 128	127 1/2 x 127 1/2	10694	1069.4	10694	1542	134	133 1/2 x 133 1/2	5344	442	337740	26263	640
130 x 130	129 1/2 x 129 1/2	10994	1099.4	10994	1568	136	135 1/2 x 135 1/2	5432	449	347400	26938	648
132 x 132	131 1/2 x 131 1/2	11298	1129.8	11298	1594	138	137 1/2 x 137 1/2	5520	456	357060	27613	656
134 x 134	133 1/2 x 133 1/2	11606	1160.6	11606	1620	140	139 1/2 x 139 1/2	5608	463	366720	28288	664
136 x 136	135 1/2 x 135 1/2	11914	1191.4	11914	1646	142	141 1/2 x 141 1/2	5696	470	376380	28963	672
138 x 138	137 1/2 x 137 1/2	12222	1222.2	12222	1672	144	143 1/2 x 143 1/2	5784	477	386040	29638	680
140 x 140	139 1/2 x 139 1/2	12530	1253.0	12530	1698	146	145 1/2 x 145 1/2	5872	484	395700	30313	688
142 x 142	141 1/2 x 141 1/2	12838	1283.8	12838	1724	148	147 1/2 x 147 1/2	5960	491	405360	30988	696
144 x 144	143 1/2 x 143 1/2	13146	1314.6	13146	1750	150	149 1/2 x 149 1/2	6048	498	415020	31663	704
146 x 146	145 1/2 x 145 1/2	13454	1345.4	13454	1776	152	151 1/2 x 151 1/2	6136	505	424680	32338	712
148 x 148	147 1/2 x 147 1/2	13762	1376.2	13762	1802	154	153 1/2 x 153 1/2	6224	512	434340	33013	720
150 x 150	149 1/2 x 149 1/2	14070	1407.0	14070	1828	156	155 1/2 x 155 1/2	6312	519	444000	33688	728
152 x 152	151 1/2 x 151 1/2	14378	1437.8	14378	1854	158	157 1/2 x 157 1/2	6400	526	453660	34363	736
154 x 154	153 1/2 x 153 1/2	14686	1468.6	14686	1880	160	159 1/2 x 159 1/2	6488	533	463320	35038	744
156 x 156	155 1/2 x 155 1/2	14994	1499.4	14994	1906	162	161 1/2 x 161 1/2	6576	540	472980	35713	752
158 x 158	157 1/2 x 157 1/2	15302	1530.2	15302	1932	164	163 1/2 x 163 1/2	6664	547	482640	36388	760
160 x 160	159 1/2 x 159 1/2	15610	1561.0	15610	1958	166	165 1/2 x 165 1/2	6752	554	492300	37063	768
162 x 162	161 1/2 x 161 1/2	15918	1591.8	15918	1984	168	167 1/2 x 167 1/2	6840	561	501960	37738	776
164 x 164	163 1/2 x 163 1/2	16226	1622.6	16226	2010	170	169 1/2 x 169 1/2	6928	568	511620	38413	784
166 x 166	165 1/2 x 165 1/2	16534	1653.4	16534	2036	172	171 1/2 x 171 1/2	7016	575	521280	39088	792
168 x 168	167 1/2 x 167 1/2	16842	1684.2	16842	2062	174	173 1/2 x 173 1/2	7104	582	530940	39763	800
170 x 170	169 1/2 x 169 1/2	17150	1715.0	17150	2088	176	175 1/2 x 175 1/2	7192	589	540600	40438	808
172 x 1												

SPECIFIC GRAVITY AND WEIGHT OF SOLID SUBSTANCES, EXCEPT METALS AND WOOD

Substance	Specific Gravity	Average Weight, Lb. per Cu. Ft.	Substance	Specific Gravity	Average Weight, Lb. per Cu. Ft.
Asbestos	2.1-2.8	153	Hornblende	3.2-3.52	210
Ashes		43	Ice	0.88-0.92	55-57
Asphaltum	1.39	87	Leather	0.86-1.02	59
Barytes	4.50	281	Lime, quick, in bulk	0.8-0.96	55
Basalt	2.7-3.2	184	Limestone	2.3-2.9	160
Bauxite	2.55	159	Magnesia, carbonate	2.4	150
Bluestone	2.2-2.5	147	Magnesite	3.0	187
Brick, soft	1.6	100	Marble	2.56-2.88	170
Brick, common	1.79	112	Masonry, dry, rubble	2.24-2.56	150
Brick, hard	2.0	125	Masonry, dressed	2.24-2.88	160
Brick, pressed	2.16	135	Mica	2.80	175
Brick, fire	2.24-2.4	145	Mortar	1.44-1.6	99
Brick, sand-lime	2.18	136	Mud	1.7-1.8	111
Brickwork, mortar	1.6	100	Paper	0.70-1.15	58
Brickwork, cement	1.79	112	Paraffin	0.87-0.91	56
Borax	1.7-1.8	112	Peat	0.65-0.85	47
Cement, American, natural	2.8-3.2	187	Phosphate rock	3.2	200
Cement, Portland	3.05-3.15	190	Pitch	1.15	72
Cement, Portland loose	1.44	92	Plaster-of-Paris	1.5-1.8	103
Cement, Portland barreled	1.84	115	Porcelain	2.3-2.5	250
Cement, slag	1.9-2.3	130	Porphyry	2.6-2.9	172
Chalk	1.8-2.6	137	Pumice	0.37-0.90	40
Clay	1.92-2.4	137	Riprap, limestone	1.3-1.4	80-85
Coal, anthracite	1.4-1.8	97	Riprap, sandstone	1.4	90
Coal, bituminous	1.2-1.5	84	Riprap, shale	1.7	105
Coal, lignite	1.1-1.4	78	Rubber, caoutchouc	0.92-0.96	59
Coal, charcoal	0.27-0.58	18	Rubber, manufactured	1.0-2.0	95
Coke	1.0-1.4	22-27	Salt	0.77	48
Concrete	1.92-2.48	133	Salt-peter	1.07	67
Cork	0.22-0.26	15	Sand	1.44-1.76	100
Dolomite	2.9	181	Sand wet	1.89-2.07	125
Earth, dry, loose	1.2	75	Sandstone	2.24-2.4	145
Earth, dry, packed	1.5	93	Serpentine	2.4-2.7	165
Earth, moist, loose	1.3	81	Shale	2.6-2.9	172
Earth, moist, packed	1.6	100	Slag, bank	1.1-1.2	69
Earth, mud, flowing	1.7	106	Slag, bank screenings	1.5-1.9	107
Earth, mud, packed	1.8	112	Slag, machine	1.5	96
Emery	4.0	250	Slag, sand	0.8-0.9	53
Feldspar	2.5-2.6	159	Slate	2.72-2.88	175
Glass, common	2.5-2.75	164	Soapstone	2.65-2.8	170
Glass, crystal	2.90-3.00	184	Starch	1.53	96
Glass, flint	2.9-2.31	188	Stone, various	2.16-3.4	135-200
Glass, plate	2.45-2.72	161	Stone, crushed	1.6	100
Gneiss	2.4-2.7	165	Sulphur	1.93-2.07	125
Granite	2.5-3.1	179	Talc	2.6-2.8	169
Graphite	1.9-2.3	126	Tar, bituminous	1.20	75
Gravel, dry, loose	1.4-1.7	90-105	Terra-cotta	1.9	119
Gravel, dry, packed	1.6-1.9	100-120	Tile	1.76-1.92	115
Gravel, wet	1.9	120	Trap rock	2.72-3.4	185
Greenstone	2.8-3.2	187	Wool	1.32	82
Gypsum	2.08-2.4	140			

MELTING POINT OF SUBSTANCES

Substance.	Melts °F.	Substance.	Melts °F.	Substance.	Melts °F.
Asphaltum	210	Nitroglycerine	45	Spermaceti	120
Bees-wax	154	Paraffine	130	Stearine	128
Ice	32	Phosphorous	112	Sulphur	239
Iodine	225	Rosin	175	Water freezes	32
Mercury	39	Selenium	442	Tallow	92

WEIGHTS AND SPECIFIC GRAVITY OF METALS

Metals, Etc.	Weight, per Cubic in. lb.	Weight, per Cubic Ft. Lbs.	Specific Gravity	Melting Point Deg. F.
Aluminum.....	0.0924	159.7	2.67	1218
Antimony.....	0.2422	418.7	6.71	1166
Barium.....	0.1354	234.0	3.75	1562
Bismuth.....	0.3538	611.5	9.80	520
Boron.....	0.0939	162.2	2.60	4000-4500
Brass.....	0.3032	524.1	8.40	1700-1850
Bronze.....	0.3195	552.2	8.85	1675
Cadmium.....	0.3105	536.6	8.60	610
Calcium.....	0.0567	98.0	1.57	1490
Chromium.....	0.2347	405.6	6.50	2939
Cobalt.....	0.3123	539.8	8.65	2696
Copper.....	0.3184	550.4	8.82	1981
Gold.....	0.6975	1205.6	19.32	1945
Iridium.....	0.8094	1399.0	22.42	4260
Iron Cast.....	0.2600	449.2	7.20	2300
Iron Wrought.....	0.2834	489.8	7.85	2750
Lead.....	0.4105	709.5	11.37	620
Magnesium.....	0.0628	108.6	1.74	1204
Manganese.....	0.2679	463.0	7.42	2246
Mercury.....	0.4902	847.4	13.58	-38
Molybdenum.....	0.3090	534.2	8.56	4620
Nickel.....	0.3177	549.1	8.80	2646
Platinum Rolled.....	0.8184	1414.6	22.67	3191
Platinum Wire.....	0.7595	1312.9	21.04	3191
Potassium.....	0.0314	54.3	0.87	144
Silver.....	0.3802	657.1	10.53	1761
Sodium.....	0.0354	61.1	0.98	207
Steel.....	0.2816	486.7	7.80	2500
Tellurium.....	0.2256	390.0	6.25	846
Tin.....	0.2632	454.8	7.29	449
Titanium.....	0.1278	220.9	3.54	3272
Tungsten.....	0.6776	1171.2	18.77	6152
Vanadium.....	0.1986	343.2	5.50	3128
Zinc Cast.....	0.2476	428.1	6.86	787
Zinc Rolled.....	0.2581	446.1	715	787

SPECIFIC GRAVITY OF LIQUIDS

Liquid	Specific Gravity	Liquid	Specific Gravity	Liquid	Specific Gravity
Acetic acid.....	1.06	Fluoric acid.....	1.50	Petroleum oil.....	0.82
Alcohol, commercial.....	0.83	Gasoline.....	0.70	Phosphoric acid.....	1.78
Alcohol, pure.....	0.79	Kerosene.....	0.80	Rape oil.....	0.92
Ammonia.....	0.89	Linseed oil.....	0.94	Sulphuric acid.....	1.84
Benzene.....	0.69	Mineral oil.....	0.92	Tar.....	1.00
Bromine.....	2.97	Muriatic acid.....	1.20	Turpentine oil.....	0.87
Carbolic acid.....	0.96	Naphtha.....	0.76	Vinegar.....	1.08
Carbon disulphide.....	1.26	Nitric acid.....	1.22	Water.....	1.00
Cotton-seed oil.....	0.93	Olive oil.....	0.92	Water, sea.....	1.03
Ether, sulphuric.....	0.72	Palm oil.....	0.97	Wale oil.....	0.92

MELTING POINTS OF COMMON METALS

Metal	° Fahr.	Metal	° Fahr.	Metal	° Fahr.
Mercury.....	-38	Gold.....	1945	Platinum.....	3191
Sulphur (Sl).....	236	Copper.....	1981	Molybdenum.....	4595
Tin.....	450	Manganese.....	2300	Tantalum.....	5252
Bismuth.....	520	Silicon.....	2588	Tungsten.....	6152
Cadmium.....	610	Nickel.....	2646	Carbon.....	6332
Lead.....	621	Cobalt.....	2696	Brass.....	1700-1850
Zinc.....	787	Chromium.....	2768	Bronze.....	1675
Antimony.....	1166	Iron.....	2786	Solder (50-50).....	450
Magnesium.....	1204	Palladium.....	2820	Babbitt Metals.....	350-450
Aluminum.....	1218	Zirconium.....	3090	Zinc Die Casting Alloy.....	715-720
Silver.....	1761	Vanadium.....	3128		

Different Standards for Wire Gauge IN USE IN THE UNITED STATES

Dimensions of Sizes in Decimal Parts of an Inch

No. of Wire Gauge	Brown & Sharpe	Birmingham, or Stubs' Iron Wire	Washburn & Moen	Stubs' Steel Wire	U. S. Standard for Plate	Musical Wire (A. S. & W. Co.)	Zinc Gauge
000000	.58000461546875	.004
00000	.51650	.500	.43054375	.005
0000	.46000	.454	.393840625	.006
000	.40964	.425	.3625375	.007
00	.36480	.38	.331034375	.008
0	.32486	.34	.30653125	.009
1	.28930	.3	.2830	.227	.28125	.010
2	.25763	.284	.2625	.219	.265625	.011
3	.22942	.259	.2437	.212	.25	.012	.006
4	.20431	.238	.2253	.207	.234375	.013	.008
5	.18194	.22	.2070	.204	.21875	.014	.010
6	.16202	.203	.1920	.201	.203125	.016	.012
7	.14428	.18	.1770	.199	.1875	.018	.014
8	.12849	.165	.1620	.197	.171875	.020	.016
9	.11443	.148	.1483	.194	.15625	.022	.018
10	.10189	.134	.1350	.191	.140625	.024	.020
11	.090742	.12	.1205	.188	.125	.026	.024
12	.080808	.109	.1055	.185	.109375	.029	.028
13	.071961	.095	.0915	.182	.09375	.031	.032
14	.064084	.083	.0800	.180	.078125	.033	.036
15	.057068	.072	.0720	.178	.0703125	.035	.040
16	.050820	.065	.0625	.175	.0625	.037	.045
17	.045257	.058	.0540	.172	.05625	.039	.050
18	.040303	.049	.0475	.168	.05	.041	.055
19	.035890	.042	.0410	.164	.04375	.043	.060
20	.031961	.035	.0343	.161	.0375	.045	.070
21	.028462	.032	.03175	.157	.034375	.047	.080
22	.025347	.028	.0286	.155	.03125	.049	.090
23	.022571	.025	.0258	.153	.028125	.051	.100
24	.020100	.022	.0230	.151	.025	.055	.125
25	.017900	.02	.0204	.148	.021875	.059
26	.015940	.018	.0181	.146	.01875	.063
27	.014195	.016	.0173	.143	.0171875	.067
28	.012641	.014	.0162	.139	.015625	.071
29	.011257	.013	.0150	.134	.0140625	.075
30	.010025	.012	.0140	.127	.0125	.080
31	.008928	.01	.0132	.120	.0109375	.085
32	.007950	.009	.0128	.115	.01015625	.090
33	.007080	.008	.0118	.112	.009375	.095
34	.006304	.007	.0104	.110	.00859375	.098
35	.005614	.005	.0095	.108	.0078125
36	.005000	.004	.0090	.106	.00703125
37	.0044530085	.103	.00640625
38	.0039650080	.101	.00625
39	.0035310075	.099
40	.0031440070	.097

To Copper the Surface of Iron and Steel Wire—
Have the wire perfectly clean, then wash with the following solution, when it will present at once, a coppered face: Rain water, three pounds; sulphate of copper, one pound.




Standard Gauges — Sheets, Plates and Wire

		Thickness and Weight of Sheets and Plates						Thickness of Wire	
	Number of Gauge	U.S. Standard Gauge Adopted by U. S. Government July 1, 1893		Birmingham or Stubs' Gauge		American or Brown & Sharpe's Gauge		Washburn & Moen Gauge	
		Thickness, Inches	Weight, Pounds, per Sq. Ft.	Thickness, Inches	Weight, Pounds, per Sq. Ft.	Thickness, Inches	Weight, Pounds, per Sq. Ft.	Thickness, Inches	
00									00
0									0
1									1
2									2
3									3
4									4
5									5
6									6
7									7
8									8
9									9
10									10
11									11
12									12
13									13
14									14
15									15
16									16
17									17
18									18
19									19
20									20
21									21
22									22
23									23
24									24
25									25
26									26
27									27

Sheet mills roll steel sheets to U. S. gauge unless otherwise ordered. Plate mills usually roll heavy plates, $\frac{3}{16}$ and heavier, and light plate No. 8 to No. 12, to Birmingham gauge. In figuring weights of steel plates add to above the allowance for overweight, adopted by Association American Steel Manufacturers.

SAFE LOADS FOR ROPES AND CHAINS (In Pounds)

*CAUTION · When handling molten metal,
Wire Rope and chains should be 25 %
Stronger than indicated in table.*

		SAFE LOADS			
NOTE: Safe loads in table are for each single rope and chain Used double or in multiples, increase loads in proportion		Breaking Stress	When Used Straight	When Used at	When Used at
					
				Multiply by 0.866	Multiply by 0.70711
DIA.					Multiply by 0.500
PLOW STEEL	3/8	10,200	2,000	1,730	1,400
WIRE ROPE	1/2	19,500	3,700	3,200	1,800
	5/8	28,000	6,000	5,200	3,000
6 Strands of	3/4	42,000	8,000	7,000	4,000
19 or 31 Wires	7/8	54,000	10,000	8,700	5,000
If Crucible	1	70,000	14,000	12,000	7,000
Steel Rope is	1 1/8	88,000	18,000	15,600	9,000
used Reduce	1 1/4	110,000	22,000	19,000	11,000
Loads 20 %	1 3/8	136,000	28,000	24,200	14,000
	1 1/2	160,000	32,000	27,500	16,000
DIA. OF IRON					
CRANE CHAIN	1/4	5,000	1,000	860	700
	3/8	10,000	2,000	1,730	1,400
Best made of	1/2	18,000	3,600	3,100	2,550
wrought iron	5/8	27,000	5,400	4,600	3,800
hand made	3/4	40,000	8,000	8,900	5,650
tested short	7/8	48,000	9,600	8,300	6,800
link chain	1	61,000	12,200	10,700	8,800
	1 1/8	78,000	15,600	13,500	11,000
	1 1/4	95,000	19,000	16,400	13,400
	1 3/8	114,000	23,000	20,000	16,100

Comparative Weights of Steel and Brass Bars

Steel—Weights cover hot worked steel about 50% carbon. One cubic inch weighs .2833 lbs. High speed steel 10% heavier.

Brass—One cubic inch weighs .3074 lbs.

Actual weight of stock may be expected to vary somewhat from these figures because of variations in manufacturing processes.

Size, Inches	Weight of Bar One Foot Long, Lbs.					
	Steel			Brass		
	○	□	⬡	○	□	⬡
1/16	.0104	.013	.0115	.0113	.0144	.0125
1/8	.042	.05	.046	.045	.058	.050
3/16	.09	.12	.10	.102	.130	.112
1/4	.17	.21	.19	.18	.23	.20
5/16	.26	.33	.29	.28	.36	.31
3/8	.38	.48	.42	.41	.52	.45
7/16	.51	.65	.56	.55	.71	.61
1/2	.67	.85	.74	.72	.92	.80
9/16	.85	1.08	.94	.92	1.17	1.01
5/8	1.04	1.33	1.15	1.13	1.44	1.25
11/16	1.27	1.61	1.40	1.37	1.74	1.51
3/4	1.50	1.92	1.66	1.63	2.07	1.80
13/16	1.76	2.24	1.94	1.91	2.43	2.11
7/8	2.04	2.60	2.25	2.22	2.82	2.45
15/16	2.35	2.99	2.59	2.55	3.24	2.81
1	2.67	3.40	2.94	2.90	3.69	3.19
1 1/16	3.01	3.84	3.32	3.27	4.16	3.61
1 1/8	3.38	4.30	3.73	3.67	4.67	4.04
1 1/4	3.77	4.80	4.16	4.08	5.20	4.51
1 1/2	4.17	5.31	4.60	4.53	5.76	4.99
1 5/8	4.60	5.86	5.07	4.99	6.35	5.50
1 3/4	5.04	6.43	5.56	5.48	6.97	6.04
1 7/8	5.52	7.03	6.08	5.99	7.62	6.60
1 15/16	6.01	7.65	6.63	6.52	8.30	7.19
1 1/2	6.52	8.30	7.19	7.07	9.01	7.80
1 5/8	7.05	8.98	7.77	7.65	9.74	8.44
1 3/4	7.60	9.68	8.38	8.25	10.51	9.10
1 7/8	8.18	10.41	9.02	8.87	11.30	9.78
1 15/16	8.77	11.17	9.67	9.52	12.12	10.49
1 1/2	9.39	11.95	10.35	10.19	12.97	11.24
1 5/8	10.02	12.76	11.05	10.88	13.85	12.00
2	10.68	13.60	11.78	11.59	14.76	12.78
2 1/16	11.36	14.46	12.53	12.33	15.69	13.60
2 1/8	12.06	15.35	13.30	13.08	16.66	14.42
2 1/4	12.78	16.27	14.09	13.87	17.65	15.29
2 3/8	13.52	17.22	14.91	14.67	18.68	16.17
2 1/2	14.28	18.19	15.75	15.50	19.73	17.09
2 5/8	15.06	19.18	16.62	16.34	20.81	18.02

For weight of Hexagon and Octagon Rods, take weight of Round and Square, add together, and divide by two.

Specific Gravity = 8.509. Weight per Cubic Inch = .3074 lbs. Weight per Cubic Foot = 531.1 lbs. These weights are theoretically correct but variations must be expected in practice.

CASE HARDENING CAST IRON.—Salt, 21 lbs.; saltpetre, 1/2 lb.; rock alum, 1/2 lb.; carbonate ammonia, 4 oz.; salt of tartar, 4 oz. Pulverize all together and incorporate thoroughly. Use by powdering all over the iron while hot, then plunging in a cold liquid made as follows: Soft water, 10 gals.; salt, 1 peck; oil of vitrol, 1/2 pint; saltpetre, 1/2 lb.; prussiate of potash, 1/4 lb.; cyanide of potash, 1/4 lb. Heat the iron a cherry red, and if not sufficiently hard repeat the process.

Tinning Surfaces—Articles of Brass or Copper boiled in a solution of stannate of potassa, mixed with turnings or scrapings of tin, in a few moments become covered with a firmly attached layer of fine tin.

Weights of Aluminum, Brass and Copper Sheets

APPROXIMATE—POUNDS PER SQUARE FOOT

Copyright 1942 — Charles Shields, St. Louis, Mo.

American Wire or Brown & Sharpe Gauge No.	THICKNESS Inch	S. A. E. ALUMINUM ALLOYS Nos. 26-27	S. A. E. ALUMINUM ALLOYS No. 28	ALUMINUM Commercially Pure 99 to 99.4 per cent	COMMERCIAL HIGH BRASS	COPPER Cold-Rolled and Annealed
0000	0.4600	5.680	6.410	6.490	20.270	21.270
000	0.4096	5.950	5.710	5.780	18.050	18.940
00	0.3648	5.290	5.090	5.140	16.070	16.870
0	0.3249	4.720	4.530	4.580	14.320	15.030
1	0.2893	4.200	4.030	4.080	12.750	13.380
2	0.2576	3.738	3.591	3.632	11.350	11.910
3	0.2294	3.229	3.198	3.234	10.110	10.610
4	0.2043	2.964	2.848	2.880	9.000	9.450
5	0.1819	2.640	2.536	2.565	8.010	8.410
6	0.1620	2.351	2.258	2.284	7.140	7.490
7	0.1443	2.094	2.012	2.034	6.360	6.670
8	0.1285	1.865	1.792	1.812	5.660	5.940
9	0.1141	1.660	1.595	1.613	5.040	5.290
10	0.1019	1.479	1.420	1.437	4.490	4.713
11	0.0907	1.316	1.264	1.279	3.996	4.195
12	0.0808	1.172	1.126	1.139	3.560	3.737
13	0.0742	1.045	1.004	1.015	3.172	3.330
14	0.0641	0.930	0.894	0.904	2.824	2.965
15	0.0571	0.829	0.796	0.805	2.516	2.641
16	0.0508	0.737	0.708	0.716	2.238	2.349
17	0.0453	0.637	0.631	0.639	1.996	2.095
18	0.0403	0.585	0.562	0.568	1.776	1.864
19	0.0359	0.5210	0.5010	0.5060	1.5820	1.6600
20	0.0320	0.4640	0.4460	0.4510	1.4100	1.4800
21	0.0285	0.4140	0.3970	0.4020	1.2560	1.3180
22	0.0253	0.3671	0.3527	0.3567	1.1150	1.1700
23	0.0226	0.3280	0.3150	0.3186	0.9960	1.0450
24	0.0201	0.2917	0.2802	0.2834	0.8860	0.9300
25	0.0179	0.2597	0.2495	0.2524	0.7890	0.8280
26	0.0159	0.2307	0.2216	0.2242	0.7010	0.7350
27	0.0142	0.2060	0.1980	0.2002	0.6260	0.6570
28	0.0126	0.1828	0.1756	0.1776	0.5550	0.5830
29	0.0113	0.1640	0.1575	0.1593	0.4980	0.5230
30	0.0100	0.1451	0.1394	0.1410	0.4406	0.4625
31	0.0089	0.1296	0.1245	0.1259	0.3935	0.4130
32	0.0080	0.1154	0.1108	0.1121	0.3503	0.3677
33	0.0071	0.1027	0.0987	0.0998	0.3119	0.3274
34	0.0063	0.0914	0.0878	0.0888	0.2776	0.2914
35	0.0036	0.0814	0.0782	0.0791	0.2472	0.2595
36	0.0050	0.0726	0.0697	0.0705	0.2203	0.2312
37	0.0045	0.0646	0.0620	0.0627	0.1961	0.2058
38	0.0040	0.0576	0.0553	0.0560	0.1749	0.1836
39	0.0035	0.0512	0.0492	0.0498	0.1555	0.1633
40	0.0031	0.0456	0.0438	0.0443	0.1383	0.1452

Copper Sheets can be Obtained in Fractional Inch Thickness, Varying by Sixteenths of an inch from 1/16" to 2".

ALUMINUM

Aluminum is a soft and ductile metal of comparatively high tensile strength, and it is therefore peculiarly adapted for such automobile and machinery parts as require lightness and strength. The metal in a molten condition, however, oxidizes quite readily, and this point, aside from expansion and contraction, is our chief concern in the welding of this metal. By referring to our table of melting points of metals we find that aluminum melts at approximately 1200 Fahrenheit, almost half of the temperature required to melt cast iron, and by referring to our tables on heat conductivity and co-efficients of linear expansion of metals we find that aluminum conducts heat almost three times as readily as iron, as well as has a 50 per cent greater shrinkage.

Shield's Brass and Bronze Bushing Table in All Sizes

Length Outside Diam.	Solid Bushings	Cored Bushings	Thickness of Walls	Length Outside Diam.	Solid Bushings	Cored Bushings	Thickness of Walls	Length Outside Diam.	Solid Bushings	Cored Bushings	Thickness of Walls	Length Outside Diam.	Solid Bushings	Cored Bushings	Thickness of Walls
12 1	1	1/2	1/4	12 1 1/8	1 1/8	1/2	5/16	12 1 1/4	1 1/4	1/2	3/8	12 1 1/2	1 1/2	1/2	1/2
12 1 1/8	1 1/8	1/2	5/16	12 1 3/8	1 3/8	1/2	1/4	12 1 3/4	1 3/4	1/2	1/2	12 1 7/8	1 7/8	1/2	1/2
12 1 1/4	1 1/4	1/2	3/8	12 1 5/8	1 5/8	1/2	1/4	12 2	2	1/2	1/2	12 2 1/8	2 1/8	1/2	1/2
12 1 1/2	1 1/2	1/2	1/2	12 1 5/4	1 5/4	1/2	1/2	12 2 1/4	2 1/4	1/2	1/2	12 2 1/2	2 1/2	1/2	1/2
12 1 3/8	1 3/8	1/2	7/16	12 1 7/8	1 7/8	1/2	3/8	12 2 1/8	2 1/8	1/2	1/2	12 2 1/4	2 1/4	1/2	1/2
12 1 3/4	1 3/4	1/2	1/2	12 1 7/4	1 7/4	1/2	1/2	12 2 1/2	2 1/2	1/2	1/2	12 2 3/4	2 3/4	1/2	1/2
12 1 7/8	1 7/8	1/2	1/2	12 2	2	1/2	1/2	12 2 3/4	2 3/4	1/2	1/2	12 2 7/8	2 7/8	1/2	1/2
12 2	2	1/2	1/2	12 2 1/8	2 1/8	1/2	1/2	12 2 1/4	2 1/4	1/2	1/2	12 2 1/2	2 1/2	1/2	1/2
12 2 1/8	2 1/8	1/2	1/2	12 2 1/4	2 1/4	1/2	1/2	12 2 1/2	2 1/2	1/2	1/2	12 2 3/4	2 3/4	1/2	1/2
12 2 1/4	2 1/4	1/2	1/2	12 2 1/2	2 1/2	1/2	1/2	12 2 3/4	2 3/4	1/2	1/2	12 2 7/8	2 7/8	1/2	1/2
12 2 3/8	2 3/8	1/2	1/2	12 2 3/4	2 3/4	1/2	1/2	12 3	3	1/2	1/2	12 3 1/8	3 1/8	1/2	1/2
12 2 3/4	2 3/4	1/2	1/2	12 2 7/8	2 7/8	1/2	1/2	12 3 1/4	3 1/4	1/2	1/2	12 3 1/2	3 1/2	1/2	1/2
12 2 7/8	2 7/8	1/2	1/2	12 3	3	1/2	1/2	12 3 1/8	3 1/8	1/2	1/2	12 3 1/4	3 1/4	1/2	1/2
12 3	3	1/2	1/2	12 3 1/8	3 1/8	1/2	1/2	12 3 1/4	3 1/4	1/2	1/2	12 3 1/2	3 1/2	1/2	1/2
12 3 1/8	3 1/8	1/2	1/2	12 3 1/4	3 1/4	1/2	1/2	12 3 1/2	3 1/2	1/2	1/2	12 3 3/4	3 3/4	1/2	1/2
12 3 1/4	3 1/4	1/2	1/2	12 3 1/2	3 1/2	1/2	1/2	12 3 3/8	3 3/8	1/2	1/2	12 3 3/4	3 3/4	1/2	1/2
12 3 1/2	3 1/2	1/2	1/2	12 3 3/4	3 3/4	1/2	1/2	12 3 7/8	3 7/8	1/2	1/2	12 4	4	1/2	1/2
12 3 3/8	3 3/8	1/2	1/2	12 3 7/8	3 7/8	1/2	1/2	12 4	4	1/2	1/2	12 4 1/8	4 1/8	1/2	1/2
12 3 3/4	3 3/4	1/2	1/2	12 4	4	1/2	1/2	12 4 1/4	4 1/4	1/2	1/2	12 4 1/2	4 1/2	1/2	1/2
12 3 7/8	3 7/8	1/2	1/2	12 4 1/8	4 1/8	1/2	1/2	12 4 1/4	4 1/4	1/2	1/2	12 4 1/2	4 1/2	1/2	1/2
12 4	4	1/2	1/2	12 4 1/4	4 1/4	1/2	1/2	12 4 1/2	4 1/2	1/2	1/2	12 4 3/4	4 3/4	1/2	1/2
12 4 1/8	4 1/8	1/2	1/2	12 4 1/2	4 1/2	1/2	1/2	12 4 3/8	4 3/8	1/2	1/2	12 4 3/4	4 3/4	1/2	1/2
12 4 1/4	4 1/4	1/2	1/2	12 4 3/8	4 3/8	1/2	1/2	12 4 3/4	4 3/4	1/2	1/2	12 4 7/8	4 7/8	1/2	1/2
12 4 1/2	4 1/2	1/2	1/2	12 4 3/4	4 3/4	1/2	1/2	12 4 7/8	4 7/8	1/2	1/2	12 5	5	1/2	1/2
12 4 3/8	4 3/8	1/2	1/2	12 4 7/8	4 7/8	1/2	1/2	12 5	5	1/2	1/2	12 5 1/8	5 1/8	1/2	1/2
12 4 3/4	4 3/4	1/2	1/2	12 5	5	1/2	1/2	12 5 1/4	5 1/4	1/2	1/2	12 5 1/2	5 1/2	1/2	1/2
12 4 7/8	4 7/8	1/2	1/2	12 5 1/8	5 1/8	1/2	1/2	12 5 1/4	5 1/4	1/2	1/2	12 5 1/2	5 1/2	1/2	1/2
12 5	5	1/2	1/2	12 5 1/4	5 1/4	1/2	1/2	12 5 1/2	5 1/2	1/2	1/2	12 5 3/4	5 3/4	1/2	1/2
12 5 1/8	5 1/8	1/2	1/2	12 5 1/2	5 1/2	1/2	1/2	12 5 3/4	5 3/4	1/2	1/2	12 5 7/8	5 7/8	1/2	1/2
12 5 1/4	5 1/4	1/2	1/2	12 5 3/4	5 3/4	1/2	1/2	12 6	6	1/2	1/2	12 6 1/8	6 1/8	1/2	1/2
12 5 1/2	5 1/2	1/2	1/2	12 5 7/8	5 7/8	1/2	1/2	12 6 1/4	6 1/4	1/2	1/2	12 6 1/2	6 1/2	1/2	1/2
12 5 3/8	5 3/8	1/2	1/2	12 6	6	1/2	1/2	12 6 1/2	6 1/2	1/2	1/2	12 6 3/4	6 3/4	1/2	1/2
12 5 3/4	5 3/4	1/2	1/2	12 6 1/8	6 1/8	1/2	1/2	12 6 3/4	6 3/4	1/2	1/2	12 6 7/8	6 7/8	1/2	1/2
12 5 7/8	5 7/8	1/2	1/2	12 6 1/2	6 1/2	1/2	1/2	12 6 7/8	6 7/8	1/2	1/2	12 7	7	1/2	1/2
12 6	6	1/2	1/2	12 6 3/4	6 3/4	1/2	1/2	12 7	7	1/2	1/2	12 7 1/8	7 1/8	1/2	1/2
12 6 1/8	6 1/8	1/2	1/2	12 6 7/8	6 7/8	1/2	1/2	12 7 1/4	7 1/4	1/2	1/2	12 7 1/2	7 1/2	1/2	1/2
12 6 1/4	6 1/4	1/2	1/2	12 7	7	1/2	1/2	12 7 1/2	7 1/2	1/2	1/2	12 7 3/4	7 3/4	1/2	1/2
12 6 1/2	6 1/2	1/2	1/2	12 7 1/8	7 1/8	1/2	1/2	12 7 3/4	7 3/4	1/2	1/2	12 7 7/8	7 7/8	1/2	1/2
12 6 3/8	6 3/8	1/2	1/2	12 7 1/2	7 1/2	1/2	1/2	12 8	8	1/2	1/2	12 8 1/8	8 1/8	1/2	1/2
12 6 3/4	6 3/4	1/2	1/2	12 7 3/4	7 3/4	1/2	1/2	12 8 1/4	8 1/4	1/2	1/2	12 8 1/2	8 1/2	1/2	1/2
12 6 7/8	6 7/8	1/2	1/2	12 8	8	1/2	1/2	12 8 1/2	8 1/2	1/2	1/2	12 8 3/4	8 3/4	1/2	1/2
12 7	7	1/2	1/2	12 8 1/8	8 1/8	1/2	1/2	12 8 3/4	8 3/4	1/2	1/2	12 8 7/8	8 7/8	1/2	1/2
12 7 1/8	7 1/8	1/2	1/2	12 8 1/2	8 1/2	1/2	1/2	12 9	9	1/2	1/2	12 9 1/8	9 1/8	1/2	1/2
12 7 1/4	7 1/4	1/2	1/2	12 8 3/4	8 3/4	1/2	1/2	12 9 1/4	9 1/4	1/2	1/2	12 9 1/2	9 1/2	1/2	1/2
12 7 1/2	7 1/2	1/2	1/2	12 8 7/8	8 7/8	1/2	1/2	12 9 1/2	9 1/2	1/2	1/2	12 9 3/4	9 3/4	1/2	1/2
12 7 3/8	7 3/8	1/2	1/2	12 9	9	1/2	1/2	12 9 3/4	9 3/4	1/2	1/2	12 9 7/8	9 7/8	1/2	1/2
12 7 3/4	7 3/4	1/2	1/2	12 9 1/8	9 1/8	1/2	1/2	12 10	10	1/2	1/2	12 10 1/8	10 1/8	1/2	1/2
12 7 7/8	7 7/8	1/2	1/2	12 9 1/2	9 1/2	1/2	1/2	12 10 1/4	10 1/4	1/2	1/2	12 10 1/2	10 1/2	1/2	1/2
12 8	8	1/2	1/2	12 9 3/4	9 3/4	1/2	1/2	12 10 1/2	10 1/2	1/2	1/2	12 10 3/4	10 3/4	1/2	1/2
12 8 1/8	8 1/8	1/2	1/2	12 9 7/8	9 7/8	1/2	1/2	12 10 3/4	10 3/4	1/2	1/2	12 10 7/8	10 7/8	1/2	1/2
12 8 1/4	8 1/4	1/2	1/2	12 10	10	1/2	1/2	12 11	11	1/2	1/2	12 11 1/8	11 1/8	1/2	1/2
12 8 1/2	8 1/2	1/2	1/2	12 10 1/8	10 1/8	1/2	1/2	12 11 1/4	11 1/4	1/2	1/2	12 11 1/2	11 1/2	1/2	1/2
12 8 3/8	8 3/8	1/2	1/2	12 10 1/2	10 1/2	1/2	1/2	12 11 1/2	11 1/2	1/2	1/2	12 11 3/4	11 3/4	1/2	1/2
12 8 3/4	8 3/4	1/2	1/2	12 10 3/4	10 3/4	1/2	1/2	12 11 3/4	11 3/4	1/2	1/2	12 11 7/8	11 7/8	1/2	1/2
12 8 7/8	8 7/8	1/2	1/2	12 11	11	1/2	1/2	12 12	12	1/2	1/2	12 12 1/8	12 1/8	1/2	1/2
12 9	9	1/2	1/2	12 11 1/8	11 1/8	1/2	1/2	12 12 1/4	12 1/4	1/2	1/2	12 12 1/2	12 1/2	1/2	1/2
12 9 1/8	9 1/8	1/2	1/2	12 11 1/2	11 1/2	1/2	1/2	12 12 1/2	12 1/2	1/2	1/2	12 12 3/4	12 3/4	1/2	1/2
12 9 1/4	9 1/4	1/2	1/2	12 11 3/4	11 3/4	1/2	1/2	12 12 3/4	12 3/4	1/2	1/2	12 12 7/8	12 7/8	1/2	1/2
12 9 1/2	9 1/2	1/2	1/2	12 11 7/8	11 7/8	1/2	1/2	12 13	13	1/2	1/2	12 13 1/8	13 1/8	1/2	1/2
12 9 3/8	9 3/8	1/2	1/2	12 12	12	1/2	1/2	12 13 1/4	13 1/4	1/2	1/2	12 13 1/2	13 1/2	1/2	1/2
12 9 3/4	9 3/4	1/2	1/2	12 12 1/8	12 1/8	1/2	1/2	12 13 1/2	13 1/2	1/2	1/2	12 13 3/4	13 3/4	1/2	1/2
12 9 7/8	9 7/8	1/2	1/2	12 12 1/2	12 1/2	1/2	1/2	12 13 3/4	13 3/4	1/2	1/2	12 14	14	1/2	1/2
12 10	10	1/2	1/2	12 12 3/4	12 3/4	1/2	1/2	12 14 1/8	14 1/8	1/2	1/2	12 14 1/2	14 1/2	1/2	1/2
12 10 1/8	10 1/8	1/2	1/2	12 13	13	1/2	1/2	12 14 1/4	14 1/4	1/2	1/2	12 14 3/4	14 3/4	1/2	1/2
12 10 1/4	10 1/4	1/2	1/2	12 13 1/8	13 1/8	1/2	1/2	12 14 3/8	14 3/8	1/2	1/2	12 15	15	1/2	1/2
12 10 1/2	10 1/2	1/2	1/2	12 13 1/4	13 1/4	1/2	1/2	12 15 1/4	15 1/4	1/2	1/2	12 15 1/2	15 1/2	1/2	1/2
12 10 3/8	10 3/8	1/2	1/2	12 13 1/2	13 1/2	1/2	1/2	12 15 1/2	15 1/2	1/2	1/2	12 15 3/4	15 3/4	1/2	1/2
12 10 3/4	10 3/4	1/2	1/2	12 13 3/4	13 3/4	1/2	1/2	12 16	16	1/2	1/2	12 16 1/8	16 1/8	1/2	1/2
12 10 7/8	10 7/8	1/2	1/2	12 14	14	1/2	1/2	12 16 1/4	16 1/4	1/2	1/2	12 16 1/2	16 1/2	1/2	1/2
12 11	11	1/2	1/2	12 14 1/8	14 1/8	1/2	1/2	12 16 1/2	16 1/2	1/2	1/2	12 16 3/4	16 3/4	1/2	1/2
12 11 1/8	11 1/8	1/2	1/2	12 14 1/4	14 1/4	1/2	1/2	12 17	17	1/2	1/2	12 17 1/8	17 1/8	1/2	1/2
12 11 1/4	11 1/4	1/2	1/2	12 14 1/2	14 1/2	1/2	1/2	12 17 1/4	17 1/4	1/2	1/2	12 17 1/2	17 1/2	1/2	1/2
12 11 1/2	11 1/2	1/2	1/2	12 14 3/4	14 3/4	1/2	1/2	12 17 1/2	17 1/2	1/2	1/2	12 17 3/4	17 3/4	1/2	1/2
12 11 3/8	11 3/8	1/2	1/2	12 15	15	1/2	1/2	12 18	18	1/2	1/2	12 18 1/8	18 1/8	1/2	1/2
12 11 3/4	11 3/4	1/2	1/2	12 15 1/8	15 1/8	1/2	1/2	12 18 1/4	18 1/4	1/2	1/2	12 18 1/2	18 1/2	1/2	1/2
12 11 7/8	11 7/8	1/2	1/2	12 15 1/4	15 1/4	1/2	1/2	12 18 1/2	18 1/2	1/2	1/2	12 18 3/4	18 3/4		

International Atomic Weights

	Sym- bol	At. Num- ber	At. Weight	Melting Point C°		Sym- bol	At. Num- ber	At. Weight	Melting Point C°
Aluminum	Al	13	26.97	658.7	Mercury	Hg	80	200.61	-38.85
Antimony	Sb	51	121.76	630.0	Molybdenum	Mo	42	96.0	2535
Argon	A	18	39.944	-189.6	Neodymium	Nd	60	144.27	840
Arsenic	As	33	74.91	Subl. (500)	Neon	Ne	10	20.183	-253
Barium	Ba	56	137.36	850	Nickel	Ni	28	58.69	1452
Beryllium	Be	4	9.02	1280	Nitrogen	N	7	14.008	-210.5
Bismuth	Bi	83	209.00	269.2	Osmium	Os	76	191.5	2700
Boron	B	5	10.82	2000-2500	Oxygen	O	8	16.000	-218
Bromine	Br	35	79.916	-7.3	Palladium	Pd	46	106.7	1549
Caesium	Cd	48	112.41	320.9	Phosphorus	P	15	31.02	44.2
Calcium	Ca	20	40.07	810	Platinum	Pt	78	195.23	1755
Carbon	C	6	12.000	3500	Potassium	K	19	39.096	62.3
Cerium	Ce	58	140.13	640	Praseodymium	Pr	59	140.92	940
Cesium	Cs	55	132.91	26.4	Radium	Ra	88	225.97
Chlorine	Cl	17	35.457	-40	Radon	Rn	86	222
Chromium	Cr	24	52.01	1615	Rhodium	Rh	45	102.91	1950
Cobalt	Co	27	58.94	1480	Rubidium	Rb	37	85.44	38.5
Columbium	Cb	41	93.1	1950	Ruthenium	Ru	44	101.7	2450
Copper	Cu	29	63.57	1083	Samarium	Sm	62	150.43	1,000-1400
Dysprosium	Dy	66	162.46	Scandium	Sc	21	45.10	1200?
Erbium	Er	68	167.64	Selenium	Se	34	78.96	217
Europium	Eu	63	152.0	Silicon	Si	14	28.06	1420
Fluorine	F	9	19.00	-187	Silver	Ag	47	107.880	960.5
Gadolinium	Gd	64	157.3	Sodium	Na	11	22.997	97.5
Gallium	Ga	31	69.72	30.1	Strontium	Sr	38	87.63	900
Germanium	Ge	32	72.60	958	Sulfur	S	16	32.06	112.8
Gold	Au	79	197.2	1063	Tantalum	Ta	73	181.4	2910
Hafnium	Hf	72	178.6	Tellurium	Te	52	127.61	541
Helium	He	2	4.002	-268.8 B.P.	Terbium	Tb	65	159.2
Holmium	Ho	67	163.5	Thallium	Tl	81	204.39	301.7
Hydrogen	H	1	1.0078	-259	Thorium	Th	90	232.12	1700
Indium	In	49	114.76	155	Thulium	Tm	69	169.4
Iodine	I	53	126.92	113.5	Tin	Sn	50	118.70	231.9
Iridium	Ir	77	193.1	2360	Titanium	Ti	22	47.90	1800?
Iron	Fe	26	55.84	1530	Tungsten	W	74	184.0	3400
Krypton	Kr	36	83.7	-169	Uranium	U	92	238.14	near Mo.
Lanthanum	La	57	138.92	810	Vanadium	V	23	50.95	1740
Lead	Pb	82	207.2	327	Xenon	Xe	54	131.3	-140
Lithium	Li	3	6.940	186	Ytterbium	Yb	70	173.04
Lutecium	Lu	71	175.0	Yttrium	Y	39	88.92	1490
Magnesium	Mg	12	24.32	651	Zinc	Zn	30	65.38	419.4
Manganese	Mn	25	54.93	1230	Zirconium	Zr	40	91.22	2350

WEIGHT OF WIRE
Weight of 100 Lineal Feet

B. W. Gauge	Iron Lbs.	Steel Lbs.	Brass Lbs.	Copper Lbs.
0	30.58	30.92	33.43	35.17
1	25.75	26.04	28.15	29.62
2	21.34	21.57	23.32	24.54
3	15.02	15.22	19.70	20.72
4	11.11	11.28	16.52	17.38
5	12.46	12.59	13.62	14.33
6	11.45	11.57	12.51	13.16
7	9.25	9.35	10.11	10.64
8	7.29	7.37	7.97	8.38
9	6.60	6.68	7.22	7.59
10	4.96	5.02	5.43	5.71
11	4.13	4.18	4.52	4.75
12	3.14	3.18	3.43	3.61
13	2.34	2.36	2.55	2.69
14	1.69	1.71	1.85	1.95
15	1.37	1.39	1.50	1.58
16	1.05	1.06	1.15	1.21
17	.804	.815	.877	.928
18	.612	.622	.674	.704
19	.471	.478	.510	.542
20	.326	.332	.352	.372
21	.271	.276	.293	.310
22	.208	.210	.223	.237
23	.167	.169	.179	.189
24	.128	.129	.138	.147
25	.106	.107	.114	.121
26	.086	.087	.093	.098
27	.068	.069	.073	.078
28	.052	.053	.056	.059
29	.045	.046	.048	.051
30	.038	.039	.041	.044

To Compute the Weight of Cast Metal by the Weight of the Pattern—When made of pine—Multiply the weight of the pattern in pounds by the following multipliers and the product will be the weight of casting: Iron, 14 pounds to the pound of pattern; Brass, 15; Lead, 22; Tin, 14; Zinc, 13.5 pounds.

Weight per Inch

Of round bars of carbon and high speed steel in pounds per linear inch.

Diam. of Bar Inches	Weight of Bar One Inch Long		Diam. of Bar Inches	Weight of Bar One Inch Long		Diam. of Bar Inches	Weight of Bar One Inch Long	
	Carbon Steel	High Speed Steel		Carbon Steel	High Speed Steel		Carbon Steel	High Speed Steel
$\frac{1}{16}$.00087	.00098	$\frac{27}{16}$	1.33	1.496	$4\frac{13}{16}$	5.15	5.793
$\frac{1}{8}$.0035	.0039	$\frac{27}{2}$	1.39	1.563	$4\frac{7}{8}$	5.28	5.940
$\frac{3}{16}$.0078	.0088	$\frac{29}{16}$	1.46	1.642	$4\frac{15}{16}$	5.42	6.097
$\frac{1}{4}$.0139	.0156	$2\frac{5}{8}$	1.53	1.721	5	5.56	6.255
$\frac{5}{16}$.0217	.0244	$2\frac{1}{4}$	1.61	1.811	$5\frac{1}{16}$	5.70	6.412
$\frac{3}{8}$.0313	.0352	$2\frac{3}{4}$	1.68	1.890	$5\frac{1}{8}$	5.84	6.570
$\frac{7}{16}$.0425	.0478	$2\frac{13}{16}$	1.76	1.980	$5\frac{3}{16}$	5.98	6.727
$\frac{1}{2}$.0556	.0625	$2\frac{7}{8}$	1.84	2.070	$5\frac{1}{4}$	6.13	6.896
$\frac{9}{16}$.0703	.0791	$2\frac{15}{16}$	1.92	2.160	$5\frac{5}{16}$	6.27	7.053
$\frac{5}{8}$.0868	.0976	3	2.00	2.250	$5\frac{3}{8}$	6.42	7.222
$\frac{11}{16}$.105	.118	$3\frac{1}{16}$	2.08	2.340	$5\frac{1}{2}$	6.57	7.391
$\frac{3}{4}$.125	.141	$3\frac{1}{8}$	2.17	2.441	$5\frac{1}{2}$	6.72	7.560
$\frac{13}{16}$.147	.165	$3\frac{3}{16}$	2.26	2.542	$5\frac{9}{16}$	6.88	7.740
$\frac{7}{8}$.170	.191	$3\frac{1}{4}$	2.35	2.643	$5\frac{5}{8}$	7.03	7.908
$\frac{15}{16}$.195	.219	$3\frac{5}{16}$	2.44	2.745	$5\frac{11}{16}$	7.19	8.088
1	.22	.248	$3\frac{3}{8}$	2.53	2.846	$5\frac{3}{4}$	7.35	8.268
$1\frac{1}{16}$.25	.281	$3\frac{7}{16}$	2.63	2.958	$5\frac{13}{16}$	7.51	8.448
$1\frac{1}{8}$.28	.315	$3\frac{1}{2}$	2.72	3.060	$5\frac{7}{8}$	7.67	8.628
$1\frac{3}{16}$.31	.349	$3\frac{9}{16}$	2.82	3.172	$5\frac{15}{16}$	7.84	8.820
$1\frac{1}{4}$.35	.397	$3\frac{5}{8}$	2.92	3.285	6	8.00	9.000
$1\frac{5}{16}$.38	.427	$3\frac{11}{16}$	3.02	3.397	$6\frac{1}{8}$	8.34	9.382
$1\frac{3}{8}$.42	.472	$3\frac{3}{4}$	3.13	3.521	$6\frac{1}{4}$	8.68	9.765
$1\frac{7}{16}$.46	.517	$3\frac{13}{16}$	3.23	3.633	$6\frac{3}{8}$	9.03	10.16
$1\frac{1}{2}$.50	.562	$3\frac{7}{8}$	3.34	3.757	$6\frac{1}{2}$	9.39	10.56
$1\frac{9}{16}$.54	.607	$3\frac{15}{16}$	3.45	3.881	$6\frac{5}{8}$	9.76	10.98
$1\frac{5}{8}$.59	.663	4	3.56	4.005	$6\frac{3}{4}$	10.1	11.36
$1\frac{11}{16}$.63	.709	$4\frac{1}{16}$	3.67	4.128	$6\frac{7}{8}$	10.5	11.81
$1\frac{3}{4}$.68	.765	$4\frac{1}{8}$	3.78	4.252	7	10.9	12.26
$1\frac{13}{16}$.73	.821	$4\frac{3}{16}$	3.90	4.387	$7\frac{1}{8}$	11.3	12.71
$1\frac{7}{8}$.78	.877	$4\frac{1}{4}$	4.01	4.511	$7\frac{1}{4}$	11.7	13.16
$1\frac{15}{16}$.83	.933	$4\frac{5}{16}$	4.13	4.646	$7\frac{3}{8}$	12.1	13.61
2	.89	1.001	$4\frac{3}{8}$	4.25	4.781	$7\frac{1}{2}$	12.5	14.06
$2\frac{1}{16}$.94	1.057	$4\frac{7}{16}$	4.38	4.927	$7\frac{5}{8}$	12.9	14.51
$2\frac{1}{8}$	1.00	1.125	$4\frac{1}{2}$	4.50	5.062	$7\frac{3}{4}$	13.3	14.96
$2\frac{3}{16}$	1.06	1.192	$4\frac{9}{16}$	4.63	5.208	$7\frac{7}{8}$	13.8	15.52
$2\frac{1}{4}$	1.13	1.271	$4\frac{5}{8}$	4.75	5.343	8	14.3	16.08
$2\frac{5}{16}$	1.19	1.338	$4\frac{11}{16}$	4.88	5.490			
$2\frac{3}{8}$	1.25	1.406	$4\frac{3}{4}$	5.01	5.636			

WEIGHT TABLE Miscellaneous

PER CUBIC FOOT			
Pine, yellow	34	Earth, loose	94
Pine, white	34	Marble, Italian	169
Ash	53	Marble, Vermont	165
Oak, white, dry	54	Mortar	110
Poplar	23	Mud	102
Poplar, white	33	Water, salt	64
Walnut	41	Water, rain	62
Walnut, black	31	Ice	57½
Stone, com.	158	Hay, baled	95
Sand, wet	128	Hay, pressed	25
Brick, com.	102	Coal, L'y'a	50
Clay	120	Coal, Lehigh	56
		1 gal. kerosene, about	6½ lbs.

WEIGHT OF FLAT BAR STEEL, PER LINEAL FOOT

	1/2	3/8	1/2	3/4	1	1 1/8	1 1/4	1 3/8	1 1/2	1 3/4	2	2 1/4	2 1/2	2 3/4	3	3 1/2
1/8	.213	.266	.320	.372	.426	.479	.530	.585	.640	.745	.850	.955	1.07	1.18	1.28	1.49
3/16	.319	.399	.480	.558	.639	.718	.790	.878	.960	1.12	1.28	1.43	1.60	1.76	1.92	2.24
1/4	.425	.533	.640	.743	.852	.958	1.06	1.17	1.28	1.49	1.70	1.91	2.13	2.34	2.56	2.98
5/16	.531	.665	.800	.929	1.06	1.20	1.33	1.46	1.60	1.86	2.13	2.39	2.66	2.92	3.19	3.72
3/8	.638	.798	.960	1.12	1.28	1.43	1.59	1.75	1.91	2.23	2.55	2.87	3.20	3.51	3.83	4.46
7/16	.744	.931	1.12	1.30	1.49	1.67	1.86	2.05	2.23	2.60	2.98	3.35	3.72	4.09	4.46	5.21
1/2	1.07	1.28	1.49	1.70	1.91	2.13	2.34	2.55	2.98	3.40	3.83	4.26	4.68	5.10	5.96	
9/16	1.20	1.44	1.67	1.91	2.15	2.39	2.63	2.87	3.35	3.83	4.30	4.78	5.26	5.74	6.69	
5/8	1.60	1.86	2.12	2.39	2.66	2.92	3.19	3.46	4.09	4.68	5.26	5.84	6.43	7.01	8.18	
11/16	1.76	2.04	2.34	2.63	2.92	3.22	3.51	3.81	4.46	5.10	5.74	6.40	7.02	7.65	8.92	
3/4	2.23	2.55	2.86	3.19	3.50	3.83	4.14	4.46	5.10	5.74	6.40	7.02	7.65	8.29	9.67	
13/16	2.41	2.76	3.11	3.45	3.80	4.14	4.46	4.83	5.53	6.22	6.91	7.60	8.29	8.94	10.42	
7/8	2.98	3.34	3.72	4.09	4.46	4.83	5.21	5.56	6.38	7.17	7.97	8.77	9.56	10.42	11.20	
15/16	3.19	3.59	3.98	4.38	4.78	5.18	5.58	5.98	6.80	7.66	8.52	9.36	10.20	11.02		
1	3.82	4.25	4.68	5.10	5.52	5.96	6.40	6.80	7.66	8.52	9.36	10.20	11.02			

INFORMATION FOR USE OF WEIGHT TABLES

Rings—To obtain the weight of a ring, subtract the weight per inch of the inside diameter from the weight per inch of the outside diameter (as obtained from the table), and multiply this remainder by the width.

Example:

Let O. D. = 10"


I. D. = 6"

Width = 3"

From table 10" = 22.20

6" = 8.00

$$14.20 \times 3 = 42.60 \text{ lbs.}$$



Tapers—Add together the weights per inch (as given in table) of the smaller diameter, larger diameter and that for the diameter equal to the sum of the smaller and larger diameter.

Then divide this total by 3.

Example:

6" diam. weighs

4" diam. weighs

(6+4) 10" diam. weighs

8.00

3.56

22.20

6)33.76

5.63



which multiplied by the length in inches gives the weight of the tapered section.

To obtain the weights of squares, octagons or hexagons from the table, figure as rounds and then multiply the result by the following factors:

Squares, 1.274; Hexagons, 1.103; Octagons, 1.054; Decagons, 1.034.

Example:—The weight per inch of a 6" hexagon bar will be:—

From table 6" = 8.00

x1.103

8.824 lbs. per 1" of length.

The weight table gives the weight per inch of length for the various diameters.

The weight table is based on one cubic inch of steel weighing 0.283 pounds.

When weight tables cannot be used, weights must be based on cubic inch of steel weighing 0.283 pounds.

TABLE FOR ESTIMATING QUANTITY OF NAILS

Material	Size of Nail	Lbs. Required
1000 Shingles.....	4d	5
1000 Laths.....	3d	7
1000 Square Feet Beveled Siding.....	6d	18
1000 " " Sheathing.....	8d	20
1000 " " ".....	10d	25
1000 " " Flooring.....	8d	30
1000 " " ".....	10d	40
1000 " " Studding.....	10d	15
1000 " " Furring 1 x 2 in.....	10d	10
1000 " " Finished Flooring 1/2 in.....	8d to 10d Fin.	120
1000 " " " 1 1/8 in.....	10d Fin.	30

LONG MEASURE (Measures of Length)

Ins.	Feet	Yards	Fathoms	Rods	Furlongs	Mile
12	=	1				
36	=	3	=	1		
72	=	6	=	2	=	1
198	=	16 1/2	=	5 1/2	=	2 3/4
7920	=	600	=	220	=	110
63360	=	5280	=	1760	=	8
6080.26 Feet	=	1.15 Statute Miles	=	1 Nautical Mile or Knot.		

WEIGHT, ONE SQUARE FOOT OF METALS

Thickness	Wrought Iron	Cast Iron	Steel	Copper	Brass	Lead
In.	Lbs.	Lbs.	Lbs.	Lbs.	Lbs.	Lbs.
1/16	2.50	2.34	2.55	2.89	2.63	3.71
1/8	5.00	4.69	5.10	5.79	5.26	7.41
3/16	7.50	7.03	7.65	8.68	7.89	11.1
1/4	10.0	9.38	10.2	11.6	10.5	14.8
5/16	12.5	11.7	12.8	14.5	13.2	18.5
3/8	15.0	14.1	15.3	17.4	15.8	22.2
7/16	17.5	16.4	17.9	20.3	18.4	25.9
1/2	20.0	18.7	20.4	23.2	21.1	29.7

Approximate Weight and Strength of Cordage

Circumference in inches	Diameter in inches	Weight of 100 fathoms of 600 feet in lbs.	Weight of 100 fathoms Tarred in lbs.	Strength of New Ropes in lbs.	No. of feet in 1 lb.
6 thd.	3/16 in.	12	17	540	50 feet
9 " "	1/4 " "	18	24	780	33 " 4 in.
12 " "	5/16 " "	24	34	1000	25 " "
15 " "	3/8 " "	30	45	1280	20 " "
1 1/4 in.	7/16 " "	37	50	1562	17 " 8 in.
1 1/2 " "	1/2 " "	46	55	2250	13 " "
1 3/4 " "	9/16 " "	65	85	3062	9 " 3 " "
2 " "	5/8 " "	80	100	4000	7 " 6 " "
2 1/4 " "	3/4 " "	98	125	5000	6 " "
2 1/2 " "	13/16 " "	120	155	6250	5 " "
2 3/4 " "	7/8 " "	142	190	7500	4 " 3 " "
3 " "	1 " "	170	225	9000	3 " 6 " "
3 1/4 " "	1 1/16 " "	200	265	10500	3 " "
3 1/2 " "	1 1/8 " "	230	300	12250	2 " 7 " "
3 3/4 " "	1 1/4 " "	271	350	14000	2 " 3 " "
4 " "	1 1/2 " "	310	405	16000	1 " 11 " "
4 1/4 " "	1 3/8 " "	346	455	18062	1 " 8 " "
4 1/2 " "	1 1/2 " "	390	510	20250	1 " 6 " "
4 3/4 " "	1 5/8 " "	435	575	22500	1 " 5 " "
5 " "	1 3/4 " "	480	640	25000	1 " 3 " "
5 1/2 " "	1 7/8 " "	581	775	30250	1 " "
6 " "	2 " "	678	930	36000	10 3/4 " "

Note that strength is given for new rope. For safe working should be divided by 10.

WEIGHT OF CASTING OF DIFFERENT METALS PER POUND OF WOOD PATTERN

	Cast Iron	Copper	Gun Metal	Yell. Brass	Zinc	Aluminum
Mahogany.....	8 lb.	10 lb.	10 lb.	9.8 lb.	8 lb.	3 lb.
White pine.....	14 "	18 "	17.8 "	17.5 "	14.5 "	6 "
Yellow pine.....	13 "	16 "	16 "	15.5 "	12.6 "	5.5 "
Cedar.....	11.5 "	14.5 "	14.5 "	14 "	11.4 "	4.6 "
Maple.....	10 "	12.5 "	12.4 "	12 "	9.8 "	4.2 "
Cherry.....	9 "	12 "	12 "	11.8 "	9.4 "	4 "

SHRINKAGE OF CASTINGS PER FOOT — Yellow brass, $\frac{1}{64}$; gun metal, $\frac{1}{64}$; copper, $\frac{3}{16}$; zinc, $\frac{5}{16}$; cast iron, $\frac{1}{8}$; aluminum, $\frac{1}{32}$; lead, $\frac{5}{32}$. In thin brass = $\frac{3}{16}$ in.

In large cylinders = $\frac{3}{32}$ in. In small cylinders = $\frac{1}{16}$ in. In tin = $\frac{1}{4}$ in.

In bismuth = $\frac{5}{32}$ in. In beams and girders = $\frac{1}{10}$ in. In steel = $\frac{1}{4}$ in.

ESTIMATING WEIGHTS OF DIFFERENT METALS IN CUBIC INCH AND CUBIC FOOT FOR FOUNDRY

METALS	WEIGHT PER CU. IN.	WEIGHT PER CU. FT.
Iron	.263 lbs.	451 lbs.
Steel	.288 lbs.	499 lbs.
Brass	.3 lbs.	524 lbs.
Lead	.41 lbs.	708 lbs.
Copper	.32 lbs.	537 lbs.
Tin	.266 lbs.	451 lbs.

For a rough approximation, weighing the pattern and multiplying its weight in pounds by 16 is of course the easiest and quickest way and is the one most used by foundry men in estimating the amount of iron to be melted for a heat or a certain casting. The following constants may be used as multipliers for the metals named when cast:

WEIGHT OF WOOD PER FOOT

The weights in pounds, of various kinds of woods (commercially known as "dry" timber), per foot-board measure as follows: White Pine, 1.98; Spanish Mahogany, 4.42; Honduras Mahogany, 3; Poplar, 3.25; Washington Fir, 2.65; Cedar, 1.93; California Spruce, 2.08; Cherry, 3.5; Maple, 4.08.

TEMPERING LIQUID

Use *Kerosene Oil* (coal oil) for drilling or turning aluminum.

Saltpetre.....	2 ounces
Sal-ammoniac.....	2 ounces
Alum.....	2 ounces
Salt.....	1½ pounds
Soft Water.....	3 gallons

Never heat over cherry red. Draw no temper.

AVOIRDUPOIS OR COMMERCIAL WEIGHT

1 gross or long ton = 2240 pounds.
1 net or short ton = 2000 pounds.

1 pound = 16 ounces = 7000 grains.
1 ounce = 16 drachms = 437.5 grains.

The following measures for weight are now seldom used in the United States:
1 hundred-weight = 4 quarters = 112 pounds (1 gross or long ton = 20 hundred-weights); 1 quarter = 28 pounds; 1 stone = 14 pounds; 1 quintal = 100 pounds.

CIRCULAR AND ANGULAR MEASURE

60 seconds (") = 1 minute (')
60 minutes = 1 degree (°)
360 degrees = 1 circumference (C)

APOTHECARIES' WEIGHT

20 grains (gr.) = 1 scruple (sc., or ℥).
3 scruples = 1 dram (dr., or ℥).
8 drams = 1 ounce (oz., or ℥).
12 ounces = 1 pound (lb., or lb.).

WEIGHT PER BUSHEL OF DIFFERENT GRAINS, ETC.

Barley.....	48 pounds	Flax Seed.....	56 pounds
Beans.....	63 pounds	Hemp Seed.....	48 pounds
Buckwheat.....	46 pounds	Oats.....	32 pounds
Blue Grass Seed.....	14 pounds	Peas.....	64 pounds
Corn.....	56 pounds	Rye.....	56 pounds
Corn Meal.....	50 pounds	Salt.....	80 pounds
Clover Seed.....	60 pounds	Timothy Seed.....	45 pounds
Dried Apples.....	22 pounds	Wheat.....	60 pounds
Dried Peaches.....	33 pounds	Potatoes (heaped).....	60 pounds

MISCELLANEOUS UNITS OF LENGTH

1-mil = 0.001 inch	1-pole (British) = 5.5 yards
1-hand = 4 inches	1-British fathom = 6.08 feet
1-span = 9 inches	1-toise = 6 Paris feet
1-fathom = 6 feet	1-Paris foot (pied) = 12 Paris inches
1-link = 0.66 feet	12-Paris inches = 0.324839 meter
1-rod = 25 links	1-Paris line (ligne) = 0.225583 centimeter
1-Surveyor's or Gunter's chain = 100 feet	1-Light year = 5.9 x 10 ¹² miles
1-knot (nautical mile) = 1.1516 statute miles	1-point (type size) = 1/72 or 0.08333 inch
1-furlong = 40 rods	1-cubit = 18 inches

MEASURES OF PRESSURE

1 pound per square inch = 144 pounds per square foot = 0.068 atmosphere = 2.042 inches of mercury at 62 degrees F. = 27.7 inches of water at 62 degrees F. = 2.31 feet of water at 62 degrees F.

1 atmosphere = 30 inches of mercury at 62 degrees F. = 14.7 pounds per square inch = 2116.3 pounds per square foot = 33.95 feet of water at 62 degrees F.

1 foot of water at 62 degrees F. = 62.355 pounds per square foot = 0.433 pound per square inch.

1 inch of mercury at 62 degrees F. = 1.132 foot of water = 13.58 inches of water = 0.491 pound per square inch.

TROY WEIGHT, USED FOR WEIGHING GOLD AND SILVER

1 pound = 12 ounces = 5760 grains.
1 ounce = 20 pennyweights = 480 grains.
1 pennyweight = 24 grains.
1 carat (used in weighing diamonds) = 3.086 grains.
1 grain Troy = 1 grain avoirdupois = 1 grain apothecaries' weight.

NAUTICAL MEASURE

The following measures of length are also used occasionally: 1 mil equals 0.001 inch. 1 fathom equals 2 yards equals 6 feet. 1 rod equals 5.5 yards equals 16.5 feet. 1 hand equals 4 inches. 1 span equals 9 inches. 1 mile equals 1760 yards equals 5280 feet. 1 league equals 3 nautical miles. 1 nautical mile (knot) equals 6080.26 feet equals 1.1516 statute mile. One degree at the equator equals 60 nautical miles equals 69.168 statute miles. 360 degrees equals 21,600 nautical miles equals 24,874.5 statute miles equal circumference of earth at the equator.

MEASURE USED FOR DIAMETERS AND AREAS OF ELECTRIC WIRES

1 circular inch = area of circle 1 inch in diameter = 0.7854 square inch.

1 circular inch = 1,000,000 circular mils.

1 square inch = 1.2732 circular inch = 1,273,239 circular mils.

A circular mil is the area of a circle 0.001 inch in diameter.

SHIPPING MEASURE

For measuring entire internal capacity of a vessel:

1 register ton = 100 cubic feet.

For measurement of cargo:

1 U. S. shipping ton = 40 cubic feet = 32.143 U. S. bushels = 31.16 Imperial bushels.

British shipping ton = 42 cubic feet = 33.75 U. S. bushels = 32.72 Imperial bushels.

CUBIC MEASURE

1,728 cubic in. = 1 cu. ft.

27 cubic ft. = 1 cubic yard

128 cu. ft. = 1 cord (wood)

40 cu. ft. = 1 ton (shpg.)

2,150.42 cubic inches = 1 standard bushel

268.8 cubic inches = 1 standard gallon

1 cubic foot = about four-fifths of a bushel

1 cord of wood = $4 \times 4 \times 8$ feet = 128 cubic feet.

1 perch of masonry = $16\frac{1}{2} \times 1\frac{1}{2} \times 1$ foot = $24\frac{3}{4}$ cubic feet.

SURVEYORS' MEASURE

1 Link = 7.92 inches

1 Rod (or Pole) = 25 links = $16\frac{1}{2}$ feet

1 Chain = 100 links = 4 rods = 66 feet

1 Furlong = 40 rods = 10 chains = $\frac{1}{8}$ mile

1 Mile = 320 rods = 5,280 feet

1 Acre = 160 square rods = 43,560 sq. feet

1 Square Mile = 640 acres

SQUARE MEASURE

1 square mile = 640 acres = 6400 square chains.

1 acre = 10 square chains = 4840 square yards = 43,560 square feet.

1 square chain = 16 square rods = 484 square yards = 4356 square feet.

1 square rod = 30.25 square yards = 272.25 square feet = 625 square links.

1 square yard = 9 square feet.

1 square foot = 144 square inches.

An acre is equal to a square, the side of which is 208.7 feet.

DRY MEASURE

1 bushel (U. S. or Winchester struck bushel) = 1.2445 cubic foot = 2150.42 cubic inches.

1 bushel = 4 pecks = 32 quarts = 64 pints

1 peck = 8 quarts = 16 pints.

1 quart = 2 pints.

1 heaped bushel = $1\frac{1}{4}$ struck bushel.

1 cubic foot = 0.8036 struck bushel.

1 British Imperial bushel = 8 Imperial gallons = 1.2837 cubic foot = 2218.19 cubic inches.

LIQUID OR WINE MEASURE

The U. S. Standard Gallon measures 231 Cubic Inches, or 8.33888 Pounds avoirdupois of pure water, at about 39.85 degrees Fahr., the Barometer at 30 inches.

Gills	Pints	Quarts	Gallons	Tierces	Hogs- heads	Punch- cons	Pipes	Tun	Cubic Inches
4 =	1 =								28.375
8 =	2 =	1 =							57.75
32 =	8 =	4 =	1 =						231.
1344 =	336 =	168 =	42 =	1					
2016 =	504 =	252 =	63 =	$1\frac{1}{3}$ = 1					
2488 =	672 =	336 =	84 =	2 = $1\frac{1}{3}$ = 1					
4032 =	1008 =	504 =	126 =	3 = 2 = $1\frac{1}{2}$ = 1					
8064 =	2016 =	1008 =	252 =	6 = 4 = 3 = 2 = 1					

A Cubic Foot contains $7\frac{1}{2}$ Gallons.

The British Imperial Gallon contains 277.27 Cubic inches and = 1.2 U. S. Gallons.

APOTHECARIES' MEASURE.

60 minims (or drops), m.....	= 1 fluid dram, f 3.
8 fluid drams	= 1 fluid ounce, f 3.
16 fluid ounces	= 1 pint (<i>octarius</i>), O.
8 pints.....	= 1 gallon (<i>congius</i>).

CLOTH MEASURE.

2½ in.....	= 1 nail, na.	5 qr. = 45 inches.....	= 1 ell English.
4 na. = 9 inches.....	= 1 quarter, qr.	6 qr. = 54 inches.....	= 1 ell French.
4 qr. = 36 inches.....	= 1 yard, yd.	37.2 in.....	= 1 ell Scotch.
3 qr. = 27 inches.....	= 1 ell Flemish.		

NUMBERS.

12 units	= 1 dozen.	12 gross.....	= 1 great gross.
12 dozen.....	= 1 gross.	20 units.....	= 1 score.

PAPER.

24 sheets	= 1 quire.	20 quires.....	= 1 ream.
10½ quires.....	= 1 token.		

TIME.

60 seconds.....	= 1 minute.	4 weeks	= 1 month.
60 minutes.....	= 1 hour.	13 months, 1 day, 6 hours, or } 365 days, 6 hours	= 1 Julian year.
24 hours.....	= 1 day.	12 calendar months	= 1 year.
7 days.....	= 1 week.		
2 weeks.....	= 1 fortnight.		

The length of the *astronomical year* is about 365½ days, or 365 days, 5 hours, 48 minutes, 46 seconds. As the *common year* is 365 days, it becomes necessary once in every four years to add a day to the year, making the *leap year* of 366 days.

Every year whose number is divisible by 4 without a remainder is a leap year, excepting the full centuries, which to be leap years must be divisible by 400 without a remainder; 1900, therefore, was not a leap year.

January, March, May, July, August, October, and December contain 31 days.

April, June, September, and November contain 30 days. February contains 28 days, except in leap years, when it contains 29 days.

LINEAR MEASURE.

3 barleycorns, or ...	} 1 inch (in.)
13 lines, or.....	
72 points, or.....	
1,000 mils (mi.).....	
3 inches.....	= 1 palm
4 inches.....	= 1 hand
9 inches.....	= 1 span
12 inches.....	= 1 foot (ft.)
18 inches.....	= 1 cubit
3 feet.....	= 1 yard (yd.)
2½ feet.....	= 1 military pace
5 feet.....	= 1 geometrical pace
2 yards.....	= 1 fathom
5½ yards.....	= 1 rod, pole, or perch
66 feet, or.....	= 1 Gunter's chain
4 rods.....	
40 poles, or.....	= 1 furlong (fur.)
220 yards.....	
8 furlongs, or.....	
1,760 yards, or.....	= 1 mile
5,280 feet.....	
3 miles.....	= 1 league

175 lbs. troy..... = 144 lbs. AVOIRDUPOIS

The Imperial Standard Measure is used by British pharmacists. Its denominations and their relative value are:

Gal.	Quarts.	Pints.	F. Oz.	℥ Dr.	Minims
1	= 4	= 8	= 160	= 1,280	= 76,800
	1	= 2	= 40	= 320	= 19,200
		1	= 20	= 160	= 9,600
				1	= 480
					1 = 60

The relative value of United States Apothecaries' and British Imperial Measures is as follows:

(Imperial Measure.)

U. S. Apothecaries' Measure.	Pints.	F. Oz.	℥ Dr.	Minims
1 Gallon = .83311 Gallon, or	6	13	2	22.85
1 Pint = .83311 Pint, or		16	5	17.86
1 Fl. Oz. = 1.04139 Fl. Oz., or			1	0 19.86
1 Fl. Dr. = 1.04139 Fl. Dr., or				1 2.48
1 Minim = 1.04139 Minim, or				1.04

THE METRIC SYSTEM.

MEASURES FOR WOOD.

1 centistere.....	= 0.01 stere.....	= .353 cubic feet.
1 decistere.....	= 0.1 stere.....	= 3.53 cubic feet.
1 stere.....	= 1 cubic meter.....	= 35.316 cubic feet.
		= .2759 cord.
1 decastere.....	= 10 steres.....	= 13.079 cubic yards.

(Continued on top of next page.)

LONG MEASURE

Millimeters	×	.03937	=	inches
Millimeters	+	25.4	=	inches
Centimeters	×	.3937	=	inches
Centimeters	+	2.54	=	inches
Meters	=	39.37	=	inches (Act of Congress)
Meters	×	3.281	=	feet
Meters	×	1.094	=	yards
Kilometers	×	.621	=	miles
Kilometers	+	3280.7	=	feet
Kilometers	+	1.6093	=	miles

LIQUID MEASURE

Liters	×	61.022	=	cubic inches (Act of Congress)
Liters	×	33.84	=	fluid ounces (U. S. Phar.)
Liters	×	.2642	=	gallons (231 cubic inches)
Liters	+	3.78	=	gallons (231 cubic inches)
Liters	+	28.316	=	cubic feet
Hectoliters	×	3.531	=	cubic feet
Hectoliters	×	2.84	=	bushels (2150.42 cubic inches)
Hectoliters	×	.131	=	cubic yards
Hectoliters	+	26.42	=	gallons (231 cubic inches)

SQUARE MEASURE

Square millimeters	×	.0015	=	square inches
Square millimeters	+	645.1	=	square inches
Square centimeters	×	.155	=	square inches
Square centimeters	+	6.451	=	square inches
Square meters	×	10.764	=	square feet
Square kilometers	×	247.1	=	acres
Hectares	×	2.471	=	acres

CUBIC MEASURE

Cubic centimeters	+	16.383	=	cubic inches
Cubic centimeters	+	3.69	=	fluid drachms (U. S. P.)
Cubic centimeters	+	29.57	=	fluid ounce (U. S. P.)
Cubic meters	×	35.315	=	cubic feet
Cubic meters	×	1.308	=	cubic yards
Cubic meters	×	264.2	=	gallons (231 cubic inches)

WEIGHTS

Grammes	×	15.432	=	grains (Act of Congress)
Grammes	×	981.	=	dynes
Grammes (water)	+	29.57	=	fluid ounces
Grammes	+	28.35	=	ounces avoirdupois
Grammes per cubic centimeter	+	27.7	=	pounds per cubic inch
Joule	×	.7373	=	foot pounds
Kilograms	×	2.2046	=	pounds
Kilograms	×	35.3	=	ounces avoirdupois
Kilograms	+	1102.3	=	tons (2,000 pounds)
Kilograms	×	per square centimeter 14.223	=	pounds per square inch

MEASURES OF CAPACITY

Metric Denominations and Values

Names	No.	Liters	Cubic Measure
Kiloliter	=	1,000	= 1 cubic meter
Hectoliter	=	100	= .1 cubic meter
Decaliter	=	10	= 10 c. decimeters
Liter	=	1	= 1 c. decimeter
Deciliter	=	.1	= .1 c. decimeter
Centiliter	=	.01	= 10 c. centimeters
Milliliter	=	.001	= 1 c. centimeter

Metric Conversion Tables

U. S. to Metric

LINEAR

- 1 inch = 25.4001 millimeters.
 1 foot = 0.304801 meters
 1 yard = 0.914402 meters.
 1 mile = 1.60935 kilometers.

SQUARE

- 1 square inch = 6.452 square centimeters.
 1 square foot = 9.290 square decimeters.
 1 square yard = 0.836 square meters.

CUBIC

- 1 cubic inch = 16.387 cubic centimeters.
 1 cubic foot = 0.02832 cubic meters.
 1 cubic yard = 0.765 cubic meters.

WEIGHT

- 1 grain = 64.7989 milligrammes.
 1 avoirdupois ounce = 28.3495 grammes.
 1 troy ounce = 31.10348 grammes.
 1 avoirdupois pound = 0.45359 kilogrammes.

CAPACITY

- 1 fluid drachm = 3.70 cubic centimeters.
 1 fluid ounce = 29.57 milliliters.
 1 quart = 0.94636 liters.
 1 gallon = 3.78544 liters.

Metric to U. S.

LINEAR

- 1 meter = 39.3700 inches.
 1 meter = 3.28083 feet.
 1 meter = 1.09361 yards.
 1 kilometer = 0.62137 miles.

SQUARE

- 1 square centimeter = 0.1550 square inches.
 1 square meter = 10.7610 square feet.
 1 square meter = 1.196 square yards.

CUBIC

- 1 cubic centimeter = 0.0610 cubic inches.
 1 cubic meter = 35.314 cubic feet.
 1 cubic meter = 1.308 cubic yards.

WEIGHT

- 1 milligramme = 0.01543 grains.
 1 kilogramme = 15432.36 grains.
 1 hectogramme = 3.5274 avoirdupois ounces.
 1 kilogramme = 2.20462 avoirdupois pounds.

CAPACITY

- 1 milliliter = 0.27 fluid drachms.
 1 centiliter = 0.338 fluid ounces.
 1 liter = 1.0567 quarts.
 1 dekaliter = 2.6417 gallons.

Miscellaneous Metric System

- 1 kilogram per meter = .6720 pounds per foot.
 1 gram per square millimeter = 1.422 pounds per square inch.
 1 kilogram per square meter = 0.2084 pounds per square foot.
 1 kilogram per cubic meter = .0624 pounds per cubic foot.
 1 degree centigrade = 1.8 degrees Fahrenheit.
 1 pound per foot = 1.488 kilograms per meter.
 1 pound per square foot = 4.882 kilograms per square meter.
 1 pound per cubic foot = 16.02 kilograms per cubic meter.
 1 degree Fahrenheit = .5556 degrees centigrade.
 1 Calorie (French Thermal Unit) = 3.968 B. T. U. (British Thermal Unit).
 1 Horse Power = 746 Watts.
 1 Watt (Unit of Electrical Power) = $\left\{ \begin{array}{l} .00134 \text{ Horse Power.} \\ 44.22 \text{ foot pounds per minute.} \\ 1000 \text{ Watts.} \end{array} \right.$
 1 Kilowatt = $\left\{ \begin{array}{l} 1.34 \text{ Horse Power} \\ 44,220 \text{ foot pounds per minute.} \end{array} \right.$

STRENGTH OF MATERIALS

Ultimate Strength of Common Metals: Pounds Per Square Inch				
Material	Tension	Compression	Shear	Modulus o Elasticity
Aluminum	15,000	12,000	12,000	11,000,000
Brass, cast	24,000	30,000	36,000	9,000,000
Bronze, gun-metal	32,000	20,000	—	10,000,000
Bronze, manganese	60,000	120,000	—	—
Bronze, phosphor	50,000	—	—	14,000,000
Copper, cast	24,000	40,000	30,000	10,000,000
Copper Wire, annealed	36,000	—	—	15,000,000
Copper Wire, unannealed	60,000	—	—	18,000,000
Iron, cast	15,000	80,000	18,000	12,000,000
Iron Wire, annealed	60,000	—	—	15,000,000
Iron Wire, unannealed	80,000	—	—	25,000,000
Iron, wrought	48,000	46,000	40,000	27,000,000
Lead, cast	2,000	—	—	1,000,000
Steel Castings	70,000	70,000	60,000	30,000,000
Steel, structural	60,000	60,000	50,000	29,000,000
Steel Wire, annealed	80,000	—	—	29,000,000
Steel Wire, unannealed	120,000	—	—	30,000,000
Steel Wire, crucible	180,000	—	—	30,000,000
Steel Wire, plow	268,000	—	—	—
Steel Wire, susp. bridge	200,000	—	—	30,000,000
Steel Wire, piano	300,000	—	—	—
Tin, cast	3,500	6,000	—	4,000,000
Zinc, cast	5,000	20,000	—	13,000,000

Average Strength of Common Materials Other Than Metals		
Material	Compression	Tension
Bricks, best hard	12,000	400
Bricks, light red	1,000	40
Brickwork, common	1,000	50
Brickwork, best	2,000	300
Cement, Portland, one month old	2,000	400
Cement, Portland, one year old	3,000	500
Concrete, Portland	1,000	200
Concrete, Portland, one year old	2,000	400
Hemlock	4,000	6,000
Pine, short leaf yellow	6,000	9,000
Pine, Georgia	8,000	12,000
Pine, White	5,500	7,000
White Oak	7,000	10,000

Factors of Safety

Material	Steady Load	Load Varying from Zero to Maximum in one Direction	Load Varying from Zero to Maximum in both Directions	Suddenly Varying Loads and Shocks
Cast Iron	6	10	15	20
Wrought Iron	4	6	8	12
Steel	5	6	8	12
Wood	8	10	15	20
Brick	15	20	25	30
Stone	15	20	25	30

Comparative Strength of Timber and Cast Iron

Table showing the transverse strength of timber and of cast iron one foot long and one inch square.


Material.	Breaking Weight, lbs.	Weight Borne with Safety, lbs.
Ash, seasoned.....	175	105
Chestnut, seasoned.....	170	115
Hickory, seasoned.....	270	200
White Oak, seasoned.....	240	196
White Pine, seasoned.....	135	95
Yellow Pine, seasoned.....	150	100
Iron (cast).....	5,781	4,000

CARPENTER'S RULES

ROOF FRAMING

Definition of Terms.—The “gable” is the triangular end of a common double-roofed building. By the “pitch” of a roof is meant the relation which the height of the ridge above the level of the roof-plates bears to the span, or the distance between the studs on which the roof rests. Thus a roof that is one-half as high as the width of the building is “half-pitch,” one that is one-fourth as high as the width is “quarter-pitch,” etc.

The following illustration from Hodgson's “Practical Treatise on the Steel Square,” not only shows the most common pitches, but also gives the degrees:



“Most carpenters,” says Mr. Hodgson, “know that half-pitch is 45 degrees, yet few know third-pitch is nearly 34, and quarter-pitch about 27 degrees.

“A building 24 feet wide (as the rafters come to the center) has a 12-foot run and half-pitch, the rise would also be 12 feet, and the length of the rafter would be 17 feet (the diagonal of 12). Length, cuts,

etc., could all be figured from the one illustration.”

The Length of Rafters for the most common pitches can be found as follows from any given span:

If $\frac{1}{2}$ pitch,	multiply span by .559, or 7-12 nearly.
If $\frac{1}{3}$ “	“ “ “ .6, or 3-5 “
If $\frac{1}{4}$ “	“ “ “ .625, or $\frac{5}{8}$ “
If $\frac{1}{6}$ “	“ “ “ .71, or 7-10 “
If $\frac{1}{8}$ “	“ “ “ .8, or 4-5 “
If full “	“ “ “ 1.12, or $1\frac{1}{8}$ “


To lengths thus obtained must be added amount of projection of rafters at the eaves. Continued on next page

CARPENTER'S RULES

As rafters must be purchased of even lengths, a few inches more or less on their lengths will make a difference to the pitch so slight that it cannot be detected by the eye.

Example.—To determine the length of rafters for a roof constructed one-half pitch, with a span of 24 feet— $24 \times .71 = 17.04$; or, practically, just 17 feet. A projection of one foot for eaves makes the length to be purchased 18 feet.

How to Find Bevels and Length of Rafters




How to Find the Length and Bevels of Rafters.

1. **Bevels.**—Place your steel square on a board (say the building is 40 feet long), with the corner 20 inches from the edge of the board one way and 7 inches the other, and mark it as shown in the above figure. The angle at *c* will be the bevel of the upper end, and the angle at *d* at the lower end of the rafter.

2. **Length.**—From *a* to *b* on the outer edge of the board is the length of the rafter. The 20 inches shows the 20 feet, or half the width of the building; the 7 inches the 7 foot rise. The distance from *a* to *b*, on the edge of the board, is 21 inches, two-twelfths and one-quarter of a twelfth (always use a square with inches on one side divided into twelfths), therefore this rafter will be 21 feet and $2\frac{1}{4}$ inches long.

How to Determine Curves for Brick and Stone Arches



Measure width required and draw the figure above indicated. If the points in the figures are equal on both sides, the curve will be an exact part of a circle.

To Find the Area of a Gable End


Multiply the width of the building by the height of the roof, and take one-half of the result. Or, if the roof is quarter-pitch, find the area by multiplying the width of the roof by $\frac{1}{2}$ of itself.

Table for Finding the Contents of Square Tanks

A tank five feet by five feet holds	6 barrels.
A tank six feet by six feet holds	8 $\frac{1}{2}$ "
A tank seven feet by seven feet holds	11 $\frac{1}{2}$ "
A tank eight feet by eight feet holds	15 $\frac{1}{2}$ "
A tank nine feet by nine feet holds	19 $\frac{1}{2}$ "
A tank ten feet by ten feet holds	23 $\frac{1}{2}$ "

The above table is for one foot of depth only.

To find the contents of a trough, measure its depth in feet and multiply it by the contents of one foot in depth.



DIESEL ENGINE PARTS AS SHOWN ON ABOVE CHART

1	Cylinder and Base	135	Subbase and Fuel Tank	661	Fuel Filter Cover
2	Cylinder Head and Gasket	150	Piston Pin Bushing	662	Fuel Filter Cartridge
3	Fly-wheel	185	Starting Crank Assembly	*663	Fuel Filter Cover Gasket
4	Crankshaft	242	Inlet Valve Rocker Assembly	664	Governor Hub Nut
5	Side Bearing Plate	244	Valve Rocker Arm Roller and 245 Pin	665	Compression Release Lever Stud
6	Side Bearing Plate Shims	269	Governor Bearing	666	Governor Bell Crank Fulcrum Pin
7	Piston	367	Cam Case Cover Assembly	667	Valve Rod Collar
8	Piston Ring	392	Crankcase Filler Cap	668	Starting Crank Pawl
9A	Oil Regulating Ring	*337	Crankcase Filler Cap	671	Starting Crank Pawl Pin
10	Piston Pin	*435	Subbase Gasket	672	Starting Crank Pawl Spring
11	Connecting Rod Assembly (includes 11, 12, 13, 14, 15, 159, 455)	*448	Crankcase Cover Gasket	673	Fuel Transfer Pump Gasket
12	Crank Pin Bearing Shims	455	Oil Splasher Wire	*674	Fuel Transfer Pump Discharge Line
13	Connecting Rod Bolt, Nut and Cotter	458	Crankcase Filler Screw		
14	Crank Gear	*464	Cam Gear Key		
15	Camshaft	474	Crankshaft Filler Spring		
16	Camshaft	482	Crankshaft Felt		
17	Cam Roller and No. 20 Pin	484	Crankshaft Felt Retaining Washer		
18	Exhaust Valve—Silicone Steel	500	Piston Assembly—Includes 8, 9A, 9, 10, 105		
19	Inlet Valve—S.A.E. Steel	505	Governor Assembly—Includes 36, 37, 38, 39, 41, 52, 107, 129, 263, 664		
20	Valve Push Rod	509	Cylinder Head Assembly—Includes 3, 21, 22, 42, 43, 54, 520		
21	Valve Roller Rocker Assembly—In-		Crankcase Filler Breather Valve		
22	cludes 3, 20		Inlet and Exhaust Valve Stem Guides		
23	Exhaust Valve Rocker Assembly—In-		Rocker Head Stud Nut		
24	cludes 23 and Nut		Rocker Head Stud Nut		
25	Valve Rocker Fulcrum Pin with Oil		Compression Release Lever		
26	Valve Rocker Fulcrum Pin		Includes 532, 583, 584, 585, 586, 57		
27	Valve Rocker Fulcrum Pin		Fuel Valve Plug		
28	Governor Hub		Fuel Transfer Pump Relief Valve		
29	Governor Hub		Fuel Transfer Pump Relief Valve		
30	Governor Hub		Fuel Transfer Pump Relief Valve		
31	Governor Hub		Fuel Transfer Pump Relief Valve		
32	Governor Hub		Fuel Transfer Pump Relief Valve		
33	Governor Hub		Fuel Transfer Pump Relief Valve		
34	Governor Hub		Fuel Transfer Pump Relief Valve		
35	Governor Hub		Fuel Transfer Pump Relief Valve		
36	Governor Hub		Fuel Transfer Pump Relief Valve		
37	Governor Hub		Fuel Transfer Pump Relief Valve		
38	Governor Hub		Fuel Transfer Pump Relief Valve		
39	Governor Hub		Fuel Transfer Pump Relief Valve		
40	Governor Hub		Fuel Transfer Pump Relief Valve		
41	Governor Hub		Fuel Transfer Pump Relief Valve		
42	Governor Hub		Fuel Transfer Pump Relief Valve		
43	Governor Hub		Fuel Transfer Pump Relief Valve		
44	Governor Hub		Fuel Transfer Pump Relief Valve		
45	Governor Hub		Fuel Transfer Pump Relief Valve		
46	Governor Hub		Fuel Transfer Pump Relief Valve		
47	Governor Hub		Fuel Transfer Pump Relief Valve		
48	Governor Hub		Fuel Transfer Pump Relief Valve		
49	Governor Hub		Fuel Transfer Pump Relief Valve		
50	Governor Hub		Fuel Transfer Pump Relief Valve		
51	Governor Hub		Fuel Transfer Pump Relief Valve		
52	Governor Hub		Fuel Transfer Pump Relief Valve		
53	Governor Hub		Fuel Transfer Pump Relief Valve		
54	Governor Hub		Fuel Transfer Pump Relief Valve		
55	Governor Hub		Fuel Transfer Pump Relief Valve		
56	Governor Hub		Fuel Transfer Pump Relief Valve		
57	Governor Hub		Fuel Transfer Pump Relief Valve		
58	Governor Hub		Fuel Transfer Pump Relief Valve		
59	Governor Hub		Fuel Transfer Pump Relief Valve		
60	Governor Hub		Fuel Transfer Pump Relief Valve		
61	Governor Hub		Fuel Transfer Pump Relief Valve		
62	Governor Hub		Fuel Transfer Pump Relief Valve		
63	Governor Hub		Fuel Transfer Pump Relief Valve		
64	Governor Hub		Fuel Transfer Pump Relief Valve		
65	Governor Hub		Fuel Transfer Pump Relief Valve		
66	Governor Hub		Fuel Transfer Pump Relief Valve		
67	Governor Hub		Fuel Transfer Pump Relief Valve		
68	Governor Hub		Fuel Transfer Pump Relief Valve		
69	Governor Hub		Fuel Transfer Pump Relief Valve		
70	Governor Hub		Fuel Transfer Pump Relief Valve		
71	Governor Hub		Fuel Transfer Pump Relief Valve		
72	Governor Hub		Fuel Transfer Pump Relief Valve		
73	Governor Hub		Fuel Transfer Pump Relief Valve		
74	Governor Hub		Fuel Transfer Pump Relief Valve		
75	Governor Hub		Fuel Transfer Pump Relief Valve		
76	Governor Hub		Fuel Transfer Pump Relief Valve		
77	Governor Hub		Fuel Transfer Pump Relief Valve		
78	Governor Hub		Fuel Transfer Pump Relief Valve		
79	Governor Hub		Fuel Transfer Pump Relief Valve		
80	Governor Hub		Fuel Transfer Pump Relief Valve		
81	Governor Hub		Fuel Transfer Pump Relief Valve		
82	Governor Hub		Fuel Transfer Pump Relief Valve		
83	Governor Hub		Fuel Transfer Pump Relief Valve		
84	Governor Hub		Fuel Transfer Pump Relief Valve		
85	Governor Hub		Fuel Transfer Pump Relief Valve		
86	Governor Hub		Fuel Transfer Pump Relief Valve		
87	Governor Hub		Fuel Transfer Pump Relief Valve		
88	Governor Hub		Fuel Transfer Pump Relief Valve		
89	Governor Hub		Fuel Transfer Pump Relief Valve		
90	Governor Hub		Fuel Transfer Pump Relief Valve		
91	Governor Hub		Fuel Transfer Pump Relief Valve		
92	Governor Hub		Fuel Transfer Pump Relief Valve		
93	Governor Hub		Fuel Transfer Pump Relief Valve		
94	Governor Hub		Fuel Transfer Pump Relief Valve		
95	Governor Hub		Fuel Transfer Pump Relief Valve		
96	Governor Hub		Fuel Transfer Pump Relief Valve		
97	Governor Hub		Fuel Transfer Pump Relief Valve		
98	Governor Hub		Fuel Transfer Pump Relief Valve		
99	Governor Hub		Fuel Transfer Pump Relief Valve		
100	Governor Hub		Fuel Transfer Pump Relief Valve		
101	Governor Hub		Fuel Transfer Pump Relief Valve		
102	Governor Hub		Fuel Transfer Pump Relief Valve		
103	Governor Hub		Fuel Transfer Pump Relief Valve		
104	Governor Hub		Fuel Transfer Pump Relief Valve		
105	Governor Hub		Fuel Transfer Pump Relief Valve		
106	Governor Hub		Fuel Transfer Pump Relief Valve		
107	Governor Hub		Fuel Transfer Pump Relief Valve		
108	Governor Hub		Fuel Transfer Pump Relief Valve		
109	Governor Hub		Fuel Transfer Pump Relief Valve		
110	Governor Hub		Fuel Transfer Pump Relief Valve		
111	Governor Hub		Fuel Transfer Pump Relief Valve		
112	Governor Hub		Fuel Transfer Pump Relief Valve		
113	Governor Hub		Fuel Transfer Pump Relief Valve		
114	Governor Hub		Fuel Transfer Pump Relief Valve		
115	Governor Hub		Fuel Transfer Pump Relief Valve		
116	Governor Hub		Fuel Transfer Pump Relief Valve		
117	Governor Hub		Fuel Transfer Pump Relief Valve		
118	Governor Hub		Fuel Transfer Pump Relief Valve		
119	Governor Hub		Fuel Transfer Pump Relief Valve		
120	Governor Hub		Fuel Transfer Pump Relief Valve		
121	Governor Hub		Fuel Transfer Pump Relief Valve		
122	Governor Hub		Fuel Transfer Pump Relief Valve		
123	Governor Hub		Fuel Transfer Pump Relief Valve		
124	Governor Hub		Fuel Transfer Pump Relief Valve		
125	Governor Hub		Fuel Transfer Pump Relief Valve		
126	Governor Hub		Fuel Transfer Pump Relief Valve		
127	Governor Hub		Fuel Transfer Pump Relief Valve		
128	Governor Hub		Fuel Transfer Pump Relief Valve		
129	Governor Hub		Fuel Transfer Pump Relief Valve		
130	Governor Hub		Fuel Transfer Pump Relief Valve		
131	Governor Hub		Fuel Transfer Pump Relief Valve		
132	Governor Hub		Fuel Transfer Pump Relief Valve		
133	Governor Hub		Fuel Transfer Pump Relief Valve		
134	Governor Hub		Fuel Transfer Pump Relief Valve		
135	Governor Hub		Fuel Transfer Pump Relief Valve		
136	Governor Hub		Fuel Transfer Pump Relief Valve		
137	Governor Hub		Fuel Transfer Pump Relief Valve		
138	Governor Hub		Fuel Transfer Pump Relief Valve		
139	Governor Hub		Fuel Transfer Pump Relief Valve		
140	Governor Hub		Fuel Transfer Pump Relief Valve		
141	Governor Hub		Fuel Transfer Pump Relief Valve		
142	Governor Hub		Fuel Transfer Pump Relief Valve		
143	Governor Hub		Fuel Transfer Pump Relief Valve		
144	Governor Hub		Fuel Transfer Pump Relief Valve		
145	Governor Hub		Fuel Transfer Pump Relief Valve		
146	Governor Hub		Fuel Transfer Pump Relief Valve		
147	Governor Hub		Fuel Transfer Pump Relief Valve		
148	Governor Hub		Fuel Transfer Pump Relief Valve		
149	Governor Hub		Fuel Transfer Pump Relief Valve		
150	Governor Hub		Fuel Transfer Pump Relief Valve		
151	Governor Hub		Fuel Transfer Pump Relief Valve		
152	Governor Hub		Fuel Transfer Pump Relief Valve		
153	Governor Hub		Fuel Transfer Pump Relief Valve		
154	Governor Hub		Fuel Transfer Pump Relief Valve		
155	Governor Hub		Fuel Transfer Pump Relief Valve		
156	Governor Hub		Fuel Transfer Pump Relief Valve		
157	Governor Hub		Fuel Transfer Pump Relief Valve		
158	Governor Hub		Fuel Transfer Pump Relief Valve		
159	Governor Hub		Fuel Transfer Pump Relief Valve		
160	Governor Hub		Fuel Transfer Pump Relief Valve		
161	Governor Hub		Fuel Transfer Pump Relief Valve		
162	Governor Hub		Fuel Transfer Pump Relief Valve		
163	Governor Hub		Fuel Transfer Pump Relief Valve		
164	Governor Hub		Fuel Transfer Pump Relief Valve		
165	Governor Hub		Fuel Transfer Pump Relief Valve		
166	Governor Hub		Fuel Transfer Pump Relief Valve		
167	Governor Hub		Fuel Transfer Pump Relief Valve		
168	Governor Hub		Fuel Transfer Pump Relief Valve		
169	Governor Hub		Fuel Transfer Pump Relief Valve		
170	Governor Hub		Fuel Transfer Pump Relief Valve		
171	Governor Hub		Fuel Transfer Pump Relief Valve		
172	Governor Hub		Fuel Transfer Pump Relief Valve		
173	Governor Hub		Fuel Transfer Pump Relief Valve		
174	Governor Hub		Fuel Transfer Pump Relief Valve		
175	Governor Hub		Fuel Transfer Pump Relief Valve		
176	Governor Hub		Fuel Transfer Pump Relief Valve		
177	Governor Hub		Fuel Transfer Pump Relief Valve		
178	Governor Hub		Fuel Transfer Pump Relief Valve		
179	Governor Hub		Fuel Transfer Pump Relief Valve		
180	Governor Hub		Fuel Transfer Pump Relief Valve		
181	Governor Hub		Fuel Transfer Pump Relief Valve		
182	Governor Hub		Fuel Transfer Pump Relief Valve		
183	Governor Hub		Fuel Transfer Pump Relief Valve		
184	Governor Hub		Fuel Transfer Pump Relief Valve		
185	Governor Hub		Fuel Transfer Pump Relief Valve		
186	Governor Hub		Fuel Transfer Pump Relief Valve		
187	Governor Hub		Fuel Transfer Pump Relief Valve		
188	Governor Hub		Fuel Transfer Pump Relief Valve		
189	Governor Hub		Fuel Transfer Pump Relief Valve		
190	Governor Hub		Fuel Transfer Pump Relief Valve		
191	Governor Hub		Fuel Transfer Pump Relief Valve		
192	Governor Hub		Fuel Transfer Pump Relief Valve		
193	Governor Hub		Fuel Transfer Pump Relief Valve		
194	Governor Hub		Fuel Transfer Pump Relief Valve		
195	Governor Hub		Fuel Transfer Pump Relief Valve		
196	Governor Hub		Fuel Transfer Pump Relief Valve		
197	Governor Hub		Fuel Transfer Pump Relief Valve		
198	Governor Hub		Fuel Transfer Pump Relief Valve		
199	Governor Hub		Fuel Transfer Pump Relief Valve		
200	Governor Hub		Fuel Transfer Pump Relief Valve		

Parts marked * are not illustrated.

THE PISTON RING

The pistons, which receive the force of the explosion and expansion and transmit the motion to the connecting rod and crank, are commonly made of soft gray cast iron, although some pistons of aluminum and also of an aluminum alloy called *lynite* are being used.

The aluminum and alloy pistons have the advantage of being light, and it is also claimed that they radiate heat much faster than cast iron. Being lighter than cast iron, the aluminum or alloy piston is easier to move up and down in the cylinder.

The expansion of these pistons is more than for cast iron and, consequently, a greater clearance must be provided when they are being fitted to the cylinders. The pistons are turned and ground so that they will be a few thousandths of an inch smaller in diameter than the cylinder in order that there will be a good sliding fit without undue friction. The pistons are made gas-tight by means of cast iron piston rings placed in grooves around the body of the piston. Ordinarily, three rings, placed in the piston above the wrist pin, are used. In some cases an oil groove is also cut in the piston below the rings to improve the lubrication between the piston and the cylinder walls.

Piston rings are of two general types, the concentric and eccentric; the concentric rings are of uniform thickness, while the eccentric rings are considerably thicker on the side opposite the opening. It is impossible with a concentric ring to get a uniform bearing pressure between ring and cylinder wall, but with an eccentric ring, this is accomplished. In addition to these types, of one-piece rings, numerous patented and two-piece rings have been devised so as to get the advantages both of the concentric and eccentric types.

The pistons used in automobile engines are of the trunk type, explosions taking place on one end only. The other end is open and allows for the movement of the connecting rod. The length of the piston is usually $1\frac{1}{4}$ times the diameter. The head of the piston is commonly made flat, although occasionally pistons with slightly concave or convex heads are used.

PISTON RING-GAP CLEARANCE

The average ring-gap clearance, or the distance between the end of a gap-cut ring, should be .0015" ($1\frac{1}{2}$ -thousandths) to .002" for each inch in diameter of the cylinder. Some of the manufacturers advise .003" clearance for each inch diameter of the cylinder.

The following gap clearance table below can be followed:

2" to 3"	.006"
3" to 3½"	.007"
3½" to 4"	.008"
4" to 4½"	.009"

S. A. E. DEPTH AND WIDTH OF RING-GROOVE

Size of Piston	Depth of Groove	Width of Groove
2½"	.113"	.126"
3"	.127"	.188"
3½"	.142"	.188"
4"	.158"	.188"
4½"	.174"	.251"
5"	.190"	.251"
5½"	.207"	.314"
6"	.224"	.314"
6½"	.240"	.377"

THE CONSTRUCTION OF THE PISTON

The Construction of a Piston Used in a Gasoline Engine

It is a single acting, or trunk, kind. Made of Cast Iron, and turned to a good working fit in the cylinder. Near the upper end three or four grooves are cut entirely around its outer circumference, and in these grooves the packing rings are sprung. The displacement of the piston is the volume swept out by the piston. It equals area of piston multiplied by length of stroke. The govern length of a piston when designing one is, for verticle cylinder, piston length should not be less than its diameter; and for horizontal cylinder, piston length should be never less than one and one-third diameter.

The law that governs the velocity or speed of a piston in an explosive motor. The velocity of a piston must be considerably less than the rate of combustion of the explosive mixture, in order that the motor may produce power. The estimated speed limit, or piston velocity, is between 14 and 16 feet per second.

The right kind of material for the contact points of the vibrator of an induction coil is platinum.

Mechanical Adjustments

General Maintenance—Besides the *three important maintenance duties, Oiling, Cooling and Fueling*, there are a number of simple mechanical adjustments the average operator should understand, and make as occasions arise to avoid serious delays. Many times it is desirable merely to recognize the need of them, and have the work done by an experienced mechanic, but even then some rules of procedure will save time and expense. This part of the book, therefore, treats of adjustments to:

Valves and Valve Timing.
Bearings.

Governors.
Accessories.

THE VALVE MECHANISM

Testing Valves—To secure the best power and economy, and to avoid missing and overheating, the valves should always seat fully, and hold a charge so that the hand crank will bounce back or "rock" as the engine is turned over. If the engine fails to offer added resistance to the crank on the compression stroke, the leakage can generally be heard as a hiss. If it comes most distinctly through the carburetor, the intake valve is leaking; through the exhaust, the exhaust valve is leaking or if most distinctly through the breather, the leak is past the piston and rings. Leaks at the spark plugs and petcocks can be seen while the engine is running. If any of the valves leak, they should all be inspected and reground.

Removing Valves—It is always necessary to remove the cylinder head to take the valves out, and if care is used, injury to the cylinder head gasket will be avoided and a new one *will not be required*. The head can generally be loosened by cranking the engine after the hold-down nuts have been removed.

Valve Tappets—By examination of the individual engine the workman can determine whether it is easier to remove the tappets or merely screw down the adjusting screw to give clearance for valve grinding. Either way will afford suitable working conditions.

Valve Spring Retainers—The end of each valve stem is fitted with a shallow steel cup that surrounds the end of the valve spring, and is held to the stem either

by a small horse shoe lock, a pair of wedge blocks or a thread and locking pin. The locking device must be removed before the valve can be withdrawn, and it is advisable to stuff rags beneath the valve stems to prevent these small pieces from falling into the engine or dropping out and becoming lost. To release the lock from the recess in the spring retainer, it is only necessary to pry the retainer up against the spring pressure far enough to push the horse shoe to one side, or let the wedge blocks fall away from the valve stem; with the screw type retainer withdraw the pin from the valve stem, and unscrew the retainer nut.

Examine Valve Seat—Upon removing each valve, clean it thoroughly, and remove all carbon and burned oil. Carefully inspect the valve and valve seat for deep pits or shoulders that must be machined off before grinding begins. **Hy-Powr Engines** have "shrouded" intake valves so that the valve is counter-sunk into the seat. This shoulder must not be removed. (See tabulated data.)

Grinding Equipment—To facilitate the grinding a light spring should be slipped on the valve stem which will serve to lift the valve off the seat when changing its grinding position. Any good commercial grinding compound may be used provided it is not too coarse.

Grinding the Valves—Apply the grinding compound sparingly around the entire valve seat, slip the light lifting spring over the stem, lubricate the stem, and drop the valve into its original place in the cylinder block. The spring should just barely hold the valve off its seat. Exhaust valves can be identified from the intake valves by the number of grinding tool recesses in the top face. Exhaust valves have four recesses while intake valves have but two.

Oscillating Motion—Place the grinding tool in the two holes in the head of the valve to be ground. Press down until the valve is seated. Turn the valve a quarter turn, first in one direction, then in the other. Do this three, or four times. Release the pressure on the valve, and the little spring will lift it off its seat. Now turn the valve about 10 or 15 degrees to another position, and repeat the grinding. Do this until all




Fig. 1—Standard Types of Valve Retainers and Locks

P—Spring retainer lock. S—Valve spring. V—Lower end of valve stem. W—Spring retainer cup.

the compound is rubbed off the valve seat. Withdraw the valve, and put on some fresh compound. Repeat the grinding operation.

• • • **Don't Over-Do the Grinding**—Clean the valve and its seat occasionally to see how the grinding is progressing. When all pits and grooves have disappeared, place eight or ten equally spaced marks with a soft lead pencil on the cleaned face of the valve seat. Then drop the valve in place, give it a quarter turn, and remove it. A perfect seat will be indicated if every pencil mark shows where the valve has rubbed it. If any pencil marks are left untouched, continue the grinding. When the grinding is completed, oil the valve stem, *clean all traces of the grinding compound* from the valve chamber and cylinder walls in the combustion chamber, and re-assemble each valve in its proper port.

• • • **Don't Forget Tappet Clearance**—Refer to Tabulated Data, Figure for the proper valve tappet clearance. *This must be right to avoid valve burning.*

• • • *Never attempt to adjust the tappets without first releasing the lock nut.*

612. *Do not use heavy wrenches on the valve tappet adjusting nuts as they are apt to break the tappet.*

VALVE TIMING

• • • **How to Check the Valve Timing**—Although the flywheel is marked to indicate the valve timing for No. 1 cylinder, and the gears are marked to insure that the camshaft is in correct relation to the crankshaft, it may be necessary on some occasion to check the valve timing. The easiest way with an L-head engine is by measuring the piston travel from top dead center at various valve positions. The valve-in-head engines must be checked by the marks on the flywheel and on the timing gears.




Fig. 2.—Measuring for Dimension "A"
S—Scale measuring from top of piston to top dead center position.

• • • **Remove Cylinder Head**—Before taking any measurements *be sure* the ex-

haust valve tappet clearance is as specified in the Tabulated Data, Figure otherwise the timing cannot be correctly set. Rotate the mushroom type tappets when checking the clearance to make sure there are no high spots. Now with the cylinder head off, measure the distance the piston of No. 1 cylinder *has traveled down* when the exhaust valve just starts to open. This distance corresponds to Dimension "A" in the Tabulated Data, Figure This can be measured directly with a steel scale "S" as shown in Figure 14. *Don't forget it is the MOVEMENT that must be measured.*

• • • **Check Tappet Clearance**—Having checked the opening of the exhaust valve for No. 1 cylinder, it is unnecessary to check the relative setting of the camshaft and crankshaft for any other valves as the cams are all forged integral with the shaft, although the tappet clearance of each valve should be carefully checked and set.




Fig. 3.—Typical Cylinder Head Layout

The order in which cylinder head nuts should be tightened is shown by consecutive numbering. Pull down snugly the first time. Then repeat drawing each nut tight. After the engine gets hot tighten a third time.

• • • **Replacing Cylinder Head**—There is a best way to replace cylinder heads that should always be followed to prevent trouble later. As shown in the typical case illustrated, the hold-down studs should be tightened in successive stages and in such order as will insure even pressure over the entire surface of the cylinder head and gasket. If the outside nuts are pulled up first instead of the center ones, the head will be cocked, and the gasket will not fit tight enough to prevent burning or blowing out between cylinders. Some Hy-Powr Engines have oil-seal washers on the hold-down studs which pass through the intake ports of the head. Be sure that these washers are replaced on the proper studs in good condition—otherwise an excess of lubricating oil will be drawn into the cylinders and wasted.




Figure 4—Ensign Gas Carburetor and Fuel Regulator

A—Idle fuel adjustment. B—Upper or pilot diaphragm. C—Pilot valve. D—Section passage from engine. E—Main fuel supply valve. F—Main diaphragm. G—Restricted passage. H—Air choke for starting. I—Gas shutter. J—Air intake. K—Gas passage. L—Air orifice in choke. M—Gas orifice used in choking. N—Adjustment for gas passage. O—Main fuel adjustment. P—Choke lever. R—Nozzle in atmosphere by-pass to regulator diaphragm. S—Atmosphere by-pass to regulator diaphragm.

BEARING ADJUSTMENT

*** **Taking Up Bearings**—It is not advisable for any inexperienced person to attempt bearing adjustment. However, it is necessary for the operator or owner to know the symptoms that indicate the need, and to be able to tell the mechanic who does the work what clearances and tolerances are required.




Figure 5—Testing Connecting Rod Bearings

A—Pry bar. B—Fulcrum point on case. C—Fingers overlap rod end and crank cheek. D—Connecting rod lower end.

*** **Bearing Looseness**—In general, any bearing that is loose will cause an abnormal knock that increases with use. The heavier the thump, the greater the need for prompt attention. Call in the mechanic, have him locate the cause of the trouble, and remedy both the cause and the trouble itself.

*** **Locating Loose Bearings**—A loose connecting rod bearing may be located by running the engine slowly, and short circuiting each spark plug in turn. If any connecting rod bearing is loose, the knock will disappear when that particular cylinder is cut out. A knock in a main bearing is harder to locate, and after all other possible causes of the knock have been investigated and eliminated, remove the oil pan or inspection plate, and try the adjustment of the main bearings.


*** **Inspecting Main Bearing Caps**—It is possible to make an inspection of the main crankshaft bearing caps one at a time without removing the crankshaft. If any trouble has been experienced it will be evident in the cap. If the bearings are loose, but otherwise in good condition, it is possible to take out shims enough to make up for the wear which has taken place. It is very important when doing this to take the same amount out of each of the bearings and each of the shims, otherwise the crankshaft will be thrown out of line, and even as little as a few thousandths of an inch will cause excessive friction in the bearings, wear, and loss of power. Do not remove so many thicknesses of shims that the caps pinch the shaft when the nuts are pulled as tight as possible.

*** **Bearing Clearances**—If it is necessary to replace the entire bearing in any case, the side clearances are important. Connecting rods should have side clearance as shown in Tabulated Data, Figure 3; Dimension "B." Main crankshaft side clearances are also shown in the Data. Dimension "C" is the thrust bearing side clearance, while Dimension "D" is the side clearance for all other crankshaft bearings.

THE GOVERNOR MECHANISM

*** **A Protective Device**—The governor built into Waukesha Engines is designed for each particular engine to do two main things: 1—to prevent damage from overspeeding as mentioned in the "CAUTION" following the guarantee (see page 118) 2—to automatically maintain constant speeds under varying loads while driving industrial machinery. *As the life of any machine falls off rapidly when it is speeded up beyond safe limits, the governor should be kept in operation at all times to protect the engine against damage and abuse.*

*** **Governor Adjusting**—The governor is adjusted for the correct speed at the factory, and *should not be changed to a higher speed without consulting the Company.* The general rules given here apply only in those cases where it may be necessary to re-assemble the governor after the manifolds have been taken down or other work



Above—Governor used on Model 6-LRO.

Right—Governors used on Models HS, HL, WS, WL, WK, WOK, 6-MS, 6-ML, 6-MK, 6-MKR, 6-MZ, 6-MZR, 6-SRS, 6-SRL, 6-SRLR, 6-SRK, 6-SRKR, 6-RB, 6-RBR, 6-EL, 6-EK, 6-NK, 6-LS, 6-LK.




Figure 6—Typical Large Engine Governor Mechanisms.

A—Camshaft gear to which governor weights are attached by pins, B. C—Speed adjusting lever. D—Governor operating rod. E—Governor lever. F—Governor lever pin hole. G—Governor weight support. H—Governor valve. J—Governor valve shaft mounted on ball bearings. K—Speed adjusting screw. L—Adjustment locking nut. O—Governor spring housing. P—Ball joint. R—Governor spring. S—Governor shift plate. T—Governor weights. U—Stop screw to prevent surging. V—Drive shaft.

done which incidentally involves the governor mechanism.

• • • **Governor Types**—In general principle, all Waukesha governors are alike, and in all but two or three engines, the general arrangement and location of the parts are the same. The general scheme is shown in Figure 6— which applies to the larger sizes, while Figures 7 and 8 show the special arrangement used for the small fours and sixes as indicated by the title, and Figure 9 the type used on valve-in-head engines. Each

of these is automatically lubricated by the engine oiling system.

• • • **Operation of Governor**—The operation of the Waukesha governor is as follows: Two weights in the gear chamber attached to gear, A, Figure 6 are held by and swivel around two pins, B. These weights fly out when the engine speeds up, moving the governor shifter, S, outward. This action presses a ball bearing thrust at the center of S, outward. This moves lever, E, Figure 6. This lever, E, swivels on pin, F,




Figure 7—Diagram of Governor as Used on Models V and VK Four-Cylinder, and TS, TL, BA, BL, BM, BK and BZ Six-Cylinder Engines

A—Governor drive shaft and gear. B—Governor weight hinge pins. D—Governor throttle rod. E—Governor lever. F—Governor lever hinge pin. H—Governor throttle valve. K—Speed adjusting screw. L—Adjusting screw lock nut. P—Throttle rod adjustable ball joint. R—Governor spring. S—Governor ball thrust shift plate. T—Governor weights.




Figure 8—Diagrams of Governors Used on Small Four-Cylinder Engines

A—Governor drive shaft and gear. B—Governor weight hinge pins. C—Water pump seal—external. D—Governor throttle rod. E—Governor lever. F—Governor lever hinge pin. G—Governor weight support keyed to drive shaft. H—Governor throttle valve. J—Water pump seal—internal. K—Speed adjusting screw. L—Adjusting screw lock nut. M—Water pump impeller. P—Throttle rod adjustable ball joint. R—Governor spring. S—Governor ball thrust shift plate. T—Governor weights. U—Stop screw to prevent surging.

Figure 9—Diagram of Governor for Overhead Valve Engines

A—Governor drive shaft and gear. B—Governor weight hinge pins. C—Magneto impulse coupling. D—Governor throttle rod. E—Governor lever. F—Governor lever hinge pin. G—Governor weight support keyed to drive shaft. H—Governor throttle valve rod. J—Magneto impulse coupling spring. K—Speed adjusting screw. L—Adjusting screw lock nut. P—Throttle rod adjustable ball joint. R—Governor spring. S—Governor ball thrust shift plate. T—Governor weights. U—Stop screw to prevent surging.





Figure 10—Diagram of Close Regulating Type Governor Used on Models 6-GAL and 6-GAK

A—Governor drive shaft and gear. B—Governor weight hinge pins. D—Governor throttle rod. E—Governor lever. F—Governor lever hinge pin. G—Governor weight support keyed to drive shaft. H—Governor throttle valve. K—Speed adjusting screw. L—Adjusting screw lock nut. M—Speed adjusting lever. P—Throttle rod adjustable ball joint. R—Governor spring. S—Governor ball thrust shift plate. T—Governor weights.



which is held in the gear cover. The movement of E, causes a movement of the rod, D, which closes the butterfly valve, H, and throttles the engine independently of the carburetor throttle.

• • • **Governor Accelerator**—In operating some industrial machinery there are periods in the operating cycle which demand an excess of power beyond the routine requirements—raising the loaded skip of a paving mixer, and starting a heavy hoist load are common examples—which can be met by properly connecting the Waukesha governor accelerator. Its action is fully diagrammed in *Figure 11*, and its use should be restricted to such service as just described. *It should not be used* for operating the engine *continuously* at its maximum accelerated speed.

• • • **Re-Setting the Governor**—As previously stated, governor adjustments should only be necessary if the governor or parts included in its assembly have been taken down for other work such as manifold gasket replacement, timing gear adjustment or gear cover gasket renewal. If any of this work deranges the governor parts be sure that it is re-assembled as it was originally. Make sure that the ball joint lock nut at P, *Figure 6*, is tight, and that the governor throttle valve is assembled right side up as indicated by the raised letters cast in the

edge of the butterfly itself. If all of these points have been carefully followed, the governor should operate exactly as before, provided the tension of the spring, R, or the length of the rod, D, has not been changed. To secure the best regulation, make sure that the length of the rod, D, is adjusted so that the throttle, H, stands a trifle towards the closing position when the engine is stopped. Variation from the speed shown in the Tabulated Data, *Figure* can be corrected by the screw, K. Turning it clockwise increases the maximum speed, counter-clockwise, decreases the speed.

SPECIAL EQUIPMENT

• • • **Auxiliary Accessories**—There are many auxiliary accessories that are applied to Waukesha Engines from time to time, each one usually meeting the special need of some individual client. The principal items include air compressors for air brakes, large capacity electric generators and special cylinder lubricating systems.

AIR BRAKE COMPRESSORS

• • • **Air Compressors**—There are three general types of air compressor mounting, each one designed with automatic lubrication system. The forward chain drive mounting and its typical application to the engine is shown in *Figure 12*. In this type, the silent chain is entirely enclosed, and receives oil from the engine oiling system. Do not use grease. The chain slack is adjusted either by an idler as shown in the diagram sketch, or by shims being placed beneath the compressor itself. The belt drive forward mounting is too simple to require description. The care of the compressor is covered by the air compressor manufacturer's instruction book. **NEVER CHANGE** the size of the oil line feed, to do so will unbalance the engine oil distribution.

• • • **Rear Mounted Compressor**—A special bracket replacing the magneto bracket is used for the rear mounting, therefore, battery ignition must be used. As in the case of the front mounted compressor, the lubrication is entirely automatic from the engine system, and does not require any attention. Do not put grease in the gear case. Adjustment of the chain should be made by shims under the compressor base.

ELECTRIC GENERATORS

• • • **Generator Selection**—Occasionally generators for storage battery charging and auxiliary lights are required with capacities from 300 to 800 watts. If, for any reason, this equipment is not furnished by the Waukesha Motor Company and with specific recommendations, it is important that care be exercised in its selection. Make sure that the generator is of the proper size, that it is equipped with a voltage regulator, and that




Figure 11. Diagram of Governor Accelerator

A—Ball joint. B—Governor spring which controls maximum engine speed, increasing tension increases speed, reducing tension reduces speed. C—Lever which pushing plunger, D, increases spring tension and engine speed. E—Rod connected to accelerator for remote control by foot pedal or by linkage to operating levers of driven machine. G—Camshaft gear which carries governor weights. W—Governor operating lever actuated by governor weights. R—Governor valve operating rod.




Figure 12—Diagram of Chain Drive Air Compressor Mounting of Early Design; Later Designs Have No Idler.

the charging rate is adjusted to meet the electrical load. This will prevent damage to the storage battery.

• • • **Generator Care**—Specific instructions for the care of generator are included in the accessory makers' directions furnished with these units. When the generator is bolted by a flange to the timing gear housing, it is important, in mounting, to see that sufficient back lash be allowed between the generator and driving gears to avoid overheating the generator bearing.

• • • **Generator Noises**—If a rattle or thump is located in the generator at low engine speeds, it can generally be traced to too much back lash in the gears or excessive end play in the generator. Correct the back lash in the gears by loosening the upper attaching screws, and crowding the generator slightly toward the crankcase. This can be done most conveniently if the cap screws are only freed enough to move the generator by light blows from a rawhide or wooden mallet. When proper running conditions are secured, tighten the cap screws. If it is end play, it is controlled in different ways in different machines, and the trouble should be located, and remedied by the nearest service representative of the electrical equipment manufacturer.

SPECIAL LUBRICATION

• • • **For Special Industrial Service**—Extra precautions are necessary to insure ample lubrication of industrial engines that

must be started after long periods of rest, or after standing in a cold place. They should be filled with fresh warm oil, and run idle for the first few minutes to permit the oiling system to fill, and insure oil reaching all parts of the engine. It is good practice where industrial equipment stands out of doors overnight in cold weather, to drain the oil from the crankcase each evening and keep it in a warm place, replacing it in the crankcase the following morning. **Do not put it near a stove or open fire.**

• • • **Fire Engine Equipment**—Fire engine equipment requires special care to avoid serious damage when it is new. Until the engine has been thoroughly limbered by at least 300 hours of service, **lubricating oil must be added to the fuel**—one pint of oil to each five gallons of gasoline. If the equipment is kept in a station where the temperature is below 50, unless the apparatus is in frequent use, a lighter oil should be used than the standard recommendation given in the Tabulated Data, Figure Specifications for this service call for a **viscosity of 65 to 70 Saybolt at 210 degrees F., not over 600 viscosity at 100 degrees F.** with a minimum flash point of 420 degrees F. Beside using a lighter oil, the oil supply should be checked frequently, and maintained at top level. When checking the oil supply if the drop from the bayonet gauge is thin and fast, it indicates poor lubricating qualities, and the oil should be changed.

Electric Oil Heaters—The most satisfactory arrangement to insure prompt response of the lubricating system is the use of a small electric heater attached to the oil pan sump. This will serve to keep the oil at a proper consistency in the coldest weather, and will also avoid the accumulation of water and gasoline in the sump. Not over 100 to 150 watts are needed. Our Engineering Department will provide suitable sketches on request, showing a permanent attachment of this kind.

DUPLEX OILING

(Obsolete Equipment)

The Duplex System an "Extra"—In special cases, the added precaution of directly oiling the cylinder walls and pistons is recommended, and for this purpose the Madison-Kipp Duplex Oiling System was devised. It is auxiliary to and not a substitute for the standard pressure circulating system. It provides a positive delivery of fresh oil in a metered quantity at regular intervals to each piston and cylinder, as soon as the engine starts instead of depending entirely upon crankcase mist for this duty.

Simple Equipment—The extra equipment is securely built into the engine, and consists of an outside oil reservoir with a glass level gauge, and a tube which connects it to a fitting on the outside of the

crankcase. The oil in this tank is led to a valveless plunger pump which receives a predetermined quantity of oil, and forces it through a distributing valve to each cylinder in turn. This pump is incorporated in the drive of the main oil pump, and is driven by a worm as shown in Figure 13.

Keeping the System Clean—Owing to the small quantities of oil which are used, even with the relatively large oil tubes employed, particles of foreign matter and sludge sometimes collect and stop the system. It has been found that this collects most frequently in the tube leading from the supply tank to the crankcase, and that by blowing out this tube, the system will be restored to full operation. **Do not attempt any adjustment** of the Duplex oil feed **without** first clearing this outside delivery pipe.

Adjustment of Oil Feed—An adjusting screw is provided at, A, Figure 13. To increase the rate of oil feed, turn the screw counter-clockwise; to decrease the rate of feed, turn it clockwise. This screw may be reached by removing a plug in the side of the oil pan. It is unnecessary to remove the pan for any of the oiling system adjustments. A correct adjustment will add enough oil through the duplex system to balance the normal loss in the circulating system—usually about 11 drops per cylinder




Figure 13—Details of "Duplex" Lubricating Pump

"Fresh oil" leads to their respective cylinders are indicated by the number of the cylinder, i.e., 1-2-3-4-5-6. A—Adjustment screw for regulating "fresh oil" pump. B—Cross over connection from feed line, F, to "fresh oil" pump cylinder, L. C—Cover over oil pump gears. G—Worm gear which drives "fresh oil" auxiliary pump. H—Housing for main oil pump. N—Pin on arm, M, which engages, W, and turns it one notch for each complete revolution of the shaft, S. P—"Fresh oil" pump piston. S—Eccentric shaft driven by worm wheel, G. T—Universal connection on end of piston and connected to driving eccentric, E. V—Rotary distributor valve which directs each shot of the plunger pump to the right cylinder—each cylinder in sequence. W—Distributor valve slow motion gear.

per minute—so that between crankcase draining periods all fresh oil is added to the engine through the duplex system. To check the delivery of oil to each cylinder, the small copper tube loop connecting the cylinder with the crankcase may be removed. Watch the oil level carefully, and if it is found to be increasing, reduce the duplex feed rate. If the level is falling, increase the duplex feed rate. Be sure that the oil is not thinning from an over-rich carburetor mixture.

• • • **Top Cylinder Oiling**—When removable sleeve cylinders are used, the Madison-Kipp Duplex System is replaced with the Jay Vacuum Operated "Motop" Oiler. This system is entirely automatic and equipped with a sight gauge, its operation is constantly in view. Follow the manufacturer's instructions accompanying the device if adjustments are needed. Always use the best grade of light oil as recommended by the maker.




Figure 14—Operation Diagram of Typical Reciprocating Fuel Pump

The eccentric, H, on revolving shaft, G, moves the lever, D, back and forth, and pulls diaphragm plunger, F, up and down against the spring, C. This draws fuel by vacuum into the upper chamber, M, through the check valve, N, from the supply line connected at J. When the diaphragm, A, moves up, the fuel is forced through the valve, O, and opening, P, to the carburetor. When the carburetor float chamber is full and the float holds the needle valve closed, the back pressure on the diaphragm holds it down, the motion of the lever, D, is absorbed by the joint, R, instead of the diaphragm plunger, F.

hand, the general principles of adjusting all carburetors here outlined will give fair to good results.

CARBURETOR ADJUSTING

• • • **Low Speed Adjustment**—In making carburetor adjustments the usual object is to secure the best pulling power possible. This does not necessarily mean the highest or lowest speed or best economy of the engine. When adjusting the carburetor, first set the spark in the position found most favorable for pulling, and leave it there while making all adjustments. The idling adjustment should be made first, with the gas control nearly closed. If the engine loads up or seems logy, it is an indication that the mixture is too rich. If the engine slows down and pops in the carburetor, the mixture is too lean. Adjustment should be made accordingly—by the low speed adjustment only.

High Speed Adjustment—In making the high speed adjustment, do not change the spark control, but set the gas throttle about one-fourth open, that is, one-fourth away from the closed position. The high speed adjustment should then be turned

either right or left, depending on which way it gives the desired effect, until the engine runs smoothly. If possible make this adjustment with the *engine under load*, so that if a *governor* is used, it *will not be affecting the adjustment*. When the desired results are thus obtained, retard the throttle control, and allow the engine to idle for at least one minute. When this is done, quickly open the throttle about one-third and then quickly close it. If the mixture is too lean, it will pop back through the carburetor, indicating that the high speed fuel feed adjustment must be opened slightly, or if an air adjustment is used, the air flow slightly decreased. If the mixture is too rich, a popping noise will come from the muffler or exhaust outlet, and the high speed fuel feed adjustment should be closed slightly or the air adjustment opened to the desired position. A little experience and careful attention will make possible all carburetor adjustments which may be necessary, but if the engine is working well, *don't experiment*. The best pulling power will be obtained with a mixture slightly richer than the leanest mixture that will give smooth running.

TABULATED DATA FOUR-CYLINDER ENGINES

ENGINE MODEL	FCS-FS	FL	FK-FC	XA	XA ^H	XA ^K	V	V ^K	VIS
Bore.....	2¾	3	3¼	3½	3¾	3¾	4	4¼	4½
Stroke.....	4	4	4	4½	4½	4¾	5	5	5½
Displacement, cu. in.....	95	113	133	173	186	210	251	284	281
N.A.C.C. hp. rating (actual hp. is higher)	12.1	14.4	16.9	19.6	21.0	22.4	25.6	28.9	27.2
Oil capacity, qts., standard automotive type oil pan	4	4	4	4	4	4	7	7	10
Oil capacity, qts., flat base stationary type	8	8	8	9	9	9	11	11	12
Oil pressure, lbs. at 1000 rpm, hot	65-75	65-75	15	15	15	15	20	20	25
*Oil SAE Saybolt Viscosity @ 210° F.	11-13	11-13	11-13	11-13	11-13	11-13	11-13	11-13	11-13
Spec. Kinematic viscosity @ 210° F., poises	40	40	40	40	40	40	40	40	40
ifications S.A.E., No.	1800	1800	1800	1500	1500	1500	1400	1400	1200
Water capacity, Industrial units, gals	2600	2600	2600	2200	2200	2200	2000	2000	1500
Permissible (Continuous, full load)	.005-.005	.005-.005	.005-.005	.004-.004	.004-.004	.005-.005	.005-.005	.005-.005	.014
Governed Speeds Intermittent, part load	.007-.007	.007-.007	.007-.007	.005-.005	.005-.005	.005-.005	.008-.008	.008-.008	.016
Valve tappet Intake, inches	.009-.009	.009-.009	.009-.009	.006-.006	.006-.006	.006-.006	.010-.010	.012-.012	.018
Setting, cold Exhaust, inches	.011-.011	.011-.011	.011-.011	.008-.008	.008-.008	.008-.008	.010-.010	.012-.012	.018
Firing Order	1-3-4-2	1-3-4-2	1-3-4-2	1-2-4-3	1-2-4-3	1-2-4-3	1-2-4-3	1-2-4-3	1-2-4-3
Spark advance, maximum, flywheel, degrees	25°	18°	19°	20°	28°	30°	29°	31°	43°
Dimension "A" (See paragraph 614)	¾	¾	¾	4½	4½	4½	4½	4½	4½
Dimension "B"	.004-.004	.004-.004	.004-.004	.005-.005	.005-.005	.005-.005	.005-.005	.005-.005	.010-.010
(See paragraph 621)	.007-.007	.007-.007	.007-.007	.010-.010	.010-.010	.010-.010	.010-.010	.010-.010	.015-.015
Dimension "C"	.005-.005	.005-.005	.005-.005	.003-.003	.003-.003	.003-.003	.003-.003	.003-.003	.003-.003
(See paragraph 621)	.009-.009	.009-.009	.009-.009	.005-.005	.005-.005	.005-.005	.005-.005	.005-.005	.005-.005
Dimension "D"	.030-.030	.030-.030	.030-.030	.015-.015	.015-.015	.015-.015	.015-.015	.015-.015	.060-.060
(See paragraph 621)	.060-.060	.060-.060	.060-.060	.025-.025	.025-.025	.025-.025	.025-.025	.025-.025	.090-.090

[illegible][illegible]

SIX-CYLINDER ENGINES

ENGINE MODEL	6ZKA	6BA	6BL	6BM	6BK	6BZ	6MS	6ML	6MK
Bore	3 3/8	3 3/8	3 3/8	3 3/8	3 3/8	3 3/8	3 3/8	4	4 1/8
Stroke	4 1/8	4 1/8	4 1/8	4 1/8	4 1/8	4 1/8	4 1/8	4 3/4	4 3/4
Displacement, cu. in.	221	228	245	263	282	315	315	358	381
N.A.C.C. hp. rating (actual hp. is higher)	27.3	27.3	29.4	31.5	33.8	38.4	33.8	38.4	41.0
Oil cap., qts., std. auto type oil pan	6	8	8	8	8	8	8	8	8
Oil capacity, qts., flat base stationary type	40	40	40	40	40	40	40	40	40
Oil pressure, lbs., at 1500 rpm, hot	65-75	65-75	65-75	65-75	65-75	65-75	65-75	65-75	65-75
Spec. Oil Saybolt Viscosity @ 210° F.	11-13	11-13	11-13	11-13	11-13	11-13	11-13	11-13	11-13
Spec. Kine. visc. @ 210° F., poises	40	40	40	40	40	40	40	40	40
Water capacity, Industrial units, gals.	9 1/2	9 1/2	9 1/2	9 1/2	9 1/2	9 1/2	9 1/2	9 1/2	9 1/2
Permissible (Continuous, full load)	1800	2000	2000	2000	2000	2000	1600	1600	1600
Governed Speeds (Intermittent, part load)	2500	2800	2800	2800	2800	2200	2200	2200	2200
Valve tappet Intake, inches	.008-	.010	.010-	.010-	.010-	.010-	.008-	.008-	.008-
Setting, cold Exhaust, inches	.010	.012	.012	.012	.012	.010	.010	.010	.010
Exhaust, inches	.012-	.014-	.014-	.014-	.014-	.014-	.014-	.014-	.014-
Firing Order	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4
Spark advance, maximum, flywheel, deg.	25°	30°	34°	34°	34°	25°	24°	25°	25°
Dimension "A" (See paragraph 614)	.005-	.005-	.005-	.005-	.005-	.005-	.005-	.005-	.005-
Dimension "B" (See paragraph 621)	.010	.010	.010	.010	.010	.010	.010	.010	.010
Dimension "C" (See paragraph 621)	.003-	.003-	.003-	.003-	.003-	.003-	.003-	.003-	.003-
Dimension "D" (See paragraph 621)	.005	.005	.005	.005	.005	.005	.005	.005	.005
Dimension "D" (See paragraph 621)	.010-	.060-	.060-	.060-	.060-	.010-	.010-	.010-	.010-
	.045	.090	.090	.090	.090	.045	.045	.045	.045

ENGINE MODEL	6MZ	6SRS	6SRL	6SRK	6DHS	6DHK
Bore	4 1/8	4 1/8	4 1/8	4 1/8	4 1/8	5
Stroke	4 1/8	5 1/8	5 1/8	5 1/8	5 1/8	5 1/8
Displacement, cu. in.	404	411	462	517	525	648
N.A.C.C. hp. rating (actual hp. is higher)	42.5	41.0	46.0	51.3	48.6	60.0
Oil cap., qts., std. auto type oil pan	8	10	10	10	14	14
Oil capacity, qts., flat base stationary type	40	40	40	40	50	50
Oil pressure, lbs., at 1500 rpm, hot	75-105	75-105	75-105	75-105	75-105	75-105
Spec. Oil Saybolt Viscosity @ 210° F.	13-20	13-20	13-20	13-20	13-20	13-20
Spec. Kine. visc. @ 210° F., poises	50	50	50	50	50	50
Water capacity, Industrial units, gals.	10	14	14	14	19	19
Permissible (Continuous, full load)	1500	1500	1500	1400	1400	1400
Governed Speeds (Intermittent, part load)	2000	2000	2000	*2000	1800	1800
Valve tappet Intake, inches	.008-	.008-	.008-	.008-	.010-	.010-
Setting, cold Exhaust, inches	.010	.010	.010	.010	.012	.012
Exhaust, inches	.014-	.016-	.016-	.016-	.014-	.014-
Firing Order	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4
Spark advance, maximum, flywheel, deg.	25°	27°	24°	28°	25°	29°
Dimension "A" (See paragraph 614)	.005-	.005-	.005-	.005-	.005-	.005-
Dimension "B" (See paragraph 621)	.010	.010	.010	.010	.010	.010
Dimension "C" (See paragraph 621)	.003-	.003-	.003-	.003-	.004-	.004-
Dimension "D" (See paragraph 621)	.005	.005	.005	.005	.006	.006
Dimension "D" (See paragraph 621)	.010-	.010-	.010-	.010-	.060-	.060-
	.045	.045	.045	.045	.090	.090

ENGINE MODEL	6GAL	6GAK	6EL	6EK	6RB	6LS	6LK	6LRO
Bore	5	5 1/2	6 1/2	7	5	7	7 1/4	8 1/2
Stroke	5 1/2	5 1/2	7	7	5 1/4	8 1/2	8 1/2	8 1/2
Displacement, cu. in.	648	784	1395	1616	677	1962	2406	2894
N.A.C.C. hp. rating (actual hp. higher)	60	72.5	101.4	117.7	60.0	117.6	144.0	173.4
Oil cap., qts., std. auto type oil pan	14	14	70	70	14	60	60	60
Oil capacity, qts., flat base stationary type	40	40	***40	***40	40	***50	***50	***50
Oil pressure, lbs., 1500 rpm, hot	75-105	75-105	75-105	75-105	75-105	105-125	105-125	105-125
Spec. Oil Saybolt Viscosity @ 210° F.	13-20	13-20	13-20	13-20	13-20	20-24	20-24	20-24
Spec. Kine. visc. @ 210° F., poises	50	50	50	50	50	60	60	60
Water capacity, Industrial units, gals.	11 1/2	14	45	45	19	62	62	62
Permissible (Continuous, full load)	1400	1050	1300	1300	900	900	900	850
Governed Speeds (Intermittent, part load)	1800	1125	*1900	1200	1200	1200	1200	1100
Valve tappet Intake, inches	.010-	.012-	.006-	.012-	.012-	.012-	.012-	.020-
Setting, cold Exhaust, inches	.012	.014	.008	.014	.014	.014	.014	.022
Exhaust, inches	.014-	.020-	.010-	.020-	.020-	.020-	.020-	.026-
Firing Order	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4	1-5-3-6-2-4
Spark advance, maximum, flywheel deg.	45°	28°	23°	23°	25°	30°	40°	40°
Dimension "A" (See paragraph 614)	.008-	.009-	.005-	.005-	.010-	.010-	.010-	.010-
Dimension "B" (See paragraph 621)	.014	.017	.010	.010	.015	.015	.015	.015
Dimension "C" (See paragraph 621)	.004-	.004-	.003-	.003-	.009-	.009-	.009-	.009-
Dimension "D" (See paragraph 621)	.007	.010	.005	.012	.012	.012	.012	.012
Dimension "D" (See paragraph 621)	.085-	.061-	.030-	.060-	.060-	.060-	.060-	.060-
	100	101	060	090	090	090	090	090

Kinematic viscosity of oils is given because it is the expectation that this method of expressing viscosity will become a universal standard. Saybolt viscosity is common in the United States, and has a limited use in other countries. The two systems are convertible, one to the other.

*Note—Top speeds marked with asterisk permissible only when aluminum pistons are used

**For Natural Gas Engines } Use Oil one grade lighter.

***For Winter Service

***At Governed Speed.

REGULATION OF THE FLAME

The welding flame may be three kinds, namely, a carbonizing flame, a neutral flame and an oxidizing flame. While at first it appears difficult to recognize these flames, reference to Fig. 1 and a careful study of the characteristics of the flame will enable the operator to immediately recognize the proper flame and detect any variation. No fixed rule can be applied to the pressures of the two gases, however, the schedule as shown on the following page will serve as an approximate guide to the operator for the average run of work. Some operators, after considerable experience, desire an extremely long flame for certain classes of work. This requires higher gas pressures and it is then necessary to increase the pressures to give the desired flame.

In lighting the torch, open the acetylene valve until the acetylene gas is noted to be coming out at the tip, then light it at a gas jet, a spark lighter or other suitable means. Before lighting the gas, however, give it sufficient time to replace the air which is usually present in the hose and torch as this will eliminate the possibility of carbonizing the interior of the torch and thereby fouling it.

REGULATION OF THE FLAME




Fig. 1

Now increase the flow of acetylene gas by further opening the valve until the flame has the appearance of Flame No. 1, in Fig. 10, that is, the gas does not ignite until it has reached a point of about $\frac{3}{16}$ of an inch from the end of the tip on a large tip and a much smaller distance on


Continued on next page

a smaller tip. Now open the oxygen valve until the flame resembles that of Flame No. 2, which is known as a carbonizing flame. In this flame the yellow appearance disappears and it assumes a blue color with a long, roughly-pointed white cone. This flame is called a carbonizing flame since there is an insufficient supply of oxygen gas to completely burn up the acetylene gas.

Now further increase the supply of oxygen until the flame assumes the form of Flame No. 3. This is known as neutral flame and the one desired for practically all classes of welding work. Sufficient oxygen is supplied to completely burn all of the acetylene gas, and little or no effect should be noted on the material welded due to carbonization or oxidation where this flame is properly employed.

By supplying a further increase of oxygen the flame will assume the form of flame No. 4, which is known as an oxidizing flame and which is easily detected by the fact that the white cone or welding flame is choppy and the entire flame does not possess the clear appearance of flame No. 3.

A properly adjusted flame does not always continue to burn in a neutral manner, but may vary slightly with the operation of the regulators or with the temperature of the torch head. The operator must therefore continually watch his flame, making such adjustments as are necessary immediately at the time a variation is detected. Either a carbonizing or an oxidizing flame is detrimental to good welding. A carbonizing flame having a tendency to make the metal, especially mild steel, hard and brittle, and an oxidizing flame will burn up a part of the metal, producing a weak weld.



Type N. Lead Burning Torch

Turn on both tank valves adjusting the screws on both oxygen and acetylene regulators a few times until a pressure of a few pounds shows on the gauge. This will then blow out the hose, and any dirt that may have accumulated in packing or shipping will be dislodged from the hose. This is important as dirt clogs up the torch and makes good burning impossible. Then apply hose to torch, being sure that the proper hose is applied to the proper connections.

With the adjusting screw screwed in on the acetylene regulator so the gauge reads about two pounds and the adjusting screw screwed in on the oxygen regulator so that the gauge reads about two to five pounds open the acetylene valve on the torch and light. If the torch does not readily light and produces a blowing effect, the valve is opened too wide and must be closed a little. When the acetylene is lit and coming out of the torch in a fairly strong stream, the flame must not leave the tip. If too much force is applied to the flame, the flame will leave the tip and be lit from $\frac{1}{8}$ to 1 inch away from the tip. To produce the best results we must have the flame start immediately at the tip.

Where low pressure city gas is used with the No. 2 or 2-A outfits, simply apply the flash-back to the gas line and apply the red hose to the outfit. A much higher oxygen pressure is required depending upon the size of tip used and intensity of flame required.

Always keep torch clean, as foreign matter getting into the same has a tendency to clog up and does not produce uniform results. If torch tip becomes clogged, a tip drill the size of the hole should be put in with the fingers, and this will clear the foreign matter.

WELDING KNOWLEDGE

In preparing a broken part for welding it is common practice to bevel the joint to be welded. This practice is well illustrated by Figs. 1 and 2. Lighter sections are beveled from one side only, as shown in Fig. 1 and heavier sections, where possible, are beveled from two sides, as shown in Fig. 2. This beveling is usually accomplished by means of grinding, chipping with a hammer and chisel, and in some cases machined off, or in many heavy, awkward pieces burned out with the torch flame. Burning out with the flame is strongly recommended against and is used only in cases where it is impossible to bevel by the first mentioned methods. Beveling has the further advantage of allowing the operator to begin the weld at the bottom of the break, thus preventing the possibility of a flaw in the weld.




Fig. 1

This well illustrates the first and most essential lesson in welding, that is, TO WELD OR FUSE THE METAL AT THE POINT OF THE BREAK, AND THROUGH ITS ENTIRE THICKNESS, AND NOT SIMPLY ON THE SURFACE. This bevel, as a rule, is usually about 90°, however, it may be varied to suit the various welding conditions the operator is required to work under. The material used in filling up the space left by beveling is commonly termed the welding or filler rod. The quality of this rod is of utmost importance and sometimes becomes the success or failure of the weld. For smaller work $\frac{3}{16}$ or $\frac{1}{4}$ -inch diameter filler rods is sufficient; however, on large work a larger rod should be used, the size being governed entirely by experience and convenience of its use by the operator.




Fig. 2

In bringing the metals to their fusing point certain changes in their chemical analysis occur. Such elements as burn more readily have a tendency to oxidize and we find the use of a flux of considerable aid. A good flux should not only help cleanse and make the metal more fluid, but should also produce a protective coating over the molten metal to prevent unnecessary oxidation. The cost of MECO FLUX is so small in comparison with the value of good welds that it behooves the operator to adopt it and not experiment around with other cheap materials with which he is not familiar.

The different metals used in machinery production vary in melting point, have different co-efficients of heat conductivity and are of various thicknesses. These are the factors that positively govern the size of the flame to be used. No set rule can be given the inexperienced operator as to what size tip should be used for a particular job. Too large a tip will melt the metal faster than the operator can control it and too small a tip will not melt quick enough, the heat being radiated to other parts of the casting faster than it is supplied by the flame. The following table, however, will assist the inexperienced operator greatly in giving the proper size tip he should use and enable him at least to make an intelligent start.

GAS PRESSURE FOR DIFFERENT SIZE TIPS

Tip No.	Thickness of Metal	Acetylene Pressure	Oxygen Pressure	Oxygen Consumption per Hour	Lineal Ft. Welded per Hour
1	1/32"	1/2 lb.	1/2 lb.	7.80	30 ft.
2	1/16"	1 "	1 "	7.90	25 "
3	3/32"	1 "	1 1/2 "	8.10	20 "
4	1/8"	1 "	2 "	9.75	15 "
5	3/16"	1 1/2 "	2 1/2 "	16.80	9 "
6	5/16"	2 "	2 1/2 "	26.40	6 "
7	3/8"	3 "	5 "	39.35	5 "
8	1/2"	5 "	8 "	51.15	4 "
9	5/8"	8 "	14 "	69.10	3 "
10	3/4" up	10 "	18 "	80.00	2 "

Note:—Consumption given above, taken with Hydrex Flow Indicator, with maximum size Flame. They are intended for estimating purposes only, and should amply cover adverse conditions.

EXPANSION AND CONTRACTION

The art of welding also brings us in contact with some of the old natural laws. The most essential being that of EXPANSION AND CONTRACTION, and one which the welder should not consider TOO LIGHTLY if he is to be successful. All metals, as we know, expand when heated, and contract when cooling, and while this law is a simple one it is sometimes extremely difficult to apply it in an intelligent manner to an irregular shaped casting. Cast iron, for example, is a very brittle metal, and if the strains caused by either expansion or contraction are not properly provided for a cracked casting will result.




Fig. 3

To fully comprehend the principles of expansion and contraction, let us refer to Fig. 3. Here we have a rod or bar which is broken at X. If the weld is made no ill results will follow, since when the metal cools they are free to contract. Now refer to Fig. 4, in which case the broken bar is made the middle member of the frame with the break at the same location A. If we proceed to weld in the same manner as the previous figure we would find that as the metal at and surrounding the break A started to cool the ends D and E would not be free to contract since they are rigidly held by the members B and C, but had we previously heated members B and C until they expand the break at A will open up, the weld then be made and the frame allowed to cool with approximately an equal amount of contraction in each member. There are other means of offsetting the effects of expansion and contraction than heating, and certain metals require no safeguards whatever.

Not all parts are as simply handled as the one just illustrated. For example, take the case where a light section must be welded to a heavier one. In this case it is extremely important that the operator divide the heat from the flame between these two members in such a proportion as will render them both to approximately the same temperature and not bring one to the fusing temperature at the expense of the other. A little study and experience with individual cases should bring the operator to understand the principles of expansion and contraction and teach him that metals will expand when heated and contract when cooling in spite of the use of clamps, vises or other paraphernalia.

A good example of this would be to fix the ends of Y and Z of the broken bar as illustrated in Fig. 3. To be sure these ends would not expand if the weld was made at X, but the expansion, however, would take place from both ends toward the center, as this would be the easiest way; however, since the cold metal would occupy a smaller space than the heated metal, the weld would break on cooling. Clamps or bolts may be used to secure alignment or guide expansion, but never be used to prevent expansion, as this is absolutely impossible.




Fig. 4.

Failure to understand and apply the law of expansion and contraction is absolutely responsible for the failure of most repair welders. Each particular job should be studied and the principles applied before attempting the actual welding itself. Determine where the strain will be set up and then overcome this strain before executing the weld. The following tables will serve to give the operator the relative co-efficiency of linear expansion, of heat conductivity and the melting or fusing points of the various metals he will come in contact with.

CO-EFFICIENTS OF LINEAR EXPANSION

Aluminum (cast)	00001234
Cast Iron	00000617
Steel (untempered)	00000599
Steel (tempered)	00000702
Copper	00000955
Brass (cast)	00001037
Silver	00001060
Wrought Iron	00000686
Lead	00001571
Zinc	00001634
Tin	00001230

HEAT CONDUCTIVITY OF METALS

Silver	100.00
Copper	73.6
Gold	53.2
Aluminum	31.3
Brass	23.1
Zinc	19.0
Tin	14.5
Iron	11.9
Steel	11.6
Lead	8.5
Platinum	8.4

MELTING POINTS OF METALS

Wrought Iron	2730 Degrees F.
Nickel	2703 Degrees F.
Mild Steel	2680 Degrees F.
Hard Steel	2552 Degrees F.
Grey Cast Iron	2192 Degrees F.
White Cast Iron	2012 Degrees F.
Aluminum	1212 Degrees F.
Copper	1947 Degrees F.

As fly wheels and pulleys are a common type of work to be welded and as so few understand the proper method of handling them, the following will be of great assistance. This applies to the building of teeth on gear wheels for any type of wheel having only a hub and rim with spokes between. A great many wheels have a web between hub and rim. These must, as a rule, be preheated all over, unless the general idea of the following can be carried out:

As an example of taking care of expansion and contraction by the application of heat locally, consider Fig. 5, which represents a fly-wheel or pulley with broken spokes. Assuming that it is broken only at a point "A," we know that were we to weld this spoke without considering expansion or contraction the shrinkage strain would be so great that failure would occur.

Preheating the rim from W to X to a dull red heat will cause it to expand outwardly, separating the edges of the broken spoke. While in this state the weld should be rapidly made and the whole wheel allowed to cool slowly. Thus a good weld without the presence of internal strains will be produced. The expansion of the rim will offset the contraction of the weld in the spoke.

If the crack in the spoke is near the rim it is only necessary to apply a gas or oil burner to the rim at "M" until it is red hot. This will expand the spoke and rim and separate the edges of the break sufficiently to offset the contraction of the weld.




Fig. 5

As an example of making proper allowance for expansion and contraction without heating, this spoke may be also welded "cold," that is without any auxiliary heating. It is necessary that the rigidity of the rim be lessened, and in order to do this it is broken at a point "P," always close to the spoke. First one side of the spoke is strongly "Tacked" with the blowpipe at the weld. Then the other side is welded half through. The tack is then melted out and this side welded. If the weld has carried entirely through the spoke in one continuous operation, the contraction of the finished weld would be such that the rim would be out of "Round." Therefore, it is necessary that the original spacing be retained. The rim is now welded at the point "P." If the edges do not meet accurately, they may be brought to do so by heating either at point "M" or "O," according to which edge is low, and then welded.

If there are two spokes broken as at "A" and "B" the same general procedure as given above may be followed.

In case it is necessary to preheat a large portion of the casting it is important that the preheated area always extend past the spokes adjacent to those fractured as shown by "Y"—"Z." If two diametrically opposed spokes such as "B" and "C" are broken, each spoke may be treated as independent of the other and welded by any of the methods previously described.

Before attempting to do actual repair work, it is best to practice on scrap materials. Make the welds and then break them through the weld. You can then see for yourself the kind of weld you are making and you will have further learned to operate the torch properly before attempting serious work. It is best to practice on metal $\frac{1}{8}$ " to $\frac{1}{4}$ " in thickness as less gas is required to make the weld.

CAST IRON

Bevel the ends of the test pieces as previously explained and place them in position for welding. The edges should be slightly separated to allow for contraction; about 1-32-inch will be found about correct. Use the size tips recommended on the Table, Page 99. Special care should be used to heat the piece slowly. This is best done by moving the flame in a circle as illustrated in Fig. 6. When the metal becomes red for a distance of about three times as the metal is thick




Fig. 6

we are ready to begin the welding operation. Have the Cast Iron Flux in convenient reach and with the filler rod in one hand and the torch in the other, bring the welding flame down to the metal until the end of the cone is almost, but not quite, touching the edges, as illustrated in Fig. 7. The welding rod is placed near the flame to slightly heat it—then it is dipped in the flux can and the flux picked up by the hot rod is placed in the spot the flame is playing upon. Usually this is sufficient to break the film of oxide and to cause the metal to flow together. Note that we have added no material from the welding rod as yet. Now we melt the SIDES of the break and flow them towards the bottom until the weld has the general appearance of Fig. 8.

8. Then we are ready to use the material from the welding rod, which should be kept in contact with the weld at all times to avoid loss of heat. REMEMBER THAT THE ARTICLE AND THE WELDING ROD ARE THE SAME METALS, MELTING AT THE SAME TEMPERATURE. We must, then, keep the article and the rod in fusion at all times to effect a bond. Be very careful that the metal is actually melting while the rod is being added.




Fig. 7

Avoid the habit of pulling the torch away from the weld—rather use a slow circular movement which insures fusion and does away with loss of heat. Use the flux sparingly—never throwing it in with the hands—the amount picked up by the hot welding rod is sufficient at all times. At times it may be necessary to break the oxide by stirring the molten iron with the rod, and if the metal is very dirty, by pulling it out of the line of welding by means of the rod.




Fig. 8

As we progress with the welding we note that the metal does not always flow where we want it to, i. e., where we are holding the flame. The force of the flame usually prevents this and we add the metal from the welding rod at a point a little distance away from where we actually want it to flow, and when we are ready to have it join the casting we remove the flame from that point and swing the metal to the section desired by the circular motion described.

Cast iron does not immediately solidify the moment the flame is removed—it remains liquid for some little time and this condition presents two difficulties: one the danger of allowing this fluid metal to flow over, without bonding to the other metal, and the other the collapsing of the weld. The first difficulty may be offset by watching the weld carefully and bringing all parts into fusion. The second one is usually experienced by beginners and is caused by their lack of knowledge of the metal and the force of the flame with the metal in a liquid condition, is sufficient to cause the metal to collapse and create a hole.

One of the reasons for the collapse is the force or velocity of the flame—the metal is fluid all the way through and this force is sufficient to let it drop. We must, therefore, have a solid base at all times, which may be secured by the circular motion of the welding torch—not keeping the flame in one spot too long. To fill a hole, work down the sides the same as we have done in starting the weld, then dip the torch on an angle, as illustrated in Fig. 9, being careful, however, to keep the metal in fusion all the time. The idea is to divert the direction of the force of the flame. This same method is applicable where small sections may be missing.

If we have carefully followed out the directions, we should have a joint which is even stronger than the original article, and we can make it considerably stronger by adding additional metal to the line of welding.

WELDING STEEL

Preparation for the steel weld is practically the same as for Cast Iron. When the steel is heated sufficiently to begin welding, we bring

Shop Equipment Directory

In this Department, we have assembled and classified representative manufacturers and supply sources covering many lines of Shop Equipment, Machine Parts, Tools and Materials. These Manufacturers and Distributors will promptly supply additional detailed information on request. When writing Manufacturers, please mention UNIVERSAL MACHINISTS' HANDBOOK.

ABRASIVES, Cloth and Paper

Abrasive Prod., Inc., So. Braintree, Mass.
Bay State Abrasive Products Co., Westboro, Mass.
Carborundum Co., Niagara Falls, N. Y.
Schultz & Anderson Co., Newark, N. J.
Manufacturers' Supply Co., Defiance, O.

AIR HORNS

Keystone Grinder & Mfg. Co., Pittsburgh 19, Pa.

AIR LINE PARTS

AIR-WAY PUMP & EQUIPMENT CO.

1050 No. Kilbourn Ave.
Chicago 51, Ill.

"Air-O-Chek" Airguns and Air Hose Fittings.

M-B Products Co., Detroit, Mich.
Keller Tool Co., Grand Haven, Mich.
C. A. Norgren Co., Denver, Colo.

AIR MOTORS

Gast Mfg. Corp., Benton Harbor, Mich.

AIR-OPERATED CLAMPS

Lapeer Mfg. Co., Lapeer, Mich.

AIR PUMPS

Gast Mfg. Corp., Benton Harbor, Mich.

AIR PURIFIERS, (Compressed)

E. D. Bullard Company, San Francisco, Calif.

ALLOYS

Adamas Carbide Corp., Harrison, N. J.
Carboloy Co., Inc., Detroit, Mich.
McKenna Metals Co., Latrobe, Pa.
Wall-Colmonoy Corp., Detroit, Mich.

AMMONIA

Du Pont De Nemours & Co., Inc., E. I. Chemical Products, Wilmington, Del.

ANGLE PLATES

J. C. Busch Co., Milwaukee, Wis.
Challenge Machy. Co., Grand Haven, Mich.
Conrad Machine Co., Lombard, Ill.
Lassy Tool Corp., Plainville, Conn.

ARBORS AND MANDELS

Brown & Sharpe Mfg. Co., Providence, R. I.
K. O. Lee, Aberdeen, S. D.
Scully-Jones & Co., Chicago, Ill.
Western Tool & Mfg. Co., Springfield, O.

AXLE & TIRE BOLT WASHERS

The Ohio Nut & Washer Co.
Mingo Junction, Ohio

BADGES

SUPERIOR SEAL & STAMP CO.

1402 Vermont Ave.
Detroit 16, Mich.

Brass, Zinc, Aluminum Tool Checks, Name, Machine, Number Plates, Property and Inventory Tags, Employee Badges.

BALANCING EQUIPMENT

Anderson Bros. Mfg. Co., Rockford, Ill.
The N. P. Bowsher Co., South Bend, Ind.
Gisholt Machine Co., Madison, Wis.
Norton Co., Worcester, Mass.

BAND SAW MACHINES AND PARTS

Armstrong-Blum Mfg. Co., Chicago, Ill.
Atlantic Saw Mfg. Co., New Haven, Conn.
Atlas Press Co., Kalamazoo, Mich.
Continental Machines, Inc., Minneapolis, Minn.
Racine Tool & Mach. Co., Racine, Wis.
Tannewitz Works, Grand Rapids, Mich.

BARS, Boring

Adamas Carbide Corp., Harrison, N. J.
Armstrong Bros. Mfg. Co., Chicago, Ill.
Davis Boring Tool Div., St. Louis, Mo.
Elk Tools, Incorporated, New York 7, N. Y.
The Gairing Tool Co., Detroit 32, Mich.
Russell Boring Bar Co., Middletown, Ohio

BEARINGS, Ball

Abbott Ball Co., Hartford, Conn.
Ahlberg Bearing Co., Chicago, Ill.
McGill Mfg. Co., Valparaiso, Ind.
Miniature Precision Bearings, Inc., Keene, N. H.
New Departure Div., Bristol, Conn.
Norma-Hoffman Corp., Stamford, Conn.
L. C. Smith Bearings Co., Chicago, Ill.

BEARINGS, Roller

Ball & Roller Bearing Co., Danbury, Conn.
McGill Mfg. Co., Inc., Valparaiso, Ind.
Shafer Bearings Corp., Chicago, Ill.
L. C. Smith Bearings Co., Chicago, Ill.
Timken Roller Bearing Co., Canton, Ohio
Tyson Bearing Corp., Massillon, Ohio

BEDHOOKS

The Ohio Nut & Washer Co.
Mingo Junction, Ohio

BELT FASTENERS AND LACINGS

Armstrong-Bray & Co., Chicago, Ill.
Clipper Belt Lacer Co., Grand Rap., Mich.
Shippert Mfg. Co., Dixon, Ill.

BELTS AND BELTING

Chicago Belting Co., Chicago, Ill.
Graton & Knight, Worcester, Mass.
Missouri Belting Co., St. Louis, Mo.
Rockwood Mfg. Co., Inc., Indianapolis 6, Ind.

BELT DRESSING

Rockwood Mfg. Co., Inc., Indianapolis 6, Ind.

"BELT-Pull"

Rockwood Mfg. Co., Inc., Indianapolis 6, Ind.

BENCHES, Factory

Lyon Metal Prod. Inc., Aurora, Ill.
Pollard Bros. Mfg. Co., Chicago 30, Ill.
Standard Presser Steel, Jenkintown, Pa.


BENDING MACHINES, Band and

Power

Black Hawk Mfg. Co., Milwaukee 1, Wis.
Buffalo Forge Co., Buffalo, N. Y.
Cleveland Crane & Engr. Co., Wickliffe, O.
Excelsior Tool & M. Co., E. St. Louis, Ill.
Hossfeld Mfg. Co., Winona, Minn.

the cone down as shown in Fig. 10 until the end of it just about touches the surfaces to be joined. Do not make the mistake of bringing the tip of the torch to the metal—hold the torch so that the end of the cone just LICKS the surface.


Fig. 9



As the bottom of the metal melts together, the welding rod is brought down until it touches that spot and a small portion of it is melted while it is in contact with the material, as in Fig. 11.

Now, we fuse this small portion to the material by a short circular motion, making sure that the flame actually comes in contact with every portion of it and that it is thoroughly fused to the material and that it has penetrated. As we finish the circular motion, we start melting the spot immediately adjoining.

Fig. 10



Continued on next page.

BENDING ROLLS

Marshalltown Mfg. Co., Marshalltown, Ia.
Niagara Machine & Tool Works, Buffalo
11, N. Y.
Rock River Mach. Co., Chicago, Ill.

BITS

ELK TOOLS, INC.
71 West Broadway
New York 7, N. Y.

BLADES, Band and Hack

Amer. Saw & Mfg. Co., Springfield, Mass.
Armstrong-Blum Mfg. Co., Chicago, Ill.
E. C. Atkins Co., Indianapolis, Ind.
W. O. Barnes Co., Detroit, Mich.
Capewell Mfg. Co., Hartford, Conn.
Clemson Bros., Inc., Middletown, N. Y.
Henry Diston & Sons, Inc., Philadelphia
35, Pa.
Diamond Saw Works, Inc., Buffalo 2, N. Y.
Do-All Company, Des Plaines, Ill.
Forsberg Mfg. Co., Bridgeport, Conn.
John H. Graham & Co., Inc., New York 8,
N. Y.

G. W. Griffin Co., Franklin, N. H.
Miller Falls Co., Greenfield, Mass.
Napier Saw Works, Middletown, N. Y.
Fayette R. Plumb, Inc., Philadelphia, Pa.
Simonds Saw & Steel Co., Fitchburg, Mass.
Spartan Saw Works, Springfield, Mass.
The L. S. Starrett Co., Athol, Mass.
H. G. Thompson Sons, New Haven, Conn.
Victor Saw Works, Middletown, N. Y.

BLOWERS AND BLOWER SYSTEMS

American Air Filter Co., Louisville, Ky.
C. F. Berg & Co., Boston, Mass.
The Herman Nelson Corp., Moline, Ill.
Kirk & Blum, Cincinnati, Ohio
Schwitzer-Cummins Co., Indianapolis, Ind.

BLOWER AND SUCTION CLEANERS

Breuer Electric Co., Chicago, Ill.
Ideal Commut'r. Dress. Co., Sycamore, Ill.
Skilsaw, Inc., Chicago, Ill.

BLOW TORCHES

Clements Mfg. Co., Chicago, Ill.
National Safety Device Co., Chicago, Ill.
Torit Mfg. Co., St. Paul, Minn.

BLUE PRINT HOLDERS

Guedon Co., Audubon, N. J.

BOILERS

Combustion Engineering Co., Inc., New
York City, N. Y.
Nooter Corp., St. Louis 4, Mo.

BOLTS (See SCREWS AND BOLTS)

Banner Mach. Tool & Supply Co.,
St. Louis 7, Mo.
St. Louis Screw & Bolt Co., St. Louis, Mo.

BOLT AND NUT MACHINERY

Landis Machine Co., Waynesboro, Pa.
Pellow Machine Co., Detroit, Mich.

BORING AND DRILLING MACHINES

Champion Blower & Forge Co., Lancaster,
Pa.
Ex-Cell-O Corp., Detroit, Mich.
Montgomery Engineering Co., Detroit 4,
Mich.
New Britain-Gridley Machine Div. of New
Britain Machine Co., New Britain,
Conn.
Stokerunit Corp., Milwaukee, Wis.
Universal Boring Mach., Hudson, Mass.

BORING HEADS

Acme Tool Co., New York, N. Y.
Flynn Mfg. Co., Detroit, Mich.
Lovejoy Tool Co., Inc., Springfield, Vt.
Pacific Tool & Sup. Co., Los Angeles, Cal.
Precision Tool Co., Brooklyn, N. Y.
Rickert-Shafer Co., Erie, Pa.

BORING MILLS, Bench Model**BORING MILLS, Bench Model
Horizontal**

Multiple Boring Machine Co., St. Louis,
Mo.

BORING TOOLS

Adamas Carbide Corp., Harrison, N. J.

Armstrong Bros. Tool Co., Chicago, Ill.
Bokum Tool Co., Detroit, Mich.
Davis Boring Tool Co., St. Louis, Mo.
The Gairing Tool Co., Detroit 32, Mich.
Russell Boring Bar Co., Middletown, Ohio
Van Norman M. Tool, Springfield, Mass.

BORING AND TURNING MILLS

Cincinnati Planer Co., Cincinnati, Ohio
Ganey Machinery Co., Buffalo, N. Y.
The New Britain Machine Co., New
Britain, Conn.

Lucas Machine Div. of The New Britain
Machine Co., New Britain, Conn.

New Britain-Gridley Machine Div. of New
Britain Machine Co., New Britain,
Conn.

King Machine Tool Div. of American Steel
Foundries, Cincinnati 29, Ohio
Yoder Sales Co., Cleveland, Ohio

BRAKES, Hand and Power

Dreis & Krump Mfg. Co., Chicago, Ill.
Excelsior Tool and Machine Co., East St.
Louis, Ill.

O'Neill-Irwin Mfg. Co., Minneapolis
United States Steel Supply Co., Chicago
4, Ill.

United States Steel Corp. Subsidiary
Verson Allsteel Press Co., Chicago, Ill.
Whitney Metal Tool Co., Rockford, Ill.

BROACHES, Keyway

East Shore Mach. Prod. Co., Cleveland, O.

BROACHING MACHINES

Amer. Broach & Mach. Co., Ann Arbor
Colonial Broach Co., Detroit, Mich.
Detroit Broach Co., Detroit, Mich.
East Shore Mach. Prod. Co., Cleveland, O.
National Broach & Mach., Detroit, Mich.
Oilgear Corp., Milwaukee, Wis.
The du Mont Corp., Greenfield, Mass.

BUFFING AND POLISHING

Standard Elec. Tool Co., Cincinnati, O.
Vonnegut Moulder Corp., Indianapolis 2,
Ind.

BULLDOZERS

Beatty Mfg. & Mach. Co., Hammond, Ind.
Rock River Mach. Co., Chicago, Ill.

BUSHINGS, Brass and Bronze

Bunting Brass & Bronze Co., Toledo, O.
Federal-Mogul Corp., Detroit, Mich.
Johnson Bronze Co., New Castle, Pa.
Keystone Carbon Co., St. Marys, Pa.
Phosfer Bronze Smelt. Co., Philadelphia

BUSHINGS, Drill

W. F. Meyers Co., Inc., Bedford, Ind.

CALIPERS

Banner Mach. Tool & Supply Co.,
St. Louis 7, Mo.
Belf & Lustig, New York, N. Y.
Brown & Sharpe Mfg. Co., Providence
Federal Products Corp., Providence 1, R. I.
Guedon Co., Audubon, N. J.
Lufkin Rule Co., Saginaw, Mich.
Park Sales Co., New York, N. Y.
The L. S. Starrett Co., Athol, Mass.


CARBIDE, Tipped Reamers

Wendt-Sonis Co., Hannibal, Mo.

Unlike cast iron, steel does not remain a liquid—it solidifies almost the instant the flame is removed, and it is for this reason that we are able to weld it in a vertical or overhead position, as well as horizontal.

If there is an excess of sparks, the flame is improperly adjusted and contains an excess of oxygen. If the metal melts too rapidly and is difficult to control, the tip is too large. If it does not keep in fusion and there is difficulty in getting the welding rod material to actually fuse to the article, the tip is too small. The beginner will be troubled with the welding rod sticking to the metal—don't attempt to pull it away; let it stay here until it is necessary to melt a portion of it in the weld.

Fig. 11



GAS PRESSURE FOR CUTTING WITH TYPE L AND M CUTTING TORCHES

Tip No.	Thickness of Metal, Inches	Acetylene Press., Lbs.	Oxygen Press., Lbs.	Acetylene Consumption Cu. Ft. Per Hr.	Oxygen Consumption Cu. Ft. Per Hr.
L-1	$\frac{1}{8}$	4	10	9.50	35
L-1	$\frac{1}{4}$	4	15	9.50	40
L-1	$\frac{3}{8}$	4	20	9.50	45
L-1	$\frac{1}{2}$	4	25	9.50	50
L-2	$\frac{3}{4}$	5	30	15.30	60
L-2	1	5	40	15.30	100
L-2	$1\frac{1}{2}$	5	50	15.30	150
L-2	2	5	60	15.30	200
L-3	3	6	70	25.20	275
L-3	4	6	80	25.20	350
L-3	5	6	90	25.20	425
L-4	6	7	100	27.30	550
L-4	8	7	130	27.30	825
L-4	10	8	150	28.20	1000

NOTE:—Consumption of gases given above was taken with flow indicator and estimated for continuous operation of the torch. These figures will seldom be reached in actual practice and are intended for estimating purposes only.

LIGHTING THE TORCH

Above table gives the approximate pressure of both Acetylene and Oxygen for cutting different thicknesses of metal. This, however, can only be used as a guide, as metal will rust on its surface, or metal

CARBIDE, Tool Bits

Wendt-Sonis Co., Hannibal, Mo.

CATERPILLAR TRACTOR

Caterpillar Tractor Co., Peoria, Ill.

CENTERS

Pratt & Whitney, West Hartford, Conn.

CENTERING MACHINES

Ex-Cell-O Corp., Detroit, Mich.
Jones & Lamson Co., Springfield, Vt.
Pratt & Whitney, West Hartford, Conn.
Sundstrand Mach. Tool Co., Rockford, Ill.

CHAIN DRIVES

Cullman Wheel Co., Chicago, Ill.
Morse Chain Co., Ithaca, N. Y.
Potter & Johnston Co., Pawtucket, R. I.
Whitney Mfg. Co., Hartford, Conn.

CHEMICALS

Du Pont De Nemours & Co., Inc., E. I. Chemical Products, Wilmington, Del.
Mallinckrodt Chemical Works, Industrial Chemicals, St. Louis, Mo.
Monsanto Chemical Co., Chemicals & Plastics Serving Industries, St. Louis, Mo.

CHESTS, Tool

H. Gerstner & Sons, Dayton, Ohio
The Vanderman Mfg. Co., Willimantic, Conn.

CHISELS

Banner Mach. Tool & Supply Co., St. Louis 7, Mo.
Delaware Steel Corp., Wilmington 99, Delaware
Müllers Falls Co., Greenfield, Mass.

CHISELS, Carpenter

Winsted Edge Tool Works, Winsted, Conn.

CHUCKING MACHINES

Bell Machine Co., Waukegan, Wis.
J. W. Bullard Co., Bridgeport, Conn.
Foster Machine Co., Elkhart, Ind.
Gisholt Machine Co., Madison 10, Wis.
Jones & Lamson Co., Springfield, Vt.
The New Britain Machine Co., New Britain, Conn.
Lucas Machine Div. of The New Britain Machine Co., New Britain, Conn.
New Britain-Gridley Machine Div. of New Britain Machine Co., New Britain, Conn.

Potter & Johnston Co., Pawtucket, R. I.
Sundstrand Mach. Tool Co., Rockford, Ill.

CHUCKS, Air

Cushman Chuck Co., Hartford, Conn.
Gisholt Machine Co., Madison 10, Wis.
Hannifan Mfg. Co., Chicago, Ill.
Leiman Bros., Inc., Newark 5, N. J.
Logansport Machine Co., Inc., Logansport, Ind.
Skinner Chuck Co., New Britain, Conn.

CHUCKS, Drill and Tap

Alco Tool Co., Bridgeport, Conn.
T. R. Almond Mfg. Co., Ashburnham, Mass.
Chicago Tool & Engr. Co., Chicago, Ill.
Erickson Steel Co., Cleveland, Ohio
Ettco Tool Co., Brooklyn, N. Y.
Jacobs Mfg. Co., Hartford, Conn.
The Kett Tool Co., Cincinnati 2, Ohio
K. O. Lee & Son, Aberdeen, S. D.
Modern Tool Works, Rochester, N. Y.
Motor Tool Mfg. Co., Detroit, Mich.
Procanier Safety Chuck Co., Chicago, Ill.

CHUCKS, Lathe

T. R. Almond Mfg. Co., Ashburnham, Mass.
Gisholt Machine Co., Madison 10, Wis.
L-W Chuck Co., Toledo, Ohio
Morrison Mach. Prod. Div., Elmira, N. Y.
Skinner Chuck Co., New Britain, Conn.
Thomas Hoist Co., Chicago, Ill.
Universal Engr. Co., Frankenmuth, Mich.
Westcott Chuck Co., Oneida, N. Y.

AIR-OPERATED CLAMPS

Lapeer Mfg. Co., Lapeer, Mich.

CLAMPS AND CLAMPING DEVICES

Armstrong Bros. Tool Co., Chicago, Ill.
Batavia Clamp Co., Batavia, N. Y.
Brownie Mfg. Corp., Huntington, Ind.
Cincinnati Tool Co., Cincinnati, Ohio
Detroit Stamping Co., Detroit, Mich.
Grand Specialties Co., Chicago 22, Ill.
Lapeer Mfg. Co., Lapeer, Mich.
Howell Clamp Co., Cleveland, Ohio
K-O Products Co., Benton Harbor, Mich.
Mead Specialties Co., Chicago, Ill.
Richards' Industries, Inc., Grand Rapids 5, Mich.

Rivett Lathe & Grinder Co., Boston, Mass.
United States Steel Supply Co., Chicago 4, Ill.

United States Steel Corp. Subsidiary Sales Service Machine Tool Co., Saint Paul W4, Minn.

CLUTCHES

Brown Engineering Co., Reading, Pa.
Carlyle Johnson M. Co., Manchester, Conn.
L. W. Carroll Mfg. Co., Norwood, Cincinnati, Ohio
Conway Clutch Co., Cincinnati, Ohio
Twin Disc Clutch Co., Racine, Wis.

COLLETS

Brown & Sharpe Mfg., Providence, R. I.
Hardinge Bros. Inc., Elmira, N. Y.
Chas. L. Jarvis Co., Middleton, Conn.
Modern Collet & Mach. Co., Ecorse, Mich.
Rivett Lathe & Grinder Co., Boston, Mass.

SUTTON TOOL COMPANY

Sturgis, Michigan

Collets—Feeders—Collet Chucks—specials and standards for all makes of machines.

COMPRESSORS, Air

Chicago Pneu. Tool Co., New York, N. Y.
Curtis Pneu. Mch. Co., St. Louis, Mo.
Hobart Bros. Co., Troy, Ohio
Ingersoll Rand Co., New York, N. Y.

CONTRACT WORK

Amer. Pattern & Model Co., St. Louis, Mo.
Ballak & Company, St. Louis, Mo.
Friede Welding Co., St. Louis, Mo.
Hartford Spec. Machy. Co., Hartford
Jefferson Mach. Tool Co., Cincinnati, O.
Liberty Foundry Co., St. Louis, Mo.
Liberty Tool & Gage Wks., Providence
Mack Specialty Co., St. Louis, Mo.
Peters Tool Co., Milwaukee, Wis.
Quality Tool & Die Co., Indianapolis, Ind.
Severance Tool Mfg. Co., Saginaw, Mich.
Swanson Tool & Machine Products, Inc., Erie, Pa.
Taylor Machine Co., Cleveland, Ohio
Westlof Tool & Die Co., Detroit, Mich.
Witteck Mfg. Co., Chicago, Ill.

CONTROLS AND CONTROLLERS

Acme Industrial Co., Chicago, Ill.
Clark Controller Co., Cleveland, Ohio
General Electric Co., Schenectady, N. Y.

Continued

CUTTING STEEL




Fig. 12

Hold the torch as illustrated in Figure 12 to one corner of the plate to be cut. When this corner becomes red, open the oxygen cutting valve by pressing down with the thumb. The steel will immediately begin to burn and assume an incandescent heat. The torch must now be moved evenly along the line of cut to maintain this incandescent heat. If the torch is moved too slowly or if moved too fast you will lose this heat and the torch will cease to cut. It is then necessary to turn off the oxygen cutting valve and heat up the end of the cut to the bright red heat and begin over. Beginners as a rule have some trouble, as it requires some practice to move the torch at even pace.

Figure 26 illustrates the wrong method of cutting. It will be noted that the sparks instead of flying directly downward are turned at an angle, showing that the cut is not going through the metal. This also causes a part of the molten metal and flame to be blown against the torch, and will cause trouble.

The torch head should also be inclined about 5 degrees from the perpendicular to the reverse direction of the cut. This partly overcomes the trouble in Figure 13 and leaves straighter lines on the sides of the curf.

Figure 14 illustrates the torch working properly and cutting entirely through the metal. Always be sure that this is done and you will have no trouble.

Sometimes it is necessary to start a cut in the middle of a sheet. It is then well to hold the preheating flame within about $\frac{1}{8}$ of an inch of the metal until it becomes red, then lift the torch slightly and turn on the Oxygen Cutting Valve. The steel will immediately begin to burn and the hole will soon be through. This is also to be followed when it is necessary to cut one sheet riveted on to another.

Always see that the surface of the metal is as clean as possible before attempting to cut it. Old boilers especially should be struck sharply with a hammer along the line of proposed cut, in order to loosen the scale which adheres to the inside.

CONTROLS AND CONTROLLERS

Logansport Machine Co., Inc., Logansport, Ind.
 Vickers Incorporated, Detroit, Mich.
 Westinghouse Elec. Co., E. Pittsburgh, Pa.

COUNTERBORES & COUNTERSINKS

Aero Tool Co., Los Angeles 3, Calif.
 Cleveland Twist Drill Co., Cleveland, Ohio
 Gairing Tool Co., Detroit, Mich.
 J. C. Glenzer Co., Detroit, Mich.
 Midwest Tool & Mfg. Co., Detroit, Mich.
 National Twist Drill Co., Detroit, Mich.
 Putnam Tool Co., Detroit, Mich.
 Severance Tool Mfg. Co., Saginaw, Mich.

COUNTING DEVICES

Durant Mfg. Co., Milwaukee, Wis.
 Veeder Root, Inc., Hartford, Conn.

COUPLINGS

Guardian Utilities Co., Michigan City, Ind.
 Lovejoy Flex. Coupling Co., Chicago, Ill.
 Multiple Boring Machine Co., St. Louis, Mo.
 Smith Power Transmission Co., Cleveland

CRANES

Shaw Box Crane & Hoist, Muskegon, Mich.

CUT-OFF MACHINES

Boice Crane Co., Toledo, Ohio
 Catskill Metal Works, Catskill, N. Y.
 Delta Mfg. Co., Milwaukee, Wis.
 DeWalt, Inc., Lancaster, Pa.
 Modern Mach. Tool Co., Jackson, Mich.
 Porter-McLeod Mach. Tool Co., Hatfield
 Rickert-Shafer Co., Erie, Pa.
 Tannewitz Works, Grand Rapids, Mich.
 Walker-Turner Co., Plainfield, N. J.

CYLINDERS, Air**ANKER-HOLTH MANUFACTURING CO.**

2723 Connors St.
 Port Huron, Mich.

Air Cylinders, Rotating—Non-Rotating.
 Any bore, stroke, or mounting.
 Bell Machine Co., Oshkosh, Wis.
 Galland-Henning Mfg. Co., Milwaukee.
 Hannifin Mfg. Co., Chicago, Ill.
 Logansport Machine Co., Inc., Logansport, Ind.
 Tomkins-Johnson Co., Jackson, Mich.

ANKER-HOLTH MANUFACTURING CO.

2723 Connors St.
 Port Huron, Mich.

Hydraulic Cylinders. Any bore, stroke, or mounting available up to 5000 PSI.

CYLINDERS, Hydraulic**ANKER-HOLTH MANUFACTURING CO.**

2723 Connors St.
 Port Huron, Mich.

Hanna Engineering Wks., Chicago, Ill.

Logansport Machine Co., Inc., Logansport, Ind.

CYLINDERS, Welding

Independent Eng. Co., O'Fallon, Ill.

DEMAGNETIZERS

Alofs Mfg. Co., Grand Rapids, Mich.
 R. B. Annis Co., Indianapolis, Ind.
 Electro-Matic Prod. Co., Chicago, Ill.
 Luma Elec. Equip. Co., Toledo, Ohio
 Welch Industries, Inc., Colorado Springs, Colo.

DIALS

Miller Dial & Name Plate Co., Los Angeles 21, Calif.

DIAMONDS AND DIAMOND TOOLS

Abrasive Dressg. Tool Co., Detroit, Mich.
 Acme Diamond Tool Co., New York, N. Y.
 Diamond Tool Co., Chicago, Ill.
 Doebel Diamond Tool Co., Detroit, Mich.
 Golconda Diamond Prod. Co., Chicago, Ill.
 E. Karelsen, Inc., New York, N. Y.
 J. K. Smit & Sons, New York, N. Y.
 Willeys Carbide Tool Co., Detroit, Mich.

DIE CUSHIONS

Dayton Rogers Mfg. Co., Minneapolis
 Vernon Allsteel Press Co., Chicago, Ill.

DIE, Guide

Lassy Tool Corp., Plainville, Conn.

DIE FILERS

Armgo Company, Milwaukee, Wis.

DIE HEADS

Modern Tool Works, Rochester, N. Y.
 Murchey Mach. & Tool Co., Detroit, Mich.
 Rickert-Shafer Co., Erie, Pa.

DIE MAKING MACHINES

Continental Machines, Inc., Minneapolis
 Foley Mfg. Co., Minneapolis, Minn.
 Fray Mach. Tool Co., Glendale, Calif.
 Hack Machine Co., Des Moines, Ill.
 Harvey Mfg. Co., New York, N. Y.
 Kearney & Trecker Corp., Milwaukee
 Pratt & Whitney, West Hartford, Conn.

DIE AND TAP SETS

Baumbach Mfg. Co., Chicago, Ill.
 Danly Mach. Specialties, Cicero, Ill.
 Greenfield Tap & Die, Greenfield, Mass.
 Producto Machine Co., Bridgeport, Conn.

DIES, Threading

Banner Machine Tool Co., St. Louis, Mo.
 Champion Blower & Forge Co., Lancaster, Pa.
 E. Mach. Screw Corp., New Haven, Conn.
 Geometric Tool Co., New Haven Conn.
 Greenfield Tap & Die Corp., Greenfield
 National Acme, Cleveland, Ohio
 Rickert-Shafer Co., Erie, Pa.
 Winter Bros. Co., Wrentham, Mass.

DIES, Thread Rolling

Reed Roller Thread Die Co., Worcester 2, Mass.

DIVIDING HEADS

Wm. Carroll & Son, Cincinnati, Ohio
 Hart Machine Co., Boston, Mass.
 Jefferson Mach. Tool Co., Cincinnati, O.
 W. B. Knight Machy Co., St. Louis, Mo.
 N. Britain T. & Mfg., New Britain, Conn.
 Nichols-Morris Corp.,
 50 Church Street, New York 7, N. Y.

DOWEL AND ASSEMBLY PINS

Acme Industrial Co., Chicago, Ill.
 The Helm Co., Fairfield, Conn.

DRAWING KNIVES, Carpenter

Winsted Edge Tool Works, Winsted, Conn.

DRESSERS

Carboly Co., Detroit, Mich.
 Desmond-Stephan Mfg. Co., Urbana, Ohio
 E. Karelsen, Inc., New York, N. Y.
 K. O. Lee & Son, Aberdeen, S. D.
 M. & S. Dresser Co., Hartford, Conn.
 W. F. Meyers Co., Inc., Bedford, Ind.
 Vincent Steel Prod. Co., Detroit, Mich.
 Welch Industries, Inc., Detroit, Mich.
 Western Tool & Mfg. Co., Springfield, O.
 Willeys Carbide Tool Co., Detroit, Mich.




Fig. 13




Fig. 14

DRILLS

Banner Mach. Tool & Supply Co.,
St. Louis 7, Mo.
Cleveland Twist Drill Co., Cleveland, Ohio
National Twist Drill Co., Detroit, Mich.
Standard Tool Co., Cleveland, Ohio

DRILL GRINDERS

Edw. Blake Co., Newton Centre, Mass.

DRILLING HEADS

Atlas Press Co., Kalamazoo, Mich.
Boice Crane Co., Toledo, Ohio
J. F. Buhr Mach. Tool, Ann Arbor, Mich.
Dorman Machine Works, New York, N. Y.
Errington Mach. Lab., Staten Island, N. Y.
Linderme Mach. & Tool Co., Detroit, Mich.
Reed-Prentice Corp., Worcester, Mass.
B. M. Root Co., York, Pa.

DRILLS, Portable and Hand

Albertson & Co., Sioux City, Iowa
Aro Equipment Corp., Bryan, Ohio
Black & Decker Co., Towson, Md.
Buckeye Tools Corp., Dayton, Ohio
Chicago Pneu. Tool Co., New York, N. Y.
Cincinnati Elec. Tool Co., Cincinnati, O.
Dumore Company, Racine, Wis.
Gaston Power Tools, Evergreen Pk., Ill.
Independent Pneu. Tool Co., Chicago, Ill.
Keller Tool Co., Grand Haven, Mich.
K. O. Lee & Son, Aberdeen, S. D.
Millers Falls Co., Greenfield, Mass.
The Rotor Tool Co., Cleveland 12, Ohio
Skillsaw, Inc., Chicago, Ill.
Speed Way Mfg. Co., Cicero 50, Ill.
Stanley Works, New Britain, Conn.
U. S. Elec. Tool Co., Cincinnati, Ohio
United States Steel Supply Co., Chicago 4, Ill.
United States Steel Corp. Subsidiary
Wodack Elec. Tool Corp., Chicago, Ill.

DRILLS, Radial

Amer. Tool Works, Cincinnati, Ohio

DRILLS, Single and Multiple

Atlas Press Co., Kalamazoo, Mich.
Avey Drilling Mach. Co., Cincinnati, O.
Barnes Drill Co., Rockford, Ill.
Boice-Crane Co., Toledo, Ohio
Buffalo Forge Co., Buffalo, N. Y.
Canedy-Otto Mfg. Co., Chicago Hts., Ill.
Cincinnati Bickford Co., Cincinnati, Ohio
Foote-Burt Co., Cleveland, Ohio
Hamilton Tool Co., Hamilton, Ohio
Leland-Gifford Co., Worcester, Mass.
★McDonald Machinery Co., St. Louis, Mo.
(See Adv. under Lathes)
Production Mach. Co., Greenfield, Mass.
B. M. Root Co., York, Pa.
Sellew Mach. Tool Co., Pawtucket, R. I.
Walker-Turner Co., Plainfield, N. J.

DRILL ROD

United States Steel Supply Co., Chicago 4, Ill.

United States Steel Corp. Subsidiary

DRIVES, Machine Tool

Berkeley Equipment Co., Corry, Pa.
Cushman Wheel Co., Chicago, Ill.
Drive-All Mfg. Co., Detroit, Mich.
Given Machy. Co., Los Angeles, Calif.
Lima Elec. Motor Co., Lima, Ohio
Reeves Pulley Co., Columbus, Ohio
Remco Prod. Corp., York, Pa.
Smith Power Transmis'n, Cleveland, O.
Steeg Elec. & Machy. Co., Chicago, Ill.
Turner Elec. Mfg. Co., Cleveland, Ohio
Turner Uni-Drive Co., Kansas City, Mo.

DUST COLLECTORS

Acme Tool Co., New York, N. Y.
Aget-Detroit Co., Detroit, Mich.
American Air Filter Co., Louisville, Ky.
C. F. Berg & Co., Boston, Mass.
Covel Mfg. Co., Benton Harbor, Mich.
Kirk & Blum, Cincinnati, Ohio
Leiman Bros., Inc., Newark 5, N. J.
Torit Mfg. Co., St. Paul, Minn.

ENGINEERS, Mechanical

Hankins & Trapnell, Richmond, Va.

ENGRAVING MACHINES**AUTO ENGRAVER CO.**

Ridgefield, Conn.

Two and three dimensional Pantograph Engraving Machines. Bench and Portable Models Tracer controlled contour milling and profiling machines.

Brewster-Squires Co., New York, N. Y.
Dremel Mfg. Co., Racine, Wis.
Preis Engraving Mach. Co., Newark, N. J.

EXHAUST, Fans

Robbins & Myers, Inc., Springfield, Ohio
Schwitzer-Cummins Co., Indianapolis, Ind.

FACERS, Soot

The Gairing Tool Co., Detroit 32, Mich.
Genesee Mfg. Co., Inc., Rochester, N. Y.
Midwest Tool & Mfg. Co., Detroit, Mich.
Putnam Tool Co., Detroit, Mich.

FANS, Air Circulators**BALDOR ELECTRIC CO.**

Saint Louis 10, Mo.
Electrical Specialists Since 1920

FANS

Baldor Elec. Co., St. Louis, Mo.
Robbins & Myers, Inc., Springfield, Ohio

FANS, Exhaust

Robbins & Myers, Inc., Springfield, Ohio
Schwitzer-Cummins Co., Indianapolis, Ind.

FILES, Hand

American Swiss File & Tool Co., Elizabeth 1, N. J.
E. C. Atkins Co., Indianapolis, Ind.
Banner Machine & Tool Co., St. Louis, Mo.
Delta File Co., Philadelphia, Pa.
Henry Disston & Sons, Inc., Philadelphia 35, Pa.
Nicholson File Co., Providence, R. I.
Fayette R. Plumb, Inc., Philadelphia, Pa.
Severance Tool Mfg. Co., Saginaw, Mich.
Simonds Saw & Steel Co., Fitchburg, Mass.

FILES, Rotary

Delta File Co., Philadelphia, Pa.
Henry Disston & Sons, Inc., Philadelphia 35, Pa.
Graham Rotary File & Tool Corp., Philadelphia, Pa.
Grobet File Co., New York, N. Y.
Hamilton Tool Co., Hamilton, Ohio
Chas. I. Jarvis Co., Middletown, Conn.
Fayette R. Plumb, Inc., Philadelphia, Pa.
Pratt & Whitney, West Hartford, Conn.
Severance Tool Co., Saginaw, Mich.
N. A. Strand & Co., Chicago, Ill.

CUTTING CAST IRON

Cast Iron Cutting is rapidly taking its position in industry and daily directly saves many dollars and hours of time. It is now universally recognized as practical and the following brief outline will serve to acquaint the unskilled operator with the fundamental points to follow

APPLICATION

The application of cast iron cutting, while comparatively new, has already spread itself over so broad a field that it requires too much space to describe it thoroughly. However it is fair to say that it follows the cutting of steel in general with its principle virtues of speed and portability. It has been particularly effective in the cutting up of heavy cast iron scrap, such as heavy flywheels, etc., which unless reduced to convenient size would be worthless and very inconvenient to handle. Considerable saving is produced as the process can be applied where a great many other methods are impossible. Removal of large gears and pulleys from shafts is also a very common use. It also lends itself admirably in the preparation of large cast iron welds in the welding shop.

COST

The cost of cast iron cutting as compared with that of steel, is considerably more, due of course, to the nature of material cut. It is much slower and naturally more gas is consumed per unit of cut, however, this does not limit its application since it still offers the cheapest and quickest possible method in a great many instances.

EQUIPMENT

Cast Iron Cutting like a great many other valuable processes was slow to gain popularity on account of certain drawbacks. These drawbacks in the main consisted of two, about equally divided, namely, a general lack of knowledge of the art and a suitable torch. Today there are a great many skilled operators as well as a number of efficient torches which have the necessary pep or capacity so necessary for this work.

CUTTING DEPENDS ON COMPOSITION OF CAST IRON

To intelligently describe this process, we must first consider the nature of cast iron from two angles. Since it has such a wide range of use, it is natural that we may expect a wide difference in quality or chemical composition and a corresponding difference in ease of cutting. The better grades of castings such as are machined are more easily cut and those made of random grades of scrap such as counterweights, gratebars, floorplates, etc., present greater difficulty, requiring more gas, a wider kerf, and a corresponding slower rate of cutting speed. Different thickness is also a factor which will be considered later under heading of instructions.

PREPARATION

There is a rule for heavy steel cutting, which certainly applies in every way to cast iron cutting and that is **DO NOT START THE CUT UNTIL YOU ARE CERTAIN THAT YOU CAN COMPLETE IT.** It is obvious that if the cut is stopped on a heavy section, that it is extremely difficult to start it again and may doubly increase the cost as well as the annoyance. Considerable more heat as well as sparks and slag are generated in cast iron so that proper protection to the body, face, and limbs is necessary. Asbestos gloves are essential and a fire brick or suitable torch rest is desirable.

FILING MACHINES

All American Tool & Mfg. Co., Chicago 14, Ill.
 Armgro Company, Milwaukee, Wis.
 Continental Mach., Inc., Minneapolis
 H. & H. Research Co., Detroit, Mich.
 Keller Tool Co., Grand Haven, Mich.
 Postal Filing Mach. Co., Minneapolis

FILTERS, Air

Aget-Detroit Co., Detroit, Mich.
 American Air Filter Co., Louisville, Ky.
 M-B Products, Detroit, Mich.
 C. A. Norgren Co., Denver, Colo.
 Sterling Tool Prod. Co., Chicago, Ill.

FIRST AID

E. D. Bullard Company, San Francisco, Calif.

FLATING, STAMPING & FIRST OPERATIONS BLANKS

The Ohio Nut & Washer Co.
 Mingo Junction, Ohio

FLEXIBLE SHAFT EQUIPMENT

Acme Tool Co., New York, N. Y.
 Dumore Co., Racine, Wis.
 Foredom Elec. Co., New York, N. Y.
 R. G. Haskins Co., Chicago, Ill.
 Pratt & Whitney, West Hartford, Conn.
 Stow Mfg. Co., Binghamton, N. Y.
 White Dental Mfg. Co., New York, N. Y.
 Wyzenbeek & Staff, Chicago, Ill.

FORGES

Buffalo Forge Co., Buffalo, N. Y.
 Diamond Iron Works, Minneapolis, Minn.
 Johnson Gas Appl. Co., Cedar Rapids, Ia.

FURNACES, Heat Treating

Amer. Elec. Furnace Co., Boston, Mass.
 Amer. Gas Furnace Co., Elizabeth, N. J.
 Bennett Ins. Steel Trtg. Co., Newark, N. J.
 Delaware Tool Steel Corp., Wilmington 99, Delaware
 Despatch Oven Co., Minneapolis, Minn.
 Electric Furnace Co., Salem, Ohio
 Hevi Duty Elec. Co., Milwaukee, Wis.
 Stark Tool Co., Waltham, Mass.
 Thermo Electric Mfg. Co., Dubuque, Iowa
 Upton Elec. Furn. Co., Detroit, Mich.

GAGES, Indicating

Dearborn Gage Co., Dearborn, Mich.
 Federal Products Corp., Providence 1, R. I.
 Guedon Co., Audubon, N. J.
 Liberty Tool & Gage Wks., Providence
 Lufkin Rule Co., Saginaw, Mich.
 Marshalltown Mfg. Co., Marshalltown, Ia.
 ★Modern Engineering Co., St. Louis, Mo.
 (See Adv. Back Cover)
 Montgomery Engineering Co., Detroit 4, Mich.
 J. R. Reich Mfg. Co., Dayton, Ohio
 Geo. Scherr Co., New York, N. Y.
 Sheffield Gage Corp., Dayton, Ohio
 Standard Gage Co., Poughkeepsie, N. Y.
 The L. S. Starrett Co., Athol, Mass.
 Swedish Gage Co., Detroit 4, Mich.
 United Precision Prod. Co., Chicago, Ill.

GAGE BLOCKS

C. E. Johansson Gage Co., Detroit 4, Mich.

GEARS

Abart Gear & Mach. Co., Cicero, Ill.
 Boston Gear Works, No. Quincy, Mass.
 Brewer Machine & Mfg. Co., St. Louis, Mo.
 Chicago Gear Works, Chicago, Ill.
 Fellows Gear Shaper Co., Springfield, Vt.
 Gleason Works, Rochester, N. Y.
 Greaves Mach. Tool Co., Cincinnati, Ohio
 Ohio Gear Co., Cleveland, Ohio
 Phila. Gear Works, Philadelphia, Pa.

GEAR CUTTING

Brewer Machine & Mfg. Co., St. Louis, Mo.

GEAR CUTTING MACHINERY

Barber-Colman Co., Rockford, Ill.
 Fellows Gear Shaper Co., Springfield, Vt.
 Gleason Works, Rochester, N. Y.
 Hamilton Tool Co., Hamilton, Ohio
 Michigan Tool Co., Detroit, Mich.

GEAR GUARDS

Littleford Bros. Inc., Cincinnati 2, Ohio

GENERAL MACHINE WORK

Brewer Machine & Mfg. Co., St. Louis, Mo.

GOGGLES, Safety

E. D. Bullard Company, San Francisco, Calif.

GOUGES

Winsted Edge Tool Works, Winsted, Conn.

GRINDERS, Ball Bearing**BALDOR ELECTRIC COMPANY**

Manufacturers Electric Motors
 4351-59 Duncan Ave. St. Louis 10, Mo.
 Baldor Ball Bearing Grinders $\frac{1}{2}$ H.P.,
 3400 R.P.M., Wheels 7" x 1" x $\frac{5}{8}$ " \$60.00.
 A complete line 6" thru 12" $\frac{1}{4}$ H.P. thru
 3 H.P.

BALDOR ELECTRIC CO.

Saint Louis 10, Mo.
 Electrical Specialists Since 1920

Valley Electric Corp.**Manufacturer****BALL BEARING ELECTRIC MOTORS and GRINDERS**

4221-27 Forest Park St. Louis, Mo.

GRINDERS, Bench and Stand

Armgro Company, Milwaukee, Wis.
 Atlas Press Co., Kalamazoo, Mich.
 Baldor Electric Co., St. Louis, Mo.
 Brown-Brockmeyer Co., Dayton, Ohio
 Cincinnati Machy. & Sup. Co., Cincinnati
 Clizbe Bros. Mfg. Co., Plymouth, Ind.
 Cutter Machine Co., St. Louis, Mo.
 Grenby Mfg. Co., Plainville, Conn.
 Hammond Mch. Bldrs., Kalamazoo, Mich.
 Hisey-Wolf Mach. Co., Cincinnati, Ohio
 LaSalle Tool Co., Ottawa, Ill.
 K. O. Lee & Son, Aberdeen, S. D.
 The Lima Electric Motor Co., Lima, Ohio
 Keystone Grinder & Mfg. Co., Pittsburgh 19, Pa.
 M-B Products, Detroit, Mich.
 Millers Falls Co., Greenfield, Mass.

Continued on next page

PRESSURE TABLE

Type L. Standard Cutting Torch

Size of Tip	Thickness Metal	Oxygen Pressure	Acetylene Pressure
L-3CH	$\frac{1}{2}$ "	40 lbs.	7 to 8 lbs.
	$\frac{3}{4}$ "	45 lbs.	
	1"	50 lbs.	
	$1\frac{1}{2}$ "	60 lbs.	
	2"	70 lbs.	
L-4CH	3"	80 lbs.	8 to 10 lbs.
	4"	90 lbs.	
	6"	110 lbs.	
	8	120 lbs.	
	10	150 lbs.	
	12	170 lbs.	

CUTTING HINTS

For cutting the better grades of cast iron or grey iron, set the regulators to deliver the proper pressure as indicated on the pressure table. The regulator adjustment of course is made with the high pressure cutting valve open to allow for the customary drop.

Next light the torch and adjust the preheating flame so that it will show an excess of acetylene. This is preferably done with the high pressure valve wide open to avoid any change in the character of the flame during the actual cutting operation. This is important. The excess of acetylene as indicated by the length of the white cone must be varied to best suit the grade and thickness of the material cut. Experience is naturally the best guide on this point, however, it will generally vary from little or no excess of acetylene for the extremely light sections to an excess as indicated by a white cone of a length of one to two inches for the heavier sections cut.

Due to the higher cost of cast iron cutting it is well to plan the work carefully; first to avoid any unnecessary cuts, and also take advantage of all helpful hints. As the cutting of cast iron requires a higher ignition temperature, some gas can be saved by preheating the heavier sections along the line of the start of the cut.

BRASS AND BRONZE

Brasses and bronzes are composed of copper, with lower melting metals as alloys, zinc, tin, etc. Since these metals have different melting points, considerable care must be exercised in welding not to change the character of the metal too much by burning out these alloys.

The metal should be prepared the same as any other, with particular care in setting up to prevent collapse of the heated area. The metal should not be brought to fusion by bringing the cone in contact with it, but as with copper, the end of the cone should be slightly above the metal. For repair purposes, Tobin Bronze or Manganese Bronze should be used for the welding rod—for foundries or in manufacturing where the weld must be practically the same color and the same material as the metal, more judgment is necessary in the choice of the rod, with a view of replacing by means of the material in the welding rod those metals burnt out of the line of welding by the flame.

GRINDERS, Bench and Stand

Standard Elec. Tool Co., Cincinnati, O.
 Rivett Lathe & Grinder Co., Boston, Mass.
 T. C. M. Mfg. Co., Harrison, N. J.
 Valley Electric Corp., St. Louis, Mo.
 Vonnegut Moulder Co., Indianapolis, Ind.
 Walls Sales Corp., New York, N. Y.

GRINDERS, Bench Pneumatic

United States Steel Supply Co., Chicago 4, Ill.
 United States Steel Corp. Subsidiary

GRINDERS, Carbide

Baldor Electric Co., St. Louis, Mo.
 Willys Carbide Tool Co., Detroit, Mich.

GRINDERS, Cutter and Tool

Cincinnati Grinders, Inc., Cincinnati, Ohio
 Cleveland Tool & Eng. Co., Cleveland, O.
 Cutter Machine Co., St. Louis, Mo.
 Gallmeyer & Livingston, Grand Rapids
 Grenby Mfg. Co., Plainville, Conn.
 LeBlond Mach. Tool Co., Cincinnati, Ohio
 K. O. Lee & Son, Aberdeen, S. D.
 McDonough Mfg. Co., Eau Claire, Wis.
 Mico Instrument Co., Cambridge 38, Mass.

GRINDERS, Drill

Black Diamond Saw Mach., Natick, Mass.
 Edw. Blake Co., Newton Centre, Mass.
 Galland-Henning Mfg. Co., Milwaukee, Wis.
 Keystone Grinder & Mfg. Co., Pittsburgh 19, Pa.
 Kokomo Mach. Co., Kokomo, Ind.
 McDonough Mfg. Co., Eau Claire, Wis.
 Montgomery Engineering Co., Detroit Mich.
 Standard Elec. Tool Co., Cincinnati, O.
 Star Elec. Motor Co., Bloomfield, N. J.
 Washburn Shops, Worcester 2, Mass.

GRINDERS, Portable, Air

Aro Equipment Corp., Bryan, Ohio
 Buckeye Tools Corp., Dayton, Ohio
 Chicago Pneu. Tool Co., New York, N. Y.
 Independent Pneu. Tool Co., Chicago, Ill.
 Ingersoll-Rand Co., New York, N. Y.
 Keller Tool Co., Grand Haven, Mich.
 M-B Products Co., Detroit, Mich.
 Onsrud Mach. Works, Chicago, Ill.
 The Rotor Tool Co., Cleveland 12, Ohio

GRINDERS, Portable, Electric

Baldor Elec. Co., St. Louis, Mo.
 Chicago Pneu. Tool Co., New York, N. Y.
 Chicago Wheel & Mfg. Co., Chicago, Ill.
 Cincinnati Elec. Tool Co., Cincinnati, Ohio
 H. & H. Research Co., Detroit, Mich.
 Chas. L. Jarvis Co., Middletown, Conn.
 K. O. Lee & Son, Aberdeen, S. D.
 Skilsaw Inc., Chicago, Ill.
 Speed Way Mfg. Co., Cicero 50, Ill.
 Standard Elec. Tool Co., Cincinnati, O.
 Stanley Works, New Britain, Conn.
 S. S. White Dental Co., New York, N. Y.

GRINDERS, Portable Pneumatic

Jefferson Mach. Tool Co., Cincinnati, O.

GRINDERS, Snagging

Cutter Machine Co., St. Louis, Mo.
 Standard Elec. Tool Co., Cincinnati, O.
 Vonnegut Moulder Corp., Indianapolis 2, Ind.

GRINDERS, Surface (Hydraulic Feed)

Gallmeyer & Livingston Co., Grand Rapids, Mich.
 Standard Elec. Tool Co., Cincinnati, O.

GRINDERS, Swing Frame

Jefferson Mach. Tool Co., Cincinnati, O.
 Vonnegut Moulder Corp., Indianapolis 2, Ind.

GRINDERS, Tap

Gallmeyer & Livingston Co., Grand Rapids, Mich.

GRINDERS, Universal & Tool

Gallmeyer & Livingston Co., Grand Rapids, Mich.

GRINDING WHEELS

Abrasive Co., Philadelphia, Pa.
 Amer. Emery Wheel Co., Providence, R. I.
 Atlantic Abrasive Co., So. Braintree, Mass.
 Bay State Abrasive Prod., Westboro, Mass.
 Bridgeport Safety Em. Wheel, Bridgeport
 Carborundum Co., Niagara Falls, N. Y.

MANUFACTURERS' SUPPLY CO.

\$300,000 Inventory, 50% saving on abrasives in stock. Abrasives our specialty.

MANUFACTURERS' SUPPLY CO.

P. O. Box 141, Defiance, Ohio
 Phone 7457

GUARDS, Power Presses

Searjeant Metal Products, Inc., Mendon, N. Y.

HACK SAW FRAMES

Clemson Bros., Inc., Middletown, N. Y.
 Forsberg Mfg. Co., Bridgeport, Conn.
 Napier Saw Works, Middletown, N. Y.
 Simonds Saw & Steel Co., Fitchburg, Mass.
 Victor Saw Works, Middletown, N. Y.

HACK SAW MACHINES

Clemson Bros., Inc., Middletown, N. Y.
 Cove Hanchett Co., Portland, Ore.
 Forsberg Mfg. Co., Bridgeport, Conn.
 Napier Saw Works, Middletown, N. Y.
 Simonds Saw & Steel Co., Fitchburg, Mass.
 Racine Tool & Mach. Co., Racine, Wis.
 Rapid Mfg. Co., Glendale, Calif.
 Sales Service Machine Tool Co., Saint Paul W4, Minn.
 Victor Saw Works, Middletown, N. Y.

HAMMERS, Air

The Rotor Tool Co., Cleveland 12, Ohio

HAMMERS, Electric

Chicago Pneu. Tool Co., New York, N. Y.
 Independent Pneu. Tool Co., Chicago, Ill.
 Wodack Elec. Tool Corp., Chicago, Ill.

HAMMERS, Soft

Chicago Rawhide Mfg. Co., Chicago, Ill.
 Greene-Tweed & Co., New York, N. Y.
 P & C Hand Forged Tool Co., Portland 22, Oregon
 Stanley Works, New Britain, Conn.

HAULING, General**ARTHUR MORGAN TRUCKING CO.**

2923 N. Broadway, St. Louis, Mo.

HELMETS

Mine Safety Appliances Co., Pittsburgh, Pa.

containing considerable slag will require a greater oxygen pressure than new or clear metal. A safe rule to follow is that the Oxygen pressure must always be high enough to make the Oxygen burn entirely through. To light the torch for cutting, first open the Acetylene preheating valve, and light it as if for welding. Have a clear space between the burning gas and the tip of one-thirty-second to one-eighth inch, then turn on the oxygen preheating valve until the neutral flame is attained. Now open the Oxygen cutting valve controlling the high pressure oxygen jet, and observe the preheating flame. If it draws long and becomes carbonizing, open the Oxygen preheating valve more, until the preheating flame remains neutral. We are now ready to begin cutting. First be sure there is a clear space underneath the line of the cut for the slag to run free of the metal.

GENERAL ARC WELDING DATA FOR WELDING MILD STEEL SHEETS

Thickness	Electrode Recommended	Approximate Current	Spacing and Beveling
22 ga.	$\frac{1}{16}$ " coated	25 to 35 amperes	$\frac{1}{32}$ " between edges
20 ga.	$\frac{1}{16}$ " coated	30 to 40 amperes	$\frac{1}{32}$ " between edges
18 ga.	$\frac{3}{32}$ " bare or coated	60 to 75 amperes	$\frac{3}{64}$ " between edges
16 ga.	$\frac{3}{32}$ " bare or coated	65 to 80 amperes	$\frac{1}{16}$ " between edges
14 ga.	$\frac{1}{8}$ " bare or coated	70 to 85 amperes	$\frac{1}{16}$ " between edges
12 ga.	$\frac{1}{8}$ " bare or coated	85 to 95 amperes	$\frac{3}{64}$ " between edges
$\frac{7}{8}$ "	$\frac{1}{8}$ " bare or coated	90 to 100 amperes	$\frac{1}{8}$ " between edges
$\frac{5}{32}$ "	$\frac{3}{32}$ " bare or coated	110 to 125 amperes	$\frac{5}{32}$ " between edges
$\frac{3}{16}$ "	$\frac{3}{32}$ " bare or coated	120 to 140 amperes	$\frac{3}{16}$ " between edges
$\frac{1}{16}$ "	$\frac{3}{16}$ " bare or coated	140 to 165 amperes	$\frac{3}{16}$ " between edges
$\frac{1}{4}$ "	$\frac{3}{16}$ " bare or coated	150 to 175 amperes	Single "V"—90 degrees
$\frac{3}{16}$ "	$\frac{3}{16}$ " bare or coated	150 to 175 amperes	Single "V"—90 degrees
$\frac{3}{8}$ "	$\frac{1}{4}$ " coated	175 to 225 amperes	Either single or double
$\frac{1}{2}$ "	$\frac{1}{4}$ " coated	180 to 235 amperes	"V"—90 degrees (double
$\frac{5}{8}$ "	$\frac{1}{4}$ " coated	200 to 250 amperes	preferred if possible).

NOTE—The above data applies to general practice for average requirements in welding together mild steel sheets of equal thickness. Under special requirements, expert operators may deviate from these values for greater speed. When sheets of unequal thickness are to be welded together, use data applying approximately to a size about half way between the two but apply the welding arc mostly to the thicker of the two sheets. Size of electrode should favor the thinner sheet if there is no data for a thickness midway between the two.

HINGES

Auto Moulding & Mfg. Co., Chicago, Ill.
S and S Machine Wks., Chicago, Ill.

HOBGING MACHINES

Brown & Sharpe Mfg., Providence, R. I.
Gould & Eberhardt, Irvington, N. J.
The Hamilton Tool Co., Hamilton, Ohio
Lees-Bradner Co., Cleveland, Ohio

HOISTS

Amer. Engineering Co., Philadelphia, Pa.
Chisholm Moore Hoist Corp., Tonawanda
Coffing Hoist Co., Danville, Ill.
Detroit Hoist & Mach. Co., Detroit, Mich.
Grand Specialties Co., Chicago 22, Ill.
Harnischfeger Corp., Milwaukee, Wis.
Keller Tool Co., Grand Haven, Mich.
The Reading Machine Co., Reading, Ohio
Robbins & Myers, Inc., Springfield, Ohio
Shaw Box Crane & Hoist, Muskegon, Mich.

HOSE, Metallic

Chicago Metal Hose Corp., Maywood, Ill.
Titeflex Metal Hose Co., Newark, N. J.
Weatherhead Co., Cleveland, Ohio

JIGS AND FIXTURES

Richards' Industries, Inc., Grand Rapids
5, Mich.

KEYSEATERS

Amer. Broach & Mach., Ann Arbor, Mich.
Brewer Machine & Mfg. Co., St. Louis, Mo.
John T. Burr Co., Brooklyn, N. Y.
The du Mont Corp., Greenfield, Mass.
Morton Mfg. Co., Muskegon Heights, Mich.
The Reading Machine Co., Reading, Ohio

KEYWAY BROACHES

East Shore Machine Products Co., Cleve-
land, Ohio

KNIFE GRINDERS AND HONERS

Covel-Hanchett Co., Big Rapids, Mich.
Micromatic Hone Corp., Detroit, Mich.
S. C. Rogers & Son Co., Philadelphia, Pa.
Sunnen Prod. Co., St. Louis, Mo.

KNURLING TOOLS

Armstrong Bros. Tool Co., Chicago, Ill.
Graham Mfg. Co., Providence, R. I.
Reed Roller Thread Die Co., Worcester 2,
Mass.
Wade Tool Co., Waltham, Mass.

LAPPING MACHINES, Precision

Crane Packing Co., Chicago 13, Ill.

LATHES, Automatic

Cone Automatic Mach. Co., Windsor, Vt.
Gisholt Machine Co., Madison 10, Wis.
Jones & Lamson Mach., Springfield, Vt.
LeBlond Mach. Tool Co., Cincinnati, Ohio
Monarch Mach. Tool Co., Sidney, Ohio
Seneca Falls Mach. Co., Seneca Falls, N. Y.
Sundstrand Mach. Tool Co., Rockford, Ill.

LATHES, Bench

B. C. Ames Co., Waltham, Mass.
Atlas Press Co., Kalamazoo, Mich.
Elgin Tool Works, Chicago, Ill.
Hardinge Bros. Inc., Elmira, N. Y.
McDonald Machinery Co., St. Louis, Mo.
Rivett Lathe & Grinder Co., Boston, Mass.
Sloan & Chace Mfg. Co., Kearney, N. J.
South Bend Lathe Wks., South Bend, Ind.
Stark Tool Co., Waltham, Mass.

LATHE CENTERS

Pratt & Whitney, West Hartford, Conn.

LATHES, Engine

Amer. Tool Works, Cincinnati, Ohio
Bradford Mach. Tool Co., Cincinnati, Ohio
LeBlond Mach. Tool Co., Cincinnati, Ohio
Lehman Mach. Co., St. Louis, Mo.
McDonald Machinery Co., St. Louis, Mo.
Monarch Mach. Tool Co., Sidney, Ohio
Porter-McLeod Mach. Co., Hatfield, Mass.
Reed-Prentice Corp., Worcester, Mass.
The Sidney Machine Tool Co., Sidney, O.
Simmons Mach. Tool Corp., Albany, N. Y.
South Bend Lathe Wks., South Bend, Ind.

LATHES, Sebastian

King Machine Tool Div. of American Steel
Foundries, Cincinnati 29, Ohio
Sebastian Lathe Co., Cincinnati, Ohio

LATHES, Spinning, Polishing, Etc.

Atlas Press Co., Kalamazoo, Mich.
Boice-Crane Co., Toledo, Ohio
Clizbe Bros., Plymouth, Ind.
Jefferson Mach. Tool Co., Cincinnati, O.
W. C. Lipe, Inc., Syracuse, N. Y.
Standard Elec. Tool Co., Cincinnati, O.
Walker-Turner, Inc., Plainfield, N. J.

LATHES, Toolroom

Amer. Tool Works, Cincinnati, Ohio
Atlas Press Co., Kalamazoo, Mich.
The Boye & Emmes Machine Tool Co.,
Cincinnati 15, Ohio
Gisholt Machine Co., Madison 10, Wis.
Hardinge Bros., Inc., Elmira, N. Y.
LeBlond Mach. Tool Co., Cincinnati, Ohio
McDonald Machinery Co., St. Louis, Mo.
Reed-Prentice Corp., Worcester, Mass.
Rivett Lathe & Grinder Co., Boston, Mass.
The Sidney Machine Tool Co., Sidney, O.
South Bend Lathe Wks., South Bend, Ind.

LATHES, Turret

The Bullard Co., Bridgeport, Conn.
Douglas Mch. Co., New York, N. Y.
Ganey Machinery Co., Buffalo, N. Y.
Gisholt Machine Co., Madison 10, Wis.
Jones & Lamson Mach., Springfield, Vt.
Morey Machinery Co., New York, N. Y.
National Acme Co., Cleveland, Ohio
Potter & Johnston Co., Pawtucket, R. I.
Rivett Lathe & Grinder Co., Boston, Mass.
Sebastian Lathe Co., Cincinnati, Ohio
Warner & Swasey Co., Cleveland, Ohio

LIGHTING FIXTURES

Hygrade Sylvania Corp., Salem, Mass.

LOCK NUTS

Columbia Nut and Bolt Co., Bridgeport,
Conn.

LUBRICATING SYSTEMS

Alemite Co., Chicago, Ill.
Bijur Lubricating Corp., L. I. City, N. Y.
M-B Products Co., Detroit, Mich.
Madison-Kipp Corp., Madison, Wis.
C. A. Norgren Co., Denver, Colo.
Rivett Lathe & Grinder Co., Boston, Mass.
Trico Fuse Co., Milwaukee, Wis.

LUBRICATORS, Automatic Air Line

M-B Products Co., Detroit, Mich.

MACHINERY, Moving.**ARTHUR MORGAN TRUCKING CO.**

2923 N. Broadway, St. Louis, Mo.

ARC WELDING DATA

LENGTH OF FILLET WELD TO REPLACE RIVETS

Rivet Dia. Size	Rivet Shear Value at 19,000 lbs. per sq. in.	Length of Fillet Welds (to nearest 1/4 in.) "Fusion Code" (Structural) Shielded Arc Welding					
		1/4 in. Fillet	5/16 in. Fillet	3/4 in. Fillet	1 in. Fillet	1 1/4 in. Fillet	1 1/2 in. Fillet
1/2"	2356	1 1/4"	1 "	1 5/16"	1 "	1 1/4"	1 1/2"
5/8"	3682	1 3/4"	1 1/2"	1 3/4"	1 "	1 1/4"	1 1/2"
3/4"	5301	2 1/2"	2 "	1 3/4"	1 1/4"	1 1/4"	1 1/2"
7/8"	7216	3 1/4"	2 1/4"	2 1/4"	1 3/4"	1 1/4"	1 1/2"
1"	9425	4 1/4"	3 3/4"	3 "	2 1/4"	1 3/4"	1 1/2"

Note: 1/4" is added to calculated length of fillet.

SAFE ALLOWABLE LOADS FOR FILLET WELDS IN SHEAR

Size of Fillet Weld	Pounds per Lineal Inch—"Fusion Code" (Structural)—A.W.S.
1/4"	1200
3/16"	1800
1/2"	2400
5/16"	3000
3/8"	3600
1/2"	4800
5/8"	6000
3/4"	7200

PROPERTIES OF SHIELDED ARC WELD METAL AND MILD ROLLED STEEL

Material	Tensile Strength Lbs./sq. in.	% Elongation in 2 Inches	Density Grams Per c.c.	Endurance Limit* Lbs./sq. in.	Notched Bar Ft. Lbs.
Weld Metal, made with shielded arc	65,000-75,000	20-35	7.84-7.86	28,000-32,000	25-80 (120d)
Mild Rolled Steel	55,000-65,000	20-30	7.86	24,000-28,000	20-80 (120d)

* Maximum stress in outside fibres, 10 million reversals without failure. Rotating beam test.

STRENGTH OF WELDED JOINTS: Calculation of the designed strength of any welded joint should include consideration of the following factors:

- (1) Strength of weld metal.
- (2) Type of weld.
- (3) Location of weld in relation to parts joined.

In calculating the strength of fillet welds, a unit stress of 13,600 lbs. per square inch is usually employed for tension, shear and compression since in practically every fillet weld shear is present.

For dynamic, vibrational or lifting loads, the unit stress of fillet welds or the strength per lineal inch, should be reduced, depending upon the severity of the load.

Approximately 1/4 in. should be added to the designed length of fillet welds for starting and stopping the arc. The crater in the welds should be filled.

The working strength of butt welds, of 100 per cent penetration into the base metal, is usually calculated by multiplying the net cross sectional area through the throat of the weld by 15,600 lbs. for tension—by 13,600 lbs. for shear—by 18,000 lbs. for compression.

The location of the weld in relation to the parts joined, in many cases, has an effect on the strength of the welded joint. As an example, repeated tests reveal that, when other factors are equal, welds having their linear dimension transverse to the lines of stress are approximately 30 per cent stronger per average unit length than welds with linear dimension parallel to lines of stress. This is depicted graphically in Fig. 1 and is due to the stress distribution along the bead.

(Continued)

MACHINERY BUSHINGS

The Ohio Nut & Washer Co.
Mingo Junction, Ohio

MACHINERY, New and Used

Ariz. Machinery Co., Phoenix, Ariz.
McDonald Machinery Co., St. Louis, Mo.
Southern Machinery Corp., Lakeland, Fla.

MANDRELS (See ARBORS AND MANDRELS)

K. O. Lee & Son, Aberdeen, S. D.

MARKERS, Wire, Pipe and Conduit

W. H. Brady Company, Milwaukee, Wis.

MARKING & NUMBERING MACHINES

Acromark Corporation, Elizabeth, N. J.
W. H. Brady Company, Milwaukee, Wis.
Durant Mfg. Co., Milwaukee, Wis.
New Method Steel Stamp, Detroit, Mich.

Numberall Stamp & Tool Co., Inc.

379 Huguenot Ave., Hugenot Pk., S.I., N.Y.
Single and Multiple Wheel Numbering
Stamps and Machines, Automatic Num-
bering Machines, Name Plate Detail
Presses and Platforms. Stamp Holders
and Marking Apparatus.

The Pannier Corp., Pannier Bldg., Pitts-
burgh, Pa.

SUPERIOR SEAL & STAMP CO.

1402 Vermont Ave.

Detroit 16, Mich.

Brass, Zinc, Aluminum Tool Checks,
Name, Machine, Number Plates, Property
and Inventory Tags, Employee Badges.

**MASKS, Sandblasting, Tumbling,
Plating**

W. H. Brady Company, Milwaukee, Wis.

METAL NAME PLATES

The C. H. Hanson Co., Chicago 10, Ill.

METERS

Brown Instrument Co., Philadelphia, Pa.

MICROMETERS

Banner Mach. Tool & Supply Co.,
St. Louis 7, Mo.
Brown & Sharpe Mfg., Providence, R. I.
Federal Products Corp., Providence 1, R. I.
Lufkin Rule Co., Saginaw, Mich.
Micro Products Co., Detroit, Mich.
Millers Falls Co., Greenfield, Mass.
The L. S. Starrett Co., Athol, Mass.

MILLING ATTACHMENTS

Blank & Buxton Machy., Jackson, Mich.
Burke Mach. Tool Co., Conneaut, Ohio
Halco Products Co., Detroit, Mich.
Jefferson Mach. Tool Co., Cincinnati, Ohio
Kearney & Trecker Corp., Milwaukee, Wis.
Liberty Tool & Gage Wks., Providence
Precision Tool Co., Brooklyn, N. Y.

MILLING CUTTERS

Lovejoy Tool Co., Inc., Springfield, Vt.

MILLING MACHINES

Atlas Press Co., Kalamazoo, Mich.
Bridgeport Machines, Inc., Bridgeport
Brown & Sharpe Mfg. Co., Providence
Cincinnati Mill. Mach. Co., Cincinnati, O.
Cincinnati Planer Co., Cincinnati, Ohio
Douglas Machinery Co., New York, N. Y.
Ekstrom, Carlson Co., Rockford, Ill.
Ingersoll Mill. Mach. Co., Rockford, Ill.
Jackson Mach. & Tool Co., Jackson, Mich.
Jefferson Mach. Tool Co., Cincinnati, O.
Kearney & Trecker Corp., Milwaukee, Wis.
Morton Mfg. Co., Muskegon Heights, Mich.
Nichols-Morris Corp.,
50 Church Street, New York 7, N. Y.
Reed-Prentice Co., Worcester, Mass.
Sundstrand Machine Tool Co., Rockford,
Ill.
Van Norman Mch. Tool, Springfield, Mass.

MILLING MACHINES, Bench & Hand

Burke Mach. Tool Co., Conneaut, Ohio
Elgin Tool Works, Chicago, Ill.
Jefferson Mach. Tool Co., Cincinnati, O.
Kent-Owens Mach. Co., Toledo, Ohio
Nichols-Morris Corp.,
50 Church Street, New York 7, N. Y.
Palmer Industries, Chicago 21, Ill.
Pratt & Whitney, West Hartford, Conn.
Producto Mach. Co., Bridgeport, Conn.

MODELS**PATTERNS AND MODELS
WOOD or METAL**

No Casting can be better than the
Pattern from which it is made
Quality, Service and Satisfaction

American Pattern & Model Co.

1810 Elliott Ave., St. Louis, Mo.
FRanklin 6370

Baum's Metal Specialties, Kansas City, Mo.

INVENTIONS PROMOTED

Patented or Unpatented. In busi-
ness over 30 years. Send drawing
and description or model, or write
for information. Complete facilities.
References.

Adam Fisher Company

621 ENRIGHT, ST. LOUIS, MO.

MOTORS, Electric**BALDOR ELECTRIC COMPANY**

Manufacturers Electric Motors
4351-59 Duncan Ave. St. Louis 10, Mo.
Baldor Ball Bearing Grinders $\frac{1}{2}$ H.P.,
3400 R.P.M., Wheels 7" x 1" x $\frac{5}{8}$ " \$60.00.
A complete line 6" thru 12" $\frac{1}{4}$ H.P. thru
3 H.P.

BALDOR ELECTRIC CO.

Saint Louis 10, Mo.
Electrical Specialists Since 1920
Gast Mfg. Corp., Benton Harbor, Mich.

THE LELAND ELECTRIC COMPANY

1501 Webster St., Dayton 1, Ohio
HE-0461
Electric motors delivery from stock on
ratings from 1/8 to 5 horsepower. Single
phase, three phase, direct current; open
dripproof, totally enclosed. Sales repre-
sentatives and dealers in all principal
cities.

(Continued)




FIG. 1

Transverse welds are stronger than welds parallel to lines of stress.

If the load on the weld is to be properly distributed the welds should be located so as to take account of the shape of the sections joined. An example is illustrated by Fig. 2. The ratio of the lengths of the welds at heel and toe of the angle is such that there will be no tendency for the angle to turn and thus cause eccentric loads on the joint.




FIG. 2

Example of correct lengths of welds for equal load distribution.

Resistance to a turning effect of one member at a joint is best obtained by welds well separated rather than by a single weld or welds close together. In Fig. 3 a single weld at A is not as effective as welds at both A and B in resistance to turning effect. Two small welds at A and B are much more effective than a large single weld at A or B only.




FIG. 3

Example of proper placement of welds to resist turning effect of one member at the joint.

If possible, welded joints should be designed so that bending or prying action is minimized. Symmetrical joints are most desirable as they are very much stronger than non-symmetrical joints, the stress in symmetrical joints being more evenly distributed.

In some designs it may be desirable to take into account the distribution of stress through the welds in a joint. It is known that any abrupt change in surface (for example, a notch or saw cut in a square bar under tension) increases the local stress or causes stress concentration. As an illustration of this principle, the weld, Fig. 4, will have considerably more concentration of stress

(Continued)

MOTORS, Electric

The Lima Electric Motor Co., Lima, Ohio
 Robbins & Myers, Inc., Springfield, Ohio
 Speed Way Mfg. Co., Cicero 50, Ill.

Valley Electric Corp.

Manufacturer

**BALL BEARING ELECTRIC
MOTORS and GRINDERS**

4221-27 Forest Park St. Louis, Mo.

MOTOR BASES PIVOTED

Rockwood Mfg. Co., Inc., Indianapolis 6, Ind.

NAME PLATES

Colonial Brass Co., Middleboro, Mass.
 The C. H. Hanson Co., Chicago 10, Ill.

Miller Dial & Name Plate Co., Los Angeles 21, Calif.

SUPERIOR SEAL & STAMP CO.

1402 Vermont Ave.

Detroit 16, Mich.

Metal Factory, Office, and Plant Protection Badges—Stamped, Coined, Embossed, and Enameled, Tool Checks, Name Plates.

NON-REPEATING DEVICE, Power

Presses

Searjeant Metal Products, Inc., Mendon, N. Y.

NUMBERING MACHINES

Numberall Stamp & Tool Co., Inc.

379 Huguenot Ave., Huguenot Pk., S.I., N.Y.
 Single and Multiple Wheel Numbering Stamps and Machines. Automatic Numbering Machines. Name Plate Detail Presses and Platforms. Stamp Holders and Marking Apparatus.

NUTS, All Kinds

Columbia Nut and Bolt Co., Bridgeport, Conn.

NUT LOCKS

Columbia Nut and Bolt Co., Bridgeport, Conn.

OILSTONES

Bay State Abrasive Products Co., Westboro, Mass.

PATTERNS

American Pattern & Model Co., St. Louis, Mo.

PILLOW BLOCKS

Ahlberg Bearing Co., Chicago, Ill.
 Marlin Rockwell Corp., Jamestown, N. Y.
 Medart Co., St. Louis, Mo.
 Sprout, Waldron & Co., Inc., Muncy, Pa.

PIPE

Midwest Piping & Supply Co., Inc., St. Louis, Mo.

PIVOTED MOTOR BASES

Rockwood Mfg. Co., Inc., Indianapolis 6, Ind.

PLANERS

Boice Crane Co., Toledo, Ohio
 Cincinnati Planer Co., Cincinnati, Ohio
 Cleveland Planer Co., Cleveland, Ohio
 The Hamilton Tool Co., Hamilton, Ohio
 Liberty Planers, Inc., Hamilton, Ohio
 Rockford Mach. Tool Co., Rockford, Ill.

PLIERS

Lapeer Mfg. Co., Lapeer, Mich.
 Osborn Mfg. Co., Warsaw, Ind.

PRESSES, Arbor

Canedy-Otto Mfg. Co., Chicago Hts., Ill.
 Dake Engine Co., Grand Haven, Mich.
 Famco Machine Co., Racine, Wis.
 Greenerd Arbor Press Co., Nashua, N. H.
 W. H. Nicholson & Co., Wilkesbarre, Pa.

PRESS FEEDING PLIERS

Osborn Mfg. Co., Warsaw, Ind.

PRESS GUARDS

Searjeant Metal Products, Inc., Mendon, N. Y.

PRESSES, Hydraulic

Atlas Press Co., Kalamazoo, Mich.
 Beatty Mfg. & Mach. Co., Hammond, Ind.
 Dake Engine Co., Grand Haven, Mich.
 Elmes Engineering Co., Chicago, Ill.
 Hannifin Mfg. Co., Chicago, Ill.
 Hydraulic Press Mfg. Co., Mt. Gilead, O.
 O. C. Keckley Co., Springfield, Ill.
 Logansport Machine Co., Inc., Logansport, Ind.

Niagara Machine & Tool Works, Buffalo N. Y.

The Oilgear Co., Milwaukee 4, Wis.

Remco Prod. Corp., York, Pa.

Verson Allsteel Press Co., Chicago, Ill.

PRESSES, Power

Buffalo Forge Co., Buffalo, N. Y.
 Excelsior Tool and Machine Co., East St. Louis, Ill.

Federal Press Co., Elkhart, Ind.

L and J Press Corp., Elkhart, Ind.

J. L. Lucas & Son, Bridgeport, Conn.

Milliken Mach. Co., West Newton, Mass.

Niagara Machine & Tool Works, Buffalo

Ill. N. Y.

A. H. Nilson Mach. Co., Bridgeport, Conn.
 Sales Service Machine Tool Co., Saint Paul W4, Minn.

Service Machine Co., Chicago 20, Ill.

Verson Allsteel Press Co., Chicago, Ill.

Zeh & Hahnemann, Newark, N. J.

PRESSURE UNITS

Richards' Industries, Inc., Grand Rapids 5, Mich.

PRINTING

Charles Martin Lithographing Co., St. Louis 3, Mo.

Standard Press, Printing, L. A. McClenan, Prop., Box 381, St. Louis, Mo.

PULLEYS

Banner Machine Tool Co., St. Louis, Mo.

Dodge Mfg. Corp., Mishawauka, Ind.

Link-Belt Co., Chicago, Ill.

Medart Company, St. Louis, Mo.

Rockwood Mfg. Co., Inc., Indianapolis 6, Ind.

Sprout, Waldron & Co., Inc., Muncy, Pa.

Continued




FIG. 4

Example of lap weld having poor distribution of stress through weld.

than that in Fig. 5. Fig. 6 allows a much more uniform transfer of stress with a resulting minimum of stress concentration. In many cases such concentra-




FIG. 5

Example of lap weld having a more even distribution of stress through weld.

tion of stress might be small and of minor consequence. However, in heavy or repeated loadings this matter should have the attention of the designer.




FIG. 6

Example of lap weld in which there is a fairly uniform transfer of stress through the weld.

Stress in a weld having its linear dimension approximately parallel to the line of force is not evenly distributed. Under many load conditions, not at all unusual, the stress is greater at the ends of the weld than in the middle. It is therefore, advisable in certain conditions to hook the bead around the joint as indicated in Fig. 7. When this is done, far greater resistance to a tearing action on the weld is obtained.




FIG. 7

Example of welds hooked around the corners to obtain resistance to tearing action on welds when subjected to eccentric loads.

These allowable loads are based on a stress of 13,600 lbs. per square inch in throat section as specified in Structural Code of A.W.S. They are conservative, being based on a factor of safety of about 5, since weld metal has 60,000 to 65,000 pounds per square inch ultimate strength.

In many cases it may be exceeded by 20 per cent or more, depending upon the type of load and character of joint. Then, it would still give factor of safety of about 4.

PULLEYS**VACUUM CUP METAL PULLEY CO., INC.**

12536 Grand River Ave.

Detroit, Michigan

Vacuum Cup Pulleys!

(Aluminum and Gray Iron)

Save You Money!

PUMPS, Coolant, Lubricant, Etc.

Eastern Engineering, New Haven, Conn.

Fulflo Specialties Co., Blanchester, O.

Logansport Machine Co., Inc., Logansport, Ind.

Robbins & Myers, Inc., Springfield, Ohio

Ruthman Mch. Co., Cincinnati, Ohio

Tomkins-Johnson Co., Jackson, Mich.

Vickers Inc., Detroit, Mich.

PUNCHES AND DIES

E. A. Baumbach Mfg. Co., Chicago, Ill.

Excelsior Tool and Machine Co., East St. Louis, Ill.

The J. F. Kidder Mfg. Co., Inc., Burlington, Vt.

Lapeer Mfg. Co., Lapeer, Mich.

T. H. Lewthwaite & Co., New York, N. Y.
Stanley Works, New Britain, Conn.**PUNCHES, Multiple**

Beatty Mfg. & Mach. Co., Hammond, Ind.

Excelsior Tool and Machine Co., East St. Louis, Ill.

Federal Press Co., Elkhart, Ind.

Wiedeman Machine Co., Philadelphia, Pa.

RACKS and BINS, Storage

Lyon Metal Prod. Inc., Aurora, Ill.

Gordon L. Hall Co., Old Lyme, Conn.

Pollard Bross Mfg. Co., Chicago, Ill.

Stackblin Corp., Providence, R. I.

Yohe Supply Co., Canton, Ohio

Western Tool & Mfg. Co., Springfield, O.

RADIAL, Drills

Amer. Tool Works, Cincinnati, Ohio

RADIUM PAINTING

Miller Dial & Name Plate Co., Los Angeles 21, Calif.

REAMERS

Catskill Metal Works, Catskill, N. Y.

Hart Machine Co., Dorchester, Mass.

The Rotor Tool Co., Cleveland 12, Ohio

Wendt-Sonis Co., Hannibal, Mo.

RIVETING BURRS

Square & Square Beveled, Brass (Small and Large Pattern).

The Ohio Nut & Washer Co.

Mingo Junction, Ohio

RIVETING MACHINES

Allen Riveter Co., Chicago, Ill.

Buffalo Forge Co., Buffalo, N. Y.

Chicago Pneu. Tool Co., New York, N. Y.

Grant Mfg. & Mach., Bridgeport, Conn.

High Speed Hammer Co., Rochester, N. Y.

Independent Pneumatic Tool Co., Aurora, Ill.

Keller Tool Co., Grand Haven, Mich.

Lemert Engineering Co., Plymouth, Ind.

Tubular Rivet & Stud, Wollaston, Mass.

RAILROAD EQUIPMENT,Will Reaves Railway Supplies,
St. Louis, Mo.**ROTARY VACUUM PUMPS**

Leiman Bros., Inc., Newark 5, N. J.

ROUTING MACHINES

Bolce Crane Co., Toledo, Ohio

Geo. Gorton Mach. Co., Racine, Wis.

W. B. Knight Machy. Co., St. Louis, Mo.

Onsrud Machine Works, Chicago, Ill.

RULES, SteelBanner Mach. Tool & Supply Co.,
St. Louis 7, Mo.

Brown & Sharpe Mfg., Providence, R. I.

Gueden Co., Audubon, N. J.

Lufkin Rule Co., Saginaw, Mich.

The L. S. Starrett Co., Athol, Mass.

SAFETY DEVICES,Micro Switch Div. of First Industrial
Corp., Freeport, Ill.**SAFETY GUARDS, Power Presses**

Littleford Bros. Inc., Cincinnati 2, Ohio

Searjeant Metal Products, Inc., Mendon,
N. Y.**SAE WASHERS**The Ohio Nut & Washer Co.,
Mingo Junction, Ohio**SANDERS**

Armgo Company, Milwaukee, Wis.

Aro Equipment Corp., Bryan, Ohio

Atlas Press Co., Kalamazoo, Mich.

Buckeye Tools Corp., Dayton, Ohio

Chicago Pneumatic Tool Co., New York 17,
N. Y.

Detroit Surfacing Mach. Co., Detroit, Mich.

Dremel Mfg. Co., Racine, Wis.

R. G. Haskins Co., Chicago, Ill.

Chas. L. Jarvis Co., Middletown, Conn.

Jefferson Mach. Tool Co., Cincinnati, O.

Keller Tool Co., Grand Haven, Mich.

Nedco Tool Co., Waltham, Mass.

Porter Cable Mach. Co., Syracuse, N. Y.

The Rotor Tool Co., Cleveland 12, Ohio

Skilsaw Inc., Chicago, Ill.

Stanley Works, New Britain, Conn.

Stow Mfg. Co., Binghamton, N. Y.

Sundstrand Machine Tool Co., Rockford,
Ill.Vonnegut Moulder Corp., Indianapolis 2,
Ind.

Walker Turner Co., Plainfield, N. J.

SAWS

Clizbe Bros. Mfg. Co., Plymouth, Ind.

Forsberg Mfg. Co., Bridgeport, Conn.

Simonds Saw & Steel Co., Fitchburg, Mass.

SAWS, Metal Cutting

Simonds Saw & Steel Co., Fitchburg, Mass.

SAW SHARPENERS

Black Diamond Saw Mach., Natick, Mass.

★Covel Hanchett Co., Big Rapids, Mich.

(See Adv. under Knife Grinders)

Foley Mfg. Co., Minneapolis, Minn.

Huther Bros. Saw Co., Rochester, N. Y.

Wardwell Mfg. Co., Cleveland, Ohio

SCREW DRIVERS, Power

The Bodine Corp., Bridgeport, Conn.

Chicago Pneumatic Tool Co., New York 17,
N. Y.

Cincinnati Elec. Tool Co., Cincinnati, Ohio

Continued on next page

FLAME CUTTING PROCEDURE

Select the proper burning tip; gas pressures; and cutting speed from the table below. After lighting blowpipe, adjust preheat valves to produce a neutral flame.

Neutral (Pre-heat) Flame: Oxy-acetylene—a clear white flame with the feather drawn up and eliminated. City gas with oxygen—a clear blue flame similar to a gas range; flame length will depend upon existing gas pressures.

Start of the Cut: Let the tip of the neutral flame pre-heat the starting point of the cut to a white heat, then simultaneously set the torch in motion and release the cutting oxygen. After cutting is started, readjust the flame and speed to produce the quality of cut desired.

Faulty Flames: Most flame difficulties arise from dirt lodged in the orifices of the tip—make sure the tip is clean before each cut. Too hot a flame creates beads along the top edge of the cut. Too much oxygen, too slow a speed, or both, produce ragged cutting beneath the top surface. Too little oxygen, too fast cutting, or both, cause excessive drag.

Alloy or Carbon Steels: All steels require the same general type flame and speeds. However, the higher carbon steels require preheating before burning to produce a high quality cut free from surface cracks. Steels of more than .30 carbon, require annealing or flame softening after cutting if the edges are to remain soft.

Heavy Sections: Thicknesses up to one foot can be cut with ordinary equipment; thicker sections usually require special techniques and equipment.

Stainless Steel, Steel Castings, Iron in any form or Non-Ferrous Metals: These metals require special techniques for flame cutting.

FLAME CUTTING TIME AND MATERIAL

Thick- ness of Metal, Inches	Ox- weld Noz- zle No.	Cut- ting Oxy- gen Drill Size	Cutting Oxygen Pres- sure*	Linear Cutting Speed**		Consumption Per Hour	
				Machine Cutting In. Per Min.	Hand Cutting In. Per Min.	Oxygen Cu. Ft.	Acetylene Cu. Ft.
1/8	4	60	16-24	22.6-32.0	19.9-29.8	45-55	7.2-8.8
1/4	6	53	12-18	20.4-28.4	17.6-25.8	77-93	8.7-10.7
3/8	6	53	18-26	18.9-26.3	16.0-23.7	95-115	9.7-11.9
1/2	6	53	22-30	17.6-24.6	14.8-22.2	105-125	10.5-12.9
3/4	6	53	26-35	15.4-21.6	13.1-19.8	117-143	12.0-14.6
1	6	53	30-41	13.6-19.4	11.8-18.0	130-160	13.0-16.0
2	8	46	24-32	10.0-14.0	8.6-13.0	185-225	16.2-19.8
3	8	46	35-45	7.8-10.9	6.6-9.8	240-290	18.5-22.7
4	8	46	45-58	6.4-8.9	5.2-7.8	293-357	21.1-25.9
5	8	46	56-70	5.4-7.4	4.2-6.4	347-423	23.9-29.3
6	10	39	49-64	4.7-6.5	3.5-5.4	400-490	26.5-32.3
8	10	39	65-83	3.7-4.9	2.6-4.2	505-615	31.5-38.5
10	10	39	81-103	2.9-3.8	1.9-3.2	610-750	36.9-45.1
12	12	31	75-93	2.4-3.0	1.4-2.6	720-880	42.3-51.7

Courtesy of The Linde Air Products Company

*Pressure measured at regulator ahead of 50 feet of 3/8" hose.

**Lowest Speeds and highest gas consumption per linear foot are for inexperienced operators, short cuts, dirty or poor material, and hand cutting.

Highest speeds and lowest gas consumption per linear foot are for thoroughly experienced operators, long cuts, clean and good material, and machine cutting.

SCREW DRIVERS, Power

Detroit Power Screw Driver, Detroit, Mich.
Independent Pneumatic Tool Co., Aurora, Ill.

Keller Tool Co., Grand Haven, Mich.
Reed-Prentice Corp., Worcester, Mass.
The Rotor Tool Co., Cleveland 12, Ohio
Syntron Co., Homer City, Pa.

SCREW MACHINES, Automatic

Brown & Sharpe Mfg., Providence, R. I.
Cone Automatic Mach. Co., Windsor, Vt.
Foote-Burt Co., Cleveland, Ohio
National Acme Co., Cleveland, Ohio
Jones & Lamson Mach., Springfield, Vt.
Triplex Mach. Co., New York, N. Y.

SCREW MACHINES, Plain and Hand

Acme Mach. Tool Co., Cincinnati, Ohio
Gisholt Machine Co., Madison, Wis.
W. H. Nichols Co., Waltham, Mass.
Rivett Lathe & Grinder Co., Boston, Mass.
Simmons Mach. Tool Corp., Albany, N. Y.
Warner & Swasey Co., Cleveland, Ohio

SCREWS, Cap and Set

Allen Mfg. Co., Hartford, Conn.
Brighton Screw & Mfg. Co., Cincinnati, O.
Dardelet Threadlock Co., New York, N. Y.
Groove Pin Corp., Union City, N. J.
Holo Krome Screw Corp., Hartford, Conn.
Parker-Kalon Corp., New York, N. Y.
Safety Socket Screw Corp., Chicago, Ill.
Triplex Screw Co., Cleveland, Ohio

SCREWS AND BOLTS, Machine

Bristol Company, Waterbury, Conn.
Economy Machine Co., Chicago, Ill.
Lamson & Sessions Co., Cleveland, Ohio

SCREW MACHINE PRODUCTS

Modern Screw Products Co., St. Louis, Mo.

SELF-RETAINING NUTS

Columbia Nut and Bolt Co., Bridgeport, Conn.

SHACKLE BARS

The Ohio Nut & Washer Co.
Mingo Junction, Ohio

SHAFTS, Flex (See Flex Shaft Equip.)

Acme Tool Co., New York, N. Y.

SHAPERS

Atlas Press Co., Kalamazoo, Mich.
Boice Crane Co., Toledo, Ohio
Cincinnati Shaper Co., Cincinnati, Ohio
Ohio Machine Tool Co., Kenton, Ohio
Reed-Prentice Corp., Worcester, Mass.
Rockford Mach. Tool Co., Rockford, Ill.
Sales Service Machine Tool Co., Saint Paul 44, Minn.

SHAPERS, Vertical

Boice Crane Co., Toledo, Ohio
Cochrane Bly Co., Rochester, N. Y.
Hanson-Whitney Co., Hartford, Conn.
Marburg Brothers, New York, N. Y.
Morey Machy. Co., New York, N. Y.
Pratt & Whitney, West Hartford, Conn.

SHEARS, Hand and Power

Beatty Mfg. Co., Hammond, Ind.
Bremil Mfg. Co., Erie, Pa.
Buckeye Tools Corp., Dayton, Ohio
Buffalo Forge Co., Buffalo, N. Y.
Excelsior Tool and Machine Co., East St. Louis, Ill.

SHEARS, Hand and Power

The J. F. Kidder Mfg. Co., Inc., Burlington, Vt.
A. Klingelhofer, Inc., New York, N. Y.
Marshalltown Mfg. Co., Marshalltown, Ia.
Niagara Mach. & Tool Co., Buffalo, N. Y.
W. A. Whitney Mfg. Co., Rockford, Ill.

SHEARS, Rotary

E. W. Bliss Co., Brooklyn, N. Y.
Consol. Mach. Tool Co., Rochester, N. Y.
Libert Machine Co., Green Bay, Wis.
Niagara Machine & Tool Works, Buffalo 11, N. Y.
Quickwork-Whiting Corp., Harvey, Ill.

SHIMS

The B. F. Goodrich Co., Akron, Ohio

SLOTTING MACHINES

Baker Bros. Inc., Toledo, Ohio
Douglas Machy. Co., New York, N. Y.
General Machinery Corp., Hamilton, Ohio

SOLDERING EQUIPMENT

Imperial Brass Mfg. Co., Chicago, Ill.
Johnson Gas Appliance Co., Cedar Rapids, Ia.
★Modern Engineering Co., St. Louis, Mo.
(See Adv. Back Cover)
Torit Mfg. Co., St. Paul, Minn.
Wayne Chem. Co., Detroit, Mich.

SPECIAL MACHINERY**Ballak & Company**

Manufacturing Machinists
Brass and Aluminum Foundry
Super-Service - Oil-less Bearing
Bronze - Fine Machine Work
Castings and Repair Work
811 No. 9th St. St. Louis, Mo.
GARfield 3954

BREWER MACHINE & MFG. CO.

4821 North Broadway, St. Louis, Mo.
Central 9115
General machine work, gears, gear cutting, keyseating, special machinery, speed reducers, sprockets.

THE ESSMUELLER COMPANY

1220 So. 8th St., St. Louis, Mo.

SPECIAL MACHINERY**Power Transmission Supplies**

Garfield 3490

The Hamilton Tool Co., Hamilton, Ohio

**LIBERTY FOUNDRY PRODUCTS
For Faster Machining**

Gray Iron Castings, Nickel Alloy
Castings, Semi-Steel Castings
Hi-Test Castings

Liberty Foundry Co.

10 Clark-1800
7690 Vulcan Ave. St. Louis, Mo.

When You Need a Good Belt

All Kinds in Stock
Immediate Shipment
Write, Phone or Wire

Missouri Belting Company


1021 So. Grand Blvd., St. Louis, Mo.
GRand 4580

WELDABILITY OF STEELS—(Cont'd)

Heat Treatment of Welded Structures

In order to insure satisfactory results in welded construction, it is sometimes necessary to augment the welding operation with PRE-heat treatment and/or POST-heat treatment. Depending on conditions, the latter may be a stress relieving, annealing or normalizing treatment. Usually, the standard stress relieving treatment is specified.

Since both annealing and normalizing are effective in lowering residual stresses, they are sometimes confused with the simpler stress relieving form of treatment. The following paragraphs describe each of these processes as well as preheating. Note particularly that annealing and normalizing involve heating to above the critical range, whereas stress relieving consists of heating to just below the range. (See diagram.)



Preheating—Heating the base metal prior to the welding operation to the temperature range 300° to 500° F. Depending on conditions, it may be accomplished by heating in furnace, with torch flame, or by a light "preheating" welding pass.

Effect: It slows down the cooling effect (by heat absorption) of the surrounding base metal, thus lowering stresses and tendency towards hardening and cracking.

Stress Relieving—Heating after welding to approximately 1150° F. or just below the lower critical temperature. Heating and cooling rates should not exceed 300°-350° F. per hour. Holding time one hour per inch of greatest thickness.

Effect: Relieves stresses caused by expansion and contraction, serving to minimize distortion in machining operations, improve ductility and fatigue resistance properties.

Annealing (Full)—Heating to a temperature usually about 100° F. above the upper critical, followed by very slow cooling in furnace. (15°-30° F. per hour.)

Effect: Uniform softness for better machining properties.
Refined and uniform grain structure.
Relieved stresses.
Improved ductility but lowered tensile strength.

Normalizing—Heating to above critical range (usually slightly higher than in case of annealing), followed by cooling in still air at room temperature.

Effect: Dissolution of carbide network in higher carbon steels which is formed on slow cooling from high temperatures.
Refined and uniform grain structure.
Higher strength and hardness but less ductility than same steel annealed.

(Continued)

SPECIAL MACHINERY

CEntral 9360

McDonald Machinery Co.

ST. LOUIS' LARGEST STOCK

Machine Shop — Woodworking
Sheet Metal

MACHINES—BOTH NEW & USED

1531-37 N. Broadway, St. Louis, Mo.

Multiple Boring Machine Co., St. Louis,
Mo.

Will Reaves

— RAILWAY SUPPLIES —

1084 ARCADE BUILDING

ST. LOUIS, MISSOURI

Sundstrand Machine Tool Co., Rockford,
IllThe Fred J. Swaine Mfg. Co., St. Louis,
Mo.Swanson Tool & Machine Products, Inc.,
Erie, Pa.**SPEED REDUCERS**

Abart Gear & Mach. Co., Cicero, Ill.

BREWER MACHINE & MFG. CO.4821 North Broadway, St. Louis, Mo.
CEntral 9115General machine work, gears, gear cut-
ting, keyseating, special machinery, speed
reducers, sprockets.

Janette Mfg. Co., Chicago, Ill.

K. O. Lee & Son, Aberdeen, S. D.

Multiple Boring Machine Co., St. Louis,
Mo.**SPRINGS, (All Kinds)**Ace Spring Mfg. Co., Inc., New York City,
N. Y.**SPROCKETS**

Brewer Machine & Mfg. Co., St. Louis, Mo.

STEEL, Aircraft

Bethlehem Steel Co., Bethlehem, Pa.

STEEL, AlloyRepublic Steel Corp., Alloy Steel Div.,
Massillon, Ohio**STEEL STAMPS**

Acromark Corp., Elizabeth, N. J.

The C. H. Hanson Co., Chicago 10, Ill.

J. H. Matthews & Co., Pittsburgh, Pa.
New Method Steel S. Co., Detroit, Mich.
Schwerdtle Stamp Co., Bridgeport, Conn.The Pannier Corp., Pannier Bldg., Pitts-
burgh, Pa.**SUPERIOR SEAL & STAMP CO.**

1402 Vermont Ave.

Detroit 16, Mich.

Stamped and Embossed Metal Name, Ma-
chine, Number, Inventory and Property
Plates and Tags, Tool Checks.**STRAIGHTENING MACHINERY**Sleeper & Hartley, Inc., Worcester, Mass.
U. S. Tool Co., Ampere, N. J.
Watson-Stillman Co., Roselle, N. J.**STUD SETTERS**Chicago Pneumatic Tool Co., New York 17,
N. Y.Independent Pneumatic Tool Co., Aurora,
Ill.

Keller Tool Co., Grand Haven, Mich.

Modern Tool Works, Rochester, N. Y.

Titan Tool Co., Fairview, Pa.

SUPERFINISHING, Machines

Gisholt Machine Co., Madison 10, Wis.

SURFACE PLATES

J. C. Busch Co., Milwaukee, Wis.

Challenge Machy. Co., Grand Haven, Mich.

The Hamilton Tool Co., Hamilton, Ohio

Lombard Gov. Corp., Ashland, Mass.

Milliken Mach. Co., West Newton, Mass.

SWITCHESMicro Switch Div. of First Industrial
Corp., Freeport, Ill.**STENCILS, Ready To Use Letters and
Numbers**

W. H. Brady Company, Milwaukee, Wis.

TAPES, Masking

W. H. Brady Company, Milwaukee, Wis.

TAPPING MACHINES

Atlas Press Co., Kalamazoo, Mich.

Boice Crane Co., Toledo, Ohio

Cleveland Tapping Mach., Cleveland, O.

Delta Mfg. Co., Milwaukee, Wis.

Dorman Machine Works, New York, N. Y.

Ettec Tool Co., Brooklyn, N. Y.

Hamilton Tool Co., Hamilton, Ohio

Kaufman Mfg. Co., Manitowoc, Wis.

Procunier Safety Chuck Co., Chicago, Ill.

Rickert-Shafer Co., Erie, Pa.

TAPS (See DIE AND TAP SETS)

Banner Machine Tool Co., St. Louis, Mo.

TESTING MACHINES AND EQUIP.

Detroit Testing Mach. Co., Detroit, Mich.

Modern Collet & Mach. Co., Ecorse, Mich.

Physicists Research Co., Ann Arbor, Mich.

Pyro-Elec. Inst. Co., Detroit, Mich.

Riehle Testing Mach. Div., E. Moline, Ill.

Shore Inst. & Mfg. Co., Jamaica, N. Y.

TEXT. Books, Machinists & Tool MakersShields Publishing Co., Books for Machin-
ists and Toolmakers, St. Louis 7, Mo.**THREAD, Rolling Machines**Reed Roller Thread Die Co., Worchester 2,
Mass.**THREADING TAPPERS, Hand**

Lassy Tool Corp., Plainville, Conn.

TOGGLE-ACTION CLAMPS

Lapeer Mfg. Co., Lapeer, Mich.

TOGGLE-ACTIO PLIERS


Lapeer Mfg. Co., Lapeer, Mich.

WELDABILITY OF STEELS—


Estimating Electrode Consumption

Figures represent lbs. of heavily coated electrodes required per foot of various sizes and types of welded joints. Weights given are approximate and are based on average welding conditions, accounting for stub end, spatter and coating losses, as well as normal fit-up conditions. Average reinforcement is considered in each case.


Fillet Weld

	Size of Fillet=L	Lbs. of Rod Per Linear Ft.	Size of Fillet=L	Lbs. of Rod Per Linear Ft.
	$\frac{1}{8}$.06	$\frac{1}{2}$.81
	$\frac{3}{16}$.13	$\frac{5}{8}$	1.23
	$\frac{1}{4}$.23	$\frac{3}{4}$	1.76
	$\frac{5}{16}$.36	1	3.12
	$\frac{3}{8}$.46		


Plain Butt Weld 50% Penetration

	Plate Thickness=T	Space Between=S	Lbs. of Rod Per Linear Ft.
	$\frac{3}{16}$	$\frac{1}{16}$	0.21
	$\frac{1}{4}$	$\frac{3}{32}$	0.28
	$\frac{5}{16}$	$\frac{1}{8}$	0.40

Plain Butt Weld 100% Penetration


	Plate Thickness=T	Space Between=S	Lbs. of Rod Per Linear Ft.
	$\frac{1}{8}$	$\frac{1}{16}$	0.16
	$\frac{3}{16}$	$\frac{3}{32}$	0.28
	$\frac{1}{4}$	$\frac{1}{8}$	0.40

"V" Groove Weld


	Plate Thickness=T	Lbs. of Rod Per Linear Ft.	Width of Weld=W
	$\frac{1}{4}$	$0.22 + RA^{**}$	$\frac{19}{64} + S^{*}$
	$\frac{5}{16}$	$0.34 + RA$	$\frac{23}{64} + S$
	$\frac{3}{8}$	$0.49 + RA$	$\frac{7}{16} + S$
	$\frac{1}{2}$	$0.88 + RA$	$\frac{37}{64} + S$
	$\frac{5}{8}$	$1.36 + RA$	$\frac{23}{32} + S$
	$\frac{3}{4}$	$1.90 + RA$	$\frac{7}{8} + S$
	1	$3.30 + RA$	$1\frac{1}{32} + S$

*=Space between plates, or Root Opening. **=Rectangular area. See Rectangular Weld table for value corresponding to RA.

Rectangular Welds = R A Values

	Plate Thickness=T	Lbs. of Rod per Linear Ft. for R A							
		S=Space Between Plates							
		$\frac{1}{8}$ "	$\frac{5}{32}$ "	$\frac{3}{16}$ "	$\frac{1}{4}$ "	$\frac{5}{16}$ "	$\frac{3}{8}$ "	$\frac{1}{2}$ "	
	$\frac{1}{4}$ "	0.20	0.25	0.30	0.41	0.51	0.61		
	$\frac{3}{8}$ "	0.29	0.36	0.43	0.57	0.71	0.86	1.14	
	$\frac{1}{2}$ "	0.37	0.46	0.55	0.73	0.92	1.10	1.47	
	$\frac{5}{8}$ "	0.45	0.56	0.67	0.90	1.12	1.34	1.79	
	$\frac{3}{4}$ "	0.53	0.66	0.80	1.06	1.33	1.59	2.12	
	1"	0.69	0.87	1.04	1.38	1.73	2.08	2.77	

"U" Groove Weld

	Plate Thickness=T	Lbs. of Rod Per Linear Ft.	Width of Weld=W	Plate Thickness=T	Lbs. of Rod Per Linear Ft.	Width of Weld=W
	$\frac{3}{4}$	2.72	$\frac{49}{64}$	2	11.17	$1\frac{19}{64}$
	1	4.08	$\frac{7}{8}$	$2\frac{1}{4}$	13.38	$1\frac{13}{32}$
	$1\frac{1}{4}$	5.62	$\frac{63}{64}$	$2\frac{1}{2}$	15.72	$1\frac{1}{2}$
	$1\frac{1}{2}$	7.30	$1\frac{5}{16}$	$2\frac{3}{4}$	18.25	$1\frac{39}{64}$
	$1\frac{3}{4}$	9.08	$1\frac{3}{8}$	3	21.00	$1\frac{23}{32}$



Railway Supplies

ARCADE BUILDING

SAINT LOUIS

TOOLS, Carbide

Adamas Carbide Corp., Harrison, N. J.
Carboloy Co., Inc., Detroit, Mich.
The Gairing Tool Co., Detroit 32, Mich.
Lovejoy Tool Co., Inc., Springfield, Vt.
McKenna Metals Co., Latrobe, Pa.
W. F. Meyers Co., Inc., Bedford, Ind.
Michigan Tool Co., Detroit, Mich.
Morse Tool Co., Detroit, Mich.
Severance Tool Mfg. Co., Saginaw, Mich.
Super Tool Co., Detroit, Mich.
Vascoy-Ramet Corp., Waukegan, Ill.
Willeys Carbide Tool Co., Detroit, Mich.

TOOL CHECKS

The C. H. Hanson Co., Chicago 10, Ill.

SUPERIOR SEAL & STAMP CO.

1402 Vermont Ave.

Detroit 16, Mich.

Brass, Zinc, Aluminum Tool Checks,
Name, Machine, Number Plates, Property
and Inventory Tags, Employee Badges.

TOOL CHESTS, Steel & Wood

H. Gerstner & Sons, Dayton, Ohio

TOOL HOLDERS

Armstrong Bros. Tool Co., Chicago, Ill.
Auto Ordnance Co., Bridgeport, Conn.
Edw. Blake Co., Newton Centre, Mass.
Lovejoy Tool Co., Springfield, Vt.
Western Tool & Mfg. Co., Springfield, O.

TOOLS, Lathe and Planer

Adamas Carbide Corp., Harrison, N. J.
American Tool Works, Cincinnati, Ohio
Ex-Cell-O Corp., Detroit, Mich.
Hendey Mach. Co., Torrington, Conn.
LeBlond Mach. Tool Co., Cincinnati, O.
O. K. Tool Co., Shelton, Conn.
Ready Tool Co., Bridgeport, Conn.

TOOLS, Precision, Hand

Lufkin Rule Co., Saginaw, Mich.

TOTE PANS

J. L. Lucas & Son, Bridgeport, Conn.
Pollard Bros. Mfg. Co., Chicago 30, Ill.
The Salem Tool Co., Salem, Ohio
Stackbin Corp., Providence, R. I.

TRUCKS, Shop and Warehouse

Allsteel Weld. Truck Corp., Rockford, Ill.
Barrett-Cravens Co., Chicago, Ill.
Chas. E. Francis Co., Rushville, Ind.
The Hamilton Tool Co., Hamilton, Ohio
Lyon-Raymond Corp., Greene, N. Y.
Market Forge Co., Everett 49, Mass.
★Modern Engineering Co., St. Louis, Mo.
(See Adv. Back Cover)
Nutting Truck Co., Faribault, Minn.
Pollard Bros. Mfg. Co., Chicago 30, Ill.

TRUCKING SERVICE

ARTHUR MORGAN TRUCKING CO.

2923 N. Broadway, St. Louis, Mo.

TOOL HOLDERS

ELK TOOLS, INC.

71 West Broadway
New York 7, N. Y.

ELK UNIVERSAL PRECISION TOOL
HOLDER

One Toolholder
New Features!

PERFORMS THE WORK OF 10 DIFFERENT TOOLHOLDERS, WITH GREATER CONVENIENCE AND FLEXIBILITY AND AT A FRACTION OF THE COST. PRECISION MADE FOR SMOOTHER OPERATION OF CAMING MECHANISM (Lacking device) AND FOR 100% INTERCHANGEABILITY OF PARTS. LOCKING DEVICE has greater rigidity and positive locking. Can be locked in either right or left hand position. Square head on both ends of CAM cannot become clogged with chips and interfere with proper locking. No barking of knuckles.

NEW CAM DESIGN provides for increased rigidity of the tool bit. The TRUARC retaining rings in cam provide for easy removal of cam for cleaning, oiling or replacement. Range of CAM provides for locking tool bits of a wide tolerance. BIT AND HOLDER ALWAYS PARALLEL. ELK UNIVERSAL PRECISION TOOL HOLDER which supplements all of the single purpose tool holders, such as are made by other manufacturers. DOES THE JOB OF TEN TOOL HOLDERS! A few of the many different operations that can be accomplished with one same ELK UNIVERSAL PRECISION TOOL HOLDER. Handles all lathe operations—also planer, shaper and special equipment. Quick change bit locking device, special alloy steel body, drop forged and heat treated. Super X tool bit and square box wrench furnished with each tool holder. The biggest value ever offered in a tool holder. For information write Elk Tool, Inc., 71 W. Broadway, New York N. Y.

UNIVERSAL JOINTS

American Tool Works, Hartford, Conn.
Borgeson Mfg. Co., Torrington, Conn.
Mechanics Univ. Joint Co., Rockford, Ill.
McDonald Machinery Co., St. Louis, Mo.

V-BELTS

The B. F. Goodrich Co., Akron, Ohio
Rockwood Mfg. Co., Inc.

V-BLOCKS

Challenge Machy. Co., Grand Haven, Mich.
Lassy Tool Corp., Plainville, Conn.
★McDonald Machinery Co., St. Louis, Mo.
(See Adv. under Lathes)
The L. S. Starrett Co., Athol, Mass.

VALVES AIR

AIR-WAY PUMP & EQUIPMENT CO.

1050 No. Kilbourn Ave.
Chicago 51, Ill.


"Air-O-Chek"—The valve that operates by means of an internal fulcrumed lever. Air-O-Chek airguns have won acceptance with top industrial users.









Galland-Henning Mfg. Co., Milwaukee, Wis.
C. A. Norgren Co., Denver, Colo.

IDENTIFYING METALS BY SPARK TESTING

Spark tests should be made on a high speed power grinder, and the specimen should be held so that the sparks will be given off horizontally. For most accurate results, the sparks should be examined against a dark background, preferably in a dark corner of the shop.

The color, shape, average length, and activity of the sparks are details which are characteristics of the material tested. Spark testing can be a very accurate method of identifying metals but it requires considerable practice and experience to become an expert. Several common sparks are given in the table. If the operator learns the technique for identifying these metals readily, he will soon be able to expand his experience to include others by observation and comparison with the sparks from known samples.



Wrought Iron	Low-Carbon Steel	High-Carbon Steel
 <p>Color - straw yellow Average stream length with power grinder - 65 in. Volume - large Long shafts ending in forks and arrowlike appendages Color - white</p>	 <p>Color - white Average length of stream with power grinder - 70 in. Volume - moderately large Shafts shorter than wrought iron and in forks and appendages Forks become more numerous and sprigs appear as carbon content increases</p>	 <p>Color - white Average stream length with power grinder - 55 in. Volume - large Numerous small and repeating sprigs</p>
Alloy Steel*	White Cast Iron	Gray Cast Iron
 <p>Color - straw yellow Stream length varies with type and amount of alloy content Shafts may end in forks, buds or arrows, frequently with break between shaft and arrow. Few, if any, sprigs Color - white</p>	 <p>Color - red Color - straw yellow Average stream length with power grinder - 20 in. Volume - very small Sprigs - finer than gray iron, small and repeating</p>	 <p>Color - red Color - straw yellow Average stream length with power grinder - 25 in. Volume - small Many sprigs small and repeating</p>
	Malleable Iron	Nickel***
	 <p>Color - straw yellow Average stream length with power grinder - 30 in. Volume - moderate Longer shafts than gray iron ending in numerous small, repeating sprigs</p>	 <p>Color - orange Average stream length with power grinder - 10 in. Short shafts with no forks or sprigs</p>









*These data apply also to cast steel.

**Spark shown is for stainless steel.

***Monel metal spark is very similar to nickel.

Welding Symbols



Adopted As Standard by the American Welding Society, 1937

For Fusion Welding							
Type of Weld							
Bead	Fillet	Groove					Plug & Slot
		Square	Vee	Bevel	U	J	
							

For Both		
Field Weld	Weld All Around	Flush

For Resistance Welding			
Type of Weld			
Spot	Projection	Seam	Butt

Standard Location of Information on Welding Symbols



Dropped 5,000 times without affecting the filler material in any way

INDEPENDENT CYLINDERS

Meet Every Service Demand


Specify that your Acetylene be delivered in Independent Monolithic Cylinders. It will save you money in drayage and delivery costs because these cylinders will take a 5 to 10% greater charge than ordinary tanks. Furthermore, they show no tendency to "spit Acetone," consequently, you can work with higher efficiency as well as preserve your welding equipment with Independent Cylinders. Patronize the gas plant that uses Independent Cylinders . . . it is to **your** advantage.

Prices and literature on Independent Acetylene and Oxygen Cylinders available on request. Write for your free copy of "What Goes In The Bottle."

INDEPENDENT ENGINEERING CO.
O'Fallon, Ill.


WELDABILITY OF STEELS—(Cont'd)

Significance of Typical Combinations




$\frac{3}{8}$ " fillet weld both sides for 6". Welds on both sides are same size unless noted.


$\frac{3}{8}$ " fillet welds 2" long, 4" on centers, opposite sides staggered.




When one member only is to be grooved arrows point to that member, thus:





Indicates plates bevelled at root opening $\frac{1}{8}$ " on assembly, bead deposited on root side.




Indicates field weld both sides, by shop's specification A2.



Vertical plate: double J groove. Weld far side: continuous. Near side: 2" long, 6" on centers.



Significance: Weld all around (encircling member as far as possible). Near side: $\frac{1}{2}$ " fillet, 2" long, 5" on centers. Far side: plate has $\frac{3}{4}$ " J groove (shop's standard), continuous weld.




Read symbols from bottom and right-hand side of drawing; place numerical data on vertical reference lines so reader is properly oriented.




Significance: Square edges on plates clearing $\frac{1}{8}$ ", welded from near side, $\frac{1}{4}$ " penetration required.

Significance: Closely abutting plates with U groove $\frac{1}{8}$ " deep, near side chipped smooth.


Symbols govern to break in continuity of structure or to extent of hatching or dimension lines. Strength of resistance welds in hundreds of pounds noted instead of size:



2000-lb.
spot welds,
at 3" centers.



1500-lb.
projection welds,
at 6" centers.



3500-lb.
seam weld, 9" long,
flush near side.

(Continued)

VALVES, Air Pressure Reducing &

Regulating
M-B Products Co., Detroit, Mich.

VALVES, Air Safety Check

E. D. Bullard Company, San Francisco, Calif.

VALVES, Hydraulic

Berkeley Equipment Co., Corry, Pa.
Black Hawk Mfg. Co., Milwaukee 1, Wis.
Fulfilo Specialties Co., Blanchester, Ohio

GALLAND-HENNING MFG. CO.

2753 South 31st St.

Milwaukee 15, Wis.

Nopak Air and Hydraulic Cylinders—Many Mounting Styles—Up to 1500# PSI Line Pressure. Also Control Valves, Hand, Foot, and Solenoid Operated Valves.

C. B. Hunt & Son, Salem, Ohio
Logansport Mach., Inc., Logansport, Ind.
Oilgear Co., Milwaukee, Wis.
Remco Prod. Corp., York, Pa.
Vickers, Incorporated, Detroit, Mich.

VENTILATING EQUIPMENT

Robbins & Myers, Inc., Springfield, Ohio

VIBRATION FATIGUE TESTERS

All American Tool & Mfg. Co., Chicago 14, Ill.

VICES, Bench

American Scale Co., Kansas City, Mo.
Athol Machine & Foundry Co., Athol, Mass

Banner Machine Tool Co., St. Louis, Mo.
The Birtman Electric Co., Rock Island, Ill.
Brown & Sharpe Mfg., Providence, R. I.
Desmond-Stephan Co., Urbana, Ohio
Fray Mach. Tool Co., Glendale, Calif.

Grand Specialties Co., Chicago 22, Ill.

Hartmann Mfg. Co., Racine, Wis.

Hollands Mfg. Co., Erie, Pa.

Jefferson Mach. Tool Co., Cincinnati, O.

North Brothers, Philadelphia, Pa.

Richards' Industries, Inc., Grand Rapids 5, Mich.

Yost Mfg. Co., Meadville, Pa.

VICES, Combination Pipe

The Vanderman Mfg. Co., Willimantic, Conn.

VICES, Drill Press

J. E. Martin Machine Works, Springfield, Ohio

VICES, Machine

Acme Tool Co., New York, N. Y.

Athol Machine & Foundry Co., Athol, Mass

Brown Engineering Co., Reading, Pa.

Cardinal Machine Co., Glendale, Calif.

Chicago Tool & Engr. Co., Chicago, Ill.

Graham Mfg. Co., Providence, R. I.

Hartmann Mfg. Co., Racine, Wis.

L-W Chuck Co., Toledo, Ohio

J. E. Martin Machine Works, Springfield, Ohio

Mohr Lino Saw Co., Chicago, Ill.

J. E. Plunket Mach. Co., Chicago, Ill.

Richards' Industries, Inc., Grand Rapids 5, Mich.

Sales Service Machine Tool Co., Saint Paul W4, Minn.

WISE-WRENCHES

Lapeer Mfg. Co., Lapeer, Mich.

WASHERS

Flat Washers in Steel, Brass, Copper, Stainless Steel, Aluminum and Lead, The Ohio Nut & Washer Co., Mingo Junction, Ohio

WELDERS, Arc

Automotive Supply Co., Appleton, Wis.

Borm Mfg. Co., Elgin, Ill.

Ergolyte Co., Philadelphia, Pa.

Giant Grip Mfg. Co., Oshkosh, Wis.

Harnischfeger Corp., Milwaukee, Wis.

Hobart Bros. Co., Troy, Ohio

K. O. Lee & Sons, Aberdeen, S. D.

Magic Electro Welder, New York, N. Y.

National Cylinder Gas Co., Chicago, Ill.

WELDERS, Gas

Air Reduction Sales, New York, N. Y.

Linde Air Prod. Co., New York, N. Y.

Metal & Thermit Corp., New York, N. Y.

National Cylinder Gas Co., Chicago, Ill.

*Modern Engineering Co., St. Louis, Mo.

(See Adv. Back Cover)

WELDERS, Spot

Acro Welder Mfg. Co., Milwaukee, Wis.

Alphil Spot Welder Co., New York, N. Y.

Amer. Elec. Fusion Corp., Chicago, Ill.

Dyer Welder & Engr. Co., Kansas City Mo.

Ideal Mfg. Co., Des Moines, Iowa

National Cylinder Gas Co., Chicago, Ill.

Peer Incorporated, Benton Harbor, Mich.

Pier Equipment Co., Benton Harbor, Mich.

Progressive Welder Co., Detroit, Mich.

Topeka Fdy. & Iron Wks., Topeka, Kans.

Una Welding Co., Cleveland, Ohio

Weldex, Inc., Detroit, Mich.

WELDING CYLINDERS

(See CYLINDERS)

WIRE WORKING MACHINERY

Baird Machine Co., Bridgeport, Conn.

John Blaner Co., Sharon, Pa.

A. H. Nilson Mach. Co., Bridgeport, Conn.

F. B. Shuster Co., New Haven, Conn.

Wickwire Bros., Cortland, N. Y.

WRENCHES

Armstrong Bros. Tool Co., Chicago, Ill.

Billing & Spencer Co., Hartford, Conn.

Duro Metal Prod. Co., Chicago, Ill.

P & C Hand Forged Tool Co., Portland 22, Oregon

Plomb Tool Co., Los Angeles, Calif.

Ridge Tool Co., Elyria, Ohio

Trimont Mfg. Co., Roxbury, Mass.

J. H. Williams Co., New York, N. Y.

Southern Machinery Corp., Lakeland, Fla.

Bill Lindsley Machinery Co., Dallas, Texas

McGee & Hogan Machine Works, Salt Lake City, Utah

Ariz. Machinery Co., Phoenix, Ariz.

Cragin & Co., Seattle, Wash.

Precision Machine Works, Tacoma, Wash.

Miller-Knuth Mfg. Co., Omaha, Neb.

Industrial Machine Co., Oklahoma City, Okla.

Southeastern Foundries, Inc., Atlanta, Ga.

MAGNAFLUX TESTS

The Magnaflux Test is generally used to detect the presence of fine cracks, seams and other imperfections, too small to be seen by the naked eye, but which might develop local stress and cause ultimate failure in a finished part. Sometimes it is possible to detect certain defects, which are actually under, yet near the surface of the metal, and which might not otherwise be detected. Magnaflux inspection does not harm the part being tested.

Parts being tested are magnetized by one or more methods, depending on their size, shape and final application. In this condition they are a conductor of a magnetic flux. If interruptions occur in the path of the flux, a local flux leakage field is produced. When fine particles of ferro-magnetic powder come in contact with the specimen they are attracted to the local leakage field and thus outline its size and location.


Ferro-magnetic powder may be applied by: dusting on dry; dipping the parts in an oil bath containing the powder in suspension; or pouring this oil over the parts.

The creation of a flux leakage field requires an interruption in the flow of magnetic flux. The interruption or discontinuity, to be detected, must occur at an angle (preferably as close to 90° as possible) and not parallel to the direction of the flux flow. When the magnetic flux is traveling from one end of a bar to the other, the longitudinal surface discontinuities or seams are not clearly indicated, whereas, a crack extending around the bar across the magnetic flow would be readily revealed. Since the direction of magnetic flow, the amount of current used, the method of applying the ferro-magnetic powder, and the interpretation of the indications, all contribute to this highly specialized test, considerable experience is essential for interpreting results.


It is useless to Magnaflux-test the surface of a bar which is later to be machined. Surface defects indicated by the test might be eliminated while other defects, beneath the surface, might not be revealed in the test, but might show up when the bar is machined.

Because of the variations in testing, any indications that are used as a basis for acceptance or rejection of a part should be interpreted with respect to their number, size and location as well as the stresses to which the part will be subjected. The details of the Magnaflux Test and interpretation should be clearly agreed upon between the user and the steel supplier in advance of production.

(Diagram of magnetic field in and around a magnetized round sample. Note Magnetic flux leakage caused by surface discontinuity.)



BREWER MACHINE & MFG. CO.




GENERAL MACHINE WORK,
GEARS, GEAR CUTTING,
KEYSEATING, SPECIAL MA-
CHINERY, SPEED REDUCERS,
SPROCKETS, GEARS OF EV-
ERY DESCRIPTION MANU-
FACTURED.

BREWER MACHINE & MFG. CO.

4821 NORTH BROADWAY, ST. LOUIS, MO.


CEntral 9115

Meco Everything for Welding




The Meco Cut-Master . . . the most popular cutting torch on the market . . . more torch in the way of efficiency and economy of operation than its modest price would indicate.

The Meco Type-A Heavy-Duty Cutting Torch . . . is the fastest-cutting torch made . . . the torch that can be handled with utmost accuracy in gas cutting for fabrication. A complete range of Cutting Heads, including a straight head, are available for the Meco Type-A. As a result, it is a versatile and flexible cutting torch of greatest possible usefulness throughout the shop . . . the finest torch that money can buy.




the need or opportunity of Equipment arises, consult us . . . we have a complete line to offer.

For over 25 years Meco Oxy-Acetylene Welding Equipment has set the pace in improved design and construction. When you buy Gas Welding Equipment, . . . we have a complete line to offer.




Meco Aviator, . . . the precision Welding Torch . . . accurately constructed for close-flame adjustment . . . really a precision tool, particularly suitable for aviation work.



The Weld-Master Welding Torch weighs but a fraction of old-fashioned Welding Torches of similar capacity. It has the famous, exclusive Circle Mixer and spring tension needle valve. The full gooseneck tips represent an advanced construction and are highly recommended for general welding practice.

The Super Weld-Master Welding Torch is a heavy-duty torch for heavy-duty welding. Equipped with the famous Circle Mixer, which assures a long, hot flame . . . spring tension needle valves, and all the other exclusive features of the Meco Weld-Master Torches.



Meco Weldmaster Cutting Attachment enables the welder to go from welding to cutting in less than 11 seconds . . . a cutting torch that uses less gas than any designed for cutting operations alone.

Meco Safe-T-Chek Regulators . . . (left). Here is shown a cutaway view of a Meco Safe-T-Chek Regulator. The small inset shows the Safe-T-Chek device which operates in such a way so as to eliminate all hazards of explosion . . . this is to be found only on Meco Regulators and is an exclusive Meco patent.

Meco Tripl-Flint Lighter . . . lights the first time every time. Just a small item in the Meco line but indicative of the rugged construction and highest quality, built into every Meco product . . . a heavy-duty lighter that will give a life time of service and carries 3 large flints, mounted in the holder for immediate reserve. lighter and 3 flints 75c



Before purchasing Gas Welding Equipment of any kind, write for a copy of the Meco Catalog. Meco Equipment is at its best in direct comparison with other types of equipment. Wherever possible, we shall be glad to demonstrate Meco Equipment in your plant or shop.

Modern Engineering Co. - Acetylene Gas Co.

3401-15 Pine Boulevard

Jefferson 8250

St. Louis, Missouri